



1. EAST APPROACH



2. NORTH ELEVATION



3. GENERAL VIEW SOUTH IS WEST SPAN



4. UPSTREAM SOUTH



5. DOWNSTREAM NORTH



6. A/C OVERLAY LOOKING NORTH



7. SPAN 1, EXISTING PERF. IN W. WALL @ N.
END.



8. SPAN 1, ACT. COR. EASILY PERF. IN W.
WALL NEAR N. END.



9. SPAN 2, SETTLED/UNDERMINED SACKED
RIP-RAP @ N/E CORNER DRAINAGE PIPE.



10. EROSION HOLE BEHIND SACKED RIP RAP
@ N/E CORNER DRAINAGE PIPE.