



Iron Branch Road/State Street Roadway Improvements

Existing Conditions

- **23 utility poles are located in the roadway or within 1.5 feet from the curb.**
- **Multiple street signs and mailboxes are located in the roadway.**
- **Sidewalks and curb along the roadway are deteriorating.**
- **There are limited storm drain facilities resulting in poor drainage.**