## CULTURAL RESOURCE SURVEY SURVEY UPDATE FORM

CRS# N05196
-------------

1.	HISTORIC NAME/FUNCTION: OI	Ford Dairy			
2.		nt Parkway, Middle of Route 13 about o			ridge
3.	CURRENT CONDITION: exceller	☐ good ☐	fair 🗌	poor 🗌	demolished 🛚
4.	INTEGRITY: The buildings have b	en demolished sinc	e 2006 survey.		
5.	SETTING INTEGRITY: The propert	is still used for agri	cultural purpose	es.	
6. I	FORMS ADDED (give number of form	completed for eacl	n):		
	#: Form:		erty types:		
	0 CRS 2 Main Building Form	N/A			
	0 CRS 3 Secondary Building F				
	0 CRS 4 Archaeological Site F 0 CRS 5 Structure (Building-L				
	0 CRS 6 Structure (Land Feat				
	0 CRS 7 Object Form	N/A			
	0 CRS 8 Landscape Elements				
	1 CRS 9 Map Form	N/A			
	0 CRS 14 Potential District Fo	n N/A			
7.	SURVEYOR INFORMATION: Surveyor name:	Patti Kuhn/Sarah G	roesheck		
	our reyor manne.	ata Kamijoaran G	Noodeon		
	Principal Investigator name:	Patti Kuhn			
	Principal Investigator signature:				
	Organization:	The Louis Berger G	roup	Dat	te: June 2012

B. OTHER NOTES OR OBSERVATIONS:	CRS#	N05196	

Listed on the National Register in 1985 as part of the "Rebuilding St. Georges Hundred, New Castle County, 1850-1880" Multiple Property Nomination. The building was resurveyed in 2006 as part of the U.S. Route 301 Corridor Study, Cultural Resources Planning Study. At that time it was determined that the dwelling and outbuildings had suffered significant loss of integrity due to neglect and vandalism and were no longer eligible for the National Register of Historic Places.

The property is also being evaluated or reassessed for its National Register eligibility or listing status. This evaluation assessment is triggered by the federal undertaking initiated by DelDOT and the Federal Highway Administration as part of the SR 1 Roth Bridge to Interstate 95, Capacity Improvement Project (T200511001; Federal Aid NH-N067(26)). Further referenced information on this property as well as other in the vicinity, can be seen in the Architectural Evaluation entitled, "Architectural Survey Report, SR 1 Widening, New Castle County, Delaware."

STATE HISTORIC CONT in(s)):	EXT FRAMEWORK (check all a	appropriate boxes; refer to state management
a) Time period(s)	Pre-European Conta Paleo-Indian Archaic Woodland I Woodland II	ıct
	1600-1750∀ Contact Period (N 1630-1730∀ Exploration and I 1730-1770∀ Intensified and D 1770-1830∀ Early Industrialization a 1830-1880∀ Industrialization and 1840-1960∀ Suburbanization	Frontier Settlement urable Occupation ation and Early Urbanization Early Suburbanization
b) Geographical zone	☐ Piedmont ☐ Upper Penins ☐ Lower Penins ☐ Coastal ☐ Urban (City o	sula/Cypress Swamp
c) Historic period theme	<b>∌(s)</b>	
	Agriculture  Forestry  Trapping/Hunting  Mining/Quarrying  Fishing/Oystering  Manufacturing  Retailing/Wholesaling  Finance	Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations

Major Families, Individuals and Events

**Professional Services** 

# CULTURAL RESOURCE SURVEY MAP FORM

CRS# N	05196
--------	-------


1.	ADDRESS/LOCATION:	1871 Dupont Parkway, Middletown, Delaware 19709 West side of Route 13 about one mile south of St. Georges Bridge
2	NOT FOR PURLICATION	reason:

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

#### INDICATE NORTH ON SKETCH




#### **INDICATE NORTH ON PLAN**



#### 5. 1968 HISTORIC AERIAL:

#### **INDICATE NORTH ON PLAN**



CULTURAL RESOURCE SURVEY SURVEY UPDATE FORM

CRS

N05196.

1. H	ISTORIC NAMI	E/FUNCTION Old Ford	Dairy
2. A	DDRESS/LOCA	ATION: West Side o	f Rt. 13 About 1.0 Miles S of St. Georges Bridge
3. C	URRENT CON	DITION: excellent	good 🗆 fair 🗆 poor 🗹 demolished 🗆
4. IN	ITEGRITY:	National Reg	g has deteriorated significantly due to neglect since the gister nomination form was prepared in 1985. Both and material damage has occurred.
5. SI	ETTING INTEG	barns, a cor	y retains its historic agricultural land, farm lane, two dairy n crib/granary, a smokehouse, a poultry house, and a cart ver, the outbuildings are in poor condition due to neglect.
6. F	ORMS ADDED		
#:	Form:	List Property Types:	
1	CRS02	Dwelling	
6	CRS03	house, Smokehouse	granary, Dairy barn 1, Dairy barn 2, Poultry
1	CRS09	N/A	
7. SI	URVEYOR INF	ORMATION:	
	Surveyor Na	me:	Elizabeth Amisson / Architectural Historian
	Principal Inv	estigator Name:	Barbara Copp / Sr. Architectural Historian
	Principal Inv	estigator Signature:	Bulsam M. Copp
	Organization	•	A.D. Marble & Company Date: 8/12/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS#

N05196.

Listed in the National Register in 1985 as part of the "Rebuilding St. Georges Hundred, New Castle County, 1850-1880" Multiple Property Nomination. Determined not eligibled under U.S. 301 Project Development.

<ol><li>STATE HISTORIC CONTEXT FRAMEWORK (check management plan(s)):</li></ol>	k all appropriate boxes; refer to state
Paleo-la Archaid Woodla Woodla Woodla Woodla 1630-1750 Contact 1730-1770 Intensific 1770-1830 Early Ind 1830-1880 Industria 1880-1940 Urbaniza 1940-1960 Suburba	ind I ind I ind II Period (Native American) ion and Frontier Settlement ed and Durable Occupation lustrialization ition and Early Urbanization nization and Early Suburbanization nization and Early Ex-urbanization
1960-2000 Deurban	ization and Sprawi
□ Coasta	Peninsula Peninsula/Cypress Swamp
c) Historic period theme(s)	
Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services	<ul> <li>□ Transportation and Communication</li> <li>□ Settlement Patterns and Demographic Changes</li> <li>☑ Architecture, Engineering and Decorative Arts</li> <li>□ Government</li> <li>□ Religion</li> <li>□ Education</li> <li>□ Community Organizations</li> <li>□ Occupational Organizations</li> <li>□ Major Families, Individuals and Events</li> </ul>
Other	Unknown



#### **CULTURAL RESOURCE SURVEY** MAIN BUILDING FORM

CRS#	N05196.01	

1.	I. ADDRESS/LOCATION: West side of Rt. 13 about one mile south of St. George's Bridge							
2.	FUN	NCTION(S): historic s	ingle dwelling		current _	vacant/not in u	se	
3.	YEA	AR BUILT: 1850 CIRCA	A?: X ARC	HITECT/BUILDER:	unknov	vn		
4.	STY	LE OR FLOOR PLAN:	center hall with	eli				
5.	INT	EGRITY: original sit	e X	moved				
	if m N/A	oved, from where			oth N/A	er location's CF	RS #	<u>year</u> N/A
	N/A				N/A			N/A
	a. a	major alterations and addit abandoned - very dilapadate eriorated etc.			ne siding	missing; roof		year
		eriorated etc. N/A						unk.
	D.	N/A						N/A
6.	CUR	RENT CONDITION:	excellent	good	fair	poor	X	
7.	DES	SCRIPTION: (Describe the resou	rce as completely as	possible. Use N/A for a	not applicab	le; leave no blanks.)	1	
	a.	Overall shape: L - shaped Additions: N/A		Stories:	2.5			
	b	Structural system (if know	n): wood frame					
	C.	Foundation: materials basement: full X parti		no basement				

Roof: shape: main block - side gable with 2 cross gables on east elevation; ell - side gable with cross

gable on south elevation materials: asphalt shingles cornice: wood with brackets

dormers: N/A

chimney: location(s): interior of north and south (main block) and west gable ends (ell)

- **DESCRIPTION OF ELEVATIONS:** 
  - Facade: Direction: East
    - 1) Bays
    - 2) Windows 4 - 1st story; 5 - 2nd story; 2 - attic

fenestration Regular

intact - 2/2 doublehung wood - no glass

d. Exterior walls (original if visible& any subsequent coverings): wood clapboard

trim wood shutters N/A

CRS-2 **USE BLACK INK ONLY** 

Facade (cont'd)

3) Door(s) 1

location central bay - 1st story

type double-leaf opening, but no door intact

trim wood

4) Porch(es) extends width of center 3 bays - wood posts, wood floor, supported by brick under posts, replaced concrete steps, hipped roof cov. w/standing seam metal, exposed rafters Victorian/Gothic styling

b. Side: Direction: South

1) Bays 4 including ell

2) Windows 4 openings on 2nd story + 3 in attic, 1 opening in 1st story of ell

fenestration Regular

type no windows intact

trim N/A shutters N/A

3) Door(s)

location opening in 1st story of ell, but no door

type N/A trim wood

4) Porch(es) 1 story, shed roof porch attached to south elevation of rear ell

c. Side: Direction: North

1) Bays 4

2) Windows 3 - 1st story; 4 - 2nd story; 3 - attic

fenestration Regular

type no windows intact

trim wood shutters N/A Door(s) 0 location N/A

type N/A trim N/A Porch(es) N/A

+/ 1 Olon(es/ 14/

d. Rear: Direction: West

3)

3)

1) Bays 4

2) Windows 1 - 1st story main block; 4 - 2nd story main block; 2 - attlc of ell

fenestration irregular

type no windows intact

trim N/A shutters N/A Door(s) 1

location 1st story main block at intersection with rear ell

type no door intact

trim N/A
4) Porch(es) N/A

9. INTERIOR: abandoned; debris scattered throughout; plaster and lath walls

10. LANDSCAPING: yard very overgrown (vines cover several out buildings entirely); fields not planted

11. OTHER COMMENTS: outhouse addition or wood shed at southwest corner of rear ell

### CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# N05196.02

1.	. ADDRESS/LOCATION: West side of Rt. 13 about one mile so	uth of St. George's Bridge	
2.	. FUNCTION(S): historicdairy barn #1	currentvacant/not in use	
3.	3. YEAR BUILT: 1930s CIRCA?: X ARCHITECT/BUILDER	: _Unknown	
4.	STYLE/FLOOR PLAN: dairy barn/horse barn		
5.	i. INTEGRITY: original site X moved		
	if moved, from where	original location's CRS #	<u>year</u>
	N/A	N/A	N/A
	N/A	N/A	N/A
	list major alterations and additions with years (if known)		year
	a. N/A		N/A
	b. N/A		N/A
6.	CURRENT CONDITION: excellent	good fair	poor X

#### 7. DESCRIPTION:

- a. Structural system wood frame
- b. Number of stories 2
- c. Wall coverings corrugated metal
- d. Foundation concrete slab
- e. Roof structural system wood frame coverings corrugated metal openings N/A

#### 8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: north
  - 1) bays: no longer discernible
  - 2) windows: none intact
  - 3) door(s): none intact
  - 4) other: East side house horse stables; west side house milking stalls; 1 story shed roof addition to east elevation; another shed roof addition to south elevation has collapsed

CRS # N05196.02

- b. Side: direction: East
  - 1) bays: no longer discernible
  - 2) windows: none Intact
  - 3) door(s): none intact
  - 4) other: shed roof addition across 1st story
- c. Side: direction; west
  - 1) bays: Entire west section of building has collapsed
  - 2) windows: unknown
  - 3) door(s): unknown
  - 4) other: unknown
- d. Rear: direction: South
  - 1) bays: not accessible
  - 2) windows: not accessible
  - 3) door(s): not accessible
  - 4) other: not accessible
- 9. INTERIOR (if accessible):
  - a) Floor plan stables & milking stalls
  - b) Partition/walls N/A
  - c) Finishes N/A
  - d) Furnishings/machinery none intact

## CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# N05196.03

1.	ADDRESS/LOCATION: West side of Rt. 13 about one mile south of St. George's Bridge	
2.	FUNCTION(S): historic Dairy Barn #2 current vacant/not in use	
3.	YEAR BUILT: 1960 CIRCA?: X ARCHITECT/BUILDER: unknown	
4.	STYLE/FLOOR PLAN: _dairy barn	
5.	INTEGRITY: original site X moved	
	if moved, from where original location's CRS #	уеаг
	N/A	N/A
	N/A N/A	N/A
	list major alterations and additions with years (if known)	year
	a. neglected - no intact doors or windows; batten siding in poor condition	unk.
	b. N/A	N/A
6.	CURRENT CONDITION: excellent good fair	poor X

- 7. DESCRIPTION:
  - a. Structural system wood frame
  - b. Number of stories 2
  - c. Wall coverings metal standing seam
  - d. Foundation concrete slab & cinder block
  - e. Roof structural system gambrel; wood frame coverings metal standing seam openings N/A
- 8. DESCRIPTION OF ELEVATIONS:
  - a. Facade: direction: North
    - 1) bays: 1
    - 2) windows: 0
    - 3) door(s): central opening to both stories but no doors intact
    - 4) other: N/A

	b.	Side: direction: West  1) bays: 2  2) windows: 2 sets of paired window openings in 1st story, but no windows intact
		3) door(s): 0
		0) 4001(S). 0
		4) other: milk house attached to south end of elevation, silo attached to milkhouse (concrete slave)
	C.	Side: direction: East
		1) bays: Not visible - overgrown
		2) windows: 0
		3) door(s): 0
		4) other: N/A
	d.	Rear: direction: South
		1) bays: 3
		2) windows: 2 paired window openings (outer bays), window opening in attic level - no intact windows
		3) door(s): central door opening - no intact doors
		4) other: n/a
9.		RIOR (if accessible):  For plan open central bay with milking stalls on both sides, hay loft on 2nd floor
	b) Pa	rrtition/walls N/A
	c) Fir	nishes N/A
	d) Fu	rnishings/machinery 1 - story, shed roof addition to east elevation

## CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# N05196.04

1.	ADDRESS/LOCATION	: West side of	Rt. 13 about one mile so	outh of St. G	eorge's Bridge	
2.	FUNCTION(S): his	toric <u>corncrib/</u>	granary	current	vacant	
3.	YEAR BUILT: 1880	_ CIRCA?: X	ARCHITECT/BUILDER	R: <u>Unknov</u>	vn	
4.	STYLE/FLOOR PLAN:	central aisle w	th flanking gribs and lo	ft above (ci	cular sawn, cut nails)	
5.	INTEGRITY: or	iginal site X	moved			
	if moved, from where N/A				riginal location's CRS#	<u>year</u> N/A
	N/A			N.	/A	N/A
	list major alterations a	nd additions with	vears (if known)			
	a. N/A	THE GOLD THE	Tyeuro (II Kilowii)			<u>year</u> N/A
	b. N/A					
	D. 197A					N/A
6.	CURRENT CONDITION	l: e	excellent	good	fair	poor X
<b>7</b> .	DESCRIPTION:					
	a. Structural system notes taken from interior; exterior; timber frame covered with vines					
	b. Number of stories	1.5				
	c. Wall coverings wood shingles covered with corrugated metal sheets					
	d. Foundation disc	ontiguous stone				
	e. Roof structural system	gable front; com	mon rafter			

#### 8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: North
  - 1) bays: 3

openings N/A

- 2) windows: Second: (1) 1/1 dhs, lights missing
- 3) door(s): were paired hinged battened wood doors

coverings wood shingles covered with corrugated metal sheets

4) other: N/A

- b. Side: direction: East
  - 1) bays: Not visible; obscured by vines
  - 2) windows: Not visible; obscured by vines
  - 3) door(s): Not visible; obscured by vines
  - 4) other: Not visible; obscured by vines
- c. Side: direction: West
  - 1) bays: Not visible; obscured by vines
  - 2) windows: Not visible; obscured by vines
  - 3) door(s): Not visible; obscured by vines
  - 4) other: Not visible; obscured by vines
- d. Rear: direction: South
  - 1) bays: 3
  - 2) windows: Second: (1) 1/1 dhs, lights missing
  - 3) door(s): were paired hinged battened wood doors
  - 4) other: N/A
- 9. INTERIOR (if accessible):
  - a) Floor plan center aisle with flanking cribs, wide plank flooring at 1st floor
  - b) Partition/walls N/A
  - c) Finishes N/A
  - d) Furnishings/machinery N/A

## CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# N05196.05

3.	YEAR BUILT: 1880 CIRCA?: )	ARCHITECT/BUILDER:	Unknown	
4.	STYLE/FLOOR PLAN: square			
5.	INTEGRITY: original site	( moved		
	if moved, from where		original location's CRS#	<u>year</u>
			· · · · · · · · · · · · · · · · · · ·	
	N/A		N/A	N/A
	N/A N/A		N/A N/A	
	N/A	with years (if known)		N/A N/A
		with years (if known)		N/A
	N/A list major alterations and additions	with years (if known)		N/A N/A year

ADDRESS/LOCATION: West side of Rt. 13 about one mile south of St. George's Bridge

#### 7. DESCRIPTION:

- a. Structural system timber frame
- b. Number of stories 1
- c. Wall coverings wood shakes under deteriorated asphalt shingles
- d. Foundation rests on ground; on brick foundation in 1985
- e. Roof structural system gable front; common rafter coverings wood shakes under deteriorated asphalt shingles openings N/A

#### 8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: East
  - 1) bays: 1 2) windows: 0
  - 3) door(s): 1 opening; door gone; only hinge pins remain
  - 4) other: metal basketball hoop above door

- b. Side: direction: South
  - 1) bays: 1
  - 2) windows: 0
  - 3) door(s): 0
  - 4) other: not visible from exterior; overgrown with vines
- c. Side: direction: North
  - 1) bays: 1
  - 2) windows: 0
  - 3) door(s): 1 door opening
  - 4) other: not visible
- d. Rear: direction: West
  - 1) bays: 1
  - 2) windows: 0
  - 3) door(s): 0
  - 4) other: N/A
- 9. INTERIOR (if accessible):
  - a) Floor plan open, dirt floor
  - b) Partition/walls N/A
  - c) Finishes unfinished
  - d) Furnishings/machinery N/A

## CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# N05196.06

1.	ADDRESS/LOCATION:West side of Rt. 13 about one mile south of St. George's Bridge	
2.	FUNCTION(S): historic poultry house current vacant	
3.	YEAR BUILT: 1930 CIRCA?: X ARCHITECT/BUILDER: Unknown	
4.	STYLE/FLOOR PLAN: rectangular	
5.	INTEGRITY: original site  moved	
	if moved, from where N/A original location's CRS #	<u>year</u> N/A
	N/A N/A	N/A
	list major alterations and additions with years (if known)  a. N/A	<u>year</u> N/A
	b. N/A	N/A
6.	CURRENT CONDITION: excellent  good  fair	poor 🛛
7.	DESCRIPTION:	
	a. Structural system frame	
	b. Number of stories 1	
	c. Wall coverings vertical wood boards	
	d. Foundation poured concrete	
	e. Roof structural system side gable, common rafter coverings wood shingles openings N/A	
8.	DESCRIPTION OF ELEVATIONS: only visible from interior	
	a. Facade: direction: South 1) bays: 4 2) windows: 4 openings	
	3) door(s): 0	
	4) other: N/A	

- b. Side: direction: East
  - 1) bays: 2
  - 2) windows: not visible
  - 3) door(s): 1, batten, wood door
  - 4) other: N/A
- c. Side: direction: West
  - 1) bays: 2
  - 2) windows: 2 openings
  - 3) door(s): 0
  - 4) other: N/A
- d. Rear: direction: N
  - 1) bays: 3
  - 2) windows: not visible
  - 3) door(s): not visible
  - 4) other: not visible
- 9. INTERIOR (if accessible):
  - a) Floor plan open, dirt floor
  - b) Partition/walls N/A
  - c) Finishes N/A
  - d) Furnishings/machinery nesting boxes and roosting perch at N wall

## CULTURAL RESOURCE SURVEY SECONDARY BUILDING FORM

CRS# N05196.07

1.	ADDRESS/LOCATION: West side of	Rt. 13 about one mile sout	th of St. George's Bridge		
2.	FUNCTION(S): historic Cart Shed		current vacant		
3.	YEAR BUILT: 1880 CIRCA?: X	ARCHITECT/BUILDER:	Unknown		
4.	STYLE/FLOOR PLAN: rectangular				
5.	INTEGRITY: original site X	moved			
	if moved, from where		original location's CRS#	year	
	N/A		N/A	N/A	
	N/A		N/A	N/A	
	list major alterations and additions with years (if known)				
	a. later additions to west elevation	·		N/A	
	b. N/A			N/A	
6.	CURRENT CONDITION:	excellent go	ood fair	poor X	

#### 7. DESCRIPTION:

- a. Structural system original block is two bays at east end; timber frame circular sawn timbers in east block (2 bays); tree posts in central block (5 bays); 2x4's at west block (4 bays)
- b. Number of stories 1
- c. Wall coverings corrugated metal sheets
- d. Foundation rests on concrete block piers at north wall
- e. Roof structural system asymmetrical side gable; common rafter coverings corrugated metal sheets openings N/A

#### 8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: South

1) bays: 11 2) windows: 0

3) door(s): 2 sliding wood battened doors at east block - rest of bays are open

4) other: N/A

h	Side:	direction:	Fact
IJ.	Jiue.	uliecuvii.	Edst

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

#### c. Side: direction: West

- 1) bays: 0
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

#### d. Rear: direction: North

- 1) bays: 11 2) windows: 0
- 3) door(s): 0
- 4) other: eleven, evenly spaced open bays

#### 9. INTERIOR (if accessible):

- a) Floor plan open
- b) Partition/walls wooden partition wall between different blocks
- c) Finishes some paint in central block
- d) Furnishings/machinery N/A



CRS#: N05196.

1. ADDRESS/LOCATION:

West Side of Rt. 13 About 1.0 Miles S of St. Georges Bridge

- 2. NOT FOR PUBLICATION:
- 3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

