			DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901					
		CULTURAL RESOUR	CRS #	N08822	22			
	Щ	PROPERTY IDENTIF	SPO Map	08-09-32				
					Hundred	Newcas		
	a summer				Quad	St Georg	ges	
					Other	Parcel 100	4440256	
1. 2.		C NAME/FUNCTION: <u>Dw</u> S/LOCATION: <u>1080 Bea</u>	velling, 1080 Bear Roa r Road, New Castle, D		0			
3.	TOWN/N	EAREST TOWN: Bear				vicinity?	?	
4.	MAIN TY	PE OF RESOURCE:	building ⊠ landscape □	structure district	site	🗌 obj	ect	
5.	MAIN FU	INCTION OF PROPERTY:	Single Dwelling					
6.	PROJEC	T TITLE/ REASON FOR SU	RVEY (if applicable):	SR1 Lane Wid	ening			

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
1	CRS 3 Secondary Building Form	Garage
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

8. SURVEYOR INFORMATION:

Surveyor name:

Patti Kuhn and Sarah Groesbeck

Principal Investigator name:

Patti Kuhn	
Pattickup	

Principal Investigator signature:

Organization:

The Louis Berger Group, Inc. Date: June 2012

9. OTHER NOTES OR OBSERVATIONS:

Aerial photographs indicate a shed on the property, standing southwest of the house. The shed was not visible during the survey. The shed appears to have been built after 1965. An above ground pool, erected post 1965, stands southeast of the house. The yard around the pool is enclosed with wood fencing. A garage, erected prior to 1965, stands south of the house.

The property is also being evaluated or reassessed for its National Register eligibility or listing status. This evaluation assessment is triggered by the federal undertaking initiated by DelDOT and the Federal Highway Administration as part of the SR 1 Roth Bridge to Interstate 95, Capacity Improvement Project (T200511001; Federal Aid NH-N067(26)). Further referenced information on this property as well as other in the vicinity, can be seen in the Architectural Evaluation entitled, "Architectural Survey Report, SR 1 Widening, New Castle County, Delaware."

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a)	Time period(s)	 Pre-European Paleo-Indian Archaic Woodland I Woodland II 	Conta	ct
		1600-1750∀ Contact Per 1630-1730∀ Exploration 1730-1770∀ Intensified a 1770-1830∀ Early Indust 1830-1880∀ Industrializa 1880-1940∀ Urbanizatio 1940-1960∀ Suburbaniz	and F and Du trializa ation a n and	rontier Settlement Irable Occupation tion nd Early Urbanization
b)	Geographical zone	Coastal	enins. Peninsi	ula ula/Cypress Swamp Wilmington)
c)	Historic period theme	e(s)		
		Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services		Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901 CULTURAL RESOURCE SURVEY N08822.001 CRS # MAIN BUILDING FORM 1. ADDRESS/LOCATION: 1080 Bear Road, New Castle, Delaware 19720 current Single Dwelling 2. FUNCTION(S): historic Single Dwelling YEAR BUILT: 1930 CIRCA?: 🖂 3. ARCHITECT/BUILDER: Unknown STYLE OR FLOOR PLAN: 4. Bungalow 5. INTEGRITY: original site moved if moved, from where other location's CRS # year N/A N/A N/A N/A N/A N/A list major alterations and additions with years (if known) year a. N/A N/A b. N/A N/A 6. CURRENT CONDITION: excellent qood 🖂 poor \square fair 🗌 7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.) Overall shape: Rectangular w/ 2 front projecting Stories: 1.5 a. gables, enclosed rear porch Additions: Rear 1-story enclosed porch with half-hipped asphalt shingle roof and projecting front gabled bay on its southeast elevation. Porch has 1/1 vinyl-sash windows with snap-in muntins. b Structural system (if known): Frame Foundation: materials: Concrete Block C. basement: full \Box partial \Box not visible \boxtimes no basement \Box d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding Roof: shape: Side Gable e. materials: Asphalt Shingle cornice: Overhanging, open eaves, front gabled bays feature exposed rafter tails dormers: N/A chimney: location(s): Exterior-end brick chimney with a terracotta chimney pot on southeast elevation **DESCRIPTION OF ELEVATIONS:** 8. а Facade: Direction: Northeast 1) Bays 3 2) Windows Not Visible fenestration Not Visible Not Visible type Not Visible trim shutters Not Visible

Facade (cont'd)

3)	Door(s)	Not Visible				
	location	Not Visible				
	type	Not Visible				
	trim	Not Visible				
4)	Porch(es)	1 bay, front gable porch supported by triple wood posts				

- Side: Direction: Northwest b. 2
 - Bays 1)
 - 2) Windows 4
 - fenestration 2 regular windows and 1 smaller window 1st story, 1 regular window 2nd story 1/1 vinyl-sash with snap-in muntins type Vinyl trim
 - trim
 - Fixed, louvered vinyl shutters 0

2

- 3) Door(s)
- location N/A N/A type N/A trim
- 4) Porch(es) N/A
- Side: Direction: Southeast C.
 - Bavs 1)

-,		—
2)	Windows	2 visible
-	fenestratio	on 2 regular windows on 1 st story
	type	1/1 vinyl-sash with snap-in muntins
	trim	Vinyl trim
	shutters	Fixed, louvered vinyl
3)	Door(s)	N/A
-	location	N/A
	type	N/A
	trim	N/A
4)	Porch(es)	N/A

Rear: Direction: Southwest d.

1)	Bays	Not Visible
2)	Windows	Not Visible
-	fenestratio	on Not Visible
	type	Not Visible
	trim	Not Visible
	shutters	Not Visible
3)	Door(s)	Not Visible
	location	Not Visible
	type	Not Visible
	trim	Not Visible
4)	Porch(es)	1-story enclosed porch covered in vinyl siding

- 9. **INTERIOR: Not Accessible**
- 10. LANDSCAPING: Facing northeast, the house is set back from the road on a level lot. The front yard of the house is overgrown with tall shrubbery, blocking the house from view. The rear yard of the property is enclosed with a wood fence. A paved driveway is located along the east side of the house and leads to the detached garage that stands southeast of the house. Directly north of the house is State Route 1, which is partially blocked from view by mature plantings.
- OTHER COMMENTS: N/A 11.



DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # N08822.002

1.	ADDRESS/LOCATION: 1080 Bear Road, New Castle, Delaware 19720	
2.	FUNCTION(S): historic Garage current Garage	
3.	YEAR BUILT: <u>1940</u> CIRCA?: ARCHITECT/BUILDER: <u>Unknown</u>	
4.	STYLE/FLOOR PLAN: <u>N/A</u>	
5.	INTEGRITY: original site 🛛 moved 🗌	
	if moved, from where original location's CRS #	<u>year</u> N/A
	N/A N/A	N/A
	list major alterations and additions with years (if known) a.	<u>year</u> N/A
	b.	N/A
6.	CURRENT CONDITION: excellent 🛛 good 🗌 fair 🗌	poor 🗌
7.	DESCRIPTION:	
	a. Structural system Concrete block	
	b. Number of stories 1	
	c. Wall coverings Concrete block walls, vinyl-siding in gable ends	
	d. Foundation Concrete	
	e. Roof structural system Front Gable coverings Asphalt Shingle openings None	
8.	DESCRIPTION OF ELEVATIONS:	
	a. Facade: direction: Northeast	

- 1) bays: 2
 - 2) windows: None
 - 3) door(s): 2 roll-up metal garage doors with four lights, 1 single-leaf metal door with 9-light window
 - 4) other: N/A


- b. Side: direction: Northwest
 - 1) bays: 2
 - 2) windows: Not Visible
 - 3) door(s): Not Visible
 - 4) other: N/A
- c. Side: direction: Southeast
 - 1) bays: 2
 - 2) windows: Not Visible
 - 3) door(s): Not Visible
 - 4) other: N/A
- d. Rear: direction: Southwest
 - 1) bays: 2
 - 2) windows: Not Visible
 - 3) door(s): Not Visible
 - 4) other: Not Visible
- 9. INTERIOR (if accessible):
 - a) Floor plan Not Accessible
 - b) Partition/walls Not Accessible
 - c) Finishes Not Accessible
 - d) Furnishings/machinery Not Accessible

ouNO	08822	DELAWARE STATE HISTORIC PRESERVATION OFF 15 THE GREEN, DOVER, DE 19							
		CULTURAL RESOURCE SURVEY				(CRS #	N08822	
		MAP FORM							
1.	ADDRE	SS/LOCATION:	1080	Bear Road	, New Castle, Dela	aware 19720			
2.	NOT FO	OR PUBLICATION		reason:					
3.	LOCAT	ION MAP:							

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS #	N08822	Date	5/22/2012	Photo Roll #	N/A	Surveyor	S. Groesbeck
							P. Kuhn

Description East corner of main building looking (.001) looking southwest; Garage (.002) looking southwest

Negative location (if other than SHPO)

Attach contact print(s):



