

DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-08574

1. HISTORIC NAME/FUNCTION: Coleman Farmstead

2. ADDRESS/LOCATION: Route 16

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: property abandoned and overgrown

5. SETTING INTEGRITY:

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Scott M. Pickens

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: *Grace H. Ziesing*

Organization: John Milner Associates, Inc. Date: 12/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-08574

Resurveyed for the U.S. 113 North/South Study by JMA on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750—Contact Period (Native American)
- 1630-1730—Exploration and Frontier Settlement
- 1730-1770—Intensified and Durable Occupation
- 1770-1830—Early Industrialization
- 1830-1880—Industrialization and Early Urbanization
- 1880-1940—Urbanization and Early Suburbanization
- 1940-1960—Suburbanization and Early Ex-urbanization


b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-08574.001

1. ADDRESS/LOCATION: Route 16

2. FUNCTION(S): historic: domestic current: vacant/not in use

3. YEAR BUILT: 1920s CIRCA?: X ARCHITECT/BUILDER:

4. STYLE OR FLOOR PLAN: double cell plan with ell

5. INTEGRITY: original site X moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. large lower gable addition

b.

6. CURRENT CONDITION: excellent good fair poor X

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangle Stories: 2-1/2
Additions: large lower gable on south side
- b. Structural system (if known): wood-framed
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): wood shingle
- e. Roof: shape: side gable
materials: wood
cornice: exposed rafter ends
dormers:
chimney: location(s): brick, interior gable end

8. DESCRIPTION OF ELEVATIONS:


a.	Facade: Direction: west
1)	Bays: 5
2)	Windows: 5, first story; 2 second story
	Fenestration: regular
	Type: 1/1 double-hung sash; 12-light fixed
	Trim: wood
	Shutters:

	Facade (cont'd)	
	3)	Door(s): 1 Location: south end Type: wood, paneled Trim: plain
	4)	Porch(es): enclosed vestibule
b.	Side: Direction: south	
	1)	Bays: 3
	2)	Windows: 3, first story; 1, attic level Fenestration: Type: 1/1, double-hung sash; 4-light fixed; 12-light fixed Trim: wood Shutters:
	3)	Door(s): 1 Location: east side Type: vertical wood Trim:
	4)	Porch(es): concrete steps/stoop
c.	Side: Direction: north	
	1)	Bays: 2
	2)	Windows: 2, first story; 1, second story Fenestration: Type: 1/1 double-hung sash Trim: wood Shutters:
	3)	Door(s): Location: center Type: other Trim: plain
	4)	Porch(es):
d.	Rear: Direction: east	
	1)	Bays: 4
	2)	Windows: 4, first story; 1, second story Fenestration: regular Type: 1/1 and 2/2 double-hung sash Trim: wood Shutters:
	3)	Door(s): Location: Type: Trim:
	4)	Porch(es):

9.	INTERIOR:
----	------------------

10.	LANDSCAPING: surrounded by agricultural fields
-----	---

11.	OTHER COMMENTS:
-----	------------------------



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-08574.002

1. ADDRESS/LOCATION: Route 16

2. FUNCTION(S): historic barn current vacant/not in use

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. rear 3-bay extension

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories 1-1/2

c. Wall coverings asbestos shingles

d. Foundation concrete block

e. Roof
structural system side gambrel with exposed rafter ends
coverings asphalt shingles
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: west

1) bays: 3

2) windows: 1 (boarded over)

3) door(s): 2 (center garage doors)

4) other:

b. Side: direction: north

- 1) bays:
- 2) windows: 3, second story
- 3) door(s): 2 (1 ground level, 1 loft area)
- 4) other:

c. Side: direction: south

- 1) bays: 3
- 2) windows: 2, first story (6/6 double-hung sash); 3, second story (boarded over)
- 3) door(s): 1, center metal
- 4) other:

d. Rear: direction: east

- 1) bays: [not visible]
- 2) windows:
- 3) door(s):
- 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-08574

1. ADDRESS/LOCATION: Route 16


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-08575

1. HISTORIC NAME/FUNCTION: Cornelius Sutton House

2. ADDRESS/LOCATION: DuPont Highway

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: Newer siding, windows and shutters, poor condition, full width rear addition and utility room, large side addition w/ new front door facing W (addition collapsing)

5. SETTING INTEGRITY: completely overgrown, complex of newer buildings to North (trailers, debris, abandoned newer house on road-front)

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature:

Organization: John Milner Associates, Inc Date: 4/16/2008

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-08575

Resurveyed for US113 North/South Study, Delaware Department of Transportation, by John Milner Associates, Inc.

Collapsing and full of debris

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):


- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-08575.001

1. ADDRESS/LOCATION: DuPont Highway

2. FUNCTION(S): historic Dwelling current dwelling

3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: WWII-Era Cottage

5. INTEGRITY: original site moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. newer siding, windows, shutters; severe deterioration- roof ceiling collapsing

b. N side and rear has shed-roof addition (N collapsing) Front door added to West side of addition

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)


- a. Overall shape: Stories: 1
Additions: N side – shed-roof addition; Rear – shed-roofed addition; front door added to W side of N addition
- b. Structural system (if known): wood-framed
- c. Foundation: materials: concrete block pilings
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): vinyl siding
- e. Roof: shape: gable front, side gable, cross gable
materials: asphalt
cornice: boxed
dormers:
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:

a.	Facade: Direction:	<u>W</u>
	1) Bays	<u>2</u>
	2) Windows	<u>1</u>
	fenestration	<u>irregular</u>
	type	<u>curved bay window – wood with fixed and casement lights, asphalt roof</u>
	trim	<u>wood, aluminum</u>
	shutters	<u>metal, non-functional</u>

	Facade (cont'd)	
3)	Door(s)	1
	location	left side
	type	wood, 6-panel
	trim	plain
4)	Porch(es)	
b.	Side: Direction: N	
1)	Bays	1 (half of this side is not visible due to collapsed side addition)
2)	Windows	1
	fenestration	regular
	type	double-hung, 1/1, wood
	trim	wood
	shutters	n/a
3)	Door(s)	n/a
	location	
	type	
	trim	
4)	Porch(es)	
c.	Side: Direction: S	
1)	Bays	5
2)	Windows	4
	fenestration	irregular
	type	double-hung, 1/1; sliding pair of 1-light sash
	trim	wood, aluminum
	shutters	metal, non-functional
3)	Door(s)	1
	location	left, near front
	type	wood and glass, 9-light, 2 panel
	trim	plain
4)	Porch(es)	
d.	Rear: Direction: E	
1)	Bays	not visible due to full-width rear addition
2)	Windows	
	fenestration	
	type	
	trim	
	shutters	
3)	Door(s)	
	location	
	type	
	trim	
4)	Porch(es)	

9.	INTERIOR:
10.	LANDSCAPING: Lot completely overgrown w/weeds, uncontrolled evergreen shrubs. Concrete pad and unpaved drive to south of house, wooded at rear
11.	OTHER COMMENTS:



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-08575

1. ADDRESS/LOCATION: DuPont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-08576

1. HISTORIC NAME/FUNCTION: Preston Evans House

2. ADDRESS/LOCATION: DuPont Highway

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: Reoriented to face West ca 1950s; screened front porch ca mid 20th century; side porch enclosed early 20th century; double garage added at rear ca mid 20th century (1952?); picture windows installed in all N side

5. SETTING INTEGRITY: none evident


6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature: 

Organization: John Milner Associates, Inc Date: 4/16/2008

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-08576

Resurveyed for US113 North/South Study, Delaware Department of Transportation, by John Milner Associates, Inc.

House originally faced east toward Old State Road. ca mid-20th century was remodeled and reoriented to face west toward route 113. Original center door and windows visible inside garage. Front wing was original in rear ell. Garage addition is on original façade. Owner acquired ca. 1952

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750∇ Contact Period (Native American)
- 1630-1730∇ Exploration and Frontier Settlement
- 1730-1770∇ Intensified and Durable Occupation
- 1770-1830∇ Early Industrialization
- 1830-1880∇ Industrialization and Early Urbanization
- 1880-1940∇ Urbanization and Early Suburbanization
- 1940-1960∇ Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-08576.001

1. ADDRESS/LOCATION: DuPont Highway

2. FUNCTION(S): historic Ag. complex current Ag. complex

3. YEAR BUILT: 1900-1910 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE OR FLOOR PLAN: Altered I-house

5. INTEGRITY: original site moved

if moved, from where

other location's CRS #

year

list major alterations and additions with years (if known)

year

a. large front screened porch, rear garage addition; side porch enclosed-most changes+50yrs ago

b. picture window on N side in ell section; house reoriented to face west ca. mid20th century

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: complex Stories: 2.5
Additions: rear garage

b. Structural system (if known): wood-framed

c. Foundation: materials: brick
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): wood shingle


e. Roof: shape: gable front, side gable, cross gable
materials: metal – modern
cornice: boxed; partial returns – original condition
dormers:
chimney: location(s): int. gable, brick, stucco

8. DESCRIPTION OF ELEVATIONS:

a.	Facade: Direction: <u>W</u>	
	1)	Bays <u>3</u>
	2)	Windows <u>4 (2 each on 1st and 2nd story)</u>
		fenestration <u>irregular</u>
		type <u>double hung, 3/1 ca. early 1900s</u>
		trim <u>wood</u>
	shutters	

	Facade (cont'd)	
	3)	Door(s) 1
		location center
		type wood and glass
		trim
	4)	Porch(es) portico; full-width shed-roof screened porch with block foundation and triple corner posts, appears to date ca. 1950s
b.	Side: Direction: N	
	1)	Bays 4
	2)	Windows 2 (1 st story), 3 (2 nd story), 2 (3 rd story)
		fenestration regular
		type double hung, fixed; 2/2, 3/1 (in picture window)
		trim wood
		shutters
	3)	Door(s)
		location
		type
		trim
	4)	Porch(es)
c.	Side: Direction: S	
	1)	Bays 5
	2)	Windows 8 (4 (1 st story), 2 (on both 2 nd and 3 rd))
		fenestration regular
		type double hung, 2/2, 3/3
		trim wood
		shutters
	3)	Door(s) 1
		location center
		type wood and glass, 4 lights, 2 panels
		trim plain
	4)	Porch(es) portico; Enclosed side porch (kitchen) ca. early 20 th c.; brick foundation
d.	Rear: Direction: E	
	1)	Bays 3
	2)	Windows 3 (2 nd story)
		fenestration regular
		type double hung, 2/2
		trim wood
		shutters
	3)	Door(s)
		location
		type
		trim
	4)	Porch(es)

9.	INTERIOR:
10.	LANDSCAPING: House set far back from road on grassy lot. Surrounded by farm fields. Dirt driveway along S edge of grass leads straight back to turnaround loop S of house. Barn and small shed near loop, other barn to N of house. Mature tree line (evergreen and deciduous) across front yard; 2 trees in driveway loop; large tree at rear; a few bushes and perennials along foundation.
11.	OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-08576.002

1. ADDRESS/LOCATION: DuPont Highway

2. FUNCTION(S): historic Barn current Vacant/ not in use

3. YEAR BUILT: 1910-1920 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. metal cladding on 1st floor- orig. opening covered over. Now oriented to face W (faced E before?)

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood framed

b. Number of stories 1.5

c. Wall coverings metal, wood siding (vertical)

d. Foundation concrete block (old)

e. Roof
structural system gable front, shed
coverings asphalt
openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: W

1) bays: 3

2) windows: 1 (hatch door loft)

3) door(s): 3, center and both sides, 2 sliding wood batn doors, 1 hinged batten door

4) other: _____

- b. Side: direction: N
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other: 1 story rear projection – extension of side shed-roof. Addition has batten door facing east

- c. Side: direction: S
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: E
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-08576.003

1. ADDRESS/LOCATION: DuPont Highway

2. FUNCTION(S): historic Shed current Vacant/ not in use

3. YEAR BUILT: 1920-1930 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Bungalow/ Craftsman

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. bricktex siding
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-framed
- b. Number of stories 1
- c. Wall coverings wood siding (vertical), bricktex
- d. Foundation concrete block – old
- e. Roof
 - structural system gable front, exposed rafter ends
 - coverings asphalt
 - openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: W
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 1, wood, batten door – plain and old
 - 4) other: concrete slab porch – very old with lots of aggregate

- b. Side: direction: N
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: S
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: E
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-08576.004

1. ADDRESS/LOCATION: DuPont Highway

2. FUNCTION(S): historic Barn current Vacant/ not in use

3. YEAR BUILT: 1900 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. bricktex siding, windows boarded up
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-framed
- b. Number of stories 1.5
- c. Wall coverings wood siding (vertical), bricktex
- d. Foundation brick with stucco over
- e. Roof
 - structural system side gable
 - coverings old standing seam metal
 - openings n/a

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
 - 1) bays: 3
 - 2) windows: 1, boarded up – probably 4-light fixed sash
 - 3) door(s): 2, 1 large sliding wood barn door, 1 hinged batten door
 - 4) other: large poured concrete stoop

b. Side: direction: W

1) bays: 1

2) windows: 1, 6-light wood – very old wavy glass

3) door(s): 1 batten wood door, center of 2nd floor - loft

4) other:

c. Side: direction: E

1) bays: 2

2) windows: 2 (1 per story), 1-light replaced, 2nd floor has infill 1-light window and newer metal infill panel near loft door

3) door(s): 1, right side, wood batten door (poor condition)

4) other:

d. Rear: direction: N

1) bays: 0

2) windows:

3) door(s):

4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S-08576

1. ADDRESS/LOCATION: DuPont Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH

