

PROJECT DEFICIENCIES AND SOLUTIONS

DEFICIENCIES

- Substandard Turning Lane Geometry
- Roadside Obstacle
- Substandard Roadway Geometry
- Deteriorated Pipe Culvert
- Severe Intersection Capacity
- Substandard Drainage

ALTERNATIVE SOLUTIONS

