



1. EAST APPROACH ROADWAY LOOKING WEST



2. NORTH ELEVATION LOOKING SOUTH



3. GENERAL VIEW OF WEST CELL LOOKING SOUTH



4. UPSTREAM LOOKING NORTH



5. ASPHALT OVERLAY WEARING SURFACE LOOKING NORTH



6. SPAN 1, W CELL, SMALL CORROSION BLISTERS & PITTING ON FASTENERS LOOK E



7. EROSION BETWEEN SPANS 1 & 2 IN THE NORTH SACK
RIPRAP HEADWALL LOOK NORTH



8. SPAN 2, E CELL, FASTENER SECTION LOSS AT 13 FEET FROM N END,
LOOKING EAST