2006 Overtopping and Embankment Erosion

2006 Overtopping and Embankment Erosion

Existing Dam Overview

Existing Spillway Gates

Existing Spillway Culverts

Historic Mill on South Abutment