BR 3-132 West Approach

BR 3-132 Upstream Looking North

BR 3-132 Downstream Looking South

BR 3-132 Damage at North End

BR 3-132 General View of Span # 2

BR 3-132 Span # 3 Easily Perforated at North End