


Safety Analysis

- ❑ Reviewed 342 crashes along SR 141 within study limits over 5 year period.

- ❑ For clusters, data was analyzed for:
 - Surface conditions
 - Lighting conditions
 - Collision type
 - Contributing factor

Crash Analysis



Condition Assessment

- ❑ Bridges originally constructed in 1963.
- ❑ Relocated a pier for all 4 bridges in 1982.
- ❑ Introduced pin and hinge detail to lengthen Bridge 1-675 and 1-678.
- ❑ Shoulder on Northbound I-95 under SR 141 bridges was removed for widening.
- ❑ Recommendation:
 - All SR 141 bridges over I-95 should be considered for major rehabilitation or replacement as part of improvement project.

