

US 113 North/South Study Milford Area Working Group Meeting #16: March 21, 2007

Agenda

5:45 PM	Call Meeting to Order	Bob Kramer
5:50	Introduction	Monroe Hite, III
6:00	Answers to Specific Questions from the Last Working Group Meeting	Monroe Hite, III
6:10	Review of Workshop Comments	Monroe Hite, III
6:20	Bond Bill Committee Meeting	Monroe Hite, III
6:30	Discussion on Recommended Preferred Alternative	Working Group and Project Team
7:55	Schedule/Next Steps	Monroe Hite, III
8:00	Adjourn	