



-Erosion and drainage issues to be rectified

-South Wall: 80' length -North Wall: 54' length

-10.5' travel lanes

-2' shoulders along culvert section

-Updated striping

