Appendix C: Geomorphological Investigation Reports

FIG. GEO-1: SR 1, Frederica Interchange
P 730
Test Unit N590/E554: South Wall
DRAFT



Ap	10YR3/2 pebbly sandy loam
E	10YR5/4, 6/4pebbly sandy loam
EB	7.5YR5/4 pebbly sandy loam
Bt1	7.5YR4/4 pebbly sandy loam
Bt2	7.5YR4/4 pebbly sandy loam
F1	10YR6/6 mixed clean sand with occasional pebble

Abrupt Boundary
Clear Boundary
Gradual Boundary
Eroded Contact
Root/Void Cast
Pebble
Fire Cracked Rock
Water Table
Sample

FIG. GEO-2: SR 1, Frederica Interchange
P 730
Test Unit N660/E584: South Wall
DRAFT



Ap	10YR3/2 very fine sandy loam
E	10YR5/4, very fine sandy loam
EB	7.5YR5/4, 5/6 very fine sandy loam
Bt1	7.5YR4/6 pebbly, mixed sandy loam

Abrupt Boundary
Clear Boundary
Gradual Boundary
Eroded Contact
Root/Void Cast
Pebble
Fire Cracked Rock
Sample

FIG. GEO-2: SR 1, Frederica Interchange
P 730
Test Unit N590/E554: South Wall



Ap	10YR3/2 pebbly sandy loam
E	10YR5/4, 6/4pebbly sandy loam
EB	7.5YR5/4 pebbly sandy loam
Bt1	7.5YR4/4 pebbly sandy loam
Bt2	7.5YR4/4 pebbly sandy loam
F1	10YR6/6 mixed clean sand with occasional pebble

Abrupt Boundary
Clear Boundary
Gradual Boundary
Eroded Contact
Root/Void Cast
Pebble
Fire Cracked Rock
Water Table
Sample

FIG. GEO-3: SR 1, Frederica Interchange
P 730
Test Unit N660/E584: South Wall



Ap	10YR3/2 very fine sandy loam
E	10YR5/4, very fine sandy loam
EB	7.5YR5/4, 5/6 very fine sandy loam
Bt1	7.5YR4/6 pebbly, mixed sandy loam

Abrupt Boundary
Clear Boundary
Gradual Boundary
Eroded Contact
Root/Void Cast
Pebble
Fire Cracked Rock
Sample

FIG. GEO-1: SR 1, Frederica Interchange
P 730
Test Unit N590/E554: South Wall
DRAFT



Ap	10YR3/2 pebbly sandy loam
E	10YR5/4, 6/4pebbly sandy loam
EB	7.5YR5/4 pebbly sandy loam
Bt1	7.5YR4/4 pebbly clay loam
Bt2	7.5YR4/4 pebbly clay loam
F1	10YR6/6 mixed clean sand with occasional pebble

Abrupt Boundary
Clear Boundary
Gradual Boundary
Eroded Contact
Root/Void Cast
Pebble
Fire Cracked Rock
Water Table
Sample

FIG. GEO-2: SR 1, Frederica Interchange
P 730
Test Unit N660/E584: South Wall



Ap	10YR3/2 sandy loam
E	10YR5/4 sandy loam
EB	7.5YR5/4, 5/6 sandy loam
Bt1	7.5YR4/6 sandy loam

Abrupt Boundary
Clear Boundary
Gradual Boundary
Eroded Contact
Root/Void Cast
Pebble
Fire Cracked Rock
Sample

Figure: Geo-3
Unit N590 E554
Geoarchaeological Data Profile



Figure: Geo-4
Unit N600 E584
Geoarchaeological Data Profile