

HEP NCC, SR896 AND PORTER ROAD INTERSECTION IMPROVEMENTS



PROPOSED IMPROVEMENTS

- 1 IMPROVE SIGNAL SYSTEM AND CHANGE TIMING
- 2 CHANGE LANE CONFIGURATION TO ONE DEDICATED LEFT AND ONE DEDICATED THRU LANE
- 3 EXTEND LEFT TURN LANE AND REMOVE CONCRETE MEDIAN
- 4 REMOVE GUARDRAIL
- 5 WIDEN AND ADD AUXILIARY LANE
- 6 EXTEND LEFT TURN LANE