

**Progress Report (2021)**

<b>Category</b>	<b>Self-Evaluation total</b>	<b>Self-Evaluation Non-Compliant</b>	<b>Prior Progress</b>	<b>Non-Compliant after Prior Progress</b>	<b>Current Year Progress</b>	<b>Non-Compliant Remaining</b>
Curb Barrier	626	625	3	622	17	605
Curb Ramps	5,274	3,411	174	3,237	301	2,936
Driveway Crossings	1,650	956	2	954	21	933
Driveway Crossings Along Non-Compliant Sidewalk	2,283	2,283	2	2,281	46	2,235
Vertical Elevation Difference > 1/2 inch	472	472	2	470	6	464
Horizontal Gaps >1/2 inch	202	202	1	201	8	193
Median/Channelized Island	530	287	10	277	24	519
Non-Compliant Sidewalk 20 Feet or Less	533	533	3	530	11	530
On-Street Parking Location	0	0	0	0	0	0
Path/Trail Berm Running Slope	31	29	0	29	0	29
Pedestrian Signal	1,730	709	14	695	28	667
Pinch Points	298	132	1	131	7	124
Railroad Crossing	48	45	0	45	0	45
Sidewalk Passing Areas	56	0	0	0	0	0
Stub Ends	1,009	520	4	516	54	511
Marked Crosswalk (Count)	1,923	109	0	109	3	106
Missing Sidewalk Links (Miles)	10.79	10.79	0	10.79	0.36	10.43
Sidewalk (Miles)	233.56	101.76	0.07	101.69	1.33	100.36