



**CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM**

CRS # K-02739

1. **HISTORIC NAME/FUNCTION:** Postles/Buffalo Run Farm/Agricultural Complex
2. **ADDRESS/LOCATION:** 4657 Barratts Chapel Road/Northeast of intersection of Barratts Chapel Road and Buffalo Road
3. **CURRENT CONDITION:** excellent good fair poor demolished
4. **INTEGRITY:** Farmhouse has large front and rear additions, as well as replacement roofing, siding, windows, and shutters. Seven of the 10 outbuildings are not historic.
5. **SETTING INTEGRITY:** The farmhouse and outbuildings are surrounded by over 116 acres of farmland. The setting retains integrity.

6. **FORMS ADDED (give number of forms completed for each):**

#:	Form:	List property types:
1	CRS 2 Main Building Form	Farmhouse
10	CRS 3 Secondary Building Form	10 outbuildings (sheds and barns)
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

7. **SURVEYOR INFORMATION:**

Surveyor name: Laura C. Ricketts and Bradley S. Reese

Principal Investigator name: Laura C. Ricketts

Principal Investigator signature: *Laura C. Ricketts*

Organization: Skelly and Loy, Inc. Date: 1/2008

8. OTHER NOTES OR OBSERVATIONS:

CRS# K-02739

The property is currently known as the Caulk Buffalo Run Farm.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750± Contact Period (Native American)
 - 1630-1730± Exploration and Frontier Settlement
 - 1730-1770± Intensified and Durable Occupation
 - 1770-1830± Early Industrialization
 - 1830-1880± Industrialization and Early Urbanization
 - 1880-1940± Urbanization and Early Suburbanization
 - 1940-1960± Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # K-02739.001

1. ADDRESS/LOCATION: 4657 Barratts Chapel Road/Northeast of intersection of Barratts Chapel Road and Buffalo Road

2. FUNCTION(S): historic Farmhouse current Farmhouse

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: N/A

4. STYLE OR FLOOR PLAN: I-house with front and rear additions

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>other location's CRS #</u>	<u>year</u>
N/A	N/A	N/A

list major alterations and additions with years (if known)

	<u>year</u>
a. Front one-story addition with bay window (before 1980)	N/A
b. Rear one-story addition with attached two-car garage (before 1980)	N/A

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: Rectangular plan with wings Stories: 2 1/2
Additions: One-story front addition with enclosed porch and extension to SE, three one-story rear additions including two-car garage and passage to garage

b. Structural system (if known): Frame

c. Foundation: materials: Concrete block
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): White aluminum siding

e. Roof: shape: Side gable with flat, shed, and front gable roofs on additions
materials: Asphalt shingle
cornice: Simple boxed cornice with rain gutters
dormers: 0
chimney: location(s): 1 exterior W main, 1 interior E main, 1 exterior N addition

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: South
 - 1) Bays 3 (main), 2 (addition)
 - 2) Windows 9 (replacement)
 - fenestration Regular (main), irregular (addition)
 - type 1/1 sash, paired 6/6 sash, paired 8/8 sash, 3-sided bay
 - trim Simple
 - shutters Replacement aluminum louvered shutters

Facade (cont'd)

- 3) **Door(s)** 0
 location N/A
 type N/A
 trim N/A
 4) **Porch(es)** One-story enclosed porch addition

b. Side: Direction: West

- 1) **Bays** 6
 2) **Windows** 4 (replacement)
 fenestration Regular
 type 1/1 sash, paired 1/1 sash
 trim Simple
 shutters Replacement aluminum louvered shutters
 3) **Door(s)** 3
 location 2 overhead garage doors at N end, 1 pedestrian door at south end
 type Aluminum, not visible
 trim Simple
 4) **Porch(es)** 0

c. Side: Direction: East

- 1) **Bays** 6
 2) **Windows** 6 (replacement)
 fenestration Regular
 type Paired 8/8
 trim Simple
 shutters Replacement aluminum louvered shutters
 3) **Door(s)** 2
 location Midpoint of east elevation at rear addition
 type Aluminum and glass
 trim Simple
 4) **Porch(es)** Open porch on raised decking


d. Rear: Direction: North

- 1) **Bays** 5
 2) **Windows** 3 visible (replacement)
 fenestration Irregular
 type Paired 8/8 sash, 1/1 sash
 trim Simple
 shutters 0
 3) **Door(s)** 0
 location N/A
 type N/A
 trim N/A
 4) **Porch(es)** 0

9. **INTERIOR:** Not accessible.

10. **LANDSCAPING:** Mature trees and shrubs with minimal foundation plantings.

11. **OTHER COMMENTS:** In-ground pool located behind (NE) house.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-02739.002

1. ADDRESS/LOCATION: 4657 Barratts Chapel Road/Northeast of intersection of Barratts Chapel Road and Buffalo Road

2. FUNCTION(S): historic Shed current Shed

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: N/A

4. STYLE/FLOOR PLAN: Utilitarian/Rectangular plan

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	<u>N/A</u>

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
<u>a. N/A</u>	<u>N/A</u>
<u>b.</u>	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system Frame

b. Number of stories 1

c. Wall coverings Aluminum siding and vertical board panels

d. Foundation Not visible

e. Roof

structural system Front gable frame

coverings Standing seam metal roofing

openings 0

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: South

1) bays: 1

2) windows: 0

3) door(s): 1 wood pedestrian door at center

4) other: Linked by wood gate to K-02739.003 to east

b. Side: direction: West

- 1) bays: 2
- 2) windows: 0
- 3) door(s): 4 sliding barn doors cover entire elevation
- 4) other: N/A

c. Side: direction: East

- 1) bays: 2
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

d. Rear: direction: North

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-02739.003

1. ADDRESS/LOCATION: 4657 Barratts Chapel Road/Northeast of intersection of Barratts Chapel Road and Buffalo Road

2. FUNCTION(S): historic Chicken house current Shed

3. YEAR BUILT: 1920 CIRCA?: ARCHITECT/BUILDER: N/A

4. STYLE/FLOOR PLAN: Utilitarian/Rectangular plan

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year
N/A N/A N/A

list major alterations and additions with years (if known) year
a. N/A N/A
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system Frame
b. Number of stories 1
c. Wall coverings Aluminum siding
d. Foundation Not visible
e. Roof
structural system Side gable frame
coverings Standing seam metal roofing
openings 0

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: South
1) bays: 3
2) windows: 2 9-pane fixed windows
3) door(s): 1 wood pedestrian door
4) other: Linked by wood gate to K-02739.002 to west and K-02739.004 to east

- b. **Side: direction: West**
 - 1) **bays: 1**
 - 2) **windows: Not visible**
 - 3) **door(s): Not visible**
 - 4) **other: N/A**

- c. **Side: direction: East**
 - 1) **bays: 1**
 - 2) **windows: Not visible**
 - 3) **door(s): Not visible**
 - 4) **other: N/A**

- d. **Rear: direction: North**
 - 1) **bays: 3**
 - 2) **windows: Small wood access panel at lower east corner**
 - 3) **door(s): 0**
 - 4) **other: Two half-height frame coop structures appended behind shed**


9. **INTERIOR (if accessible):**

a) **Floor plan** Not accessible

b) **Partition/walls** Not accessible

c) **Finishes** Not accessible

d) **Furnishings/machinery** Not accessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-02739.004

1. ADDRESS/LOCATION: 4657 Barratts Chapel Road/Northeast of intersection of Barratts Chapel Road and Buffalo Road

2. FUNCTION(S): historic Shed current Shed

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: N/A

4. STYLE/FLOOR PLAN: Utilitarian/Rectangular plan

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
N/A	N/A	N/A

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
a. N/A	N/A
b.	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system Frame

b. Number of stories 1

c. Wall coverings Aluminum siding and vertical groove plywood panels

d. Foundation Not visible

e. Roof

structural system Side gable with shed roof at rear frame

coverings Corrugated metal roofing

openings Square plan small cupola/vent with weathervane at center

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: South

1) bays: 2

2) windows: 0

3) door(s): 1 wood pedestrian door at west end of facade

4) other: N/A

b. Side: direction: West

- 1) **bays:** 1
- 2) **windows:** Not visible
- 3) **door(s):** Not visible
- 4) **other:** N/A

c. Side: direction: East

- 1) **bays:** 1
- 2) **windows:** 0
- 3) **door(s):** 1 sliding door at north corner
- 4) **other:** N/A

d. Rear: direction: North

- 1) **bays:** 2
- 2) **windows:** 0
- 3) **door(s):** 0
- 4) **other:** N/A

9. INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-02739.005

1. ADDRESS/LOCATION: 4657 Barratts Chapel Road/Northeast of intersection of Barratts Chapel Road and Buffalo Road

2. FUNCTION(S): historic Machine shed current Shed

3. YEAR BUILT: 1975 CIRCA?: ARCHITECT/BUILDER: N/A

4. STYLE/FLOOR PLAN: Utilitarian/rectangular plan

5. INTEGRITY: original site moved

if moved, from where
N/A

original location's CRS # year
N/A N/A

list major alterations and additions with years (if known)

a. N/A

year
N/A

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system Frame

b. Number of stories 1

c. Wall coverings Plywood panels

d. Foundation Not visible

e. Roof

structural system Shed roof (enclosed area), shed roof (open storage) frame

coverings Standing seam metal roofing

openings 0

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: South

1) bays: 2

2) windows: 1 1/1 sash

3) door(s): 0

4) other: A tall antenna/light tower is located at the SE corner of the structure

b. Side: direction: West

- 1) **bays:** 1
- 2) **windows:** 0
- 3) **door(s):** 0
- 4) **other:** N/A

c. Side: direction: East

- 1) **bays:** 1
- 2) **windows:** 0
- 3) **door(s):** 1 sliding wood door
- 4) **other:** Open area under shed roof

d. Rear: direction: North

- 1) **bays:** 2
- 2) **windows:** 0
- 3) **door(s):** 1 pedestrian door
- 4) **other:** N/A

9. INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-02739.006

1. ADDRESS/LOCATION: 4657 Barratts Chapel Road/Northeast of intersection of Barratts Chapel Road and Buffalo Road

2. FUNCTION(S): historic Garage current Garage

3. YEAR BUILT: 1970 CIRCA?: ARCHITECT/BUILDER: N/A

4. STYLE/FLOOR PLAN: Prefabricated utilitarian/Rectangular plan

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year
N/A N/A N/A

list major alterations and additions with years (if known) year
a. One-story shed roof addition on south side N/A
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system Frame

b. Number of stories 1

c. Wall coverings Ridged metal siding

d. Foundation Concrete slab

e. Roof

structural system Side gable (main) and shed roof (addition) frame

coverings Standing seam metal roofing and corrugated metal roofing

openings 0

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: East

1) bays: 4

2) windows: 0

3) door(s): 1 pedestrian door to south and 1 overhead double garage door at center

4) other: N/A

- b. Side: direction: South
 - 1) bays: 3
 - 2) windows: 0
 - 3) door(s): 3 metal pedestrian doors
 - 4) other: N/A

- c. Side: direction: North
 - 1) bays: 3
 - 2) windows: 0
 - 3) door(s): 0
 - 4) other: N/A

- d. Rear: direction: West
 - 1) bays: 4
 - 2) windows: Not visible
 - 3) door(s): Not visible
 - 4) other: N/A

9. INTERIOR (if accessible):

- a) Floor plan Not accessible

- b) Partition/walls Not accessible

- c) Finishes Not accessible

- d) Furnishings/machinery Not accessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-02739.007

1. ADDRESS/LOCATION: 4657 Barratts Chapel Road/Northeast of intersection of Barratts Chapel Road and Buffalo Road

2. FUNCTION(S): historic Storage shed current Storage shed

3. YEAR BUILT: 1992 CIRCA?: ARCHITECT/BUILDER: N/A

4. STYLE/FLOOR PLAN: Prefabricated pole building/Rectangular plan

5. INTEGRITY: original site moved

if moved, from where
N/A

original location's CRS # year
N/A N/A

list major alterations and additions with years (if known)

a. One-story shed roof additions on east (open) and west (enclosed) sides year
N/A

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system Frame

b. Number of stories 1 double story

c. Wall coverings Green standing seam metal cladding

d. Foundation Not visible

e. Roof

structural system Front gable with shed roof wings at east and west frame

coverings Standing seam metal roofing

openings 0

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: South

1) bays: 6

2) windows: 0

3) door(s): Sliding barn doors at center, pedestrian door at west of center

4) other: N/A

b. Side: direction: West

- 1) bays: 6
- 2) windows: 0

- 3) door(s): 0

- 4) other: N/A

c. Side: direction: East

- 1) bays: 6
- 2) windows: 0

- 3) door(s): 0

- 4) other: N/A

d. Rear: direction: North

- 1) bays: 6
- 2) windows: 0

- 3) door(s): Sliding barn doors at center

- 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-02739.008

1. ADDRESS/LOCATION: 4657 Barratts Chapel Road/Northeast of intersection of Barratts Chapel Road and Buffalo Road

2. FUNCTION(S): historic Storage shed current Storage shed

3. YEAR BUILT: 1985 CIRCA?: ARCHITECT/BUILDER: N/A

4. STYLE/FLOOR PLAN: Prefabricated utilitarian/Rectangular plan

5. INTEGRITY: original site moved

if moved, from where original location's CRS # year
N/A N/A N/A

list major alterations and additions with years (if known) year
a. N/A N/A
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system Frame
b. Number of stories 1
c. Wall coverings Green standing seam metal cladding
d. Foundation Not visible
e. Roof
structural system Front gable frame
coverings Standing seam metal roofing
openings 0

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: South
1) bays: 1
2) windows: 0
3) door(s): 1 overhead double door at center
4) other: N/A

b. Side: direction: West

- 1) bays: 3
- 2) windows: 0
- 3) door(s): 1 pedestrian door at south corner
- 4) other: N/A

c. Side: direction: East

- 1) bays: 3
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

d. Rear: direction: North

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-02739.009

1. ADDRESS/LOCATION: 4657 Barratts Chapel Road/Northeast of intersection of Barratts Chapel Road and Buffalo Road

2. FUNCTION(S): historic Shed (pool storage) current Shed (pool storage)

3. YEAR BUILT: 1990 CIRCA?: ARCHITECT/BUILDER: N/A

4. STYLE/FLOOR PLAN: Utilitarian/Rectangular plan

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	<u>N/A</u>

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
<u>a. N/A</u>	<u>N/A</u>
<u>b.</u>	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system Frame
- b. Number of stories 1 (short story)
- c. Wall coverings Vertical board and board and batten
- d. Foundation Not visible
- e. Roof
 - structural system Shed with front overhang frame
 - coverings Asphalt shingle
 - openings 0

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: West
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 1 at center
 - 4) other: N/A

b. Side: direction: South

- 1) **bays: 1**
- 2) **windows: 0**
- 3) **door(s): 0**
- 4) **other: N/A**

c. Side: direction: North

- 1) **bays: 1**
- 2) **windows: 0**
- 3) **door(s): 0**
- 4) **other: N/A**

d. Rear: direction: East

- 1) **bays: 1**
- 2) **windows: 0**
- 3) **door(s): 0**
- 4) **other: N/A**

9. INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-02739.010

1. ADDRESS/LOCATION: 4657 Barratts Chapel Road/Northeast of intersection of Barratts Chapel Road and Buffalo Road

2. FUNCTION(S): historic Shed current Shed

3. YEAR BUILT: 1985 CIRCA?: ARCHITECT/BUILDER: N/A

4. STYLE/FLOOR PLAN: Utilitarian/Rectangular plan

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year
N/A N/A N/A

list major alterations and additions with years (if known) year
a. N/A N/A
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system Frame
b. Number of stories 1
c. Wall coverings Plywood panels
d. Foundation Not visible
e. Roof Shed roof
structural system Shed roof frame
coverings Corrugated metal roofing
openings 0

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: South
1) bays: 1
2) windows: 0
3) door(s): 1 large opening at center
4) other: N/A

b. Side: direction: West

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

c. Side: direction: East

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

d. Rear: direction: North

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-02739.011

1. ADDRESS/LOCATION: 4657 Barratts Chapel Road/Northeast of intersection of Barratts Chapel Road and Buffalo Road

2. FUNCTION(S): historic Equipment shed current Equipment shed

3. YEAR BUILT: 1990 CIRCA?: ARCHITECT/BUILDER: N/A

4. STYLE/FLOOR PLAN: Utilitarian/Rectangular plan

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year
N/A N/A N/A

list major alterations and additions with years (if known) year
a. N/A N/A
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system Frame
b. Number of stories 1 double story
c. Wall coverings Partially open sides with plywood panels
d. Foundation None
e. Roof Shallow front gable
structural system Shallow front gable frame
coverings Corrugated metal roofing
openings 0

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: West
1) bays: 4
2) windows: 0
3) door(s): Mostly open elevation
4) other: N/A

b. Side: direction: North

- 1) bays: 4
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

c. Side: direction: South

- 1) bays: 4
- 2) windows: 0
- 3) door(s): 0
- 4) other: N/A

d. Rear: direction: East

- 1) bays: 4
- 2) windows: 0
- 3) door(s): Mostly open elevation
- 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan Open plan.

b) Partition/walls Framing posts and center divider.

c) Finishes Plywood exterior panels.

d) Furnishings/machinery Nothing permanent.



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # K-02739

1. **ADDRESS/LOCATION:** 4657 Barratts Chapel Road/Northeast of intersection of Barratts Chapel Road and Buffalo Road


2. **NOT FOR PUBLICATION** **reason:** _____

3. **LOCATION MAP:**

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # K-02739 Date 1/1/2008 Photo Roll # C-4866 Surveyor Laura C. Ricketts

Description

C-4866:21 Outbuilding (.011), W elevation, facing SE; C-4866:22 Outbuilding (.010), W and S (front) elevations, facing NE; C-4866:23 Farmhouse (.001) and outbuildings (.009 and .004), E and N (rear) elevations, facing SW; C-4866:24 Outbuildings (.007 and .008), S (front) elevations, facing N; C-4866:25 Outbuildings (.008 and .007), S and E elevations, facing NW; C-4866:26 Outbuildings (.002, .003, and .004), W and S (front) elevations, facing NE; C-4866:27 Outbuildings (.005, .002, and attached garage .001), W and S elevations, facing NE; C-4866:28 Outbuildings (.006, .008, .005, and .002), S and E elevations, facing N; C-4866:29 Farmhouse (.001), S (front) elevation, facing N; C-4866:30 Farmhouse (.001), W and S (front) elevations, facing NE

Negative location (if other than SHPO) Skelly and Loy, Inc.

Attach contact print(s):



DX-21.JPG



DX-22.JPG



DX-23.JPG



DX-24.JPG



DX-25.JPG



DX-26.JPG



DX-27.JPG



DX-28.JPG

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # K-02739 Date 1/1/2008 Photo Roll # C-4866 Surveyor Laura C. Ricketts

Description

C-4866:21 Outbuilding (.011), W elevation, facing SE; C-4866:22 Outbuilding (.010), W and S (front) elevations, facing NE; C-4866:23 Farmhouse (.001) and outbuildings (.009 and .004), E and N (rear) elevations, facing SW; C-4866:24 Outbuildings (.007 and .008), S (front) elevations, facing N; C-4866:25 Outbuildings (.008 and .007), S and E elevations, facing NW; C-4866:26 Outbuildings (.002, .003, and .004), W and S (front) elevations, facing NE; C-4866:27 Outbuildings (.005, .002, and attached garage .001), W and S elevations, facing NE; C-4866:28 Outbuildings (.006, .008, .005, and .002), S and E elevations, facing N; C-4866:29 Farmhouse (.001), S (front) elevation, facing N; C-4866:30 Farmhouse (.001), W and S (front) elevations, facing NE

Negative location (if other than SHPO) Skelly and Loy, Inc.

Attach contact print(s):



DX-29.JPG



DX-30.JPG