



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # K-07606
SPO Map 12-13-18
Hundred S. Murderkill
Quad Frederica
SM-00-122.00-
Other 02-28.00

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 4417 Barratts Chapel Road/Northeast corner of Barratts Chapel Road and Buffalo Road intersection
3. TOWN/NEAREST TOWN: Frederica vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
landscape district
5. MAIN FUNCTION OF PROPERTY: Dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
Barratts Chapel Road Improvements

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
1	CRS 2 Main Building Form	Dwelling
2	CRS 3 Secondary Building Form	Garage and shed
0	CRS 4 Archaeological Site Form	N/A
0	CRS 5 Structure (Building-Like) Form	N/A
0	CRS 6 Structure (Land Feature) Form	N/A
0	CRS 7 Object Form	N/A
0	CRS 8 Landscape Elements Form	N/A
1	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	N/A

8. SURVEYOR INFORMATION:

Surveyor name: Laura C. Ricketts and Bradley S. Reese

Principal Investigator name: Laura C. Ricketts

Principal Investigator signature: *Laura C. Ricketts*

Organization: Skelly and Loy, Inc. Date: 1/2008

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750± Contact Period (Native American)
 - 1630-1730± Exploration and Frontier Settlement
 - 1730-1770± Intensified and Durable Occupation
 - 1770-1830± Early Industrialization
 - 1830-1880± Industrialization and Early Urbanization
 - 1880-1940± Urbanization and Early Suburbanization
 - 1940-1960± Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # K-07606.001

1. ADDRESS/LOCATION: 4417 Barratts Chapel Road/Northeast corner of Barratts Chapel Road and Buffalo Road intersection
2. FUNCTION(S): historic Dwelling current Dwelling
3. YEAR BUILT: 1939 CIRCA?: ARCHITECT/BUILDER: N/A
4. STYLE OR FLOOR PLAN: Cape Cod/T-shaped plan
5. INTEGRITY: original site moved
if moved, from where N/A other location's CRS # N/A year N/A
- list major alterations and additions with years (if known)
- a. N/A year N/A
- b.
6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: T-shaped Stories: 1
Additions: 0
- b. Structural system (if known): Frame
- c. Foundation: materials: Concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): White vinyl siding
- e. Roof: shape: Side gable
materials: Asphalt shingle
cornice: Simple
dormers: 0
chimney: location(s): 1 interior brick chimney at east end of house
8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: South
- | | | |
|----|---------|---|
| 1) | Bays | 3 |
| 2) | Windows | 2 |
- fenestration Regular
type 1/1 aluminum sash
trim Simple vinyl trim
shutters Fixed louvered shutters

Facade (cont'd)

- 3) **Door(s)** 1
 location Near center
 type 3-light wood door with aluminum storm door
 trim Simple vinyl trim
- 4) **Porch(es)** 3-step concrete stoop with wrought iron railing

b. Side: Direction: West

- 1) **Bays** 3
- 2) **Windows** 3
 fenestration Regular
 type 1/1 sash and 2-pane attic window
 trim Simple vinyl trim
 shutters 0
- 3) **Door(s)** 0
 location N/A
 type N/A
 trim N/A
- 4) **Porch(es)** 0

c. Side: Direction: East

- 1) **Bays** 3
- 2) **Windows** 3
 fenestration Regular
 type 1/1 sash and 2-pane attic window
 trim Simple vinyl trim
 shutters 0
- 3) **Door(s)** 1
 location Rear wing
 type Not visible
 trim Simple vinyl trim
- 4) **Porch(es)** 0

d. Rear: Direction: North

- 1) **Bays** 3
- 2) **Windows** 3
 fenestration Regular
 type 1/1 sash
 trim Simple vinyl trim
 shutters 0
- 3) **Door(s)** 1
 location Right side of rear wing
 type Glass and wood
 trim Simple vinyl trim
- 4) **Porch(es)** Small fenced porch to east of rear wing

9. **INTERIOR:** Not accessible

10. **LANDSCAPING:** The house features minimal foundation plantings and a few trees. It is surrounded on all sides by farmland.

11. **OTHER COMMENTS:** N/A



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-07606.002

1. ADDRESS/LOCATION: 4417 Barratts Chapel Road/Northeast corner of Barratts Chapel Road and Buffalo Road intersection

2. FUNCTION(S): historic Garage current Garage

3. YEAR BUILT: 1970 CIRCA?: ARCHITECT/BUILDER: N/A

4. STYLE/FLOOR PLAN: Utilitarian/Rectangular plan

5. INTEGRITY: original site moved

if moved, from where
N/A

original location's CRS #
N/A year
N/A

list major alterations and additions with years (if known)

a. N/A year
N/A

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system Frame

b. Number of stories 1

c. Wall coverings White vinyl siding

d. Foundation Concrete block

e. Roof

structural system Front gable frame

coverings Asphalt shingle

openings 0

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: South

1) bays: 1

2) windows: Louvered vent under gable

3) door(s): Overhead garage door at center

4) other: N/A

- b. Side: direction: West
 - 1) bays: 2
 - 2) windows: 0
 - 3) door(s): 1 steel pedestrian door at far right
 - 4) other: N/A

- c. Side: direction: East
 - 1) bays: 2
 - 2) windows: 1 8/8 sash
 - 3) door(s): 0
 - 4) other: N/A

- d. Rear: direction: North
 - 1) bays: 1
 - 2) windows: Louvered vent under gable
 - 3) door(s): 0
 - 4) other: N/A

9. INTERIOR (if accessible):

a) Floor plan Not accessible

b) Partition/walls Not accessible

c) Finishes Not accessible

d) Furnishings/machinery Not accessible



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-07606.003

1. ADDRESS/LOCATION: 4417 Barratts Chapel Road/Northeast corner of Barratts Chapel Road and Buffalo Road intersection

2. FUNCTION(S): historic Shed current Shed

3. YEAR BUILT: 1970 CIRCA?: ARCHITECT/BUILDER: N/A

4. STYLE/FLOOR PLAN: Utilitarian/Rectangular plan

5. INTEGRITY: original site moved

<u>if moved, from where</u>	<u>original location's CRS #</u>	<u>year</u>
<u>N/A</u>	<u>N/A</u>	<u>N/A</u>

<u>list major alterations and additions with years (if known)</u>	<u>year</u>
<u>a. N/A</u>	<u>N/A</u>
<u>b.</u>	

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system Frame

b. Number of stories 1

c. Wall coverings Vertical board

d. Foundation Not visible

e. Roof

structural system Front gable frame with exposed rafter tails

coverings Asphalt shingle

openings 0

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: West

1) bays: 1

2) windows: 0

3) door(s): 1 wood door at far right

4) other: N/A

- b. **Side: direction:** South
 - 1) **bays:** 2
 - 2) **windows:** 2 6-light casement windows
 - 3) **door(s):** 0
 - 4) **other:** N/A

- c. **Side: direction:** North
 - 1) **bays:** 2
 - 2) **windows:** 0
 - 3) **door(s):** 0
 - 4) **other:** N/A

- d. **Rear: direction:** East
 - 1) **bays:** 1
 - 2) **windows:** 0
 - 3) **door(s):** 0
 - 4) **other:** N/A


9. **INTERIOR (if accessible):**

a) **Floor plan** Not accessible

b) **Partition/walls** Not accessible

c) **Finishes** Not accessible

d) **Furnishings/machinery** Not accessible



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # K-07606

1. ADDRESS/LOCATION: 4417 Barratts Chapel Road/Northeast corner of Barratts Chapel Road and Buffalo Road (intersection)


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # K-07606 Date 1/1/2008 Photo Roll # C-4866 Surveyor Laura C. Ricketts

Description

C-4866:17 Garage (.002) and house (.001), N (rear) and W elevations, facing SE; C-4866:18 House (.001), W elevation, facing E; C-4866:19 Garage (.002) and shed (.003), W and S elevations, facing NE; C-4866:20 House (.001), S (front) and E elevations, facing N

Negative location (if other than SHPO) Skelly and Loy, Inc.

Attach contact print(s):



DX-17.JPG



DX-18.JPG



DX-19.JPG



DX-20.JPG
CRS-13