

APPENDIX B

**PRE-EXISTING
CRS FORMS**

K-103

NATIONAL REGISTER OF HISTORIC PLACES
INVENTORY - NOMINATION FORM

(Type all entries - complete applicable sections)

STATE: Delaware	
COUNTY: Kent	
FOR NPS USE ONLY	
ENTRY NUMBER	DATE

1. NAME

COMMON:
Barratt's Chapel

AND/OR HISTORIC:
Barratt's Chapel

2. LOCATION

STREET AND NUMBER:
North U.S. 113

CITY OR TOWN:
Frederica

STATE: Delaware CODE: 10 COUNTY: Kent CODE: 001

3. CLASSIFICATION

CATEGORY (Check One)	OWNERSHIP	STATUS	ACCESSIBLE TO THE PUBLIC
<input type="checkbox"/> District <input type="checkbox"/> Site <input type="checkbox"/> Object	<input checked="" type="checkbox"/> Building <input type="checkbox"/> Structure <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private <input type="checkbox"/> Both	<input checked="" type="checkbox"/> Occupied <input type="checkbox"/> Unoccupied <input type="checkbox"/> Preservation work in progress	<input type="checkbox"/> Yes: <input type="checkbox"/> Restricted <input checked="" type="checkbox"/> Unrestricted <input type="checkbox"/> No

PRESENT USE (Check One or More as Appropriate)

<input type="checkbox"/> Agricultural	<input type="checkbox"/> Government	<input type="checkbox"/> Park	<input type="checkbox"/> Transportation	<input type="checkbox"/> Comments
<input type="checkbox"/> Commercial	<input type="checkbox"/> Industrial	<input type="checkbox"/> Private Residence	<input type="checkbox"/> Other (Specify)	
<input type="checkbox"/> Educational	<input type="checkbox"/> Military	<input checked="" type="checkbox"/> Religious		
<input type="checkbox"/> Entertainment	<input checked="" type="checkbox"/> Museum	<input type="checkbox"/> Scientific		

4. OWNER OF PROPERTY

OWNER'S NAME:
Commission on Archives and History of Peninsula Annual Conference

STREET AND NUMBER:
Barratt's Chapel of the United Methodist Church, Inc.

CITY OR TOWN: Frederica STATE: Delaware CODE: 10

5. LOCATION OF LEGAL DESCRIPTION

COURTHOUSE, REGISTRY OF DEEDS, ETC:
Kent County Court House, Recorder of Deeds Office

STREET AND NUMBER:
South State Street

CITY OR TOWN: Dover STATE: Delaware CODE: 10

6. REPRESENTATION IN EXISTING SURVEYS

TITLE OF SURVEY:
Historic American Buildings Survey, #Del-16

DATE OF SURVEY: 1936 Federal State County Local

DEPOSITORY FOR SURVEY RECORDS:
Library of Congress

STREET AND NUMBER:
Washington, D.C.

SEE INSTRUCTIONS

STATE

COUNTY

FOR NPS USE ONLY

ENTRY NUMBER

DATE

7. DESCRIPTION	
CONDITION	(Check One)
	<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Ruins <input type="checkbox"/> Unexposed <input checked="" type="checkbox"/> Altered <input type="checkbox"/> Unaltered <input type="checkbox"/> Moved <input checked="" type="checkbox"/> Original Size
DESCRIBE THE PRESENT AND ORIGINAL (If known) PHYSICAL APPEARANCE	
<p>Barratt's Chapel is a two-story brick meeting house with a west gable-end frontage.</p> <p>The south wall, facing the cemetery, is laid in Flemish bond with a glazed header pattern. In the center of this wall is a double door flanked by two windows. Three second-story windows light the gallery.</p> <p>The west, or front, wall is laid in unglazed Flemish bond brick, with diaper patterns in glazed brick on the face of the attic story. Two belt courses appear on this facade; the lower one divides the first and second stories, and the upper one separates the second story from the attic. There are three doors in the first floor of this facade, and on the second story there are three windows. A window has been cut into the attic story, destroying a segment of the diapered brick design.</p> <p>The north wall is laid in common bond, with three windows on each story. The east gable wall is covered with stucco. An off-center doorway in this wall provides access to the chancel.</p> <p>Exterior shutters follow the Delaware tradition of solid shutters on the first floor, with louvered shutters above. The box cornices on the north and south facades are elaborately moulded, and return onto the gable end to create a seat to receive the bargeboard.</p> <p>The interior is arranged as a traditional aisled hall. Square posts extend from the ground to the rafters, in two rows parallel to the north and south sidewalls. A three-sided gallery is hung from these posts and from the north, west, and south walls. A wooden floor and simple open bench pews, finished in rustic fashion, appear to date from the first quarter of the nineteenth century. Against the east</p>	

SEE INSTRUCTIONS

Form 10-200a
(July 1967)

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE
NATIONAL REGISTER OF HISTORIC PLACES
INVENTORY - NOMINATION FORM

(Continuation Sheet)

STATE	Delaware	
COUNTY	Kent	
FOR NPS USE ONLY		
ENTRY NUMBER	DATE	

(Number of entries)

7. DESCRIPTION (continued)---

wall is a high two-level pulpit, now enclosed with a balustrade but formerly panelled. Although the balustrade was installed around the middle of the nineteenth century, the bench behind the pulpit is said to be part of the original furnishings.

SIGNIFICANCE			
PERIOD (Check One or More as Appropriate)			
<input type="checkbox"/> Pre-Columbian	<input type="checkbox"/> 16th Century	<input checked="" type="checkbox"/> 18th Century	<input type="checkbox"/> 20th Century
<input type="checkbox"/> 18th Century	<input type="checkbox"/> 17th Century	<input type="checkbox"/> 19th Century	
SPECIFIC DATE(S) (If Applicable and Entered)			
AREAS OF SIGNIFICANCE (Check One or More as Appropriate)			
<input type="checkbox"/> Aboriginal	<input type="checkbox"/> Education	<input type="checkbox"/> Political	<input type="checkbox"/> Urban Planning
<input type="checkbox"/> PreHistoric	<input type="checkbox"/> Engineering	<input checked="" type="checkbox"/> Religion/Phi-	<input type="checkbox"/> Other (Specify)
<input type="checkbox"/> Historic	<input type="checkbox"/> Industry	losophy	_____
<input type="checkbox"/> Agriculture	<input type="checkbox"/> Invention	<input type="checkbox"/> Science	_____
<input checked="" type="checkbox"/> Architecture	<input type="checkbox"/> Landscape	<input type="checkbox"/> Sculpture	_____
<input type="checkbox"/> Art	Architecture	<input type="checkbox"/> Social/Human-	_____
<input type="checkbox"/> Commerce	Literature	itation	_____
<input type="checkbox"/> Communications	<input type="checkbox"/> Military	<input type="checkbox"/> Theater	_____
<input type="checkbox"/> Conservation	<input type="checkbox"/> Music	<input type="checkbox"/> Transportation	_____
STATEMENT OF SIGNIFICANCE			
<p>In the summer of 1780 Philip Barratt gave the Methodist Society a plot of land, near the Murderkill River in Kent County, Delaware. The two-story brick meeting house, named in honor of Barratt, was begun immediately.</p> <p>Barratt's Chapel was the first church in Kent County that was built especially for Methodist worship, and one of the first two erected in Delaware.</p> <p>For two generations, the interior remained in an unfinished condition, with only dirt floors and no heat; in spite of these primitive conditions, Barratt's Chapel was the best meeting house in America belonging to the Methodists as a house of worship. St. George's in Philadelphia was, at this time, serving as a barracks and stable for the British army.</p> <p>Barratt's Chapel today is known as the "Cradle of American Methodism" because of its unique place in the development of the denomination. It was here that Dr. Thomas Coke and the Reverend Francis Asbury, later the first two Methodist bishops, met to make the preliminary arrangements for the formation of the Methodist Episcopal Church in America. Here the sacramental ordinances were first administered to Methodist communicants on American soil by</p>			

SEE INSTRUCTIONS

Form 10-200a
(July 1967)

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE
NATIONAL REGISTER OF HISTORIC PLACES
INVENTORY - NOMINATION FORM

(Continuation Sheet)

STATE	Delaware	
COUNTY	Kent	
FOR NPS USE ONLY		
ENTRY NUMBER		DATE

(Number of entries)

8. SIGNIFICANCE (continued)---

duly authorized Methodist ministers, Dr. Coke and the Reverend Richard Whatcoat.

According to Scharf's History of Delaware, "The edifice was forty-two by forty-eight feet, two stories high, and had a vestry room connected with it. There is a tradition that the brick of which it was built were imported from Holland, which is improbable, as the clay in the immediate vicinity is as good as any in the world for bricks and the art of making bricks was already well-known...The house was furnished with a pulpit and occupied as a place of worship...The old fashioned high pulpit which was reached by a flight of steps and which almost concealed the preacher from his congregation has been remodeled to suit modern ideas; but the seat or wooden bench, upon which Bishops Coke and Asbury, and other pioneers of the church, sat, is still preserved as a memento For the first sixty years of its existence the ground was the only flooring and the walls were left in an uncouth and primitive state."

7. MAJOR BIBLIOGRAPHICAL REFERENCES

Scharf, J. Thomas. History of Delaware. Philadelphia: L.J. Richards and Company, 1888.

Barratt, Norris S. Barratt's Chapel and Methodism. Wilmington: Historical Society of Delaware, 1911.

10. GEOGRAPHICAL DATA

LATITUDE AND LONGITUDE COORDINATES DEFINING A RECTANGLE LOCATING THE PROPERTY				OR	LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN TEN ACRES				
CORNER	LATITUDE		LONGITUDE		LATITUDE		LONGITUDE		
	Degrees	Minutes	Seconds	Degrees	Minutes	Seconds	Degrees	Minutes	Seconds
NW	.	.	.	39	01	28	75	27	34
NE	.	.	.						
SE	.	.	.						
SW	.	.	.						

APPROXIMATE ACREAGE OF NOMINATED PROPERTY: Ten

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE:	CODE	COUNTY:	CODE

11. FORM PREPARED BY

NAME AND TITLE: Rev. Charles E. Covington, President

ORGANIZATION: Commission on Archives and History of Peninsula... DATE: 8/23/72

STREET AND NUMBER: 36 Baltimore Avenue

CITY OR TOWN: Rehoboth Beach STATE: Delaware 19971 CODE: 10

12. STATE LIAISON OFFICER CERTIFICATION

As the designated State Liaison Officer for the National Historic Preservation Act of 1966 (Public Law 89-665), I hereby nominate this property for inclusion in the National Register and certify that it has been evaluated according to the criteria and procedures set forth by the National Park Service. The recommended level of significance of this nomination is:

National State Local

Name: E. Berkeley Tompkins
 Title: Director, Div. of Historical and Cultural Affairs
 Date: 9-22-72

NATIONAL REGISTER VERIFICATION

I hereby certify that this property is included in the National Register.

Chief, Office of Archeology and Historic Preservation

ATTEST:
Keeper of The National Register
 Date: _____

SEE INSTRUCTIONS

(Form 10-201)
(July 1969)

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE
NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY MAP FORM


(Type all entries - attach to or enclose with map)

STATE Delaware	
COUNTY Kent	
FOR NPS USE ONLY	
ENTRY NUMBER	DATE

SEE INSTRUCTIONS

1. NAME			
COMMON: Barratt's Chapel			
AND/OR HISTORIC: Barratt's Chapel			
2. LOCATION			
STREET AND NUMBER: North U.S. 113			
CITY OR TOWN: Frederica			
STATE: Delaware	CODE 10	COUNTY: Kent	CODE 001
3. MAP REFERENCE			
SOURCE: USGS Map, Frederica sheet, 7.5 minute series			
SCALE: 1:24,000			
DATE: 1956			
4. REQUIREMENTS			
TO BE INCLUDED ON ALL MAPS			
1. Property boundaries where required.			
2. North arrow.			
3. Latitude and longitude reference.			

United States Geological Survey Topographic Map 7.5 minute series, Frederica sheet, 1956



39°01'28" Barratt's Chapel

370 000 FEET

39°00' 75°30'

Mapped by U. S. Coast and Geodetic Survey Edited and published by the Geological Survey

Control by USC&GS and USGS

Culture and drainage in part compiled from aerial photographs taken 1946. Topography by planetable surveys 1946. Revised by USGS 1956

Hydrography compiled from USC&GS chart 1218 (1955)

Polyconic projection. 1927 North American datum 10,000-foot grid based on Delaware coordinate system 1,000-meter Universal Transverse Mercator grid ticks, zone 18, shown in blue

Unchecked elevations are shown in brown

TRUE NORTH
MAGNETIC NORTH
APPROXIMATE MEAN DECLINATION, 1956

75° 27' 34"

UNITED STATES DEPARTMENT OF THE INTERIOR
 NATIONAL PARK SERVICE


NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

STATE Delaware	
COUNTY Kent	
FOR NPS USE ONLY	
ENTRY NUMBER	DATE

SEE INSTRUCTIONS

1. NAME			
COMMON: Barratt's Chapel			
AND/OR HISTORIC: Barratt's Chapel			
2. LOCATION			
STREET AND NUMBER: North U.S. 113			
CITY OR TOWN: Frederica			
STATE:	CODE	COUNTY:	CODE
Delaware	10	Kent	001
3. PHOTO REFERENCE			
PHOTO CREDIT: Edward F. Heite			
DATE OF PHOTO: August 14, 1972			
NEGATIVE FILED AT: Hall of Records, Dover, Delaware			
4. IDENTIFICATION			
DESCRIBE VIEW, DIRECTION, ETC. View from Southwest			



() UN) STATES DEPARTMENT OF THE INT) R ()
NATIONAL PARK SERVICE


NATIONAL REGISTER OF HISTORIC PLACES
PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

STATE Delaware	
COUNTY Kent	
FOR NPS USE ONLY	
ENTRY NUMBER	DATE

SEE INSTRUCTIONS

1. NAME			
COMMON: Barratt's Chapel			
AND/OR HISTORIC: Barratt's Chapel			
2. LOCATION			
STREET AND NUMBER: North U.S. 113			
CITY OR TOWN: Frederica			
STATE: Delaware	CODE 10	COUNTY: Kent	CODE 001
3. PHOTO REFERENCE			
PHOTO CREDIT: Edward F. Heite			
DATE OF PHOTO: August 14, 1972			
NEGATIVE FILED AT: Historic Registrar's Office, Hall of Records, Dover, Delaware			
4. IDENTIFICATION			
DESCRIBE VIEW, DIRECTION, ETC. South facade			



RECEIVED OCT 16 1972

ENTRIES IN THE NATIONAL REGISTER

STATE DELAWARE

Date Entered OCT 10 1972

Name

Location


Barratt's Chapel

Frederica
Kent County

COPY OF CONGRESSIONAL NOTIFICATION

Also Notified

Hon. J. Caleb Boggs
Hon. William V. Roth, Jr.
Hon. Pierre S. du Pont, IV



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # K01689

1. HISTORIC NAME/FUNCTION: W. C. Fountain Agricultural Complex

2. ADDRESS/LOCATION: Barratts Chapel Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: Significance of dwelling was compromised by additions, addition of vinyl siding

5. SETTING INTEGRITY: All buildings are slated for demolition; agricultural fields slated for subdivision

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Rochelle Bohm

Principal Investigator name: Rochelle Bohm

Principal Investigator signature: _____

Organization: Kent County Date: 5/1/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS# K01689

Parcel reviewed through RPC application process for Chapel Farms Subdivision

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750± Contact Period (Native American)
- 1630-1730± Exploration and Frontier Settlement
- 1730-1770± Intensified and Durable Occupation
- 1770-1830± Early Industrialization
- 1830-1880± Industrialization and Early Urbanization
- 1880-1940± Urbanization and Early Suburbanization
- 1940-1960± Suburbanization and Early Ex-urbanization


b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|---|--|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # K-1689
SPO Map 12-13-18
Hundred S. Murderkill
Quad Frederica
Other SM-00-131.00-1-12.00-000

- HISTORIC NAME/FUNCTION: W.C. Fountain (Beer's)/Agricultural Complex
- ADDRESS/LOCATION: Southwest Corner Of Barratt's Chapel Road (RD 371) And US 113/SR-1
- TOWN/NEAREST TOWN: Frederica vicinity? X
- MAIN TYPE OF RESOURCE: building X landscape structure site object
district
- MAIN FUNCTION OF PROPERTY: Agricultural Complex
- PROJECT TITLE/ REASON FOR SURVEY (if applicable): Complex may be demolished for Chapel Farm development project – commercial and residential development (see ER# 2004.06.07.07, PLUS 2004-06-08)


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
	CRS 2 Main Building Form	Main block and rear ell – 2 forms
	CRS 3 Secondary Building Form	10 outbuildings (sheds and barns)
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
	CRS 9 Map Form	1 site map and 1 site plan, 1 house plan
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Anne McCleave, Gwen Davis, Dan Griffith, Craig Lukesic, Chuck Fithian

Principal Investigator name: DE SHPO

Principal Investigator signature: Anne McCleave 

Organization: DE SHPO Date: 10/29/04

9. OTHER NOTES OR OBSERVATIONS:

CRS# K-1689

Complex may be demolished for Chapel Farm development project – commercial and residential development (see ER# 2004.06.07.07, PLUS 2004-06-08)

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY

8. OTHER NOTES OR OBSERVATIONS:

CRS# K-1689

Complex may be demolished for Chapel Farm development project – commercial and residential development (see ER# 2004.06.07.07, PLUS 2004-06-08)


9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input checked="" type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # K-1689

1. ADDRESS/LOCATION: _____


2. NOT FOR PUBLICATION reason: _____


3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH





CULTURAL RESOURCE SURVEY
MAP FORM

CRS # K-1689

1. ADDRESS/LOCATION: SW Corner of Barrett's Chapel Rd (Rd 371) & US 113/SR-1


2. NOT FOR PUBLICATION reason: _____


3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # K-1689.001

1. ADDRESS/LOCATION: Southwest Corner Of Barratt's Chapel Road (Rd 371) And Us 113/Sr-1
 2. FUNCTION(S): historic Farmhouse (main section) current Farmhouse/Vacant
 3. YEAR BUILT: 1810 CIRCA?: ARCHITECT/BUILDER: Unknown
 4. STYLE OR FLOOR PLAN: Ell: Colonial - rear wing (see second Main Building form); Main section - center passage, single-pile, Georgian with Italianate porch;
 5. INTEGRITY: original site moved
if moved, from where other location's CRS # year
Main section on original site; Rear ell was originally located on same property as separate house, southeast of current location;
- | <u>list major alterations and additions with years (if known)</u> | <u>year</u> |
|--|-------------|
| <u>a. front porch added late 19th century (c. 1870)</u> | <u>1870</u> |
| <u>b. rear side porches (on ell) added later - probably in 20th century</u> | |
6. CURRENT CONDITION: excellent good fair poor
 7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
 - a. Overall shape: L-shaped (includes both sections): Stories: 2-1/2
Main section - rectangle; Ell - rectangle
Additions: porches - 1 front porch; 2 rear porches (on ell)
 - b. Structural system (if known): frame
 - c. Foundation: materials: brick
basement: full partial not visible no basement
 - d. Exterior walls (original if visible & any subsequent coverings): clapboard; later, the entire house was covered with asbestos; after 1980, main section covered with vinyl siding (over asbestos & clapboard);
 - e. Roof: shape: gable
materials: standing seam metal
cornice: box; at one time had cyma molding, molding is now gone or covered with vinyl
dormers: 0
chimney: location(s): 2 interior, end chimneys; brick, covered with stucco; 1 on rear ell
 8. DESCRIPTION OF ELEVATIONS:
 - a. Facade: Direction: N
 - 1) Bays 5
 - 2) Windows
fenestration 5 windows on 2nd story; 4 windows on 1st story with center door;
type 6/6 double-hung wood; aluminum storm windows
trim plain wood surrounds, covered in vinyl;
shutters 0

Facade (cont'd)

- 3) **Door(s)** 1 center door; added late 19th c;
location center
type 4 panel, top panels are arched and take up 2/3 of door; bottom panels are rectangular; screen door; 3 light transom with center light wider than the other 2;
trim decorative pediment; simple pilasters flanking door;
- 4) **Porch(es)** small, 1 bay center porch with remnants of balustrade of simple balusters and railing, porch openings now partially covered with plywood or corrugated plastic; 4 square columns; cyma cornice - still exposed; concrete foundation; 2 concrete steps (includes porch floor); cement floor; beaded board ceiling;

b. Side: Direction: E

- 1) **Bays** 2
- 2) **Windows**
fenestration 6 windows; 2 on each floor - incl. attic
type 1st and 2nd stories are wood, 6/6 double-hung; attic/gable windows are wood, casement w/2 lights side-by-side
trim simple wood surrounds covered with vinyl
shutters 0
- 3) **Door(s)** 0
location
type
trim
- 4) **Porch(es)** 0 (see other sheet for rear ell elevation descriptions)

c. Side: Direction: W

- 1) **Bays** 2
- 2) **Windows** 2 attic windows exposed; 4 windows on 1st and 2nd stories are covered by siding and no longer visible
fenestration 2 windows on each floor including attic/gable windows
type attic windows are square, wood casement w/2 lights side-by-side
trim simple wood surrounds covered with vinyl
shutters 0
- 3) **Door(s)** 0
location
type
trim
- 4) **Porch(es)** 0 (see other sheet for rear ell elevation descriptions)

d. Rear: Direction: S

- 1) **Bays** 3 (probably 5 before rear ell was attached)
- 2) **Windows**
fenestration 2 windows on first story; 3 on 2nd story; central door now enclosed by porch
type wood, 6/6 double-hung;
trim simple wood surrounds covered with vinyl
shutters 0
- 3) **Door(s)**
location center of main section - accessed by porch that is attached to rear ell
type wood
trim
- 4) **Porch(es)** See other sheet for rear ell elevation descriptions

9. **INTERIOR: First Floor:** central plan with stair in entrance hall; turned balusters; newel post; rear hall door leading to back porch;
west room: 2 front and 2 rear windows; door leading to center hall is 4 panel; molded casing; fireplace with mantel
east room: 2 front windows and 2 side windows; 1 doorway on south wall leading to ell, which is one step lower than main house; 1 built-in cabinet; fireplace with mantel
Second Floor: hall running east to west along back of interior;
2 small bedrooms on east side of house; the center bedroom has the stairway leading to attic; master bedroom on west side of house with 2 front and 2 rear windows; all rooms have wood floor & baseboards;

10. **LANDSCAPING:** Overgrown lawn; some bushes in front; gravel dirt road leading to the Ag complex and continuing to the wooded area along back of property and Spring Creek; deciduous trees along road near house; evergreen trees; See landscape sheet for further description;
11. **OTHER COMMENTS:** Complex may be demolished for Chapel Farm development project – commercial and residential development (see ER# 2004.06.07.07, PLUS 2004-06-08)

USE BLACK INK ONLY

CRS-2



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # K-1689.001

1. ADDRESS/LOCATION: Southwest Corner Of Barratt's Chapel Road (Rd 371) And Us 113/Sr-1
2. FUNCTION(S): historic Farm house rear ell current Farm house/Vacant
3. YEAR BUILT: 1730 CIRCA?: ARCHITECT/BUILDER: Unknown
4. STYLE OR FLOOR PLAN: Ell: Colonial - rear wing; Main section (see previous Main Building form) - center passage, single-pile, Georgian with Italianate porch;

5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year
Rear wing was originally located on same property, southeast of current location; main section on original site;

list major alterations and additions with years (if known) year
a. rear side porches added later - probably in 20th century
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: L-shaped (includes both sections): Stories: 2-1/2
 Ell - rectangle; Main section - rectangle
 Additions: porches - 2 porches on rear ell; one on east, one on west
- b. Structural system (if known): frame
- c. Foundation: materials: brick - handmade
 basement: full partial not visible no basement
- d. Exterior walls (original if visible & any subsequent coverings): clapboard; later, the entire house was covered with asbestos; after 1980, main section covered with vinyl siding (over asbestos & clapboard); rear ell still asbestos (no vinyl)
- e. Roof: shape: gable
 materials: standing seam metal
 cornice: box; at one time had cyma molding, molding is now gone or covered with vinyl
 dormers: 0
 chimney: location(s): 1 on rear ell - interior end chimney; brick covered with stucco

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: N
- 1) Bays north elevation of ell is attached to main section
- 2) Windows fenestration type trim shutters

Facade (cont'd)

- 3) **Door(s)**
location
type
trim

- 4) **Porch(es)**

b. Side: Direction: E

- 1) **Bays** 2

- 2) **Windows**

fenestration 2 on second floor - one 6/6 double-hung; one 3/3 double-hung;
type wood; storm windows
trim wood covered in vinyl
shutters 0

- 3) **Door(s)**
location
type
trim

- 4) **Porch(es)** 1 - shed roof; walls are plywood

c. Side: Direction: W

- 1) **Bays** 2

- 2) **Windows**

fenestration 2 on second floor - 6/6 double-hung;
type wood; storm windows
trim wood covered in vinyl
shutters 0

- 3) **Door(s)** 1 enclosed by porch addition
location
type
trim

- 4) **Porch(es)** 1 - shed roof; center door; paired windows on north side of door - 2/2 wood, double-hung; south side of porch enclosed with corrugated plastic;

d. Rear: Direction: S

- 1) **Bays** 2

- 2) **Windows** two 2/2 wood, double-hung attic windows, covered in vinyl; one 6/6 wood double-hung; (one window is hidden by asbestos siding); one 1/1 windows on the west side of door

fenestration
type
trim
shutters

- 3) **Door(s)** 1
location located on the east porch addition
type wood; 4 lights with panels below
trim

- 4) **Porch(es)** 0 - can see south elevation of east porch

9. **INTERIOR:** functions as kitchen; one step lower than main section; hearth; door on east and west elevations; winder stair behind hearth; exposed and beaded structural members - beams and corner posts; chair rails on first and second stories; plaster walls; small porch (encloses rear door of main section) between kitchen and back porch;
Second floor: wood floor; baseboards; chair rail; bath in connector on 2nd floor (above small porch on 1st floor);
Attic: hand-hewn rafters; some circular sawn; pegged joinery


10. **LANDSCAPING:** See description on main section sheet and landscape sheet

K 1689.001

11. **OTHER COMMENTS: Complex may be demolished for Chapel Farm development project – commercial and residential development (see ER# 2004.06.07.07, PLUS 2004-06-08)**

USE BLACK INK ONLY

CRS-2



CULTURAL RESOURCE SURVEY
MAP FORM

CRS# K-1689.001

1. ADDRESS/LOCATION: SW corner of Barratt's Chapel Rd (Rd 371) & US 113/SR-1


2. NOT FOR PUBLICATION reason: _____


3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-1689.002

1. ADDRESS/LOCATION: Southwest corner of Barratt's Chapel Road (RD 371) and US 113/SR-1; located east of house
2. FUNCTION(S): historic Shed current Shed
3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: Unknown
4. STYLE/FLOOR PLAN: rectangle
5. INTEGRITY: original site moved
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known)

year

- a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system Frame
- b. Number of stories 1
- c. Wall coverings vertical beaded board
- d. Foundation n/a
- e. Roof
structural system frame; Shed roof type
coverings asphalt
openings 0

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: N
- 1) bays: 1
- 2) windows: 1; wide window;
- 3) door(s):
- 4) other:

b. Side: direction: E

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 0
- 4) other:

c. Side: direction: W

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 1
- 4) other:

d. Rear: direction: S

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 0
- 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-1689.003

1. ADDRESS/LOCATION: Southwest corner of Barratt's Chapel Road (RD 371) and US 113/SR-1; located directly behind house

2. FUNCTION(S): historic Shed current Shed

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system frame

b. Number of stories 1

c. Wall coverings board-n-batten

d. Foundation brick and concrete piers

e. Roof
structural system frame; gable
coverings standing seam metal
openings 0

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: N

- 1) bays: 1
- 2) windows: 0

3) door(s): 1

4) other: _____

b. Side: direction: E

- 1) bays: 1
- 2) windows: 0

- 3) door(s): 0

- 4) other:

c. Side: direction: W

- 1) bays: 1
- 2) windows: 0

- 3) door(s): 0

- 4) other:

d. Rear: direction: S

- 1) bays: 1
- 2) windows: 0

- 3) door(s): 0

- 4) other:

9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K1689.004

1. ADDRESS/LOCATION: Southwest corner of Barratt's Chapel Road (RD 371) and US 113/SR-1; located in farmyard, south of house; could not access

2. FUNCTION(S): historic privy current vacant/storage

3. YEAR BUILT: 1860 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: square

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known)

a. _____ year _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system frame

b. Number of stories 1

c. Wall coverings vertical board covered in chip board

d. Foundation none

e. Roof
structural system frame
coverings standing seam metal
openings _____

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: N
1) bays: 1
2) windows: 0
3) door(s): 0
4) other: louvered vent; fascia board

b. Side: direction: E

- 1) bays: 1
- 2) windows:
- 3) door(s):
- 4) other:

c. Side: direction: W

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 0
- 4) other:

d. Rear: direction: S

- 1) bays: 1
- 2) windows:
- 3) door(s):
- 4) other: fascia board


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-1689.005

1. ADDRESS/LOCATION: Southwest corner of Barratt's Chapel Road (RD 371) and US 113/SR-1; this shed is located in the farmyard - could not access;

2. FUNCTION(S): historic Multi-use shed current Multi-use shed/hay shed

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. small shed addition (possibly) on SE elevation; could have been constructed at same time as main shed section;
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system frame; exposed rafter tails
b. Number of stories 1
c. Wall coverings vertical boards
d. Foundation None
e. Roof
structural system frame
coverings corrugated metal
openings _____

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: N
1) bays: too deteriorated to decipher
2) windows: too deteriorated to decipher
3) door(s): too deteriorated to decipher
4) other: small building sitting directly in front of shed; form and shape are similar to a privy (see next form)

b. Side: direction: E

- 1) bays:
- 2) windows:

- 3) door(s):

- 4) other: may be a shed addition to larger section; or may have been constructed at same time

c. Side: direction: W

- 1) bays:
- 2) windows: 0

- 3) door(s): 0

- 4) other: vertical board now covered by plywood

d. Rear: direction: S

- 1) bays:
- 2) windows: 0

- 3) door(s): 2 large doors; corrugated metal; 1 small door opening on shed addition

- 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-1689.006

1. ADDRESS/LOCATION: Southwest corner of Barratt's Chapel Road (RD 371) and US 113/SR-1; this barn is located southwest and outside of the farmyard

2. FUNCTION(S): historic Multi-use barn current Multi-use barn

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system frame
b. Number of stories 1-1/2
c. Wall coverings vertical beaded board
d. Foundation concrete block piers
e. Roof
structural system frame; gable
coverings corrugated metal
openings _____

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: N
1) bays: 1
2) windows: 0
3) door(s): 3 sliding doors; vertical beaded boards; 1 smaller door
4) other: _____

b. Side: direction: E

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 0

4) other: lower shed addition or may have been constructed at same time as main section

c. Side: direction: W

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 1

4) other: exposed rafter tails

d. Rear: direction: S

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 0

4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-1689.007

1. ADDRESS/LOCATION: Southwest corner of Barratt's Chapel Road (RD 371) and US 113/SR-1; this shed is the farthest north, located on the west side of the dirt road;

2. FUNCTION(S): historic Milk house current Storage

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system frame
b. Number of stories 1-1/2
c. Wall coverings horizontal board
d. Foundation concrete block
e. Roof
structural system frame
coverings corrugated metal
openings _____

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: N
1) bays: 1
2) windows: one 2/2 wood, double-hung;
3) door(s): 0
4) other: cornice

b. Side: direction: E

- 1) bays: 1
- 2) windows: 1 gable vent
- 3) door(s): 1 vertical beaded board, metal strap hinges
- 4) other: eave returns

c. Side: direction: W

- 1) bays: 1
- 2) windows: one 2/2 wood, double-hung
- 3) door(s): 0
- 4) other: eave returns are missing - either removed or deteriorated

d. Rear: direction: S

- 1) bays: 1
- 2) windows: one 2/2 wood, double-hung
- 3) door(s): 0
- 4) other: cornice

9. INTERIOR (if accessible):

- a) Floor plan rectangular; open
- b) Partition/walls 0
- c) Finishes vertical beaded board on walls and ceiling
- d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-1689.008

1. ADDRESS/LOCATION: Southwest corner of Barratt's Chapel Road (RD 371) and US 113/SR-1; this shed is the farthest south located on the west side of the dirt road

2. FUNCTION(S): historic Shed current Shed

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: rectangular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known)

a. _____ year
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system frame

b. Number of stories 1

c. Wall coverings vertical beaded board

d. Foundation

e. Roof
structural system frame; gable
coverings corrugated metal
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: N
1) bays: 1
2) windows: 0
3) door(s): 0
4) other: bulkhead leading to well

b. Side: direction: E

- 1) bays: 1
- 2) windows: one 6/6 wood, fixed
- 3) door(s): 0
- 4) other:

c. Side: direction: W

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 0
- 4) other: 2 circular metal vents

d. Rear: direction: S

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 1 vertical beaded board w/metal strap hinges
- 4) other:


9. INTERIOR (if accessible):

a) Floor plan **open**

b) Partition/walls **0**

c) Finishes **no finishes**

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-1689.009

1. ADDRESS/LOCATION: Southwest corner of Barratt's Chapel Road (RD 371) and US 113/SR-1; 2nd wood barn located south of farmyard

2. FUNCTION(S): historic Barn current Barn

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system frame
b. Number of stories 2-1/2
c. Wall coverings VERTICAL BOARD-N-BATTEN; VERTICAL BEADED BOARD on lower west elevation with vertical boards in west gable end;
d. Foundation brick piers
e. Roof
structural system frame; gable; exposed rafter tails
coverings metal
openings _____

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: N
1) bays: 1
2) windows: 0
3) door(s): 1 board-n-batten w/metal strap hinges
4) other: fascia board

b. Side: direction: E

- 1) bays: 1
- 2) windows: 0

3) door(s): 1 attic door

4) other: pieces of board-n-batten siding missing in a pattern indicating a gable addition may have existed at one time

c. Side: direction: W

- 1) bays: 1
- 2) windows: 0

3) door(s): 0

4) other: vertical beaded board on bottom; vertical boards in gable

d. Rear: direction: S

- 1) bays: 1
- 2) windows: 0

3) door(s): first story - double sliding door in center- vertical board; second story - one opening/door

4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-1689.010

1. ADDRESS/LOCATION: Southwest Corner Of Barratt's Chapel Road (RD 371) And US 113/SR-1; farthest southwest structure on property

2. FUNCTION(S): historic Machine shed current Machine shed

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system frame
- b. Number of stories 1
- c. Wall coverings corrugated metal on south and west elevations; open on north and east elevations
- d. Foundation none; posts in ground
- e. Roof
structural system frame; gable
coverings METAL
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: N
 - 1) bays: 1
 - 2) windows: 0
 - 3) door(s): 1 large door opening; at one time there were metal sliding doors that took up entire elevation;
 - 4) other:

b. Side: direction: E

- 1) bays: 5 - all open for machine entries
- 2) windows: 0
- 3) door(s): 0
- 4) other: exposed rafter tails

c. Side: direction: W

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 0
- 4) other: walls are corrugated metal; exposed rafter tails

d. Rear: direction: S

- 1) bays: 1
- 2) windows: 0
- 3) door(s): 0
- 4) other: walls are corrugated metal


9. INTERIOR (if accessible):

a) Floor plan open

b) Partition/walls none

c) Finishes none; dirt floor; exposed framing

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # K-1689.011

1. ADDRESS/LOCATION: Southwest corner of Barratt's Chapel Road (RD 371) and US 113/SR-1; located west of the dirt road, west of the two sheds

2. FUNCTION(S): historic Dairy barn current Dairy barn

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: Unknown

4. STYLE/FLOOR PLAN: rectangle; open

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. vinyl siding in some areas
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system first story - concrete block; second story - frame

b. Number of stories 2-1/2

c. Wall coverings concrete block and vertical board (no beads)

d. Foundation concrete block

e. Roof
structural system frame; gable
coverings standing seam metal
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: N

1) bays: 2

2) windows: one 9 light, single casement; 1/1 wood double-hung window on second floor (used to be a door/opening)

3) door(s): 0

4) other: the second story on this elevation is covered in vinyl

b. Side: direction: E

- 1) bays: 4
- 2) windows: Three 9 light, single casement; wood
- 3) door(s): first story - 1 Dutch covered in vinyl - still functions as a Dutch door; second story - 1 door/opening
- 4) other:

c. Side: direction: W

- 1) bays: 4
- 2) windows: 3 total; two 9 light, single casement; one 2/2 single hung (replacement)
- 3) door(s): first story - 1 Dutch; second story - 1 door/opening
- 4) other: top floor covered in vinyl; exposed rafter tails

d. Rear: direction: S

- 1) bays: 2
- 2) windows: one 9 light, single casement; wood
- 3) door(s): first story - 1 Dutch; second story - 1 door/opening; attic level - 1 door/opening
- 4) other:

9. INTERIOR (if accessible):

a) Floor plan open

b) Partition/walls dairy stalls; hayloft

c) Finishes no finishes

d) Furnishings/machinery dairy related

BEGIN

ROAD 371 - FARMHOUSE

Use black ink and completely fill each box. Entries above the ruled line will appear on fiche labels.

CRS K-2739.



STATE OF DELAWARE
DIVISION OF DEPT. OF RECORDS • DOVER • DEPT.
HISTORICAL & CULTURAL AFFAIRS
FICHE TITLE FRAME

Date ordered:

Camera:

Date filmed:

Operator's Signature:

The images on this microfiche are unaltered photocopies of the material contained in the survey files, Bureau of Archaeology and Historic Preservation-

Inventory

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM



DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314

FORM CRS-3

FOR OFFICE USE ONLY

CRS # _____
Quad Frederica
SPO map # 12-13-19
Hundred 2 MURDERKILL
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: _____
2. STREET LOCATION: RA 371 _____
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field c) woodland _____
d) scattered buildings e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: VALERIE COSNA _____ TEL. # _____
YOUR ADDRESS: _____
ORGANIZATION (if any) BA/HA _____ DATE: 6.27.80

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM





DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314

Form CRS-1
FOR OFFICE USE ONLY

CRS # K 2134
Quad Frederica
SPO map # 12-13-19
Hundred Murphy
DOCUMENT 20-06778/09/14

- 1. ADDRESS OF STRUCTURE : 1277
- 2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:


- a) Overall shape
stories 2 1/2
bays 2
wings none
- b) Structural system frame
- c) Foundation enclosed under wings + house
materials basement
- d) Exterior walls
materials aluminum siding
color(s) white
- * e) Roof
shape: materials gables, new asbestos tile asphalt shingles
cornice bar w/ rain gutter
dormers
chimney location(s) 3 new stack - 2 exterior, 1 interior Cx2
- f) Windows
spacing painted, even; all new 6/6, 1 bay window
type
trim aluminum
shutters green, nonfunctional, aluminum
- g) Door
spacing in new entrance
type
trim middle wood
- h) Porches
location(s) enclosed front, new wing
materials
supports
trim cement blocks found
- i) Interior details (if accessible)



USE BLACK INK ONLY

SKETCH MAP

Please indicate position of items in relation to geographical landmarks such as streets and roads.



9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

- A- VERT. PLANK SHED W/ WOOD SHINGLE GABLE ROOF, HORIZ. SLIDING DOORS
- B- CHICKEN HOUSE - VERT BOARD, GABLE ROOF
- C- SHED -
- D- MACHINE SHED - SHED ROOF, PLYWOOD WALLS, LATE 1970'S
- E- ALUM. PRE-FAB. SHED

TE NORTH ON SKETCH

ETE. 115

USE BLACK INK ONLY

PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION


Document 20-06/79/01/11

CRS Number 68K2739 Date July 80 Contact Sheet # TIEC1243

Description (1) 3/4 facade (2) addition closeup (3) left side closeup
(4) 3/4 outbuilding facade

Location (if other than Bureau collection) _____

Attach contact print



BEGIN

R	O	A	D	.	3	7	6	-	H	O	U	S	E	
---	---	---	---	---	---	---	---	---	---	---	---	---	---	--

Use black ink and completely fill each box. Entries above the ruled line will appear on fiche labels.

C	R	S		K	-	2	7	4	1	.			
---	---	---	--	---	---	---	---	---	---	---	--	--	--



STATE OF DELAWARE
DIVISION OF
HISTORICAL & CULTURAL AFFAIRS
FICHE TITLE FRAME

HALL OF RECORDS • EXETER • 1980

Date ordered:

Camera:

Date filmed:

Operator's Signature:

The images on this microfiche are unaltered photocopies of the material contained in the survey files, Bureau of Archaeology and Historic Preservation.

Inventory

70

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM



DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314

FORM CRS-1

FOR OFFICE USE ONLY

CRS # 10001
Quad Endicott
SPO map # 12-13-18
Hundred S. Main Street
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: 10001
2. STREET LOCATION: Bl. 276
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field c) woodland _____
d) scattered buildings e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: VALERIE CAGNA TEL. # _____
YOUR ADDRESS: _____
ORGANIZATION (if any) DA/HA DATE: 6.27.00

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314



Form CRS-1
FOR OFFICE USE ONLY

CRS # 02-741
Quad Frederica
SPO map # R-13-18
Hundred MURKIN
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : Rd 371 just W of R2 376

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape ell
stories 2 1/2
bays 3 down 2 up
wings ell + shed wing along side ell.

b) Structural system frame

c) Foundation materials brick
basement

d) Exterior walls white
materials aluminum or vinyl siding on shed ell wing.
color(s)



e) Roof shape: materials gable, asphalt sh
cornice - br
dormers -
chimney location(s) : left side, interior and gable, brick, with brick cornice

f) Windows spacing even
type 2nd story diamond window over the shed ell
trim
shutters -

g) Door spacing center in 3 bay facade
type
trim

h) Porches location(s) front, screened in
materials
supports
trim


i) Interior details (if accessible)



USE BLACK INK ONLY

MAP

indicate position of locus in relation to graphical landmarks such as streets and



NORTH ON SKETCH

USE BLACK INK ONLY

9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

OWNER REFUSED SURVEY

(THIS IS A ROUGH SKETCH)

← THERE ARE SEVERAL MORE ^{SMALL} OUTBUILDINGS THAT ARE NOT INDICATED HERE

3 PHOTOS TAKEN FROM THE ROAD

PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION


Document 20-06/79/01/11

CRS Number K2741 Date July 80 Contact Sheet # 1101243

Description (12) facade (13) 3/4 facade (14) farmstead

Location (if other than Bureau collection) _____

Attach contact print



BEGIN

HSE., RTE. 371

Use black ink and completely fill each box. Entries above the ruled line will appear on fiche labels.

CRS K-2742.



STATE OF DELAWARE
DIVISION OF
HISTORICAL & CULTURAL AFFAIRS
FICHE TITLE FRAME

Date ordered:

Camera:

Date filmed:

Operator's Signature:

The images on this microfiche are unaltered photocopies of the material contained in the survey files, Bureau of Archaeology and Historic Preservation-

Inventory

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM



DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314

FORM CRS-2

FOR OFFICE USE ONLY


CRS # K-2742
Quad Frederica
SPO map # 12-18-18
Hundred S. MURKIN
DOCUMENT 20-06778/0477

1. NAME OF LOCUS: "The old Barney Wynn Place" (The owner's name)
2. STREET LOCATION: RD 371, w of RD 375
3. OWNER'S NAME: Milford Carter TEL. # 335-4284
ADDRESS: Frederica
4. TYPE OF LOCUS: a) structure b) district c) archaeological site
d) other
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field b) cultivated field c) woodland prop. trees
d) scattered buildings e) densely built up f) other garden of prop
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning c) roads d) developers
e) deterioration f) other structure seems solid, tho walling is 2x4 - no rot
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Gordon Sands TEL. # _____
YOUR ADDRESS: _____
ORGANIZATION (if any) B.A.H.P. DATE: 6-27-80

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streets and roads.



INDICATE NORTH ON SKETCH



USE BLACK INK ONLY

9. COMMENTS:

★ in main house, The 2nd floor extends 1/2 way into roofing system. The rafters collars also serve as ceiling joists + take load for ceiling plaster.

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area



- a) tiny shed for storage, gabled, no door. asphalt shingle made 4" on wood sill. vertical boards w/ vert. 1/2" below over-steps. corner post construction w/ 1 she



- b) larger shed, gabled, four-paneled door on 9 brick piers. weatherboard cladding 2/2 window wood shingle roofing. common rafter + tie beam but purlins between ties, crown posts between ties + common rafters (crown posts made of split 3" diameter shooks. 1/4" pin purlin notched into + below the tie beams.



shook pin



CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314



Form CRS-1

FOR OFFICE USE ONLY

CRS # 12-376
Quad Fredonia
SPD map # 12-13-18
Hundred S. H. DEBELL
DOCUMENT 20-06/78/09/14

1. ADDRESS OF STRUCTURE : Rd 371, just SW of Rd 376

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape SQUARE - 1 RM. HIGH
stories 1 1/2
bays 3
wings DETACHED KITCHEN IN REAR

b) Structural system

c) Foundation materials BRICK PIER
basement —



SKETCH PLAN

d) Exterior walls RANDOM WIDTH
materials WEATHERBOARDS W/ CORNER BOARDS
color(s) BARE WOOD (TRACES OF WHITE), TRACES OF RED, A FEW
PIECES OF ASPHALT SIDING REMAIN

e) Roof shape: materials GABLE; NOOD SHINGLE W/ RIDGE COMB
cornice BOX
dormers —
chimney location(s) 1 BRICK INTERIOR END
1/4 OF THE WAY UP, THE CHIMNEY NARROWS & THERE IS

f) Windows spacing 3 BAY, CENTER DOOR, SYMMETRICAL
type 1/2 SASH ON 1ST FL. / 3 PANE
trim PLAIN BOARD SURROUND W/ SILL AND OVERHANGING BOARD
shutters — AT LINTEL

g) Door spacing CENTER FACADE
type VERTICAL BOARD (APPROX. 6" UNIFORM BOARDS
trim PLAIN BOARD SURROUND

h) Porches —
location(s)
materials
supports
trim

i) Interior details (if accessible) (SEE REVERSE)

USE BLACK INK ONLY

3. CONDITION: good _____ deteriorated

remarks: ABANDONED

4. INTEGRITY: a) original site b) moved _____
c) if moved, when and from where _____
d) list major alterations and dates (if known) _____

5. DATE OF INITIAL CONSTRUCTION: _____

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:
a) barn _____ b) carriage house _____ c) garage _____ d) privy _____
e) shed f) greenhouse _____ g) shop _____ h) gardens _____
i) icehouse _____ j) springhouse _____ k) other DETACHED KITCHEN
describe: SEE LOCUS FORM

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:


INTERIOR - FIREPLACE HAD BEEN BLOCKED AND MANTEL REMOVED

UPBOARD PLANKS FIREPLACE; VERT BOARD DOORS ON LOWER PORTION, SHELVES (4) PLAIN, CORNER WINDER STAIRCASE W/ CLOSET BELOW, 1/2" BASEBOARD W/ NARROW CURVED MOLDING, RANDOM WIDTH FLOORBOARDS, MACHINE CUT LATH AND PLASTER ON WALLS AND CEILING, CUT NAILS ON FLOORBOARDS
UPSTAIRS: 3 ROOMS



9. Primary References: (include location of reference)

FRAME STRUCTURE: BEAM SILLS ON BRICK PIER FOUNDATION, CORNER POSTS MORTISE AND TENONED INTO SILLS, TWO TO THREE COURSES OF BRICK INFILL ON TOP OF SILLS BET. JOISTS. SQUARE BEAM AT SECOND FLOOR LEVEL, DOWNBRACING FROM 2ND FL. BEAM TO CENTER OF 1ST FL. SILL, DOWNBRACING FROM EAVES TO 2ND FL. BEAM (NOTCHED INTO BEAM) COLLAR BEAM SERVES AS BASE FOR CEILING LATH ON 2ND FLOOR. GABLE END FRAMING



10. Surveyor: VALERIE CEGNA Date of Form: 6-27-80

USE BLACK INK ONLY

PHOTOGRAPHIC INVENTORY


BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION

CRS Number k2742 ~~71K242~~ Document 20-06/79/01/11 Date July 80 Contact Sheet # C1243

Description (16) 3/4 facade (17) 3/4 facade (18) 3/4 rear-rt side
(19) closeup of rt. side (20) 3/4 rear + out buildingside

Location (if other than Bureau collection) _____

Attach contact print



BEGIN

ROAD 371-FARMHSE.

(C.1875)

Use black ink and completely fill each box. Entries above the ruled line will appear on fiche labels.

CRS K-2743.



STATE OF DELAWARE
DIVISION OF
HISTORICAL & CULTURAL AFFAIRS
FICHE TITLE FRAME

Date ordered:

Camera:

Date filmed:

Operator's Signature:

The images on this microfiche are unaltered photocopies of the material contained in the survey files, Bureau of Archaeology and Historic Preservation-

Inventory

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314



FORM CRS-2

FOR OFFICE USE ONLY


CRS # H-2743
Quad Fredonia
SPO map # H-13-1P
Hundred 2 MURKELL
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Home Farm
2. STREET LOCATION: RD 371
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field c) woodland _____
d) scattered buildings e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: VALERIE CESNA TEL. # _____
YOUR ADDRESS: _____
ORGANIZATION (if any) _____ DATE: 6.27.80

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314



Form CRS-1
FOR OFFICE USE ONLY

CRS # K-2743
Quad Fire 6000
SPO map # 12-13-10
Hundred S. Mesepek
DOCUMENT 20-06/78/09/14

1. ADDRESS OF STRUCTURE : rd. 371
2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape
stories 2 1/2
bays 5
wings etc

b) Structural system frame

c) Foundation materials brick
basement CONCRETE

d) Exterior walls materials asbestos tile
color(s)



e) Roof shape: materials gable asphalt tile
cornice bar
dormers
chimney location(s) (3) interior and brick chimney blocks (The one near to newer garage addition is now fully interior (access from ext))

f) Windows spacing even
type 1/1
trim plain wood sills, surrounds, drip boards
shutters

g) Door spacing central
type 3" dash reveal, new jamb for screen door placed flush w/ ext.
trim

h) Porches location(s)
materials
supports
trim

i) Interior details (if accessible)



3 light transom
plain trim: sill, transom bar, jamb, top rail, drip bar.

USE BLACK INK ONLY

3. CONDITION: good _____ deteriorated _____

remarks: _____

4. INTEGRITY: a) original site _____ b) moved _____

c) if moved, when and from where _____

d) list major alterations and dates (if known) _____

5. DATE OF INITIAL CONSTRUCTION: 3rd Q. 19th c

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:

a) barn _____ b) carriage house _____ c) garage _____ d) privy _____

e) shed _____ f) greenhouse _____ g) shop _____ h) gardens _____

i) icehouse _____ j) springhouse _____ k) other Silo

describe: a 3rd beam had been moved for a garage
laid a roof on all that remained

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:


9. Primary References: (include location of reference).

10. Surveyor: Green Sands Date of Form: 6/27/80

USE BLACK INK ONLY

SKETCH MAP

Please indicate position of loans in relation to geographical landmarks such as streams and roads.



9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

A - RUSTICATED CEMENT BLOCK SHED W) WOOD SHINGLE GABLE ROOF

D - BARN: BRICK FOUND., VERT. BOARDS, WOOD SHINGLE GABLE ROOF

C - SILO

D - BARN: BRICK TIER FOUND., VERT. PLANK, WOOD SHINGLE GABLE ROOF, HEWN BEAMS, HOR AND TENONED

E - SHED ROOF ANIMAL STALLS, FRAME

F - GABLE ROOF ANIMAL STALLS, CEMENT BLOCK

G - SHED ROOF PRIVY

H - SITE OF BARN THAT WAS MOVED OFF THE PROPERTY TO BE USED AS A GARAGE

INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION

Document 20-06/79/01/11

CRS Number K-2743 ¹² Date 8-30 Contact Sheet # (-1262)

Description 11) front 12) detail cornice 13) rear wing

Location (if other than Bureau collection) _____

Attach contact print



BEGIN

ROAD 371-HOUSE

Use black ink and completely fill each box. Entries above the ruled line will appear on fiche labels.

CRS K-2744.



STATE OF DELAWARE
DIVISION OF
HISTORICAL & CULTURAL AFFAIRS
FICHE TITLE FRAME

Date ordered:

Camera:

Date filmed:

Operator's Signature:

The images on this microfiche are unaltered photocopies of the material contained in the survey files, Bureau of Archaeology and Historic Preservation-

Inventory

73

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314



FORM CR-2

FOR OFFICE USE ONLY

CRS # K-2744
Quad Fedence
SPO map # 12-13-18
Hundred S. Murchick
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: iml
2. STREET LOCATION: R2311
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure h) district c) archaeological site
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field b) cultivated field c) woodland _____
d) scattered buildings _____ e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Gordon Sands TEL. # _____
YOUR ADDRESS: _____
ORGANIZATION (if any) B. A. H. P. DATE: 6-27-80

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314




Form CRS-1
FOR OFFICE USE ONLY

CRS # 149
Quad Fredonia
SPO map # 12-13-18
Hundred S. Mullica
DOCUMENT 20-06778/09/14

1. ADDRESS OF STRUCTURE : RD. 471
2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape SINGLE PILE W/ REAR ELL
stories 2
bays 3
wings 2 STORY REAR ELL, 1/2 DASH WINDOWS,
INT. END BRICK CHIMNEY
- b) Structural system
FRAME
- c) Foundation
materials (NOT VISIBLE)
basement BULKHEAD ENTR.
- d) Exterior walls
materials ASPHALT SHINGLE
color(s) GREY
- e) Roof
shape: materials GABLE, TIN OVER WOOD SHINGLE
cornice ENCLOSED RAFTER ENDS
dormers —
chimney location(s) BRICK INTERIOR END
- f) Windows
spacing 3 BAY, SIDE DOOR, SYMMETRICAL
type ELONGATED 3/2 DASH
trim
shutters REMOVED
- g) Door
spacing SIDE FACADE
type REPLACED W/ MODERN DOOR
trim
- h) Porches
location(s) REAR ELL
materials ENCLOSED SHED ROOF PORCH
supports
trim
- i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good _____ deteriorated _____

remarks: _____

4. INTEGRITY: a) original site _____ b) moved _____

c) if moved, when and from where _____

d) list major alterations and dates (if known) _____

5. DATE OF INITIAL CONSTRUCTION: LAST 1/2 19TH C. ~~1900-1905~~

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:

a) barn _____ b) carriage house _____ c) garage _____ d) privy _____

e) shed (3) f) greenhouse _____ g) shop _____ h) gardens _____

i) icehouse _____ j) springhouse _____ k) other _____

describe: TWO ARE CORRUGATED METAL / THE OTHER IS A SMALL

VERT. BOARD SHEAR, W/ TIN GAUGE ROOF

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:


9. Primary References: (include location of reference).

10. Surveyor: VALERIE CESNA Date of Form: 6-27-80

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

- a) barn tin wall + roofing gabled
- b) shed, gabled.
- c) round 1 story site

PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION

Document 20-06/79/01/11

CRS Number K-2744 Date 8-80 Contact Sheet # C-1262

Description 18) front 19) left side 20) back

Location (if other than Bureau collection) _____

Attach con



BEGIN

R	O	A	D		3	7	1	-		A	D	H	O	U	S	E
---	---	---	---	--	---	---	---	---	--	---	---	---	---	---	---	---

Use black ink and completely fill each box. Entries above the ruled line will appear on fiche labels.

C	R	S		K	-	2	7	4	6	.			
---	---	---	--	---	---	---	---	---	---	---	--	--	--



STATE OF DELAWARE
DIVISION OF
HISTORICAL & CULTURAL AFFAIRS
FICHE TITLE FRAME

Date ordered:

Camera:


Date filmed:

Operator's Signature:

The images on this microfiche are unaltered phot. copies of the material contained in the survey files, Bureau of Archaeology and Historic Preservation.

Inventory

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM



DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314

FORM CP-1

FOR OFFICE USE ONLY

CRS #
Quad *Franklin*
SPO map # *12-13-14*
Hundred *S. Mendenhall*
DOCUMENT *20-06/78/04/7*

1. NAME OF LOCUS: _____
2. STREET LOCATION: Rd 371
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field c) woodland _____
d) scattered buildings _____ e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: M. Cross TEL. # _____
YOUR ADDRESS: BAHP
ORGANIZATION (if any) _____ DATE: Nov 30, 80

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314



FOR OFFICE USE ONLY

FORM CR-1

CRS # 12-276
Quad 17060110
SPO map # 12-13-18
Hundred 5 Murdock II
DOCUMENT 20-06778/08/14

1. ADDRESS OF STRUCTURE : Rd 371, across from corner Rd 376

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape
stories 2 1/2
bays 5
wings rear ell 1 story

b) Structural system frame

c) Foundation brick, 7 course stretcher
materials
basement rearest ell, rimson block

d) Exterior walls asbestos tile
materials
color(s) white; rear wall of main block, and north wall of ell is painted red.



e) Roof
shape: materials gable tin panel over wood shingle (main block) - rear ell, and asphalt tile.
cornice box w/ cyma moldings above, broken at gable end
dormers
chimney location(s) 1 at intersection of 2 rear ells, interior (at one time ext)
this, rear ell, prob. original state of cond.

f) Windows
spacing even extra window at left end of 5-bay facade double window
type 1/1 sash
trim very wide surmounts; sill, drip board
shutters -

g) Door
spacing central
type
trim

h) Porches
location(s) front
materials frame base, covered with tin panel (coarsed + rusticated like stone)
supports turned columns, painted black
trim wood flooring (tongue + groove)

i) Interior details (if accessible)
rear porch: under gable, w/ black, single, square column
cement foundation.



USE BLACK INK ONLY

3. CONDITION: good deteriorated _____

remarks: _____

4. INTEGRITY: a) original site b) moved _____
c) if moved, when and from where _____
d) list major alterations and dates (if known) _____

5. DATE OF INITIAL CONSTRUCTION: late 16th c

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:

a) barn b) carriage house _____ c) garage _____ d) privy _____
e) shed f) greenhouse _____ g) shop _____ h) gardens _____
i) icehouse _____ j) springhouse _____ k) other round, tin, single story c/o

describe: Shed: vert. panel board, on single corner block pier. gable roof w/ tin panels. door centrally in gable end.

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:


9. Primary References: (include location of reference).

10. Surveyor: Gordon Sands Date of Form: 6/30/80

USE BLACK INK ONLY

TCH MAP

see indicate position of locus in relation to geographical landmarks such as streams and etc.



9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

a. far from road facing rd 376 and rd 371

d similar

E NORTH ON SKETCH

USE BLACK INK ONLY

PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION


Document 20-06/79/01/11

CRS Number K2746 Date July 80 Contact Sheet # C1242

Description (9) 3/4 facade (10) facade (11) 3/4 facade (12) detail of
additions left side (13) outbuilding facade

Location (if other than Bureau collection) _____

Attach contact print



BEGIN

R	O	A	D		3	7	1	-		H	O	U	S	E
---	---	---	---	--	---	---	---	---	--	---	---	---	---	---

Use black ink and completely fill each box. Entries above the ruled line will appear on fiche labels.

C	R	S		K	-	2	7	4	7	.			
---	---	---	--	---	---	---	---	---	---	---	--	--	--



STATE OF DELAWARE
DIVISION OF
HISTORICAL & CULTURAL AFFAIRS
FICHE TITLE FRAME

Date ordered:

Camera:

Date filmed:

Operator's Signature:

The images on this microfiche are unaltered photocopies of the material contained in the survey files, Bureau of Archaeology and Historic Preservation-

Inventory

7b

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM



DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314

FORM CRS-2

FOR OFFICE USE ONLY

CRS # 10-247
Quad Wilmington
SPU map # 10-11-9E
Hundred S. M. Hedgesville
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: _____
2. STREET LOCATION: Rd 371
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field _____ c) woodland _____
d) scattered buildings _____ e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: GORDON SANDS TEL. # _____
YOUR ADDRESS: _____
ORGANIZATION (if any) B. A. H. P. DATE: 6/30/84

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314




Form CRS-1
FOR OFFICE USE ONLY

CRS # R. 247
Quad 4-10 min
SPO map # 10-11-12
Hundred So. Murderkill
DOCUMENT 20-06/78/09/14

1. ADDRESS OF STRUCTURE : Rd 371

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape
 - stories 2
 - bays
 - wings 1 with very slight roof slope - gable
- b) Structural system frame
- c) Foundation
 - materials brick
 - basement yes, under front part
- d) Exterior walls
 - materials wide clapboard
 - color(s) white
- e) Roof
 - shape: materials gambrel - the outer two peak lines are \pm 1 ft from center peak line
 - cornice return end gable w cornice board under eaves
 - dormers
 - chimney location(s) o on sketch, brick, modern
- f) Windows
 - spacing regular
 - type 1/1 sash
 - trim green board architrave
 - shutters
- g) Door
 - spacing nt on facade
 - type 3 horizontal panes of glass
 - trim green architrave
- h) Porches
 - location(s) front
 - materials plywood, screen, 4x4 black posts, hip roof
 - supports cement block
 - trim
- i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good _____ deteriorated _____

remarks: _____

4. INTEGRITY: a) original site _____ b) moved _____

c) if moved, when and from where _____

d) list major alterations and dates (if known) _____

modern casement replacement windows in wing

5. DATE OF INITIAL CONSTRUCTION: _____

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:

a) barn _____ b) carriage house _____ c) garage _____ d) privy _____

e) shed _____ f) greenhouse _____ g) shop _____ h) gardens _____

i) icehouse _____ j) springhouse _____ k) other _____

describe: ~~as?~~ equipment garages - cement block

dog house

collapsed shed

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

9. Primary References: (include location of reference).

Marilyn Cross


10. Surveyor: Marilyn Cross

Date of Form: June 30, 80

USE BLACK INK ONLY

ATCH MAP

use indicate position of locus in relation to geographical landmarks such as etc. etc. etc.



9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

- a) barn - cinder block, ~~w/~~ w/ out boards, gable end vertical boards
- b) collapsed barn: cement found, supporting wood sill, principal post framing, exposed end rafters notched into plate, vertical board walling.
- c. Shed/Garage (2 door) cinder block, cinder block store flue, gable end is vertical board walling, exposed rafters
- d. barn, w/ cement ramp below ground level. cinder four post in hole tie beam columns. vert. board walling exposed rafter ends.

TE NORTH ON SKETCH

USE BLACK INK ONLY

PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION


Document 20-06/79/01/11

CRS Number 3 K2747 Date July 80 Contact Sheet # 10 C1242

Description (17) portion of burned facade (18) rear addition (19) rubble
(20) outbuildings from house

Location (if other than Bureau collection) _____

Attach contact print



BEGIN

J.	B.	T	R	A	C	Y	H	S	E		
----	----	---	---	---	---	---	---	---	---	--	--

Use black ink and completely fill each box. Entries above the ruled line *(Bevia)* will appear on fiche labels.

CRS	K	-	2	7	4	8	.			
-----	---	---	---	---	---	---	---	--	--	--



STATE OF DELAWARE
DIVISION OF HISTORICAL & CULTURAL AFFAIRS
FICHE TITLE FRAME

Date ordered:

Camera:

Date filmed:

Operator's Signature:

The images on this microfiche are unaltered photocopies of the material contained in the survey files, Bureau of Archaeology and Historic Preservation-

Inventory

77

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314



FORM CRS-1

FOR OFFICE USE ONLY

CRS # K. 2748
Quad W. James
SPO map # 70-11-18
Hundred S. Murderkill
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: J.B. Tracy *veebs*
2. STREET LOCATION: Rd 319
3. OWNER'S NAME: _____ TEL. # _____
ADDRESS: _____
4. TYPE OF LOCUS: a) structure b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field c) woodland
d) scattered buildings _____ e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: J. Cross TEL. # _____
YOUR ADDRESS: _____
ORGANIZATION (if any) _____ DATE: 20 June 80

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314



Form CRS-1
FOR OFFICE USE ONLY

CRS # L-2748
Quad Wilmington
SPO map # 10-11-18
Hundred S.M. 1000k.11
DOCUMENT 20-06/78/09/14

1. ADDRESS OF STRUCTURE : Rd 370, Corner Rd 371

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape square
stories 2 1/2
bays 3
wings side wing, 1 story enclosed porch

b) Structural system framed

c) Foundation brick, stuccoed over.
materials
basement yes

d) Exterior walls aluminum siding
materials
color(s) white

e) Roof hipped w/ window walk (iron railings)
materials
cornice aluminum
dormers
Chimney location(s)




f) Windows even
spacing
type double 1/2 sash
trim architrave
shutters unfunctional black aluminum shutters

g) Door central, one in side porch
spacing
type 1-light transoms
trim classical column pilasters + architectural engaged pedestal



h) Porches
location(s) front
materials victorian
supports brick piers; turned columns
trim

i) Interior details (if accessible) porch floor rests on brick piers stuccoed over. roof supported by 6 turned columns which rest on porch floor



SKETCH PLAN

USE BLACK INK ONLY

3. CONDITION: good _____ deteriorated _____

remarks: _____

4. INTEGRITY: a) original site _____ b) moved _____
c) if moved, when and from where _____
d) list major alterations and dates (if known) _____

5. DATE OF INITIAL CONSTRUCTION: ~~18~~ m2 - late 1920s _____

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:
a) barn _____ b) carriage house _____ c) garage _____ d) privy _____
e) shed _____ f) greenhouse _____ g) shop _____ h) gardens _____
i) icehouse _____ j) springhouse _____ k) other _____
describe: white, gabled w. + band

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:


9. Primary References: (include location of reference).

10. Surveyor: Steven Sand Date of Form: 6/30/50

USE BLACK INK ONLY

ETCH MAP

also indicate position of home by relation to geographical landmarks such as structure of site.



9. COMMENTS:

Consider the following:

- a) relationship to setting
 - b) associated traditions or stories
 - c) noteworthy features
 - d) comparison with others in area
- a. on 4-5 ft bank above road, L to road house faces south
- b. Aunt Sally lived here w summer kitchen out back she lived to be over 100 years old. There are pictures of her sitting here w wolly hocks growing when she was two cadars on front lawn gone.
- c. note narrow paired windows
note wrought iron rail around roof peak
(floor plan has a central stairwell)
- d. unusual style, appears double pile
unique in area
- b^{old} owner once owned the grist mill down the road
present owner also owns house 78

TE NORTH ON SKETCH

USE BLACK INK ONLY

PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION


Document 20-06/79/01/11

CRS Number K-2748 Date July 80 Contact Sheet # C-1232

Description (a) rt side (1) facade (2) 3/4 view of facade (3) 3/4 view of rear
(4) rt. side

Location (if other than Bureau collection) _____

Attach contact print



BEGIN

T.	H.	M	C	I	L	V	A	N	E	H	S	E
----	----	---	---	---	---	---	---	---	---	---	---	---

(Beils)

Use black ink and completely fill each box. Entries above the ruled line will appear on fiche labels.

CRS K-2749.

--	--	--



STATE OF DELAWARE
DIVISION OF
HISTORICAL & CULTURAL AFFAIRS
FICHE TITLE FRAME

Date ordered:

Camera:

Date filmed:

Operator's Signature:

The images on this microfiche are unaltered photocopies of the material contained in the survey files, Bureau of Archaeology and Historic Preservation-

Inventory

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314



FORM CRS-1

FOR OFFICE USE ONLY

CRS # 6-2749
Quad Wilmington
SPO map # 10-11-12
Hundred S. Mountb.
DOCUMENT 20-06778/04/7

1. NAME OF LOCUS: T.H. McIlvane (Beer's)
2. STREET LOCATION: Rt. 578, corner of R. 571
3. OWNER'S NAME: owner diagonally across R71 on 578 TEL. # _____
ADDRESS: in the McGinn House
4. TYPE OF LOCUS: a) structure b) district _____ c) archaeological site _____
d) other _____
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)
a) fallow field _____ b) cultivated field c) woodland _____
d) scattered buildings _____ e) densely built up _____ f) other _____
6. THREATS TO LOCUS: (check more than one if necessary)
a) none known b) zoning _____ c) roads _____ d) developers _____
e) deterioration _____ f) other _____
7. REPRESENTATION ON OTHER SURVEYS:
TITLE: _____ # _____
TITLE: _____ # _____
TITLE: _____ # _____
8. YOUR NAME: Gordon Sander TEL. # _____
YOUR ADDRESS: _____
ORGANIZATION (if any) B.A.H.P. DATE: 6-30-80

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314



FOR OFFICE USE ONLY

CRS # K-2749
Quad Wilmington
SPO map # 10-1118
Hundred S. Hunderkill
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : Rd 379 + Rd 371 corner

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape polygon
stories 2
bays 5
wings multiple

b) Structural system frame

c) Foundation materials cement
basement yes

d) Exterior walls materials asbestos shakas
color(s) white


e) Roof shape: materials gable, asphalt shingles
cornice boxed
dormers -
chimney location(s) brick one w copper rounded open shield on top
on sketch

f) Windows spacing symmetrical
type 6/6 sash
trim architrave w several machine made molding around sides and lintel
shutters -

g) Door spacing center facade
type 4 panel - 2 panels vertical in upper half, wide rail, 2 sm. panels below
trim 3/4" transom, architrave w moldings

h) Porches location(s) front
materials wood
supports cement slab, 1 step up
trim 4 block columns w board pedestal c. 1 ft. high, flat roof
side
2x2 posts
cement block, flat roof

i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good _____ deteriorated _____

remarks: _____

4. INTEGRITY: a) original site _____ b) moved _____

c) if moved, when and from where _____

d) list major alterations and dates (if known) _____

5. DATE OF INITIAL CONSTRUCTION: _____

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:

a) barn b) carriage house _____ c) garage _____ d) privy _____

e) shed f) greenhouse _____ g) s^h p _____ h) gardens _____

i) icehouse _____ j) springhouse _____ k) other _____

describe: veg. root hole

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

residence
owned by #77


9. Primary References: (include location of reference).

10. Surveyor: M. Cross Date of Form: 30 June 80

USE BLACK INK ONLY

8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streets and roads.



9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

a) barn, gable roof, join upland the roofing over orig wood
 vert. boards vert. batten wall, over heavy framing w/
 principal posts, wood sills, brick foundation, up-brace
 thru rafters w/ verge board.

b) small sheds w/ gables, thru rafters, vert. board siding, fir

INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION

Document 20-06/79/01/11

CRS Number K-2749 Date July 80 Contact Sheet # C-1232

Description (5) 3/4 view of facade (6) 3/4 view of facade (7) rear

Location (if other than Bureau collection) _____

Attach contact print



BEGIN

J. B. TRACY HOUSE

(Ben's)

Use black ink and completely fill each box. Entries above the ruled line will appear on fiche labels.

CRS K-2750.



STATE OF DELAWARE
DIVISION OF HISTORICAL & CULTURAL AFFAIRS
FICHE TITLE FRAME

HALL OF RECORDS • DOVER • 1980

Date ordered:

Camera:


Date filmed:

Operator's Signature:

The images on this microfiche are unaltered photocopies of the material contained in the survey files, Bureau of Archaeology and Historic Preservation-

Inventory

CULTURAL RESOURCE SURVEY
LOCUS IDENTIFICATION FORM



DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314

FORM CRS-2

FOR OFFICE USE ONLY

CRS # K-2750
Quad Wyoming
SPO map # 10-11-18
Hundred So. Murderkill
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: J. B Tracy depts. "JBT"

2. STREET LOCATION: Rd 379

3. OWNER'S NAME: _____ TEL: # _____

ADDRESS: _____

4. TYPE OF LOCUS: a) structure b) district _____ c) archaeological site _____
d) other _____

5. SURROUNDINGS OF LOCUS: (check more than one if necessary)

a) fallow field _____ b) cultivated field c) woodland _____

d) scattered buildings _____ e) densely built up _____ f) other _____

6. THREATS TO LOCUS: (check more than one if necessary)

a) none known b) zoning _____ c) roads _____ d) developers _____

e) deterioration _____ f) other _____

7. REPRESENTATION ON OTHER SURVEYS:

TITLE: _____ # _____

TITLE: _____ # _____

TITLE: _____ # _____

8. YOUR NAME: M. Cross TEL. # _____


YOUR ADDRESS: _____

ORGANIZATION (if any) _____ DATE: 30 June 80

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY
STRUCTURAL DATA FORM

DELAWARE BUREAU OF
ARCHAEOLOGY AND HISTORIC
PRESERVATION
HALL OF RECORDS
DOVER, DELAWARE 19901
(302) 678-5314




Form CRS-1
FOR OFFICE USE ONLY

CRS # K-2750
Quad Wyoming
SPO map # 10-11-18
Hundred S. Haverhill H.
DOCUMENT 20-06/78/09/14

1. ADDRESS OF STRUCTURE : Pa 379
2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape Square w/ additions
stories 2
bays 2
wings kitchen + porch
b) Structural system frame
c) Foundation materials brick: new sections are
basement yes concrete block
d) Exterior walls aluminum siding (recent)
materials white
color(s) white



Roof
shape: materials hipped, even top on 4 sides, coming to flat (pyramidal)
cornice - in new sections
dormers - central
chimney location(s) interior brick, stucco over, corbel cap.
new (recent) exterior brickwork

- f) Windows
spacing even, 6/6 sash
type plain trim (just plain surrounds + sills)
trim
shutters -



- g) Door
spacing central
type
trim 4 raised panels, 1 light pane

quarter round molder on surround.

- h) Porches
location(s) front: cement block foot, aluminum classical columns, square shed roof (wide eaved) fluted w/ bases + square capitals.
materials Cement floor.
supports rear: flat roof enclosed out. porch.
trim

- i) Interior details (if accessible)

USE BLACK INK ONLY

3. CONDITION: good _____ deteriorated _____

remarks: _____

4. INTEGRITY: a) original site _____ b) moved _____

c) if moved, when and from where _____

d) list major alterations and dates (if known) _____

5. DATE OF INITIAL CONSTRUCTION: very late 19th C, early 20th C

6. ARCHITECT/BUILDER: _____

7. RELATED OUTBUILDINGS:

a) barn _____ b) carriage house _____ c) garage _____ d) privy _____

e) shed _____ f) greenhouse _____ g) shop _____ h) gardens _____

i) icehouse _____ j) springhouse _____ k) other _____

describe: _____

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS.


9. Primary References: (include location of reference).

10. Surveyor: Gordon Sands Date of Form: 6-30-80

USE BLACK INK ONLY

SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



A. shiplap siding
 vertical board door with leading, exposed rafters underneath tin roof.
 b/w windows, cement foundation
 B. shed roof shed, opening on "gable" end
 C. house

9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

- a. on road curve, facing road
- c. Italianate 2' pile' plan, square house
- d. similar to J. B. Tracy # 77
- c. new fluted posts of aluminum

INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION

Document 20-06/79/01/11

CRS Number K-2750 Date July 80 Contact Sheet # E-1232

Description (12) right side (13) out building (10) facade (11)
(11) 3/4 view of facade

Location (if other than Bureau collection) _____

Attach contact print

