TABLE OF CONTENTS

page

Management Summary i
Table of Contents v
List of Figures vii
List of Plates ix
List of Tables xiii
Acknowledgments xv

1. Introduction
   A. The Site and the Project 1-2
   B. Previous Work and Chronology of the Project 1-2
   C. Research Design 1-10

2. The Context: Taverns and Roads in Northern Delaware *c.*1790 to *c.*1840
   A. Taverns in Early America 2-2
   B. Time and Place 2-3
   C. The Road System 2-7
   D. Tavern Keeping in Mill Creek Hundred and Surrounding Areas 2-14
   E. Conclusions 2-30

3. The History of the Property
   A. The Tweed Era 3-1
   B. 1830 to 1934 3-7
   C. The Giacomelli Era and Afterwards 3-10
   D. Conclusions 3-26

4. The Log Building
   A. Log Building in Delaware: A Summary 4-2
   B. Description of the Building, Its Date and Its Evolution 4-8
   C. Comparison with Other Log Buildings and with Taverns in Mill Creek and the Surrounding Area 4-59
   D. Conclusions 4-66

5. The Archaeology of the Site
   A. Methods and Description 5-3
   B. The Phase II Investigations 5-3
   C. Data Recovery Excavations 5-15
   D. Conclusions 5-28

TABLE OF CONTENTS (CONTINUED)

6. The Material Culture
   A. The Archaeology of Taverns and Approaches to "Tavern Assemblages" 6-2
   B. The Tweed's Tavern Assemblage 6-8
   C. Conclusions 6-31
   D. Postscript: Prehistoric Occupation at the Sinkhole 6-31

7. Synthesis and Evaluation of the Research Objectives
   A. Taverns and the Road System of Northern Delaware 7-1
   B. The Tavern and The Community 7-1
   C. The Later History of the Property and the Preservation of the Building 7-1
   D. Tweed's Tavern as an Example of Delaware Log Architecture 7-1
   E. The Material Culture of the Tavern 7-2

References R-1

Appendices:
   A. The Public and the Tavern A-1
   B. Summary of Subsurface Testing B-1
   C. Artifact Inventory C-1
   D. Faunal Report (Marie-Lorraine Pipes) D-1
   E. Geotechnical Engineering Report (Geo-Graf, Inc) E-1
   F. Structural Assessment Report (Ortega Consulting) F-1
   G. Dendrochronology Report (Lamont-Doherty Earth Observatory of Columbia University) G-1
   H. Resumes H-1
   I. Project Administrative Data I-1

LIST OF FIGURES

page

M.1. Explaination of Compass Directions Terminology iii

1.1. General Location of Project Area 1-3
1.2. Detailed Location of Project Area 1-4

2.1. Map of New Castle County Drainages 2-4
2.2. Evans Map of Pensilvania, New-Jersey, New-York and the Three Delaware Counties in 1749 2-8
2.3. Revolutionary War Map of Part of Modern Counties of Philadelphia, Bucks in 1775 2-10
2.4. Map Showing Roads to Philadelphia and Localities in 1776 2-11
2.5. Broome Map of New Castle County in 1777 2-12
2.6. Map of Present Day Road Network and Approximate Routes of 18th- and 19th-century Turnpikes ..... opposite 2-14
2.7. Heald Map of Roads of New Castle County in 1820 2-18
2.8. Location of Selected Taverns in Mill Creek, Christiana and White Clay Creek Hundreds 2-19

3.1. Road Plot of May 30, 1804 3-3
3.2. Deed Plot of the Acres Assembled by Tweed in 1804 3-4
3.3. Sketch Map of 1807-1808 Road Layout 3-5
3.4. Deed Plot of Tracts Conveyed by Curtis and James Tweed to Ross Dixon 1831 3-8
3.5. Rea and Price Map of New Castle County, Delaware in 1849 3-9
3.6. Beers Map of New Castle County, Delaware in 1868 3-11
3.7. Hopkins Map of New Castle County, Delaware in 1881 3-12
3.8. Baist Atlas of New Castle County, Delaware in 1893 3-13
3.9. Detail from State Highway Department Atlas in 1924-1925 3-14
3.10. Site Plan with Locations of Features on the Property *circa* 1930-1960 ..... opposite 3-16
3.11. Deed Plot of Land Sold by Alfred and Catherine Giacomelli to Virginia Ann Dennison in 1957 3-17

4.1. Plan Views of the Log House, Merryman Road, Ellicot City, MD 4-5
4.2. Section View of the Log House, Merryman Road, Ellicot City, MD 4-6
4.3. Eastern Interior Elevation ..... opposite 4-8
4.4. Eastern Elevation (Schematic) ..... opposite 4-8
4.5. Northern Interior Elevation ..... opposite 4-8
4.6. Northern Elevation (Schematic) ..... opposite 4-8
4.7. Western Interior Elevation. ..... opposite 4-8
4.8. Western Elevation (Schematic) ..... opposite 4-8
4.9. Southern Interior Elevation ..... opposite 4-8
4.10. Southern Elevation (Schematic) ..... opposite 4-8
4.11. Basement Plan 4-12

LIST OF FIGURES (CONTINUED)

4.12. First Floor Joist Plan 4-13
4.13. First Floor Plan 4-22
4.14. Second Floor Joist Plan 4-23
4.15. Detail of V-notch Corner Joinery 4-41
4.16. Second Floor Plan 4-46
4.17. Rafter Plan 4-60
4.18. Plan Views of the Old Stone Tavern, Greenwich, Cumberland County, N.J. 4-67

5.1. Site Plan Showing the Location of Archaeological Investigations ....opposite 5-4
5.2. Excavation Unit 4 South Profile 5-5
5.3. Trench 16 East Profile 5-6
5.4. Trench 19 Plan ....opposite 5-6
5.5. Excavation Units 5, 6 & 7 West and North Profiles 5-7
5.6. Excavation Unit 8 North, East and South Profiles 5-17
5.7. Excavation Unit 9 West, North and East Profiles 5-18
5.8. Trench 18 Plan, Excavation Units 11-20 ....opposite 5-18
5.9. Excavation Unit 19 North Profile. 5-19
5.10. Excavation Units 16 Plan with Feature Profiles 5-20
5.11. Trench 18 West Profile, Excavation Units 11, 14, 18-20 ....opposite 5-20

6.1. King George II Copper Alloy Halfpenny 6-9
6.2. Brass Escutcheon 6-10
6.3. Artifacts in Their Historic Setting: Oil Painting by J.L. Kimmel, 1814 6-13
6.4. Artifacts in Their Historic Setting: *The Village Politicians* by A.Raimbach, 1814 6-14
6.5. Artifacts in Their Historic Setting: *Country Wedding* by J.L. Kimmel, 1814 6-15
6.6. Artifacts in Their Historic Setting: *The Happy Family* by A Lawson, 1832-34 6-16
6.7. Artifacts in Their Historic Setting: *Country Frolic and Dance* byJ.L. Kimmel, 1820 6-25
6.8. First Regiment Light Artillery Coat Button 6-26
6.9. Slate Pencil Fragments 6-27
6.10. Red Earthenware Marble 6-28
6.11. Rhyolite Broadspear 6-32

A.1. Open day interpretive sign A-6

LIST OF PLATES

		page
1.1.	A view of the house from the northwest in the spring of 2000	1-5
1.2.	Exterior view of Tweed's Tavern looking south	1-6
1.3.	Exterior view of Tweed's Tavern looking west	1-7
1.4.	Exterior view of Tweed's Tavern looking east	1-8
1.2.	Etching of a stage wagon departing a tavern circa 1795	2-15
1.2.	List of Rates for services provided by inns and taverns issued by the New Castle County Justices of the Peace in 1797	2-16
3.1.	Tweed's Tavern from the east in the 1930s	3-15
3.2.	The northwest corner of the living room in the log building, *c.* 1950	3-18
3.3.	A family friend displays a chicken in front of the outbuildings west of the house, *c.*1945-6	3-19
3.4.	Family group showing outbuildings west of the house	3-20
3.5.	Historic photograph of Tweed's tavern showing western façade and the two story shed roofed kitchen	3-21
3.6.	Historic photograph of the lower section of the eastern façade of Tweed's Tavern showing gable roofed porch	3-22
3.7.	Historic photograph of Tweed's Tavern showing western façade of building including Door 102b and basement bulkhead door	3-23
3.8.	Oblique aerial photograph, facing south, of the Tweed's Tavern property in the early 1950s	3-24
3.9.	The porch and double entry doors on the east side of the house	3-25
4.1.	Archaeologist Bill Bulger removing wall fabric to expose the log structure	4-3
4.2.	View of the V-notch joinery method from the Log Blacksmith Shop, Berks County, PA	4-7
4.3.	View of the Konig-Speicher Log House, Berks County PA	4-9
4.4.	View of Room B-1, looking southeast	4-14
4.4.	View showing the stone rubble foundation and the large arched stone fireplace support	4-15
4.6.	View of first floor framing, Room B-1 looking northeast	4-16
4.7.	View of cellar wall in Room B-1 looking northeast	4-17
4.8.	Artifacts recovered from between horizontal timbers sealed inside of the walls	4-19
4.9.	View of first floor replacement joists in Room B-1 looking south	4-20
4.10.	Interior view of north wall, Rooms 101 and 102	4-24
4.11.	View of the interior face of the junction of northern and eastern walls, Room 101	4-25
4.12.	Interior of south wall, Room 101	4-26
4.13.	View of the interior face of the junction of southern and western walls, Room 101	4-27
4.14.	Interior of western Rooms 101 and 102	4-28

LIST OF PLATES (CONTINUED)

4.15. View of the interior face of the junction of the northern and eastern walls, Room 102 4-30
4.16. Interior face of the northern wall of Room 102 4-31
4.17. View of the interior face of the junction of the western and northern walls, Room 102 4-32
4.18. View of second floor joist end (east wall) showing evidence of the raising of the first floor ceiling height 4-34
4.19. View of reused staircase stringer in ceiling above and in front of Door 102G 4-35
4.20. Northern face of southern wall of Room 103 showing intact log matrix beneath studs and a previous layer of stucco and lath 4-36
4.21. View of exposed original exterior wall surface in Room 105 4-38
4.22. View of exposed original exterior wall surface in Room 105 4-39
4.23. View of former exterior (eastern) face of west wall of Room 105 4-42
4.24. View of Former exterior (eastern) face of west wall of Room 105 looking north west 4-43
4.25. View of exposed corner V-Notch joinery, west wall of Room 105 4-44
4.26. View of the junction of the southern and western walls, Room 201 4-47
4.27. View of Western wall of Room 201 and Window 201a 4-48
4.28. View showing eastern and southern walls of Room 202 prior to the removal of the majority of plaster and lath 4-49
4.29. Junction of eastern and southern walls of Room 202 4-50
4.30. Interior of eastern wall of Room 202 looking northeast 4-51
4.31. View of inner (western) face of east wall of Room 202 showing the void in log matrix marking the former location of Window 202d 4-53
4.32. Interior of Room 203 before removal of plaster surfaces 4-54
4.33. Junction of northern and eastern walls of Room 203 4-55
4.34. View showing northern face of southern wall of Room 205 4-58
4.35. Interior of Attic showing rafters, looking southeast 4-61
4.36. View of rafters 3, 4 and 5, looking south 4-62
4.37. View of the former exterior face of the former northwest corner of the building from within the attic of the western addition 4-63
4.38. View of the former exterior face of the top of the northern gable taken from within the attic of the northern addition 4-64

5.1. View of fragmentary northwest corner of stone foundation wall of outbuilding in Trench 17, facing southwest 5-8
5.2. View facing northwest of shallow dry-laid stone garden wall in Trench 7 5-9
5.3. View of Excavation Unit 1 facing northwest 5-10
5.4. View of Excavation Units 2 and 3 facing east 5-11
5.5. View of Excavation Unit 4 facing northwest 5-12
5.6. View of the best-preserved portion of stone foundation wall of outbuilding in Trench 14, facing southwest 5-13
5.7. Plan View of Excavation Units 5, 6 & 7 facing east 5-14
5.8. View of Excavation Unit 8 facing south 5-21

LIST OF PLATES (CONTINUED)

5.9. View of Excavation Unit 9 facing south 5-22
5.10. View of Excavation Unit 9 facing south 5-23
5.11. View of Excavation Units 12-14 and 19 within Trench 18, facing north 5-24
5.12. View of cut through the sink hole in Trench 18, Excavation Units 13 & 17 facing west from the second floor of the house 5-25
5.13. Jason Uebelacker monitors the activities of the backhoe during the excavation of the upper clay fill [87] of the sink hole in Trench 18 5-26
5.14. View of stone-lined well under the floor of the east porch looking down from the second story of tavern/house 5-27

6.1. Selected utilitarian coarse red earthenware 6-17
6.2. Mended ceramic vessels 6-18
6.3. Selected refined earthenware ceramics 6-19
6.4. Selected refined earthenware ceramics 6-20
6.5. Selected prehistoric lithic artifacts from the Woodland I and Woodland II periods 6-33

A.1. Visitors lined up for open day A-7
A.2. Screening at open day A-8
A.3. Children's activities table at open day A-9
A.4. Artifact display at open day A-10
A.5. Exterior view of Tweed's tavern looking east A-11
A.6. Foundation after tavern removed A-12
A.7. Tavern on blocks A-13
A.8. Tavern at new location on Limestone Road A-14

LIST OF TABLES

		page
2.1.	Wealth, Occupations and Building Materials in Mill Creek Hundred 1804 (Table by Edward F. Heite)	2-6
2.2.	Taverns and their Operators in Mill Creek Hundred during First Quarter of the 19th Century (Table by Edward F. Heite)	2-20
2.3.	Analysis of Select 19th-century Tavernkeeper's Inventories in Brandywine, Christiana, Mill Creek and White Clay Hundreds (Excluding Wilmington)	2-22
2.4.	Values of Tavernkeepers Estates	2-23
2.5.	Real Estate Tax Assessments of Delaware Taverns 1798	2-24
2.6.	Real Estate Tax Assessments of Delaware Taverns 1818	2-25
2.7.	Real Estate Tax Assessments of Delaware Taverns 1825	2-26
2.8.	Real Estate Tax Assessments of Delaware Taverns 1836	2-27
2.9.	Number of Tavern Petitions Issued in Mill Creek Hundred Per Year	2-29
6.1.	Tweed's Tavern Minimum Number of Vessel	6-12
6.2.	Tweed's Tavern: Vessel Forms and Minimum Number of Vessels	6-23
6.3.	Tweed's Tavern Artifact Totals by Class	6-24
6.4.	Intersite Ceramic Type Comparison	opposite 6-28
6.5.	Intersite Artifact Comparisons by Class	6-29