

DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S-00210

1. HISTORIC NAME/FUNCTION: Sussex Correctional Institution

2. ADDRESS/LOCATION: East side of U.S. 113

3. CURRENT CONDITION:    **excellent**                  **good**                  **fair**                  **poor**                  **demolished**

4. INTEGRITY: Many historic-period buildings have been removed from the site since it was recorded in 1980 and 1998; additional buildings have been constructed, and the site is dominated by modern constructions.

5. SETTING INTEGRITY:

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
X	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:

Organization: John Milner Associates Inc.                  Date: 06/2006

**8. OTHER NOTES OR OBSERVATIONS:**

**CRS# S-00210**

JMA architectural historians walked the property with warden Richard Kenney. Several resources that had been recorded in 1980 and 1998 were no longer extant: Warden's house (.001), feed barn (.005), machine shed (.006), maintenance office (.007), machine shop (.008), print building (.009), armory (.011), and kitchen (.012). Four additional elements were identified that had not previously been recorded: potato shed (.013), swine barn (.014), vehicle equipment shed (.015), and potters' field cemetery (.016).

Warden Kenney reported that the former potato sheds were renovated as offices in the 1980s and the main building's interior and exterior were renovated in 1977.

**9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):**

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- X 1830-1880- Industrialization and Early Urbanization
- 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |                       |   |   |
|-----------------------|---|---|
| Agriculture           |   | Transportation and Communication              |
| Forestry              |   | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      |   | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      | X | Government                                    |
| Fishing/Oystering     |   | Religion                                      |
| Manufacturing         |   | Education                                     |
| Retailing/Wholesaling |   | Community Organizations                       |
| Finance               |   | Occupational Organizations                    |
| Professional Services |   | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-00210.002

1. ADDRESS/LOCATION: East side of U.S. 113

2. FUNCTION(S): historic prison current prison

3. YEAR BUILT: 1931 CIRCA?: ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site moved  
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. numerous additions

b.

6. CURRENT CONDITION: excellent good X fair poor

7. DESCRIPTION:

a. Structural system brick

b. Number of stories 2-1/2

c. Wall coverings none

d. Foundation brick

e. Roof hipped  
structural system  
coverings asphalt shingle  
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: west

1) bays: multiple

2) windows: regular fenestration; vinyl-trim, awning windows with brick sills and brick lintels with centered concrete keystones

3) door(s): 1, metal, center

4) other:

- b. **Side: direction:** north
  - 1) **bays:** [obscured by modern addition]
  - 2) **windows:**
  - 3) **door(s):**
  - 4) **other:**

- c. **Side: direction:** south
  - 1) **bays:** [inaccessible]
  - 2) **windows:**
  - 3) **door(s):**
  - 4) **other:**

- d. **Rear: direction:** east
  - 1) **bays:** [obscured by modern addition]
  - 2) **windows:**
  - 3) **door(s):**
  - 4) **other:**

9. **INTERIOR (if accessible):**

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



- b. **Side: direction:** east
  - 1) **bays:** 11
  - 2) **windows:** 9, first story; regular; fixed
  - 3) **door(s):** 2; irregular; wood
  - 4) **other:**
  
- c. **Side: direction:** west
  - 1) **bays:** 5
  - 2) **windows:** 5, first story; irregular; fixed
  - 3) **door(s):** none
  - 4) **other:**
  
- d. **Rear: direction:** north
  - 1) **bays:** 1
  - 2) **windows:** 1, first story; fixed
  - 3) **door(s):** none
  - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-00210.004

1. ADDRESS/LOCATION: East side of U.S. 113

2. FUNCTION(S): historic potato shed current prison office

3. YEAR BUILT: 1945 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. modernized with modern windows; added height to building  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good x fair \_\_\_\_\_ poor \_\_\_\_\_

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories 1-1/2

c. Wall coverings

d. Foundation concrete block

e. Roof  
structural system gable front  
coverings asphalt  
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: south
  - 1) bays: 3
  - 2) windows: 2, first story; regular
  - 3) door(s): 1; center; metal
  - 4) other:

- b. **Side: direction:** west
  - 1) **bays:** 3
  - 2) **windows:** 2, first story; regular
  - 3) **door(s):** 1; NW corner; metal
  - 4) **other:**
  
- c. **Side: direction:** east
  - 1) **bays:** 2
  - 2) **windows:** 2, first story; irregular
  - 3) **door(s):** none
  - 4) **other:**
  
- d. **Rear: direction:** north
  - 1) **bays:** [obscured by modern additions]
  - 2) **windows:**
  - 3) **door(s):**
  - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-00210.010

1. ADDRESS/LOCATION: East side of U.S. 113

2. FUNCTION(S): historic potato shed current prison office

3. YEAR BUILT: 1945 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_

a. connected to two other parallel buildings by a perpendicular addition at the rear

b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good x fair \_\_\_\_\_ poor \_\_\_\_\_

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories 1-1/2.

c. Wall coverings wood siding, vertical in gable end

d. Foundation concrete block

e. Roof

structural system gable front

coverings asphalt

openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: south

1) bays: 3

2) windows: 2; regular; 1/1 double hung

3) door(s): 1; center; metal

4) other:

**b. Side: direction: west**

1) **bays:** [inaccessible]

2) **windows:**

3) **door(s):**

4) **other:**

**c. Side: direction: east**

1) **bays:** 1

2) **windows:** 1; double hung; aluminum trim with metal security bars on exterior

3) **door(s):** none

4) **other:**

**d. Rear: direction: north**

1) **bays:** [obscured by modern addition]

2) **windows:**

3) **door(s):**

4) **other:**

**9. INTERIOR (if accessible):**


**a) Floor plan**

rectangle

**b) Partition/walls**

**c) Finishes**

**d) Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-00210.013

1. ADDRESS/LOCATION: East side of U.S. 113

2. FUNCTION(S): historic potato shed current prison Vo-Tech center

3. YEAR BUILT: 1945 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_

a. covered from a potato shed; building raised off original foundation and cellar filled in

b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good x fair \_\_\_\_\_ poor \_\_\_\_\_

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories 1-1/2

c. Wall coverings wood siding, vertical in gable end

d. Foundation concrete block

e. Roof  
structural system gable front  
coverings  
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: south

1) bays: 1

2) windows: none

3) door(s): 1; center; metal

4) other:

**b. Side: direction: west**

1) **bays:** none

2) **windows:**

3) **door(s):**

4) **other:**

**c. Side: direction: east**

1) **bays:** none

2) **windows:**

3) **door(s):**

4) **other:**

**d. Rear: direction: north**

1) **bays:** [obscured by rear addition]

2) **windows:**

3) **door(s):**

4) **other:**

**9. INTERIOR (if accessible):**


**a) Floor plan**

rectangle

**b) Partition/walls**

**c) Finishes**

**d) Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-00210.014

1. ADDRESS/LOCATION: East side of U.S. 113

2. FUNCTION(S): historic swine barn current storage

3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good x fair \_\_\_\_\_ poor \_\_\_\_\_

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories 1

c. Wall coverings

d. Foundation concrete block

e. Roof  
structural system gable front  
coverings composition  
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: south  
1) bays: 1  
2) windows: none  
3) door(s): 1; W side; metal  
4) other:

- b. **Side: direction:** east
  - 1) **bays:** 8
  - 2) **windows:** 8; regular; fixed
  - 3) **door(s):** none
  - 4) **other:**
  
- c. **Side: direction:** west
  - 1) **bays:** 8
  - 2) **windows:** 8; regular; fixed
  - 3) **door(s):** none
  - 4) **other:**
  
- d. **Rear: direction:** north
  - 1) **bays:** none
  - 2) **windows:**
  - 3) **door(s):**
  - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-00210.015

1. ADDRESS/LOCATION: East side of U.S. 113

2. FUNCTION(S): historic vehicle shed current vehicle shed

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good \_\_\_\_\_ fair \_\_\_\_\_ poor x

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings wood siding, horizontal & vertical
- d. Foundation none
- e. Roof structural system shed  
coverings wood, corrugated metal  
openings \_\_\_\_\_

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: south
  - 1) bays: 4; open bays separated by wooden posts
  - 2) windows: \_\_\_\_\_
  - 3) door(s): \_\_\_\_\_
  - 4) other: \_\_\_\_\_

- b. Side: direction: west
  - 1) bays: 1
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: east
  - 1) bays: 1
  - 2) windows:
  - 3) door(s):
  - 4) other:

- d. Rear: direction: north
  - 1) bays: 4
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
LANDSCAPE ELEMENTS FORM

CRS # S-00210.016

1. ADDRESS/LOCATION: Sussex County Correctional Institute, East Side Of Rt. 113

2. TYPE/FUNCTION/NAME: Potters Field

3. YEAR BUILT: 1900 CIRCA?:

list major alterations and additions with years (if known) year

a. \_\_\_\_\_

b. \_\_\_\_\_

4. DESIGNER: original \_\_\_\_\_  
alteration(s) \_\_\_\_\_

5. STYLE: Pauper's graves, prisoner burials with no distinguishable marking on most graves.

6. CURRENT CONDITION: excellent  good  fair  poor

7. RELATIONSHIP TO OTHER PROPERTIES: Almshouse, Sussexx County Poor Farm / State Prison

8. DESCRIPTION:

a) Scenic views/vistas: Access to property is from Wood Branch rd., cemetery is situated west of roadway, east of cornfields adjacent to east side of US113.

b) Circulation system: No discernable paths

c) Spatial subdivisions: unknown, many graves unmarked.


d) Paving material(s): packed dirt (small turnoff at entrance gate is the only entrance for vehicles.)

e) Utilities:

f) Water elements:

g) Vegetation:

h) Other: The proprty is bounded by a post & rail fence. Main gate features concrete hitching posts. Fence posts along Wood Branch rd. are cement; others are 4"x4" wood posts. Main gate is simple metal tubing. "No Trespassing" sign at right of main entrance.



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901


CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-00210

1. ADDRESS/LOCATION: East side of U.S. 113
2. NOT FOR PUBLICATION                      reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.  
(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-00210

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S-03188

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: McColley's Chapel Road

3. CURRENT CONDITION: excellent  good  fair  poor  demolished

4. INTEGRITY:  
\_\_\_\_\_

5. SETTING INTEGRITY:  
\_\_\_\_\_

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature:

Organization: John Milner Associates, Inc Date: 4/3/2008

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03188

Resurveyed for US113 North/South Study, Delaware Department of Transportation, by John Milner Associates, Inc.

Demolished

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750∇ Contact Period (Native American)
- 1630-1730∇ Exploration and Frontier Settlement
- 1730-1770∇ Intensified and Durable Occupation
- 1770-1830∇ Early Industrialization
- 1830-1880∇ Industrialization and Early Urbanization
- 1880-1940∇ Urbanization and Early Suburbanization
- 1940-1960∇ Suburbanization and Early Ex-urbanization


b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |  |  |
|--|--|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication              |
| <input type="checkbox"/> Forestry              | <input type="checkbox"/> Settlement Patterns and Demographic Changes   |
| <input type="checkbox"/> Trapping/Hunting      | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government                                    |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion                                      |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education                                     |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                       |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                    |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events        |

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S-03192

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: 17097 Gravelly Branch Road

3. CURRENT CONDITION:    excellent                      good                       fair                      poor                      demolished

4. INTEGRITY: original site  
\_\_\_\_\_

5. SETTING INTEGRITY:  
\_\_\_\_\_

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc.                      Date: 09/2006

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03192


Resurveyed by JMA for the U.S. 113 North/South Study on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
- 1600-1750- Contact Period (Native American)  
 1630-1730- Exploration and Frontier Settlement  
 1730-1770- Intensified and Durable Occupation  
 1770-1830- Early Industrialization  
 1830-1880- Industrialization and Early Urbanization  
 X 1880-1940- Urbanization and Early Suburbanization  
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |                       |   |   |
|-----------------------|---|---|
| Agriculture           |   | Transportation and Communication              |
| Forestry              |   | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      |   | Government                                    |
| Fishing/Oystering     |   | Religion                                      |
| Manufacturing         |   | Education                                     |
| Retailing/Wholesaling |   | Community Organizations                       |
| Finance               |   | Occupational Organizations                    |
| Professional Services |   | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-03192.001

1. ADDRESS/LOCATION: 17097 Gravelly Branch Road
2. FUNCTION(S): historic current
3. YEAR BUILT: 1900 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, central hall
5. INTEGRITY: original site  moved  
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in aluminum, replacement windows, porch enclosure on front and back

b.

6. CURRENT CONDITION: excellent good  fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: T-Plan Stories: 1.5  
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials:  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Side Gable  
materials: Composition  
cornice:  
dormers:  
chimney: location(s): interior, gable, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: south
- 1) Bays: 5
- 2) Windows: 4, 4  
Fenestration: regular  
Type: double hung, awning, 1/1, single pane  
Trim: wood  
Shutters:

**Facade (cont'd)**

- 3) **Door(s):** 1  
**Location:** center  
**Type:** wood & glass  
**Trim:** plain
- 4) **Porch(es):** full-width

**b. Side: Direction: east**

- 1) **Bays:** 2
- 2) **Windows:** 2  
**Fenestration:** irregular  
**Type:** double hung, casement, 1/1, octagonal pane  
**Trim:** vinyl  
**Shutters:**
- 3) **Door(s):**  
**Location:**  
**Type:**  
**Trim:**
- 4) **Porch(es):** porch enclosure on 1-story gabled ell, enclosed by vinyl and modern 1/1 windows

**c. Side: Direction: west**

- 1) **Bays:** 3
- 2) **Windows:** 3  
**Fenestration:** irregular  
**Type:** double hung, awning, 1/1, single pane  
**Trim:** vinyl  
**Shutters:**
- 3) **Door(s):**  
**Location:**  
**Type:**  
**Trim:**
- 4) **Porch(es):**


**d. Rear: Direction: north**

- 1) **Bays:**
- 2) **Windows:** 0, 3  
**Fenestration:** irregular  
**Type:** awning, single pane  
**Trim:** vinyl  
**Shutters:**
- 3) **Door(s):**  
**Location:**  
**Type:**  
**Trim:**
- 4) **Porch(es):** partially obscured by rear ell

**9. INTERIOR:**

- 10. **LANDSCAPING:** faces Gravelly Branch Rd., dirt driveway to one side, trees and shrubs across front lawn, shrubs to rear, fallow fields further to rear

**11. OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03192.002

1. ADDRESS/LOCATION: 17097 Gravelly Branch Road

2. FUNCTION(S): historic shed current \_\_\_\_\_

3. YEAR BUILT: 1900 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good \_\_\_\_\_ fair X poor \_\_\_\_\_

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Horizontal

d. Foundation \_\_\_\_\_

e. Roof  
structural system Gable Front  
coverings Other: metal  
openings \_\_\_\_\_

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: south

1) bays: 1

2) windows: \_\_\_\_\_

3) door(s): Count: 1

4) other: \_\_\_\_\_

- b. Side: direction: east
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: west
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- d. Rear: direction: north
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY

CRS # S-03192

MAP FORM

1. ADDRESS/LOCATION: 17097 Gravelly Branch Road


2. NOT FOR PUBLICATION reason: \_\_\_\_\_

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH







DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S-03205

1. HISTORIC NAME/FUNCTION: Short Farm

2. ADDRESS/LOCATION: Dupont Highway and Pond Street

3. CURRENT CONDITION:    **excellent**                      **good**                      **fair**                      **poor**                      **demolished**

4. INTEGRITY: complex dismantled, fall 2008

5. SETTING INTEGRITY:  
\_\_\_\_\_


6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: \_\_\_\_\_

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc.                      Date: 11/2008

**8. OTHER NOTES OR OBSERVATIONS:**

**CRS# S-03205**


This property was dismantled after it had been recorded, evaluated, and determined eligible for the National Register of Historic Places under Criteria A and C, as reviewed and concurred upon by the Delaware Department of Transportation (the Department) and DelSHPO. By July 2008, the buildings on the abandoned property were in an advanced state of deterioration, as documented by the Department in a series of photographs, and the Department stated that they no longer concurred that the property was eligible. By November 2008, major elements of the property had been demolished, and the former feed and grain store (.011)—originally the Georgetown Fire House—had been moved to a site in downtown Georgetown according to a representative from DelSHPO. The property as currently configured no longer retains the integrity necessary to convey its significance under Criterion A as an agricultural and agricultural/commercial property or under Criterion C as an agricultural complex. The property is therefore no longer eligible for listing on the National Register. The original evaluation is included in Appendix E in the final report, *Evaluation of National Register Eligibility for Architectural Properties in the Georgetown Study Area, U.S. 113 North/South Study*, prepared for the Delaware Department of Transportation and Federal Highway Administration by John Milner Associates, Inc., Philadelphia, PA, 2009.

**9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):**

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
- 1600-1750- Contact Period (Native American)  
 1630-1730- Exploration and Frontier Settlement  
 1730-1770- Intensified and Durable Occupation  
 1770-1830- Early Industrialization  
 1830-1880- Industrialization and Early Urbanization  
 X 1880-1940- Urbanization and Early Suburbanization  
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |  |  |
|--|--|
| <ul style="list-style-type: none"> <li>X Agriculture</li> <li>Forestry</li> <li>Trapping/Hunting</li> <li>Mining/Quarrying</li> <li>Fishing/Oystering</li> <li>Manufacturing</li> <li>Retailing/Wholesaling</li> <li>Finance</li> <li>Professional Services</li> </ul> | <ul style="list-style-type: none"> <li>X Transportation and Communication</li> <li>Settlement Patterns and Demographic Changes</li> <li>Architecture, Engineering and Decorative Arts</li> <li>Government</li> <li>Religion</li> <li>Education</li> <li>Community Organizations</li> <li>Occupational Organizations</li> <li>Major Families, Individuals and Events</li> </ul> |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S-03205

1. HISTORIC NAME/FUNCTION: Short Farm

2. ADDRESS/LOCATION: Dupont Highway and Pond Street

3. CURRENT CONDITION:    excellent                      good                       fair                      poor                      demolished

4. INTEGRITY: original site

5. SETTING INTEGRITY:

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
X	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc.                      Date: 09/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03205


Resurveyed by JMA for the U.S. 113 North/South Study on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
- 1600-1750- Contact Period (Native American)  
 1630-1730- Exploration and Frontier Settlement  
 1730-1770- Intensified and Durable Occupation  
 1770-1830- Early Industrialization  
 1830-1880- Industrialization and Early Urbanization  
 X 1880-1940- Urbanization and Early Suburbanization  
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- X Agriculture
  - Forestry
  - Trapping/Hunting
  - Mining/Quarrying
  - Fishing/Oystering
  - Manufacturing
  - Retailing/Wholesaling
  - Finance
  - Professional Services
  - Transportation and Communication
  - Settlement Patterns and Demographic Changes
  - X Architecture, Engineering and Decorative Arts
  - Government
  - Religion
  - Education
  - Community Organizations
  - Occupational Organizations
  - Major Families, Individuals and Events



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-03205.001

1. ADDRESS/LOCATION: Dupont Highway and Pond Street
2. FUNCTION(S): historic current
3. YEAR BUILT: 1890 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Victorian, Vernacular, side hall
5. INTEGRITY: original site  moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in asbestos, house has undergone change in size and entrance, present entrance post dates rear ell

b.

6. CURRENT CONDITION: excellent good  fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: T-Plan Stories: 2.5  
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials:  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): Asbestos
- e. Roof: shape: Cross Gable  
materials: Asphalt  
cornice: other: garble returns within gable  
dormers:  
chimney: location(s): interior, gable; exterior, gable, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: northwest
- 1) Bays: 3
- 2) Windows: 2, 3  
Fenestration: regular  
Type: double hung, 1/1  
Trim: wood  
Shutters: vinyl, non-functional

- 3) **Door(s):** 1  
**Location:** side  
**Type:** wood & glass  
**Trim:** plain
- 4) **Porch(es):** full-width

**b. Side: Direction:** northeast

- 1) **Bays:**
- 2) **Windows:** 1, 2, 2  
**Fenestration:** irregular  
**Type:** double hung, 1/1  
**Trim:** wood  
**Shutters:**
- 3) **Door(s):** 1  
**Location:** corner  
**Type:** other: northeast  
**Trim:** plain
- 4) **Porch(es):**

**c. Side: Direction:** southwest

- 1) **Bays:**
- 2) **Windows:** 7, 6, 3  
**Fenestration:** regular  
**Type:** double hung, 1/1  
**Trim:** wood  
**Shutters:** (vinyl, non-functional)
- 3) **Door(s):**  
**Location:**  
**Type:**  
**Trim:**
- 4) **Porch(es):**


**d. Rear: Direction:** southeast

- 1) **Bays:**
- 2) **Windows:** 0, 3, 2  
**Fenestration:** irregular  
**Type:** double hung, 1/1  
**Trim:** wood  
**Shutters:**
- 3) **Door(s):** 1  
**Location:** side  
**Type:** wood & glass  
**Trim:** plain
- 4) **Porch(es):** wrap-around, wrap around porch on present rear, 1-story, metal roofing, asbestos siding

**9. INTERIOR:**

**10. LANDSCAPING:** sits at corner of Rt. 113 and Pond Rd., dwelling shrouded in overgrown trees and brush, outbuildings to rear of house

**11. OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03205.002

1. ADDRESS/LOCATION: Dupont Highway and Pond Street

2. FUNCTION(S): historic smokehouse current \_\_\_\_\_

3. YEAR BUILT: 1935 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site moved  
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. \_\_\_\_\_

b. \_\_\_\_\_

6. CURRENT CONDITION: excellent good X fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Horizontal

d. Foundation other: not visible

e. Roof  
structural system Gable Front  
coverings Asphalt  
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southwest

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: wood

4) other:

- b. **Side: direction:** northwest
  - 1) **bays:** 1
  - 2) **windows:** Count: 1; regular ; other: ventilation bay
  - 3) **door(s):**
  - 4) **other:**

- c. **Side: direction:** southeast
  - 1) **bays:**
  - 2) **windows:**
  - 3) **door(s):**
  - 4) **other:**

- d. **Rear: direction:** northeast
  - 1) **bays:**
  - 2) **windows:**
  - 3) **door(s):**
  - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03205.003

1. ADDRESS/LOCATION: Dupont Highway and Pond Street

2. FUNCTION(S): historic garage current \_\_\_\_\_

3. YEAR BUILT: 1935 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good X fair \_\_\_\_\_ poor \_\_\_\_\_

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories \_\_\_\_\_
- c. Wall coverings Wood Siding Horizontal
- d. Foundation other: not visible
- e. Roof structural system Gable Front  
coverings Asphalt  
openings \_\_\_\_\_

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: southwest
  - 1) bays: 1
  - 2) windows: \_\_\_\_\_
  - 3) door(s): Count: 1; Location: center ; Type: wood  
Details: double door
  - 4) other: \_\_\_\_\_

- b. Side: direction: northwest
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: southeast
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- d. Rear: direction: northeast
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03205.004

1. ADDRESS/LOCATION: Dupont Highway and Pond Street

2. FUNCTION(S): historic garage current \_\_\_\_\_

3. YEAR BUILT: 1925 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good X fair \_\_\_\_\_ poor \_\_\_\_\_

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Wood Siding Horizontal
- d. Foundation other: not visible
- e. Roof structural system Gable Front  
coverings Asphalt  
openings \_\_\_\_\_

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: southwest
  - 1) bays: 1
  - 2) windows: \_\_\_\_\_
  - 3) door(s): Count: 1; Location: center ; Type: wood & glass
  - 4) other: \_\_\_\_\_

- b. Side: direction: southeast
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: northwest
  - 1) bays: 1
  - 2) windows: Count: 1; regular ; fixed, multi pane
  - 3) door(s):
  - 4) other:

- d. Rear: direction: northeast
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03205.005

1. ADDRESS/LOCATION: Dupont Highway and Pond Street

2. FUNCTION(S): historic garage current \_\_\_\_\_

3. YEAR BUILT: 1925 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good X fair \_\_\_\_\_ poor \_\_\_\_\_

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Wood Siding Horizontal
- d. Foundation other: not visible
- e. Roof structural system Gable Front  
coverings Asphalt  
openings \_\_\_\_\_

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: southwest
  - 1) bays: 1
  - 2) windows: \_\_\_\_\_
  - 3) door(s): Count: 1; Location: center ; Type: wood & glass, other Details: garage door
  - 4) other: \_\_\_\_\_

- b. Side: direction: southeast
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: northwest
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- d. Rear: direction: northeast
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03205.006

1. ADDRESS/LOCATION: Dupont Highway and Pond Street

2. FUNCTION(S): historic equipment shed current \_\_\_\_\_

3. YEAR BUILT: 1945 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site  moved \_\_\_\_\_  
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year  
a. replacement garage doors  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent good  fair poor

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories 1

c. Wall coverings

d. Foundation poured concrete

e. Roof  
structural system Side Gable  
coverings Other: metal  
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: southwest  
1) bays: 7  
2) windows: Count: 2; irregular ; awning  
3) door(s): Count: 5; Location: other: irregular ; Type: wood, metal  
4) other:

- b. Side: direction: northwest
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: southeast
  - 1) bays: 1
  - 2) windows:
  - 3) door(s): Count: 1
  - 4) other:

- d. Rear: direction: northeast
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03205.007

1. ADDRESS/LOCATION: Dupont Highway and Pond Street

2. FUNCTION(S): historic equipment shed current \_\_\_\_\_

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good X fair \_\_\_\_\_ poor \_\_\_\_\_

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Metal

d. Foundation poured concrete

e. Roof  
structural system Gable Front  
coverings Other: metal  
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: northwest  
1) bays: 5  
2) windows: Count: 3; regular ; double hung, 6/6  
3) door(s): Count: 2; Location: center, side ; Type: wood  
4) other:

b. Side: direction: southwest

1) bays:

2) windows:

3) door(s):

4) other:

c. Side: direction: northeast

1) bays:

2) windows:

3) door(s):

4) other:

d. Rear: direction: southeast

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: wood

4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03205.008

1. ADDRESS/LOCATION: Dupont Highway and Pond Street

2. FUNCTION(S): historic stable current \_\_\_\_\_

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good X fair \_\_\_\_\_ poor \_\_\_\_\_

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Metal
- d. Foundation other: none
- e. Roof structural system Gable Front  
coverings Other: metal  
openings \_\_\_\_\_

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: southeast
  - 1) bays: 1
  - 2) windows: \_\_\_\_\_
  - 3) door(s): Count: 1; Location: center ; Type: wood, other  
Details: sliding door
  - 4) other: \_\_\_\_\_

b. Side: direction: southwest

1) bays:

2) windows:

3) door(s):

4) other:

c. Side: direction: northeast

1) bays:

2) windows:

3) door(s):

4) other:

d. Rear: direction: northwest

1) bays:

2) windows:

3) door(s):

4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03205.009

1. ADDRESS/LOCATION: Dupont Highway and Pond Street

2. FUNCTION(S): historic corncrib current \_\_\_\_\_

3. YEAR BUILT: 1920 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_

a. \_\_\_\_\_

b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good \_\_\_\_\_ fair **X** \_\_\_\_\_ poor \_\_\_\_\_

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Vertical

d. Foundation other: none

e. Roof  
structural system Gable Front  
coverings Other: metal  
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southwest

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: wood

4) other:

- b. Side: direction: northwest
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: southeast
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- d. Rear: direction: northeast
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03205.010

1. ADDRESS/LOCATION: Dupont Highway and Pond Street

2. FUNCTION(S): historic barn current \_\_\_\_\_

3. YEAR BUILT: 1920 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good \_\_\_\_\_ fair \_\_\_\_\_ poor **X**

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Vertical

d. Foundation other: none

e. Roof  
structural system Gable Front  
coverings Other: metal  
openings \_\_\_\_\_

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southwest

1) bays: 1

2) windows: \_\_\_\_\_

3) door(s): Count: 1

4) other: \_\_\_\_\_

- b. Side: direction: northwest
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: southeast
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- d. Rear: direction: northeast
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03205.011

1. ADDRESS/LOCATION: Dupont Highway and Pond Street

2. FUNCTION(S): historic feed and grain store current \_\_\_\_\_

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site moved  
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year  
a.  
b.

6. CURRENT CONDITION: excellent good X fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1.5

c. Wall coverings Metal

d. Foundation other: none

e. Roof  
structural system Gable Front  
coverings Other: metal  
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: southwest
  - 1) bays: 6
  - 2) windows: Count: 2; double hung, 6/6
  - 3) door(s): Count: 6; Location: other: side by side ; Type: other  
Details: sliding doors
  - 4) other:

- b. Side: direction: northwest
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: southeast
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- d. Rear: direction: northeast
  - 1) bays: 1
  - 2) windows:
  - 3) door(s): Count: 1; Location: side ; Type: metal
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03205.012

1. ADDRESS/LOCATION: Dupont Highway and Pond Street

2. FUNCTION(S): historic general store current \_\_\_\_\_

3. YEAR BUILT: 1950 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site moved  
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year  
a.  
b.

6. CURRENT CONDITION: excellent good X fair poor

7. DESCRIPTION:

a. Structural system stone

b. Number of stories 1

c. Wall coverings Asbestos

d. Foundation concrete block

e. Roof structural system Flat  
coverings  
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: southwest
  - 1) bays: 4
  - 2) windows: Count: 3; irregular ; double hung, 1/1, 6/6
  - 3) door(s): Count: 1; Location: side ; Type: wood & glass  
Details: double doors
  - 4) other:

- b. **Side: direction:** northwest
  - 1) **bays:** 3
  - 2) **windows:** Count: 2; irregular ; double hung, 1/1
  - 3) **door(s):** Count: 1; Location: center ; Type: wood
  - 4) **other:**

- c. **Side: direction:** southeast
  - 1) **bays:**
  - 2) **windows:**
  - 3) **door(s):**
  - 4) **other:**

- d. **Rear: direction:** northeast
  - 1) **bays:**
  - 2) **windows:**
  - 3) **door(s):**
  - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # S-03205

1. ADDRESS/LOCATION: Dupont Highway and Pond Street
2. NOT FOR PUBLICATION reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-03205

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S-03208

1. HISTORIC NAME/FUNCTION: Dwelling/Agricultural Property

2. ADDRESS/LOCATION: Bedford

3. CURRENT CONDITION:    excellent                      good                       fair                      poor                      demolished

4. INTEGRITY:  
\_\_\_\_\_

5. SETTING INTEGRITY:  
\_\_\_\_\_


6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
X	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc.                      Date: 09/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03208

Resurveyed by JMA for the U.S. 113 North/South Study on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- X 1830-1880- Industrialization and Early Urbanization
- 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |                       |   |   |
|-----------------------|---|---|
| Agriculture           |   | Transportation and Communication              |
| Forestry              |   | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      |   | Government                                    |
| Fishing/Oystering     |   | Religion                                      |
| Manufacturing         |   | Education                                     |
| Retailing/Wholesaling |   | Community Organizations                       |
| Finance               |   | Occupational Organizations                    |
| Professional Services |   | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-03208.001

1. ADDRESS/LOCATION: Bedford
2. FUNCTION(S): historic domestic current domestic
3. YEAR BUILT: late 19th century CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Victorian
5. INTEGRITY: original site moved  
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. dwelling resided in aluminum, replacement windows, fenestration changes, entrance to dwelling has changed to sides, shed-roof addition attached to ell

b.

6. CURRENT CONDITION: excellent good X fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: T-Plan Stories: 2.5  
Additions:
- b Structural system (if known): wood-frame
- c. Foundation: materials: other: not visible  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Cross Gable  
materials: Wood  
cornice:  
dormers:  
chimney: location(s): exterior, gable, brick

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: southwest
- 1) Bays: 3
- 2) Windows: 3, 3  
Fenestration: irregular  
Type: double hung, 1/1  
Trim: vinyl  
Shutters:

**Facade (cont'd)**

- 3) **Door(s):**  
  - Location:**
  - Type:**
  - Trim:**
- 4) **Porch(es):**

**b. Side: Direction: southeast**

- 1) **Bays: 5**
- 2) **Windows: 4, 4, 1**  
  - Fenestration:** irregular
  - Type:** double hung, 1/1,2/2
  - Trim:** wood, vinyl
  - Shutters:**
- 3) **Door(s): 1**  
  - Location:** center
  - Type:** wood & glass
  - Trim:** plain
- 4) **Porch(es):** 1-story, shed-roof, supported by turned wood posts on concrete decking

**c. Side: Direction: northwest**

- 1) **Bays: 4**
- 2) **Windows: 3, 4, 1**  
  - Fenestration:** regular
  - Type:** double hung, 1/1
  - Trim:** vinyl
  - Shutters:**
- 3) **Door(s): 1**  
  - Location:** center
  - Type:** wood & glass
  - Trim:** plain
- 4) **Porch(es):** 1-story, hipped-roof, supported by wood posts on concrete block piers on concrete decking


**d. Rear: Direction: northeast**

- 1) **Bays: 2**
- 2) **Windows: 2, 4, 2**  
  - Fenestration:** regular
  - Type:** double hung, fixed, 1/1
  - Trim:** wood, vinyl
  - Shutters:**
- 3) **Door(s): 2**  
  - Location:** corner
  - Type:** wood
  - Trim:** plain
- 4) **Porch(es):**

**9. INTERIOR:**

**10. LANDSCAPING:** property surrounded by agricultural fields, dwelling stands at angle along Bedford Rd, gravel driveway to front

**11. OTHER COMMENTS:**



**CULTURAL RESOURCE SURVEY  
MAP FORM**


CRS # S-03208

1. ADDRESS/LOCATION: Bedford
2. NOT FOR PUBLICATION           reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


**INDICATE NORTH ON SKETCH**



4. SITE PLAN:


CRS # S-03208

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S-03216

1. HISTORIC NAME/FUNCTION: Dwelling/Agricultural Property

2. ADDRESS/LOCATION: 20006 Wilson Road

3. CURRENT CONDITION:    excellent                      good                       fair                      poor                      demolished

4. INTEGRITY: original site  
\_\_\_\_\_

5. SETTING INTEGRITY:  
\_\_\_\_\_

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc.                      Date: 09/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03216

Resurveyed by JMA for the U.S. 113 North/South Study on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- X 1830-1880- Industrialization and Early Urbanization
- 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |   |                       |   |   |
|---|-----------------------|---|---|
| X | Agriculture           |   | Transportation and Communication              |
|   | Forestry              |   | Settlement Patterns and Demographic Changes   |
|   | Trapping/Hunting      | X | Architecture, Engineering and Decorative Arts |
|   | Mining/Quarrying      |   | Government                                    |
|   | Fishing/Oystering     |   | Religion                                      |
|   | Manufacturing         |   | Education                                     |
|   | Retailing/Wholesaling |   | Community Organizations                       |
|   | Finance               |   | Occupational Organizations                    |
|   | Professional Services |   | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-03216.001

1. ADDRESS/LOCATION: 20006 Wilson Road
2. FUNCTION(S): historic current
3. YEAR BUILT: 1870 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, side hall
5. INTEGRITY: original site  moved
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. shed-roof porch attached to front, replacement of some windows, resided in asbestos, enclosed shed-roof addition across rear
- b.

6. CURRENT CONDITION: excellent good  fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5  
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: brick, concrete block  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): Asbestos
- e. Roof: shape: Side Gable  
materials: Composition  
cornice:  
dormers:  
chimney: location(s): interior, gable; other: 2 chimneys, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: north
- 1) Bays: 6
- 2) Windows: 4, 3  
Fenestration: irregular  
Type: double hung, 1/1, 3/3  
Trim: wood, vinyl  
Shutters:

**Facade (cont'd)**

- 3) **Door(s):** 2  
**Location:** side  
**Type:** wood & glass  
**Trim:** plain
- 4) **Porch(es):** entry

**b. Side: Direction: west**

- 1) **Bays:**
- 2) **Windows:** , 2  
**Fenestration:** irregular  
**Type:** double hung, 2/2  
**Trim:** wood  
**Shutters:**
- 3) **Door(s):**  
**Location:**  
**Type:**  
**Trim:**
- 4) **Porch(es):**

**c. Side: Direction: east**

- 1) **Bays:**
- 2) **Windows:** 1, 1  
**Fenestration:** regular  
**Type:** double hung, fixed, 1/1  
**Trim:** wood, vinyl  
**Shutters:**
- 3) **Door(s):** 1  
**Location:** corner  
**Type:** wood & glass  
**Trim:** plain
- 4) **Porch(es):**


**d. Rear: Direction: south**

- 1) **Bays:**
- 2) **Windows:** 6, 3  
**Fenestration:** irregular  
**Type:** double hung, awning, 1/1, 3/3, 3/1  
**Trim:** wood, vinyl  
**Shutters:**
- 3) **Door(s):**  
**Location:**  
**Type:**  
**Trim:**
- 4) **Porch(es):**

**9. INTERIOR:**

- 10. **LANDSCAPING:** dwelling faces Wilson Rd., agricultural fields across the street and to rear of dwelling, modern dwellings flank both side properties, trees and shrubs throughout parcel

**11. OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03216.002

1. ADDRESS/LOCATION: 20006 Wilson Road

2. FUNCTION(S): historic equipment shed current \_\_\_\_\_

3. YEAR BUILT: 1900 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good \_\_\_\_\_ fair \_\_\_\_\_ poor X

7. DESCRIPTION:  
a. Structural system wood-frame  
b. Number of stories 1  
c. Wall coverings Metal  
d. Foundation other: none  
e. Roof structural system Side Gable  
coverings Other: metal  
openings \_\_\_\_\_

8. DESCRIPTION OF ELEVATIONS:  
a. Facade: direction: south  
1) bays:  
2) windows:  
3) door(s):  
4) other:

- b. Side: direction: east
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: west
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- d. Rear: direction: north
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03216.003

1. ADDRESS/LOCATION: 20006 Wilson Road

2. FUNCTION(S): historic pump house current \_\_\_\_\_

3. YEAR BUILT: 1910 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good \_\_\_\_\_ fair **X** \_\_\_\_\_ poor \_\_\_\_\_

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Other: tar paper
- d. Foundation concrete block: piers
- e. Roof structural system Gable Front  
coverings Other: tar paper  
openings \_\_\_\_\_

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: east
  - 1) bays: 1
  - 2) windows: \_\_\_\_\_
  - 3) door(s): Count: 1; Location: center ; Type: other  
Details: door covered in tar paper
  - 4) other: \_\_\_\_\_

- b. Side: direction: south
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: north
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- d. Rear: direction: west
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03216.004

1. ADDRESS/LOCATION: 20006 Wilson Road

2. FUNCTION(S): historic shed current \_\_\_\_\_

3. YEAR BUILT: 1910 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good \_\_\_\_\_ fair X poor \_\_\_\_\_

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Other: tar paper

d. Foundation other: none

e. Roof  
structural system Side Gable  
coverings Other: tar paper  
openings \_\_\_\_\_

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: west

1) bays: 1

2) windows: \_\_\_\_\_

3) door(s): Count: 1; Location: corner ; Type: other  
Details: door covered in tar paper

4) other: \_\_\_\_\_

- b. Side: direction: north
  - 1) bays: 1
  - 2) windows: Count: 1; regular ; fixed
  - 3) door(s):
  - 4) other:

- c. Side: direction: south
  - 1) bays: 1
  - 2) windows: Count: 1; regular ; fixed
  - 3) door(s):
  - 4) other:

- d. Rear: direction: east
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # S-03216

1. ADDRESS/LOCATION: 20006 Wilson Road
2. NOT FOR PUBLICATION reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-03216

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S-03217

1. HISTORIC NAME/FUNCTION: Carey-Wilson Property

2. ADDRESS/LOCATION: 20064 Wilson Road

3. CURRENT CONDITION:    **excellent**                      **good** ✕                      **fair**                      **poor**                      **demolished**

4. INTEGRITY: original site

5. SETTING INTEGRITY: \_\_\_\_\_

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
X	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Scott Pickens

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc.                      Date: 05/2006

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03217


Property re-surveyed for the U.S. 113 North/South Project by JMA on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
- 1600-1750- Contact Period (Native American)  
 1630-1730- Exploration and Frontier Settlement  
 1730-1770- Intensified and Durable Occupation  
 1770-1830- Early Industrialization
- X 1830-1880- Industrialization and Early Urbanization
  - X 1880-1940- Urbanization and Early Suburbanization
  - 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- X Agriculture
  - Forestry
  - Trapping/Hunting
  - Mining/Quarrying
  - Fishing/Oystering
  - Manufacturing
  - Retailing/Wholesaling
  - Finance
  - Professional Services
  - Transportation and Communication
  - Settlement Patterns and Demographic Changes
  - X Architecture, Engineering and Decorative Arts
  - Government
  - Religion
  - Education
  - Community Organizations
  - Occupational Organizations
  - Major Families, Individuals and Events



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-03217.001

1. ADDRESS/LOCATION: 20064 Wilson Road
2. FUNCTION(S): historic domestic current domestic
3. YEAR BUILT: 1900 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: I-House
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. siding added; replacement windows; additions to either side of original T-form

b.

6. CURRENT CONDITION: excellent good x fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 2.  
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block and panel-faced concrete  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): vinyl siding
- e. Roof: shape: cross gable  
materials: asphalt  
cornice: exposed rafter ends  
dormers:  
chimney: location(s): 2 interior, gable, at opposite ends of o
8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 5
- 2) Windows: 4, first story; 5 second story; 1 third  
Fenestration: regular  
Type: 1/1, 2/1 double hung  
Trim: wood, aluminum, vinyl  
Shutters: vinyl, non-functional

**Facade (cont'd)**

- 3) **Door(s):** 1  
**Location:** center  
**Type:** wood & glass  
**Trim:** plain
- 4) **Porch(es):** portico

**b. Side: Direction: south**

- 1) **Bays:** 4
- 2) **Windows:** 3, first story; 4 second story; 2 third  
**Fenestration:** regular  
**Type:** 1/1, 2/2 double hung; awning  
**Trim:** wood, aluminum  
**Shutters:** vinyl, non-functional
- 3) **Door(s):** 1  
**Location:** center of shed addition  
**Type:**  
**Trim:**
- 4) **Porch(es):** stoop; concrete-block steps

**c. Side: Direction: north**

- 1) **Bays:** 5
- 2) **Windows:** 4, first story; 4 second story; 2 third  
**Fenestration:** regular  
**Type:** 1/1 double hung; awning  
**Trim:** wood, aluminum  
**Shutters:** vinyl, non-functional
- 3) **Door(s):** 1  
**Location:** center of shed addition  
**Type:** wood & glass  
**Trim:**
- 4) **Porch(es):** stoop; concrete-block steps

**d. Rear: Direction: east**

- 1) **Bays:** 3
- 2) **Windows:** 1, first story; 3, second story; 1, thir  
**Fenestration:**  
**Type:** 1/1, 6/6 double hung  
**Trim:** wood, aluminum  
**Shutters:** vinyl, non-functional
- 3) **Door(s):** none  
**Location:**  
**Type:**  
**Trim:**
- 4) **Porch(es):**

9. **INTERIOR:**10. **LANDSCAPING:**11. **OTHER COMMENTS:**

USE BLACK INK ONLY



- b. **Side: direction:** south
  - 1) **bays:** 1
  - 2) **windows:** 1, second story; regular; covered
  - 3) **door(s):**
  - 4) **other:**

- c. **Side: direction:** north
  - 1) **bays:** [not visible]
  - 2) **windows:**
  - 3) **door(s):**
  - 4) **other:**

- d. **Rear: direction:** east
  - 1) **bays:** 2
  - 2) **windows:** 1, first story; regular; covered
  - 3) **door(s):** 1; center; covered
  - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

square; central hall

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



CULTURAL RESOURCE SURVEY  
STRUCTURE (BUILDING-LIKE) FORM

CRS # S-03217.003

1. ADDRESS/LOCATION: 20064 Wilson Rd.

2. FUNCTION: Corncrib IN USE?

3. YEAR BUILT: 1880 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/PLAN: Typical corn crib

5. INTEGRITY: original site  moved   
if moved, from where original location's CRS # year

list major alterations and additions with dates (if known) year  
a.  
b.

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION (describe the structure as completely as possible):

a) Overall shape Rectangular  
height 12 ft.  
length 14 ft.  
width 6 ft.

b) Structural system: Frame

c) Foundation: Log and plank


d) Exterior covering: wood siding (vertical)

7. DESCRIPTION (cont'd):

CRS # S-03217.003

e) Openings Doorway at opposite ends

f) Other features Exposed rafters



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03217.004

1. ADDRESS/LOCATION: 20064 Wilson Road

2. FUNCTION(S): **historic** chicken house **current** \_\_\_\_\_

3. YEAR BUILT: 1920s **CIRCA?:** Y **ARCHITECT/BUILDER:** \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: **original site** \_\_\_\_\_ **moved** \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_

a. \_\_\_\_\_

b. \_\_\_\_\_

6. CURRENT CONDITION: **excellent** \_\_\_\_\_ **good** \_\_\_\_\_ **fair** \_\_\_\_\_ **poor** **x**

7. DESCRIPTION:

a. **Structural system** wood-frame

b. **Number of stories** 1

c. **Wall coverings** wood siding, horizontal

d. **Foundation** timber

e. **Roof**

**structural system** shed

**coverings** corrugated metal

**openings**

8. DESCRIPTION OF ELEVATIONS:

a. **Facade: direction:** south

1) **bays:** 3

2) **windows:** 2; regular; ventilation bays

3) **door(s):** 1; center; open bay

4) **other:**

- b. **Side: direction:** west
  - 1) **bays:** none
  - 2) **windows:**
  
  - 3) **door(s):**
  
  - 4) **other:**

- c. **Side: direction:** east
  - 1) **bays:** [not visible]
  - 2) **windows:**
  
  - 3) **door(s):**
  
  - 4) **other:**

- d. **Rear: direction:** north
  - 1) **bays:** none
  - 2) **windows:**
  
  - 3) **door(s):**
  
  - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # S-03217

1. ADDRESS/LOCATION: 20064 Wilson Road
2. NOT FOR PUBLICATION reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-03217

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S-03224

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: North Bedford Road

3. CURRENT CONDITION:    excellent                      good                       fair                      poor                      demolished

4. INTEGRITY: moved

Resided in vinyl; replacement doors and windows; large 2 story additions to side and rear.

5. SETTING INTEGRITY:

Across the street lies another moved dwelling and cemetery; mid-to-late 20<sup>th</sup> c. architecture flanks remaining lots.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:

Organization: John Milner Associates Inc.                      Date: September 2006

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03224

Resurveyed by JMA for the US113 North/South study on behalf of Delaware Department of Transportation.

Moved to this location from N. Bedford and Edwards Streets; date unknown. Dwelling was originally on the parcel recorded as S-00744.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- X 1830-1880- Industrialization and Early Urbanization
- 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |                       |   |   |
|-----------------------|---|---|
| Agriculture           |   | Transportation and Communication              |
| Forestry              | X | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      |   | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      |   | Government                                    |
| Fishing/Oystering     |   | Religion                                      |
| Manufacturing         |   | Education                                     |
| Retailing/Wholesaling |   | Community Organizations                       |
| Finance               |   | Occupational Organizations                    |
| Professional Services |   | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM


CRS # S-03224.001

1. ADDRESS/LOCATION: North Bedford Road
2. FUNCTION(S): historic Domestic Current Trade/Commercial
3. YEAR BUILT: 1910 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN:
5. INTEGRITY: original site moved X  

<u>if moved, from where</u>	<u>other location's CRS #</u>	<u>year</u>
Moved from North Bedford and Edwards Streets; unknown year		
Dwelling was originally on the parcel recorded as S-00744		
<u>list major alterations and additions with years (if known)</u>		
a.		<u>year</u>
b.		
6. CURRENT CONDITION: excellent good X fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
  - a. Overall shape: Square Stories: 2.5  
Additions:
  - b. Structural system (if known): wood-frame
  - c. Foundation: materials: obscured by poured concrete  
basement: full  partial  not visible  no basement
  - d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
  - e. Roof: shape: Flat, Pyramidal; historically decorated with balustrade on rooftop; now removed  
materials: Asphalt  
cornice:  
dormers: gabled dormers to front  
chimney: location(s):
8. DESCRIPTION OF ELEVATIONS:
  - a. Facade: Direction: northeast
    - 1) Bays: 3
    - 2) Windows: 3, first story; 3, second story  
Fenestration: regular  
Type: double hung, 1/1  
Trim: wood  
Shutters: vinyl,non-functional

**Facade (cont'd)****3) Door(s): 1****Location:** center**Type:** fiberglass**Trim:** sidelights and transom**4) Porch(es):** portico, supported by vinylw columns on brick decking; decorative balustrade above; modern handicap ramp across front.**b. Side: Direction: southeast****1) Bays:****2) Windows:** 1, first story; 2, second story**Fenestration:** regular**Type:** double hung, 1/1**Trim:** wood**Shutters:****3) Door(s):****Location:****Type:****Trim:****4) Porch(es):****c. Side: Direction: northwest****1) Bays: 5****2) Windows:** 4, first story; 4, second story**Fenestration:** regular**Type:** double hung, 1/1; casement**Trim:** wood**Shutters:****3) Door(s): 1****Location:** center**Type:** wood & glass**Trim:** single pane, three panel**4) Porch(es):** 1 sotry hipped-roof porch; open; supported by vinyl columns on concrete decking; spans from north corner to middle of façade.**d. Rear: Direction: southwest****1) Bays:** obscured by addition**2) Windows:****Fenestration:****Type:****Trim:****Shutters:****3) Door(s):****Location:****Type:****Trim:****4) Porch(es):****9. INTERIOR:****10. LANDSCAPING:** faces North Bedford St.; slightly setback with circular driveway across front lawn; parking lot to one side; shurbs planted across front façade.**11. OTHER COMMENTS:**

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # S-03224

1. ADDRESS/LOCATION: North Bedford Road
2. NOT FOR PUBLICATION           reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-03224

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S-03229

1. HISTORIC NAME/FUNCTION: Animal Facility

2. ADDRESS/LOCATION: Dupont Highway

3. CURRENT CONDITION:    excellent                  good                  fair                  poor                  X Demolished

4. INTEGRITY:  
\_\_\_\_\_

5. SETTING INTEGRITY:  
\_\_\_\_\_


6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc.                  Date: 2/2004

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03229

Resurveyed by JMA for the US113 North/South study on behalf of Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):


- a) Time period(s)
  - Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II

- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- 1830-1880- Industrialization and Early Urbanization
- 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
  - Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

c) Historic period theme(s)

- |                       |   |
|-----------------------|---|
| Agriculture           | Transportation and Communication              |
| Forestry              | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      | Government                                    |
| Fishing/Oystering     | Religion                                      |
| Manufacturing         | Education                                     |
| Retailing/Wholesaling | Community Organizations                       |
| Finance               | Occupational Organizations                    |
| Professional Services | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # S-03232

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: 203 corner of Ennis and Truitt Street

3. CURRENT CONDITION:    excellent                      good                       fair                      poor                      demolished

4. INTEGRITY:  
\_\_\_\_\_

5. SETTING INTEGRITY:  
\_\_\_\_\_


6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc.                      Date: 09/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03232

Resurveyed by JMA for the U.S. 113 North/South Study on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- 1830-1880- Industrialization and Early Urbanization
- X 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |                       |   |   |
|-----------------------|---|---|
| Agriculture           |   | Transportation and Communication              |
| Forestry              |   | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      |   | Government                                    |
| Fishing/Oystering     |   | Religion                                      |
| Manufacturing         |   | Education                                     |
| Retailing/Wholesaling |   | Community Organizations                       |
| Finance               |   | Occupational Organizations                    |
| Professional Services |   | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-03232.001

1. ADDRESS/LOCATION: 203 corner of Ennis and Truitt Street
2. FUNCTION(S): historic current
3. YEAR BUILT: 1915 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Victorian, Vernacular, other: corner
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in vinyl, replacement windows and doors, shed-roof addition to rear, 1 room

b.

6. CURRENT CONDITION: excellent good X fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: T-Plan Stories: 2.5  
Additions:
- b Structural system (if known): wood-frame
- c. Foundation: materials: other: not visible  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Cross Gable  
materials: Asphalt  
cornice: other: decorative bricks  
dormers:  
chimney: location(s): other: interior/side, brick

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: east
- 1) Bays:
- 2) Windows: 1, 2, 1  
Fenestration: irregular  
Type: double hung, 1/1  
Trim: vinyl  
Shutters: vinyl,non-functional

**Facade (cont'd)**

- 3) **Door(s):** 1
  - Location:** center
  - Type:** wood & glass
  - Trim:** plain
- 4) **Porch(es):**

**b. Side: Direction: north**

- 1) **Bays:**
- 2) **Windows:** 1, 2
  - Fenestration:** irregular
  - Type:** double hung, 1/1
  - Trim:** vinyl
  - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
  - Location:**
  - Type:**
  - Trim:**
- 4) **Porch(es):**obscured by porch enclosure

**c. Side: Direction: south**

- 1) **Bays:**
- 2) **Windows:** 1, 3
  - Fenestration:** regular
  - Type:** double hung, 1/1
  - Trim:** vinyl
  - Shutters:** (vinyl,non-functional)
- 3) **Door(s):** 1
  - Location:** center
  - Type:** other
  - Trim:**
- 4) **Porch(es):**1-story shed-roof addition, 1 room, sided in vinyl, modern windows and doors


**d. Rear: Direction: west**

- 1) **Bays:** 2
- 2) **Windows:** 1, 2, 1
  - Fenestration:** irregular
  - Type:** double hung, 1/1
  - Trim:** vinyl
  - Shutters:** vinyl,non-functional
- 3) **Door(s):** 1
  - Location:** corner
  - Type:** other
  - Trim:** plain
- 4) **Porch(es):**other, modern wood deck

**9. INTERIOR:**

10. **LANDSCAPING:** faces Truitt St., shrubs planted on all sides, fenced in rear and side lawn

**11. OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-03232.002

1. ADDRESS/LOCATION: 203 corner of Ennis and Truitt Street

2. FUNCTION(S): historic garage current \_\_\_\_\_

3. YEAR BUILT: 1945 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good X fair \_\_\_\_\_ poor \_\_\_\_\_

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Asbestos

d. Foundation poured concrete

e. Roof  
structural system Side Gable  
coverings Asphalt  
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: east  
1) bays: 2  
2) windows:  
3) door(s): Count: 2; Location: other: side by side ; Type: wood & glass  
Details: wood and glass garage doors  
4) other:

- b. Side: direction: north
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: south
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- d. Rear: direction: west
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-03232

1. ADDRESS/LOCATION: 203 corner of Ennis and Truitt Street

2. NOT FOR PUBLICATION reason: \_\_\_\_\_

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH

