

DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-03233

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: Dupont Highway

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: moved

5. SETTING INTEGRITY:

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:

Organization: John Milner Associates Inc. Date: 09/2006

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03233

Resurveyed by JMA for the U.S. 113 North/South Study on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- X 1830-1880- Industrialization and Early Urbanization
- 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|-----------------------------------------------|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-03233.001

1. ADDRESS/LOCATION: Dupont Highway
2. FUNCTION(S): historic current
3. YEAR BUILT: 1840 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: I-House, central hall
5. INTEGRITY: original site moved X
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in aluminum, porch alterations, door and window replacements

b.

6. CURRENT CONDITION: excellent good X fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: L-Plan Stories: 2.5
Additions:

b. Structural system (if known): wood-frame

c. Foundation: materials: concrete block
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding

e. Roof: shape: Side Gable
materials: Composition
cornice: other: decorative brackets across front and rear
dormers:
chimney: location(s): interior, gable; other: 3 chimneys, brick

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: east
1) Bays: 5
2) Windows: 4, 5
Fenestration: regular
Type: double hung, 1/1
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 Location: center
 Type: wood & glass
 Trim: transom
- 4) **Porch(es):** entry

b. Side: Direction: south

- 1) **Bays:** 1
- 2) **Windows:** 1, 2, 2
 Fenestration: irregular
 Type: double hung, 1/1,6/6
 Trim: wood
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**shed-roof porch enclosure, enclosed in aluminum and plywood, double hung 2/2 windows

c. Side: Direction: north

- 1) **Bays:** 3
- 2) **Windows:** 3, 4, 2
 Fenestration: regular
 Type: double hung, 1/1
 Trim: wood
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**


d. Rear: Direction: west

- 1) **Bays:** 4
- 2) **Windows:** 4, 2, 1
 Fenestration: irregular
 Type: double hung, 2/2, 1/1
 Trim: wood
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

9. INTERIOR:

- 10. **LANDSCAPING:** faces Rt. 113, large shrub planted to one side of front facade, gravel driveway to south side of dwelling, tall trees trim property line

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03233.002

1. ADDRESS/LOCATION: Dupont Highway

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____

a. _____

b. _____

6. CURRENT CONDITION: excellent _____ good X fair _____ poor _____

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories

c. Wall coverings Aluminum Siding

d. Foundation

e. Roof
structural system Gable Front
coverings Composition
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: east

1) bays:

2) windows:

3) door(s):

4) other:

- b. **Side: direction:** north
 - 1) **bays:** 1
 - 2) **windows:** Count: 1; regular ; double hung, 1/1
 - 3) **door(s):**
 - 4) **other:**

- c. **Side: direction:** south
 - 1) **bays:** 2
 - 2) **windows:** Count: 1; regular ; double hung, 1/1
 - 3) **door(s):** Count: 1; Location: side ; Type: wood
 - 4) **other:**

- d. **Rear: direction:** west
 - 1) **bays:** 1
 - 2) **windows:** Count: 1; regular ; double hung, 1/1
 - 3) **door(s):**
 - 4) **other:**

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-03233

1. ADDRESS/LOCATION: Dupont Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-03233

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-03234

1. HISTORIC NAME/FUNCTION: Dwelling/Agricultural Property

2. ADDRESS/LOCATION: 18996 Dupont Highway

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: moved

5. SETTING INTEGRITY:

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:

Organization: John Milner Associates Inc. Date: 09/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03234

Resurveyed by JMA for the U.S. 113 North/South Study on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- 1830-1880- Industrialization and Early Urbanization
- X 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | | | |
|---|-----------------------|---|-----------------------------------------------|
| X | Agriculture | | Transportation and Communication |
| | Forestry | | Settlement Patterns and Demographic Changes |
| | Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| | Mining/Quarrying | | Government |
| | Fishing/Oystering | | Religion |
| | Manufacturing | | Education |
| | Retailing/Wholesaling | | Community Organizations |
| | Finance | | Occupational Organizations |
| | Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-03234.001

1. ADDRESS/LOCATION: 18996 Dupont Highway

2. FUNCTION(S): historic current

3. YEAR BUILT: 1899 CIRCA?: Y ARCHITECT/BUILDER:

4. STYLE OR FLOOR PLAN: Vernacular

5. INTEGRITY: original site moved X

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in asbestos, front porch enclosure, shed-roof addition to northern side, 1 room

b.

6. CURRENT CONDITION: excellent good X fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: T-Plan Stories: 2.5
Additions:

b Structural system (if known): wood-frame

c. Foundation: materials: concrete block
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): Asbestos

e. Roof: shape: Side Gable
materials: Asphalt
cornice:
dormers:
chimney: location(s): exterior, gable, concrete block

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: northeast

- 1) Bays:
- 2) Windows: 2
Fenestration: regular
Type: double hung, 2/2
Trim: wood
Shutters: wood,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 Location: center
 Type: other
 Trim: plain
- 4) **Porch(es):** full-width

b. Side: Direction: northwest

- 1) **Bays:**
- 2) **Windows:** 2, 3, 1
 Fenestration: regular
 Type: double hung, 2/2
 Trim: wood
 Shutters: (wood,non-functional)
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

c. Side: Direction: southeast

- 1) **Bays:**
- 2) **Windows:** 0, 2
 Fenestration: regular
 Type: double hung, 2/2
 Trim: wood
 Shutters: (wood,non-functional)
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**


d. Rear: Direction: southwest

- 1) **Bays:** 1
- 2) **Windows:** 1, 1
 Fenestration: regular
 Type: double hung, 1/1, 2/2
 Trim: wood
 Shutters: wood,non-functional
- 3) **Door(s):** 1
 Location: other: within shed-roof addition
 Type: other
 Trim: plain
- 4) **Porch(es):** portico, gabled

9. INTERIOR:

- 10. **LANDSCAPING:** dwelling faces Rt. 113, gravel driveway to north side, several outbuildings to rear of house, shrubs and trees planted on all sides of dwelling

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03234.002

1. ADDRESS/LOCATION: 18996 Dupont Highway

2. FUNCTION(S): historic barn/shed current _____

3. YEAR BUILT: 1910 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____
a. _____
b. _____

6. CURRENT CONDITION: excellent _____ good X fair _____ poor _____

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1.5

c. Wall coverings Asphalt

d. Foundation other: none

e. Roof structural system Gable Front
coverings Other: metal
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southeast

1) bays: 3

2) windows:

3) door(s): Count: 3; Location: other: irregular ; Type: wood, metal, other
Details: 1 open bay door

4) other:

- b. **Side: direction:** northeast
 - 1) **bays:** 2
 - 2) **windows:** Count: 2; regular ; fixed
 - 3) **door(s):**
 - 4) **other:**

- c. **Side: direction:** southwest
 - 1) **bays:**
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** northwest
 - 1) **bays:** 3
 - 2) **windows:** Count: 2; irregular ; fixed
 - 3) **door(s):** Count: 1; Location: corner
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03234.003

1. ADDRESS/LOCATION: 18996 Dupont Highway

2. FUNCTION(S): historic shed current _____

3. YEAR BUILT: 1910 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____

a. _____

b. _____

6. CURRENT CONDITION: excellent _____ good X fair _____ poor _____

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Horizontal, Wood Siding Vertical

d. Foundation concrete block: piers

e. Roof
structural system Gable Front
coverings Other: metal
openings _____

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: northeast

1) bays: 3

2) windows: _____

3) door(s): Count: 3; Location: other: side by side ; Type: wood

4) other: _____

b. Side: direction: northwest

1) bays:

2) windows:

3) door(s):

4) other:

c. Side: direction: southeast

1) bays:

2) windows:

3) door(s):

4) other:

d. Rear: direction: southwest

1) bays:

2) windows:

3) door(s):

4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-03234.004

1. ADDRESS/LOCATION: 18996 Dupont Highway

2. FUNCTION(S): historic shed current _____

3. YEAR BUILT: 1910 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____
a. _____
b. _____

6. CURRENT CONDITION: excellent _____ good X fair _____ poor _____

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Wood Siding Horizontal
- d. Foundation concrete block: piers
- e. Roof structural system Gable Front
coverings Other: metal
openings _____

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: northeast
 - 1) bays: 1
 - 2) windows: _____
 - 3) door(s): Count: 1; Location: center ; Type: wood
 - 4) other: _____

b. Side: direction: southeast

1) bays:

2) windows:

3) door(s):

4) other:

c. Side: direction: northwest

1) bays:

2) windows:

3) door(s):

4) other:

d. Rear: direction: southwest

1) bays:

2) windows:

3) door(s):

4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901


CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-03234

1. ADDRESS/LOCATION: 18996 Dupont Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.
(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-03234

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-03235

1. HISTORIC NAME/FUNCTION: Dwelling/Agricultural Property

2. ADDRESS/LOCATION: Dupont Highway

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: moved

5. SETTING INTEGRITY:


6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
X	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 07/26/2007

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03235


9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
1630-1730- Exploration and Frontier Settlement
1730-1770- Intensified and Durable Occupation
1770-1830- Early Industrialization
1830-1880- Industrialization and Early Urbanization
X 1880-1940- Urbanization and Early Suburbanization
1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|-----------------------------------------------|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-03235.001

1. ADDRESS/LOCATION: Dupont Highway
2. FUNCTION(S): historic current
3. YEAR BUILT: 1895 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, central hall
5. INTEGRITY: original site moved X
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in vinyl, replacement windows and doors, 1-story shed-roof addition on rear, 1 room, 1-story gabled addition attached to corner

b.

6. CURRENT CONDITION: excellent good X fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangle Stories: 2.5
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Side Gable
 materials: Asphalt
 cornice:
 dormers:
 chimney: location(s): other: exterior/rear, concrete block

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: southwest
- 1) Bays: 5
- 2) Windows: 4, 4
 Fenestration: regular
 Type: double hung, 1/1
 Trim: vinyl
 Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
Location: center
Type: other
Trim: plain
- 4) **Porch(es):**

b. Side: Direction: southeast

- 1) **Bays:**
- 2) **Windows:** , 2
Fenestration: regular
Type: fixed
Trim: wood
Shutters:
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**

c. Side: Direction: northwest

- 1) **Bays:**
- 2) **Windows:** 1, 0, 1
Fenestration: irregular
Type: double hung, 1/1
Trim: vinyl
Shutters: (vinyl,non-functional)
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**

d. Rear: Direction: northeast


- 1) **Bays:**
- 2) **Windows:** 1, 1
Fenestration: irregular
Type: double hung, 1/1
Trim: vinyl
Shutters:
- 3) **Door(s):** 1
Location: other: within addition
Type:
Trim: plain
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Rt. 113, driveway circles dwelling, plantings across front of house

11. OTHER COMMENTS:

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-03235

1. ADDRESS/LOCATION: Dupont Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-03235

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-03236

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: Dupont Highway

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: original site

5. SETTING INTEGRITY:

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
X	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:

Organization: John Milner Associates Inc. Date: 09/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03236

Resurveyed by JMA for the U.S. 113 North/South Study on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- 1830-1880- Industrialization and Early Urbanization
- X 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|-----------------------------------------------|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-03236.001

1. ADDRESS/LOCATION: Dupont Highway
2. FUNCTION(S): historic domestic current vacant/not in use
3. YEAR BUILT: early 20th century CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Other: Dutch Colonial Revival, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. partially sided in aluminum, doors and windows broken out or boarded over, 1-story flat-roofed wrap around enclosure across southeast and northeast sides

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: other: not visible
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Gambrel
materials:
cornice: exposed rafter ends
dormers: 3 wall dormers across front
chimney: location(s): interior, gable; exterior, gable, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: southwest
- 1) Bays: 3
- 2) Windows: 2
Fenestration: regular
Type: double hung, 99 (broken out panes)
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** other: broken out
 - Trim:** plain
- 4) **Porch(es):**

b. Side: Direction: northwest

- 1) **Bays:** 1
- 2) **Windows:** 1
 - Fenestration:** regular
 - Type:** double hung, 99 (broken out pane)
 - Trim:**
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** center
 - Type:** other: fiberglass
 - Trim:** plain
- 4) **Porch(es):**

c. Side: Direction: southeast

- 1) **Bays:**
- 2) **Windows:** 0, 1
 - Fenestration:** regular
 - Type:** double hung, 99 (broken out pane)
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: northeast


- 1) **Bays:** 3
- 2) **Windows:** 0, 3
 - Fenestration:** regular
 - Type:** double hung, 99 (broken out panes)
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: dwelling faces Rt. 113, shrouded in overgrown trees and shrubs, woods to both sides and rear

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**


CRS # S-03236

1. ADDRESS/LOCATION: Dupont Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-03236

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-03237

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: 18748 Dupont Highway

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: original site

5. SETTING INTEGRITY:


6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
X	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03237

Resurveyed by JMA for the U.S. 113 North/South Study on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- 1830-1880- Industrialization and Early Urbanization
- X 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|-----------------------------------------------|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** other
 - Trim:** plain
- 4) **Porch(es):** full-width, inset

b. Side: Direction: southeast

- 1) **Bays:** 2
- 2) **Windows:** 2, 1
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: northwest

- 1) **Bays:** 2
- 2) **Windows:** 2, 1
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: southwest

- 1) **Bays:** 4
- 2) **Windows:** 3
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** center
 - Type:** other
 - Trim:** plain
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Rt. 113, gravel driveway to one side, shrubs planted across front and side facades, woods surround property

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-03237

1. ADDRESS/LOCATION: 18748 Dupont Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-03237

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-03238

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: Dupont Highway

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: moved

5. SETTING INTEGRITY:

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
X	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-03238

Resurveyed by JMA for the U.S. 113 North/South Study on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- 1830-1880- Industrialization and Early Urbanization
- X 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|-----------------------------------------------|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-03238.001

1. ADDRESS/LOCATION: Dupont Highway
2. FUNCTION(S): historic current
3. YEAR BUILT: 1880 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Other: Dutch Colonial Revival, central hall
5. INTEGRITY: original site moved X
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. resided in asbestos, 1-story shed-roof addition on south end, concrete block, 1 room, casement and multi-pane windows, 1-story shed-roof addition on southwest corner, concrete block, 1 room
- b.

6. CURRENT CONDITION: excellent good X fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Asbestos
- e. Roof: shape: Gambrel
materials: Wood
cornice:
dormers: 3 shed-roof dormers across front with pairs of double hung 1/1, 1 shed-roof dormer on rear with pair of double hung 1/1
chimney: location(s): interior, gable; other: 2 chimneys, brick

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: east
- 1) Bays: 4
- 2) Windows: 3
Fenestration: regular
Type: double hung, 6/1
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 Location: center
 Type: wood & glass
 Trim: plain
- 4) **Porch(es):** full-width

b. Side: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 2, 2
 Fenestration: regular
 Type: double hung, 6/1
 Trim: wood
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:**
- 2) **Windows:** 0, 2
 Fenestration: regular
 Type: double hung, 1/1
 Trim: wood
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

d. Rear: Direction: west


- 1) **Bays:** 2
- 2) **Windows:** 2
 Fenestration: regular
 Type: double hung, 6/1
 Trim: wood
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

9. INTERIOR:

- 10. **LANDSCAPING:** setback from Rt. 113, faces Dupont Hwy, long dirt driveway lies to north side of dwelling, surrounded by fallow fields

11. OTHER COMMENTS:

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-03238

1. ADDRESS/LOCATION: Dupont Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-04504

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: 25200 Governor Stockley Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY:

5. SETTING INTEGRITY:


6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
x	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
x	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-04504

Resurveyed by JMA for the U.S. 113 North/South Study on behalf of the Delaware Department of Transportation.

Moved in the 1950s according to the owner.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):


- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|------------------------------------------------|-----------------------------------------------------------------------------------|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-04504.001

1. ADDRESS/LOCATION: 25200 Governor Stockley Road
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1900 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Victorian, Other: Late Gothic Revival
5. INTEGRITY: original site moved X
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. siding, door and window, replacement and other surface details
- b.

6. CURRENT CONDITION: excellent good X fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: T-Plan Stories: 2
Additions:
- b. Structural system (if known):
- c. Foundation: materials: poured concrete
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Cross Gable
materials: Asphalt, Other
cornice: boxed
dormers: 2nd sty windows rise to just above the bottom edge of the roof to become gabled wall dormers
chimney: location(s): exterior, gable, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: south
- 1) Bays: 3
- 2) Windows: 2
Fenestration: regular
Type: double hung, 1/1
Trim: aluminum
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood, wood & glass
 - Trim:** plain
- 4) **Porch(es):** entry

b. Side: Direction: east

- 1) **Bays:** 3
- 2) **Windows:** 1, 3
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):** 2
 - Location:** center, side
 - Type:** wood
 - Trim:** plain
- 4) **Porch(es):** stoop, pre-cast concrete, 3 risers and a landing at the door

c. Side: Direction: west

- 1) **Bays:** 5
- 2) **Windows:** 4, 4
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** side
 - Type:** wood, wood & glass
 - Trim:** plain
- 4) **Porch(es):** vestibule (enclosed entrance), formerly open, enclosed side (rear) porch accessed by poured concrete steps, 3 risers and a landing at the door


d. Rear: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 2, 1
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. **LANDSCAPING:** shaded by shade trees (mostly maples) with non-historic garage in lawn next to farm fields

11. OTHER COMMENTS:



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-04504

1. ADDRESS/LOCATION: 25200 Governor Stockley Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH




4. SITE PLAN:

CRS # S-04504


INDICATE NORTH ON PLAN

S-04504



USE BLACK INK ONLY

CRS-9



CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-04508

1. HISTORIC NAME/FUNCTION: J.W. Pepper House

2. ADDRESS/LOCATION: SW corner Bethesda and Zoar Roads

3. CURRENT CONDITION: excellent good fair poor demolished X

4. INTEGRITY: Dwelling demolished as of 10/2008

5. SETTING INTEGRITY:


6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Grace H. Ziesing

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 10/20/2008

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-04508

This property was demolished after it had been recorded, evaluated, and determined eligible for the National Register of Historic Places under Criterion C, as reviewed and concurred upon by the Delaware Department of Transportation and DelSHPO. The abandoned dwelling was torn down in October 2008, and the property is therefore no longer significant under National Register Criterion C as an uncommon local example of a nineteenth-century folk housing type. The original evaluation is included in Appendix E in the final report, *Evaluation of National Register Eligibility for Architectural Properties in the Georgetown Study Area, U.S. 113 North/South Study*, prepared for the Delaware Department of Transportation and Federal Highway Administration by John Milner Associates, Inc., Philadelphia, PA, 2009.


9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
1630-1730- Exploration and Frontier Settlement
1730-1770- Intensified and Durable Occupation
1770-1830- Early Industrialization
X 1830-1880- Industrialization and Early Urbanization
1880-1940- Urbanization and Early Suburbanization
1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|-----------------------|-----------------------------------------------|
| Agriculture | Transportation and Communication |
| Forestry | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | Government |
| Fishing/Oystering | Religion |
| Manufacturing | Education |
| Retailing/Wholesaling | Community Organizations |
| Finance | Occupational Organizations |
| Professional Services | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-04508

1. HISTORIC NAME/FUNCTION: J.W. Pepper House

2. ADDRESS/LOCATION: SW corner Bethesda and Zoar Roads

3. CURRENT CONDITION: **excellent** **good** **fair** **poor** **demolished**

4. INTEGRITY: original siding visible in places

5. SETTING INTEGRITY:

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Scott Pickens

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 5/2006

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-04508


Resurveyed by JMA for the U.S. 113 North/South Study on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 X 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|-----------------------------------------------|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-04508.001

1. ADDRESS/LOCATION: SW corner Bethseda and Zoar Roads
2. FUNCTION(S): historic dwelling current vacant/not in use
3. YEAR BUILT: 1840s CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: I-House
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

- a.
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangle Stories: 2
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): asphalt
- e. Roof: shape: side gable
materials: corrugated metal
cornice: boxed
dormers:
chimney: location(s): left of center;

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: east
- 1) Bays: 1
- 2) Windows: 1, first story; 2, second story
Fenestration: regular
Type: 2/2 double hung
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
Location: right of center
Type: wood
Trim:
- 4) **Porch(es):**

b. Side: Direction: north

- 1) **Bays:** 1
- 2) **Windows:** 1, second story
Fenestration: regular
Type: 2/2 double hung
Trim: wood, aluminium
Shutters: aluminium
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**

c. Side: Direction: south


- 1) **Bays:**
- 2) **Windows:**
Fenestration:
Type: 1/1 double hung replacements
Trim: vinyl
Shutters:
- 3) **Door(s):** 1
Location: center of rear addition
Type: empty bay
Trim: plain
- 4) **Porch(es):**

d. Rear: Direction: west

- 1) **Bays:** 3
- 2) **Windows:** 3, first story; 2, second story
Fenestration:
Type: 6/1, 6/6, 1/1 double hung
Trim: wood, aluminium
Shutters:
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**

9. **INTERIOR:**10. **LANDSCAPING:**11. **OTHER COMMENTS:**

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-04508

1. ADDRESS/LOCATION: SW corner Bethesda and Zoar Roads
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-04508

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-04512

1. HISTORIC NAME/FUNCTION: Baxter-Holloway Property

2. ADDRESS/LOCATION: Bethesda Rd.

3. CURRENT CONDITION: **excellent** **good** **fair** **poor** **demolished**

4. INTEGRITY: original s

5. SETTING INTEGRITY:


6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Scott Pickens

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 05/2006

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-04512

Resurveyed by JMA for the U.S. 113 North/South Study on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- 1830-1880- Industrialization and Early Urbanization
- X 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|-----------------------------------------------|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-04512.001

- 1. ADDRESS/LOCATION: Bethesda Rd.
- 2. FUNCTION(S): historic current dwelling
- 3. YEAR BUILT: 1910 CIRCA?: Y ARCHITECT/BUILDER:
- 4. STYLE OR FLOOR PLAN: I-House
- 5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year
 a. Vinyl siding, concrete wrap around porch, metal roof
 b.

- 6. CURRENT CONDITION: excellent good fair poor
- 7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
 a. Overall shape: T-Plan Stories: 2
 Additions:
 b. Structural system (if known): wood-frame
 c. Foundation: materials: poured concrete
 basement: full partial not visible no basement
 d. Exterior walls (original if visible& any subsequent coverings): vinyl siding
 e. Roof: shape: cross gable
 materials: corrugated metal
 cornice: boxed
 dormers:
 chimney: location(s):
- 8. DESCRIPTION OF ELEVATIONS:
 a. Facade: Direction: west
 1) Bays: 4
 2) Windows: 2, first story; 4, second story
 Fenestration:
 Type: 1/1 double hung replacements
 Trim: vinyl
 Shutters: viny, non-functional

Facade (cont'd)

- 3) **Door(s):** 2
Location: symmetrical, either side of T-shape
Type: wood & glass
Trim: plain
- 4) **Porch(es):** wrap-around

b. Side: Direction: north

- 1) **Bays:** 3
- 2) **Windows:** 3
Fenestration: regular
Type: 1/1 double hung replacements
Trim: vinyl
Shutters: vinyl, functional
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**wrap-around

c. Side: Direction: south

- 1) **Bays:** 6
- 2) **Windows:** 6, first story; 3, second story
Fenestration:
Type: 1/1 double hung replacements
Trim: vinyl
Shutters: vinyl, non-functional
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**wrap-around


d. Rear: Direction: east

- 1) **Bays:** 3
- 2) **Windows:** 3, first story; 3, second story
Fenestration: regular
Type: 1/1 double hung replacements
Trim: vinyl
Shutters: vinyl, non-functional
- 3) **Door(s):** 1
Location: center
Type: wood & glass
Trim:
- 4) **Porch(es):**wood patio; wood deck, rails, and steps

9. INTERIOR:

10. LANDSCAPING:

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-04512.002

1. ADDRESS/LOCATION: Bethesda Rd.

2. FUNCTION(S): historic _____ current _____

3. YEAR BUILT: _____ CIRCA?: _____ ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____
a. _____
b. _____

6. CURRENT CONDITION: excellent _____ good X _____ fair _____ poor _____

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings wood siding, horizontal; wood siding ver

d. Foundation none

e. Roof
structural system shed
coverings metal
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southwest

1) bays:

2) windows: ; (no access)

3) door(s):

4) other:

- b. Side: direction: northwest
 - 1) bays:
 - 2) windows: ; (no access)
 - 3) door(s):
 - 4) other:

- c. Side: direction: southeast
 - 1) bays:
 - 2) windows: ; (no access)
 - 3) door(s):
 - 4) other:

- d. Rear: direction: northeast
 - 1) bays:
 - 2) windows: ; (no access)
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901


CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-04512

1. ADDRESS/LOCATION: Bethesda Rd.
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.
(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH




4. SITE PLAN:


CRS # S-04512

INDICATE NORTH ON PLAN

S-04512




modern chicken houses →



gravel

utility pole
DEC 355005
PB1-58-2


gravel



- Chimney
- Structure
- - - Drive
- Road
- - - - Roofline

USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-04513

1. HISTORIC NAME/FUNCTION: Dwelling/Agricultural Property

2. ADDRESS/LOCATION: 21397 Alms House Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: original site

5. SETTING INTEGRITY:

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-04513

Resurveyed by JMA for the U.S. 113 North/South Study on behalf of the Delaware Department of Transportation.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- 1830-1880- Industrialization and Early Urbanization
- X 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|-----------------------------------------------|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-04513.001

1. ADDRESS/LOCATION: 21397 Alms House Road
2. FUNCTION(S): historic current
3. YEAR BUILT: 1890 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. resided in vinyl, replacement windows and doors, new roofing, fenestration changes, porch enclosure to rear, 1-story shed-roof addition on west side, 1 room
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: T-Plan Stories: 2.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: other: not visible
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Side Gable
materials: Other: metal
cornice: other: enclosed
dormers: gabled wall dormer on front with gothic style window
chimney: location(s): exterior, gable, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: south
- 1) Bays: 3
- 2) Windows: 2, 3
Fenestration: regular
Type: double hung, 1/1
Trim: wood, vinyl
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):**

b. Side: Direction: east

- 1) **Bays:**
- 2) **Windows:** , 2
 - Fenestration:**
 - Type:** fixed
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** center
 - Type:** other
 - Trim:** plain
- 4) **Porch(es):**shed-roof porch enclosure, 1 room, sided in vinyl, casement window

c. Side: Direction: west

- 1) **Bays:**
- 2) **Windows:** 1, 3, 2
 - Fenestration:** irregular
 - Type:** double hung, fixed, 1/1
 - Trim:** wood, vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: north

- 1) **Bays:**
- 2) **Windows:** 1, 3
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

- 10. **LANDSCAPING:** dwelling faces Alms House Rd., gravel drive to east side of house, planting across front and side facades, tall, mature trees shade dwelling, agricultural fields surround dwelling

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-04513.002

1. ADDRESS/LOCATION: 21397 Alms House Road

2. FUNCTION(S): historic shed current _____

3. YEAR BUILT: 1945 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____
a. _____
b. _____

6. CURRENT CONDITION: excellent _____ good _____ fair **X** _____ poor _____

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Other: tar paper

d. Foundation other: none

e. Roof
structural system Gable Front
coverings Other: metal
openings _____

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: east

1) bays: 1

2) windows: _____

3) door(s): Count: 1; Location: center ; Type: wood
Details: double doors

4) other: _____

- b. Side: direction: south
 - 1) bays: 1
 - 2) windows: Count: 1; irregular ; fixed
 - 3) door(s):
 - 4) other:

- c. Side: direction: north
 - 1) bays: 1
 - 2) windows: Count: 1; regular ; fixed
 - 3) door(s):
 - 4) other:

- d. Rear: direction: west
 - 1) bays: 1
 - 2) windows: Count: 1; irregular ; fixed
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901


CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-04513

1. ADDRESS/LOCATION: 21397 Alms House Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.
(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-04513

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9