

DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10766
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: Highway 113
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Scott Pickens

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 12/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10766.001

1. ADDRESS/LOCATION: Highway 113
2. FUNCTION(S): historic current dwelling
3. YEAR BUILT: early 20th century CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN:
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): aluminum siding
- e. Roof: shape: gable front
 materials: asphalt
 cornice: exposed rafter ends
 dormers:
 chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: southwest
- 1) Bays: 2
- 2) Windows: 2, first story; 1, top story
 Fenestration: regular
 Type: 1/1 double hung
 Trim: aluminum, wood
 Shutters: aluminum, non-functional

Facade (cont'd)

- 3) **Door(s):** 1
Location: center
Type: wood & glass
Trim: plain
- 4) **Porch(es):** full-width

b. Side: Direction: southeast

- 1) **Bays:** 4
- 2) **Windows:** 4, first story
Fenestration: regular
Type: 1/1 double hung
Trim: aluminum
Shutters:
- 3) **Door(s):** 0
Location:
Type:
Trim:
- 4) **Porch(es):**


c. Side: Direction: northwest

- 1) **Bays:** 3
- 2) **Windows:** 3, first story
Fenestration: regular
Type: 1/1 double hung
Trim: aluminum
Shutters:
- 3) **Door(s):** 0
Location:
Type:
Trim:
- 4) **Porch(es):**

d. Rear: Direction: northeast

- 1) **Bays:** 3
- 2) **Windows:** 1, first story; 1, top story
Fenestration: regular
Type: 1/1 double hung
Trim: aluminum, wood
Shutters:
- 3) **Door(s):** 1
Location: southeast side
Type:
Trim: plain
- 4) **Porch(es):**patio/deck; wood decking, rails, and lattice skirt

9. **INTERIOR:**10. **LANDSCAPING:**11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10766.002

1. ADDRESS/LOCATION: Highway 113

2. FUNCTION(S): **historic** chicken house **current** _____

3. YEAR BUILT: mid 20th century **CIRCA?:** Y **ARCHITECT/BUILDER:** _____

4. STYLE/FLOOR PLAN: Vernacular; one pen

5. INTEGRITY: **original site** **moved**
if moved, from where **original location's CRS #** **year**

list major alterations and additions with years (if known) **year**
a. extended in linear dimension for storage (open bays)
b. _____

6. CURRENT CONDITION: **excellent** **good** **fair** **X** **poor**

7. DESCRIPTION:

- a. **Structural system** wood-frame
- b. **Number of stories** 1
- c. **Wall coverings** wood siding, horizontal; vinyl siding
- d. **Foundation** none

- e. **Roof**
structural system gable front
coverings asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

- a. **Facade: direction:** southwest
 - 1) **bays:** 1
 - 2) **windows:**
 - 3) **door(s):** Count: 1; Location: south end ; Type: wood & glass
Details: 4 lights and 3 panels
 - 4) **other:**

- b. **Side: direction:** southeast
 - 1) **bays:** 3
 - 2) **windows:**
 - 3) **door(s):** Count: 1; Location: south end ; Type: wood
Details: vertical wood
 - 4) **other:**

- c. **Side: direction:** northwest
 - 1) **bays:** 1
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** northeast
 - 1) **bays:** 2
 - 2) **windows:**
 - 3) **door(s):** Count: 2; Location: both sides ; Type: open bays
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle ; one pen

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901


CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10766

1. ADDRESS/LOCATION: Highway 113
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.
(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10766

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10767
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

- HISTORIC NAME/FUNCTION: dwelling
- ADDRESS/LOCATION: 25189 Dupont Highway
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE: building structure site object
landscape district
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10767.001

1. ADDRESS/LOCATION: 25189 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1920 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. shed-roofed addition to rear plus a deck off of the addition, several recent outbuildings

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: cruciform Stories: 1.5
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block: rock faced
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Other: series of gables
 materials: Asphalt
 cornice: boxed
 dormers:
 chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 4
- 2) Windows: 3
 Fenestration: regular
 Type: double hung, 6/1
 Trim: aluminum
 Shutters: other: aluminum, non-functional

Facade (cont'd)

- 3) **Door(s):** 1
Location: center
Type: wood
Trim: plain
- 4) **Porch(es):** portico

b. Side: Direction: south

- 1) **Bays:** 3
- 2) **Windows:** 3
Fenestration: irregular
Type: double hung, 6/1, 1/1
Trim: aluminum
Shutters: other: aluminum, non-functional
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**

c. Side: Direction: north

- 1) **Bays:** 5
- 2) **Windows:** 5
Fenestration:
Type: double hung, 6/1, 6/6
Trim: aluminum
Shutters: other: aluminum, non-functional
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**

d. Rear: Direction: east


- 1) **Bays:** 4
- 2) **Windows:** 3
Fenestration: irregular
Type: double hung, 6/1
Trim: aluminum
Shutters: other: aluminum, non-functional
- 3) **Door(s):** 1
Location: side
Type: metal
Trim: plain
- 4) **Porch(es):** other: deck, shed-roofed addition could have been an earlier porch but now closed in with treated wood deck

9. INTERIOR:

10. LANDSCAPING: located at an intersection with a property line, house has large mown lawn, scattered trees and shrubs

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S-10767

1. ADDRESS/LOCATION: 25189 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10768
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

- 1. HISTORIC NAME/FUNCTION: Commercial Building
- 2. ADDRESS/LOCATION: 222 Dupont Highway
- 3. TOWN/NEAREST TOWN: Georgetown vicinity?
- 4. MAIN TYPE OF RESOURCE: building structure
landscape district site object
- 5. MAIN FUNCTION OF PROPERTY: domestic commercial
- 6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005; 11/2006

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|--|
| <ul style="list-style-type: none"> Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing X Retailing/Wholesaling Finance Professional Services | <ul style="list-style-type: none"> Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10768.001

1. ADDRESS/LOCATION: 222 Dupont Highway
2. FUNCTION(S): historic commercial current domestic
3. YEAR BUILT: 1920 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Colonial Revival, Other: 18th century Chesapeake,
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. new siding, steel door, non-functioning shutters, and roofing

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block: rock faced
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Side Gable
materials: Asphalt
cornice:
dormers:
chimney: location(s): center; other: center of rear wall at vestibule, brick, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 5
- 2) Windows: 4
Fenestration: regular
Type: double hung, 6/1
Trim: aluminum
Shutters: other: aluminum, non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** metal
 - Trim:** plain
- 4) **Porch(es):** stoop

b. Side: Direction: south

- 1) **Bays:** 2
- 2) **Windows:** 1, 1
 - Fenestration:** regular
 - Type:** double hung, 6/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** side
 - Type:** metal
 - Trim:** plain
- 4) **Porch(es):**

c. Side: Direction: north

- 1) **Bays:**
- 2) **Windows:** 2, 1
 - Fenestration:** regular
 - Type:** double hung, 6/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: east

- 1) **Bays:** 4
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 6/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** center
 - Type:** metal
 - Trim:** plain
- 4) **Porch(es):** vestibule (enclosed entrance), 1 bay by 1 bay completely closed-in shed-roofed porch

9. INTERIOR:

10. LANDSCAPING: flanked by 2 mature fir trees in small front lawn, gravel parking area, several abandoned cars

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10768.002

1. ADDRESS/LOCATION: 222 Dupont Highway

2. FUNCTION(S): historic commercial garage current _____

3. YEAR BUILT: 1944 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. new garage doors, large l-bay addition to rear

b. _____

6. CURRENT CONDITION: excellent _____ good fair _____ poor _____

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories

c. Wall coverings metal, wood panelin

d. Foundation concrete pad

e. Roof
structural system gable front
coverings metal
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: west
1) bays: 4
2) windows: Count: 1; double hung, 1/1
3) door(s): Count: 3; Type: woodm garage doors
4) other:

- b. Side: direction: north
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: south
 - 1) bays: 3
 - 2) windows: Count: 2; irregular ; double hung, 1/1
 - 3) door(s): Count: 1; Location: side; southeast ; Type: replacement fiberglass
 - 4) other:

- d. Rear: direction: east
 - 1) bays: 1
 - 2) windows:
 - 3) door(s): Count: 1; Location: center ; Type: garage door
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10768

1. ADDRESS/LOCATION: 222 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10768

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10769
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

- HISTORIC NAME/FUNCTION: Dwelling
- ADDRESS/LOCATION: Dupont Highway
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE: building structure site object
landscape district
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 11/2006

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10769


Notes taken from public right-of-way. Owner not in agreement with survey; access denied!

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10769.001

1. ADDRESS/LOCATION: Dupont Highway
2. FUNCTION(S): historic current dwelling
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: double pile cottage
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: (obscured by metal panels)
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): vinyl siding
- e. Roof: shape: side gable
materials: asphalt
cornice:
dormers:
chimney: location(s): exterior, gable; brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 2
- 2) Windows: 2, first story
Fenestration:
Type: 1/1 double hung
Trim: vinyl
Shutters: vinyl, non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 Location: north side
 Type: replacement
 Trim: plain
- 4) **Porch(es):** entry

b. Side: Direction: south

- 1) **Bays:** 2
- 2) **Windows:** 2, first story; 1, in gable
 Fenestration: regular
 Type: 1/1 double hung
 Trim: vinyl
 Shutters:
- 3) **Door(s):** 1
 Location: (in rear addition)
 Type:
 Trim:
- 4) **Porch(es):**

c. Side: Direction: north

- 1) **Bays:** 3
- 2) **Windows:** 3, first story; 3, second story
 Fenestration: irregular
 Type: 1/1 casement
 Trim: vinyl
 Shutters: vinyl, non-functional
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

d. Rear: Direction: east


- 1) **Bays:**
- 2) **Windows:**
 Fenestration:
 Type: (no access)
 Trim:
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: Faces rt. 113; semi-circular dirt driveway on south side; surrounded by tall shade trees; modern outbuildings to rear

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10769

1. ADDRESS/LOCATION: Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-10769

INDICATE NORTH ON PLAN



USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10770
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 24487 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 11/2006

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10770


Notes taken from public right-of-way; owner denied access! Photos and site plan limited to roadside

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10770.001

1. ADDRESS/LOCATION: 24487 Dupont Highway
2. FUNCTION(S): historic current dwelling
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: rustic
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. gabled concrete-block addition on north end with grage door on façade

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: T-Plan Stories: 1
Additions:
- b. Structural system (if known): concrete block
- c. Foundation: materials: rusticated concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings):
- e. Roof: shape:
materials: asphalt
cornice:
dormers:
chimney: location(s): exterior, gable; center; brick; concrete

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 6
- 2) Windows: 5, first story
Fenestration: irregular
Type: 6/6 double hung; fixed
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
Location: north side
Type: boarded over
Trim:
- 4) **Porch(es):** entry

b. Side: Direction: south

- 1) **Bays:**
- 2) **Windows:**
Fenestration:
Type:
Trim:
Shutters:
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**

c. Side: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 1, first story
Fenestration:
Type: 6/6 double hung
Trim: wood
Shutters:
- 3) **Door(s):** 1
Location: west side
Type: wood
Trim: plain
- 4) **Porch(es):**entry; screened side corner porch


d. Rear: Direction: east

- 1) **Bays:**
- 2) **Windows:**
Fenestration: (no access)
Type:
Trim:
Shutters:
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Rt. 113; surrounded by woods; wood fence to south side

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10770.002

1. ADDRESS/LOCATION: 24487 Dupont Highway

2. FUNCTION(S): historic barn current _____

3. YEAR BUILT: 1940s CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____

a. patches on new siding _____

b. _____

6. CURRENT CONDITION: excellent _____ good _____ fair _____ poor **X**

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories _____

c. Wall coverings metal

d. Foundation _____

e. Roof
structural system gable front
coverings _____
openings _____

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: west
1) bays: 5
2) windows: ; irregular ; 6/6 double hung; fixed
3) door(s): Count: 1; Location: center ; Type: opening
4) other: _____

- b. Side: direction: south
 - 1) bays:
 - 2) windows: ; (no access)
 - 3) door(s):
 - 4) other:

- c. Side: direction: north
 - 1) bays:
 - 2) windows: ; (no access)
 - 3) door(s):
 - 4) other:

- d. Rear: direction: east
 - 1) bays:
 - 2) windows: ; (no access)
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10770

1. ADDRESS/LOCATION: 24487 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10770

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10771
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: Kruger Trailers
2. ADDRESS/LOCATION: 24306 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2006

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10771

this bungalow is surrounded by 7-8 post 1962 industrial sheds and buildings

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- 1830-1880- Industrialization and Early Urbanization
- X 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10771.001

1. ADDRESS/LOCATION: 24306 Dupont Highway
2. FUNCTION(S): historic current commerce/trade, domestic,
industry/processing/extraction
3. YEAR BUILT: 1920 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. porch enclosure

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Gable Front
materials: Other: metal
cornice:
dormers:
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 3
- 2) Windows: 2, 1
- Fenestration: irregular
Type: awning, other: jalousie
Trim: aluminum
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** metal
 - Trim:** plain
- 4) **Porch(es):** wrap-around

b. Side: Direction: north

- 1) **Bays:** 3
- 2) **Windows:** 3
 - Fenestration:** irregular
 - Type:** double hung, awning, 1/1,6/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:** 3
- 2) **Windows:** 3
 - Fenestration:** irregular
 - Type:** double hung, awning, 6/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: west

- 1) **Bays:** 3
- 2) **Windows:** 2, 1
 - Fenestration:** irregular
 - Type:** double hung, other: jalousie, 1/1, 6/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** corner
 - Type:** metal
 - Trim:**
- 4) **Porch(es):** stoop, concrete pad with row lock border

9. **INTERIOR:**

10. **LANDSCAPING:** shaded by several mature trees

11. **OTHER COMMENTS:**



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S-10771

1. ADDRESS/LOCATION: 24306 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10771

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10772
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: Commercial Building
2. ADDRESS/LOCATION: Dupont Highway Route 113
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: commerce/trade, industry/processing/extraction commercial
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10772

construction yard, there are post-1960 buildings on this property

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- 1830-1880- Industrialization and Early Urbanization
- X 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|--|
| <ul style="list-style-type: none"> Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing X Retailing/Wholesaling Finance Professional Services | <ul style="list-style-type: none"> Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events |
|--|--|

Facade (cont'd)

- 3) **Door(s):** 2
Location: center, side
Type: metal
Trim: plain
- 4) **Porch(es):** stoop

b. Side: Direction: north

- 1) **Bays:** 1
- 2) **Windows:**
Fenestration:
Type:
Trim:
Shutters:
- 3) **Door(s):** 1
Location: center
Type: wood & glass
Trim: plain
- 4) **Porch(es):** other, concrete loading platform, concrete slab is broken and in poor repair

c. Side: Direction: south

- 1) **Bays:** 3
- 2) **Windows:** 1
Fenestration: irregular
Type: casement, 9 pane casements
Trim: wood
Shutters:
- 3) **Door(s):** 2
Location: corner
Type: metal
Trim: plain
- 4) **Porch(es):** full-width, porch is raised concrete pad, former loading dock possibly


d. Rear: Direction: west

- 1) **Bays:** 11
- 2) **Windows:** 10
Fenestration: regular
Type: double hung, fixed, 4/4
Trim:
Shutters:
- 3) **Door(s):** 1
Location: center
Type: metal
Trim: plain
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: set in a construction yard with trucks, trailers, dumpsters, pipes, and backhoe

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10772.002

1. ADDRESS/LOCATION: Dupont Highway Route 113

2. FUNCTION(S): historic storage current _____

3. YEAR BUILT: 1940 CIRCA?: _____ ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular, Other: vernacular storage building

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. asbestos siding partially replaced with plywood, garage doors replaced ca. 1990

b. _____

6. CURRENT CONDITION: excellent _____ good _____ fair poor _____

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Other: plywood

d. Foundation concrete block

e. Roof structural system Flat
coverings Composition
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: east

1) bays: 5

2) windows:

3) door(s): Count: 5
Details: 1 door with 3 panes over 3 panels, 4 ca. 1990 pressed metal panel roll-up garage doors

4) other:

- b. **Side: direction:** south
 - 1) **bays:** 1
 - 2) **windows:** Count: 1; irregular ; double hung, 6/6
 - 3) **door(s):**
 - 4) **other:**

- c. **Side: direction:** north
 - 1) **bays:** 3
 - 2) **windows:** Count: 2; regular ; casement, steel casements
 - 3) **door(s):** Count: 1; Location: center ; Type: metal
Details: roll-up pressed metal garage door
 - 4) **other:**

- d. **Rear: direction:** west
 - 1) **bays:**
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10772

1. ADDRESS/LOCATION: Dupont Highway Route 113


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10772

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10773
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: Melvin L. Joseph Construction Company
2. ADDRESS/LOCATION: 25136 and 25154 DuPont Highway
3. TOWN/NEAREST TOWN: between Georgetown and Millsboro vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
X	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai/Courtney L. Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:


Organization: John Milner Associates Inc. Date: 09/2005; 11/2006

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|--|
| <ul style="list-style-type: none"> Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering X Manufacturing Retailing/Wholesaling Finance Professional Services | <ul style="list-style-type: none"> Transportation and Communication Settlement Patterns and Demographic Changes X Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10773.001

1. ADDRESS/LOCATION: 25136 DuPont Highway
2. FUNCTION(S): historic construction company current construction company
3. YEAR BUILT: 1956 CIRCA?: N ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: industrial building with Colonial Revival style second-story shutters
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year


a.

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 2
Additions: several additions
- b. Structural system (if known): concrete block and wood frame
- c. Foundation: materials: rusticated concrete block: brick faced
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): aluminum siding on second story;
remainder is exposed concrete block
- e. Roof: shape: flat and shed
materials: not visible
cornice: boxed
dormers: none
chimney: location(s): brick, northwest corner of back wall

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 5
- 2) Windows: 5, first story; 3 second story
Fenestration: regular
Type: 8/8 and 1/1 double-hung sash; fixed
Trim: wood and vinyl
Shutters: vinyl, non-functional

Facade (cont'd)**3) Door(s): 1****Location:****Type:** metal with 12-light upper half**Trim:****4) Porch(es):** small, one-bay design with very shallow gable roof on wood posts on concrete-block bases, with windows in sides between posts and wall**b. Side: Direction: north****1) Bays:****2) Windows:** 7, first story; 1, second story**Fenestration:** regular**Type:** 8/8 and 1/1 double-hung sash in eastern half; 18 pane steel casements in western half**Trim:** wood, vinyl; concrete sills and lintels at steel casements**Shutters:** vinyl, non-functional**3) Door(s): 3****Location:** side, near northeast corner**Type:** metal: 2 are large wood roll-down garage doors; 1 (second story) is 9 lights above 2 metal panels**Trim:****4) Porch(es):** uncovered stairway to second-story entrance, with landing at second-story level; has metal pipe railings, metal deck, and metal treads with open risers**c. Side: Direction: south****1) Bays: 6****2) Windows:** 5, first story; 1 second story**Fenestration:** regular**Type:** 16-pane steel casements and 2-pane horizontal fixed**Trim:** wood; concrete sills and lintels**Shutters:****3) Door(s): 1****Location:** 3rd bay from southeast corner**Type:** wood-and-glass (1 large pane in upper half)**Trim:****4) Porch(es):****d. Rear: Direction: west****1) Bays: 4****2) Windows:****Fenestration:** irregular**Type:** steel casement**Trim:** concrete sills and lintels**Shutters:****3) Door(s): 3****Location:****Type:** 2 large wood roll-down garage doors and 1 metal-and-glass door (1 large pane in upper half)**Trim:****4) Porch(es):****9. INTERIOR:****10. LANDSCAPING:****11. OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10773.002

1. ADDRESS/LOCATION: 25136 DuPont Highway

2. FUNCTION(S): historic horse stable current horse stable

3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. recently covered in metal

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Metal

d. Foundation none

e. Roof

structural system Side Gable

coverings Wood; heavy timber frame

openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: east

1) bays: 1

2) windows:

3) door(s): 1; center; dutch door

4) other: shed-roof hood sheltering entrance

b. Side: direction: south

1) bays: 1

2) windows:

3) door(s): 1; center; wood

4) other:

c. Side: direction: north

1) bays: none

2) windows:

3) door(s):

4) other:

d. Rear: direction: west

1) bays: [inaccessible]

2) windows:

3) door(s):

4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10773.003

1. ADDRESS/LOCATION: 25136 DuPont Highway

2. FUNCTION(S): historic cow shed current cow shed

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings wood siding

d. Foundation none

e. Roof structural system side gable
coverings Other: metal and translucent fiberglass
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: south
 - 1) bays: [inaccessible]
 - 2) windows:
 - 3) door(s): dutch door
 - 4) other:

- b. **Side: direction:** west
 - 1) **bays:** none
 - 2) **windows:**

 - 3) **door(s):**

 - 4) **other:**

- c. **Side: direction:** east
 - 1) **bays:** [inaccessible]
 - 2) **windows:**

 - 3) **door(s):**

 - 4) **other:**

- d. **Rear: direction:** north
 - 1) **bays:** [inaccessible]
 - 2) **windows:**

 - 3) **door(s):**

 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10773.004

1. ADDRESS/LOCATION: 25136 Dupont Highway

2. FUNCTION(S): historic dwelling current dwelling

3. YEAR BUILT: 1962 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Ranch, Center Hall

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. window replacement

b. _____

6. CURRENT CONDITION: excellent good _____ fair _____ poor _____

7. DESCRIPTION:

a. Structural system brick

b. Number of stories 1

c. Wall coverings

d. Foundation brick

e. Roof

structural system side gable

coverings asphalt

openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: east

1) bays: 9

2) windows: 7; 6/6 double hung, casement, fixed

3) door(s): 2; center, north side; wood & glass

4) other: entry porch; gabled, wood columns, brick deck, iron railing

- b. **Side: direction:** north
 - 1) **bays:** 4
 - 2) **windows:** 1; double hung, 6/6
 - 3) **door(s):** 3; metal garage doors
 - 4) **other:**

- c. **Side: direction:** south
 - 1) **bays:** 2
 - 2) **windows:** 2; regular; double hung, 6/6
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** west
 - 1) **bays:** 11
 - 2) **windows:** 9; 6/6 double hung, fixed
 - 3) **door(s):** 2; center, north side; wood & glass
 - 4) **other:** brick deck

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle ; central hall

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



CULTURAL RESOURCE SURVEY
STRUCTURE (LAND FEATURE) FORM

CRS # S-10773.005

1. ADDRESS/LOCATION: 25136 DuPont Highway

2. FUNCTION: Air strip / Landing strip

3. YEAR BUILT: 1963 CIRCA?: ARCHITECT/BUILDER: _____

4. INTEGRITY:

list major changes with years (if known) year

a. Lengthened to the north end

b. _____

5. CURRENT CONDITION: excellent good fair poor

6. DESCRIPTION:

a) Circulation system Gov. Stockley Rd. on south end; fencing notates end of strip; open farmland to the west and south; dense wood to north.

b) Spatial subdivisions Farmland to west and south sides; wood to north end; Rt. 113 to east

c) Retaining wall/lining material(s) Asphalt air strip

d) Other

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10773.006

1. ADDRESS/LOCATION: 25136 Dupont Highway

2. FUNCTION(S): historic airplane hangar current _____

3. YEAR BUILT: 1962 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent _____ good fair _____ poor _____

7. DESCRIPTION:
a. Structural system wood-frame
b. Number of stories 1
c. Wall coverings metal
d. Foundation _____
e. Roof
structural system shed
coverings metal
openings _____

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: west
1) bays: 1
2) windows: _____
3) door(s): 1; center; sliding
4) other: _____

- b. **Side: direction:** north
 - 1) **bays:** none
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

- c. **Side: direction:** south
 - 1) **bays:** none
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** east
 - 1) **bays:** none
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10773.007

1. ADDRESS/LOCATION: 25154 Dupont Highway

2. FUNCTION(S): historic dwelling current dwelling

3. YEAR BUILT: 1948 CIRCA?: N ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Colonial Revival, central hall

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent _____ good fair _____ poor _____

7. DESCRIPTION:
a. Structural system wood-frame
b. Number of stories 1.5
c. Wall coverings Aluminum Siding
d. Foundation concrete block
e. Roof structural system Side Gable
coverings Asphalt
openings _____

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: east
1) bays: 4
2) windows: 3, first story; 3, second story; regular; 6/1 double hung, and 1 fanlight window in second-story dormer wall above doorway
3) door(s): 1; center; wood & glass
Details: wood door with 6 panes in top third and 2 tall panels below
4) other: enclosed gabled entry vestibule, accessed by concrete stoop with wrought metal railing on one side

- b. **Side: direction:** north
- 1) **bays:** 4
 - 2) **windows:** 3, first story, 1 second story; regular; 3/1 double hung in wing; 6/1 second story; bay in first story with 8/8 double-hung center and 4/4 double-hungs flanking it
 - 3) **door(s):** 1; center; wood & glass
Details: 6 panes in top third over 2 long panels below
 - 4) **other:** poured-in-place concrete stoop with wrought metal railing to one side
- c. **Side: direction:** south
- 1) **bays:** 3
 - 2) **windows:** 3, first story; 1, second story; regular; 6/1 double hung with aluminum trim
 - 3) **door(s):**
 - 4) **other:**
- d. **Rear: direction:** west
- 1) **bays:** 3
 - 2) **windows:** 2, first story; irregular; 6/1 double hung
 - 3) **door(s):** 1; center; wood & glass
Details: 6 lights in top half over 3 horizontal panels below
 - 4) **other:** poured concrete stoop with wrought metal rail to one side

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle; central hall

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10773.008

1. ADDRESS/LOCATION: 25154 Dupont Highway

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1948 CIRCA?: N ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Colonial Revival, one pen

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Aluminum Siding
- d. Foundation concrete block
- e. Roof structural system Gable Front coverings Asphalt shingles openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: east
 - 1) bays: 2
 - 2) windows:
 - 3) door(s): 2; wood roll-down garage doors
 - 4) other:

- b. **Side: direction:** north
 - 1) **bays:** 2
 - 2) **windows:** 2; regular; double hung, 2/2
 - 3) **door(s):**
 - 4) **other:**

- c. **Side: direction:** south
 - 1) **bays:** 2
 - 2) **windows:** 1; regular; double hung, 2/2
 - 3) **door(s):** 1; side, near southeast corner; wood & glass
Details: 4 panes over 3 horizontal panels
 - 4) **other:**

- d. **Rear: direction:** west
 - 1) **bays:** 2
 - 2) **windows:** 2; regular; double hung, 2/2
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

T-Plan; one pen

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-10773

1. ADDRESS/LOCATION: 25136 and 25154 DuPont Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10773

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10900
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: agricultural complex
2. ADDRESS/LOCATION: 26042 Governor Stockley Road
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
X	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 08/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10900


property also has a non-historic garage, playhouse and shed

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- X Agriculture
 - Forestry
 - Trapping/Hunting
 - Mining/Quarrying
 - Fishing/Oystering
 - Manufacturing
 - Retailing/Wholesaling
 - Finance
 - Professional Services
 - Transportation and Communication
 - Settlement Patterns and Demographic Changes
 - X Architecture, Engineering and Decorative Arts
 - Government
 - Religion
 - Education
 - Community Organizations
 - Occupational Organizations
 - Major Families, Individuals and Events



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10900.001

1. ADDRESS/LOCATION: 26042 Governor Stockley Road
2. FUNCTION(S): historic agricultural complex current domestic
3. YEAR BUILT: 1920 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: square Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block: brick faced
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Wood Shingle
- e. Roof: shape: Side Gable
materials: Asphalt
cornice: exposed rafter ends
dormers: 1 shed-roofed dormer with a bank of 3 sets of double hung windows centered in the east, 1 dormer on the west facade
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays:
- 2) Windows: 3, 1
Fenestration: regular
Type: double hung, 1/1
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 Location: center
 Type: other: not visible
 Trim: plain
- 4) **Porch(es):** full-width

b. Side: Direction: south

- 1) **Bays:** 4
- 2) **Windows:** 2, 1
 Fenestration: regular
 Type: double hung, 1/1
 Trim: wood, aluminum
 Shutters:
- 3) **Door(s):** 1
 Location: side
 Type: metal
 Trim: plain
- 4) **Porch(es):** hood, gabled canopy/hood on knee braces on this elevation, shelters concrete stoop with new wood railing to one side

c. Side: Direction: north

- 1) **Bays:** 4
- 2) **Windows:** 3, 1
 Fenestration: irregular
 Type: 1/1, 2/2, 4/1
 Trim: wood, aluminum
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**


d. Rear: Direction: west

- 1) **Bays:** 1
- 2) **Windows:** 1, 1
 Fenestration: irregular
 Type: double hung, 1/1
 Trim: wood, aluminum
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING:

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10900.002

1. ADDRESS/LOCATION: 26042 Governor Stockley Road

2. FUNCTION(S): historic equipment shed current _____

3. YEAR BUILT: 1880-1940 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1.5
- c. Wall coverings Wood Siding Horizontal

d. Foundation

e. Roof

structural system Center Gable
coverings Other: corrugate metal
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: southeast
 - 1) bays: 2
 - 2) windows:
 - 3) door(s): Count: 2; Location: center ; Type: other
Details: 1 pair of wood doors with stucco applied over
 - 4) other:

- b. **Side: direction:** southwest
 - 1) **bays:** 5
 - 2) **windows:**
 - 3) **door(s):** Count: 3; Location: side
 - 4) **other:**

- c. **Side: direction:** northeast
 - 1) **bays:**
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** northwest
 - 1) **bays:**
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
STRUCTURE (BUILDING-LIKE) FORM

CRS # S-10900.003

1. ADDRESS/LOCATION: 26042 Governor Stockley Road

2. FUNCTION: corncrib IN USE?

3. YEAR BUILT: 1920 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/PLAN: Pentagonal front with sloped side walls, standard lumber framing (nailed) with light horizontal lath (1/2" x 3")

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with dates (if known) year
a. Interior lined to make it usable for storing household items and building material
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION (describe the structure as completely as possible):

a) Overall shape
height +/- 10 ft.
length +/- 9 ft.
width +/- 6 ft.

b) Structural system: Frame

c) Foundation: Concrete block


d) Exterior covering: wood siding with horizontal lath,

7. DESCRIPTION (cont'd):

CRS # S-10900.003

e) Openings Door on east wall

f) Other features Building was lined with a sheet material "Homosote" and used for storage, but is now open and in poor condition.



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10900

1. ADDRESS/LOCATION: 26042 Governor Stockley Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10900

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10901
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: agricultural complex
2. ADDRESS/LOCATION: 26029 Governor Stockley Road
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: commerce/trade, domestic agricultural complex
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- X Agriculture
 - Forestry
 - Trapping/Hunting
 - Mining/Quarrying
 - Fishing/Oystering
 - Manufacturing
 - Retailing/Wholesaling
 - Finance
 - Professional Services
 - Transportation and Communication
 - Settlement Patterns and Demographic Changes
 - Architecture, Engineering and Decorative Arts
 - Government
 - Religion
 - Education
 - Community Organizations
 - Occupational Organizations
 - Major Families, Individuals and Events



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10901.001

1. ADDRESS/LOCATION: 26029 Governor Stockley Road
2. FUNCTION(S): historic agricultural complex current commerce/trade, domestic
3. YEAR BUILT: 1880-1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, other: irregular
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: other: steel column with stuccoed panels
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Wood Shingle
- e. Roof: shape: Side Gable
materials: Other: metal
cornice: exposed rafter ends
dormers:
chimney: location(s): exterior, gable, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 5
- 2) Windows: 3
- Fenestration: irregular
Type: double hung, 6/6
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 Location: side
 Type: metal
 Trim: plain
- 4) **Porch(es):** stoop

b. Side: Direction: north

- 1) **Bays:** 3
- 2) **Windows:** 3, 1
 Fenestration: regular
 Type: double hung, 6/6
 Trim: wood, other: bungalow trim
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:** 3
- 2) **Windows:** 3, 1
 Fenestration: regular
 Type: double hung, 6/6
 Trim: wood, other: bungalow trim
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**


d. Rear: Direction: east

- 1) **Bays:** 3
- 2) **Windows:** 2
 Fenestration: irregular
 Type: double hung, other: slider, 6/6
 Trim: wood
 Shutters:
- 3) **Door(s):** 1
 Location: center
 Type: metal
 Trim:
- 4) **Porch(es):** entry, shed-roofed ca. 1980 porch built of treated 'deck' lumber with an accessibility ramp

9. INTERIOR:

10. LANDSCAPING: surrounded by lawn and corn fields, second house and some barns, linear equipment shed

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10901.002

1. ADDRESS/LOCATION: 26029 Governor Stockley Road

2. FUNCTION(S): historic barn/shed current _____

3. YEAR BUILT: 1900-1985 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Other: linear

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. originally a ground floor barn, linear stables or chicken house added to east ca. 1940 but with a gap between the 2 building until later closed in, addition on the west wing, half of original barn now a dwelling

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1.5

c. Wall coverings Other: plywood

d. Foundation concrete block

e. Roof structural system Other: metal coverings openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: west

1) bays: 3

2) windows: Count: 2, 1; regular ; double hung, 1/1


3) door(s): Count: 1; Location: center ; Type: metal Details: 6 panel pressed steel

4) other: _____

b. Side: direction: north1) **bays:** 162) **windows:** Count: 11; irregular ; double hung, other: slider, 1/13) **door(s):** Count: 5; Location: other: every 25 feet ; Type: wood
Details: plywood stable doors with nailed-on framework4) **other:****c. Side: direction:** south1) **bays:** 162) **windows:** Count: 7; irregular ; double hung, 1/13) **door(s):** Count: 3; Location: side ; Type: metal
Details: 1 steel door with diamond lattice covered pane in upper half/ flush below, 1
barn door made of vertical boards, 1 plywood stable door4) **other:****d. Rear: direction:** east1) **bays:** 12) **windows:** Count: 1; irregular ; double hung, 1/13) **door(s):**4) **other:****9. INTERIOR (if accessible):****a) Floor plan**

other: linear

b) Partition/walls**c) Finishes****d) Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10901.003

1. ADDRESS/LOCATION: 26029 Governor Stockley Road

2. FUNCTION(S): historic chicken house current _____

3. YEAR BUILT: 1962 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Other: utilitarian, one pen

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Other: plywood
- d. Foundation concrete block
- e. Roof structural system Gable Front
coverings Other: corrugate metal
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: west
 - 1) bays:
 - 2) windows:
 - 3) door(s): Count: 1; Location: center ; Type: wood
Details: 2 sheets of plywood on hinges form a paired center door
 - 4) other:

- b. **Side: direction:** south
 - 1) **bays:** 40
 - 2) **windows:** Count: 31; irregular
 - 3) **door(s):** Count: 9; Location: other: every 15 feet ; Type: wood
Details: plywood sheets with 2 hinges on each
 - 4) **other:**

- c. **Side: direction:** north
 - 1) **bays:** 40
 - 2) **windows:** ; irregular ; other: open bays with chicken wire
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** east
 - 1) **bays:**
 - 2) **windows:** ; other: openings with chicken wire flank doorway
 - 3) **door(s):** Count: 1; Location: center
Details: had plywood doors but they are now missing
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle ; one pen

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10901

1. ADDRESS/LOCATION: 26029 Governor Stockley Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-10901

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9