

DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10902
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

- HISTORIC NAME/FUNCTION: dwelling
- ADDRESS/LOCATION: 126 Bethesda Road
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10902.001

1. ADDRESS/LOCATION: 126 Bethesda Road
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1920 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. front vestibule may have originally been a porch, front entrance steps are missing, house has 2 layers on new siding (asbestos and aluminum)
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: square Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block: rock faced
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Side Gable
materials: Asphalt
cornice: exposed rafter ends
dormers:
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: north
- 1) Bays: 3
- 2) Windows: 2
Fenestration: regular
Type: double hung, 1/1
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** metal
 - Trim:** plain

- 4) **Porch(es):**

b. Side: Direction: east

- 1) **Bays:**
- 2) **Windows:** 3, 1
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:**

- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**

- 4) **Porch(es):**

c. Side: Direction: west

- 1) **Bays:** 4
- 2) **Windows:** 4, 1
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** wood
 - Shutters:**

- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**

- 4) **Porch(es):**

d. Rear: Direction: south

- 1) **Bays:** 2
- 2) **Windows:** 1
 - Fenestration:** irregular
 - Type:** double hung, 6/6
 - Trim:** aluminum
 - Shutters:**

- 3) **Door(s):** 1
 - Location:** side
 - Type:** metal
 - Trim:** plain


- 4) **Porch(es):** other, deck across full-width, built with treated lumber

9. INTERIOR:

- 10. **LANDSCAPING:** simple lawn with ca. 1990 shed and dog pens, 3 mature shade trees, an ornamental fruit tree and 6 small shrubs

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10902

1. ADDRESS/LOCATION: 126 Bethesda Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10903
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: agricultural complex
2. ADDRESS/LOCATION: Governor Stockley Road
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic, vacant/not in use agricultural complex
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005; 10/2008

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|--|
| <ul style="list-style-type: none"> X Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services | <ul style="list-style-type: none"> X Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10903.001

1. ADDRESS/LOCATION: Governor Stockley Road
2. FUNCTION(S): **historic** agricultural complex **current** domestic, vacant/not in use
3. YEAR BUILT: 1920 **CIRCA?:** Y **ARCHITECT/BUILDER:**
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, other: irregular
5. INTEGRITY: **original site** **moved**
if moved, from where other location's CRS # year

list major alterations and additions with years (if known)

year

a. only the shutters and a few windows appear to have been changed

b.

6. CURRENT CONDITION: **excellent** **good** **fair** **poor**

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangle
Additions:

Stories: 1.5

b. Structural system (if known): wood-frame

c. Foundation: materials: rusticated concrete block: rock faced
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): Wood Siding Horizontal

e. Roof: shape: Other: clipped gable
materials: Asphalt
cornice: exposed rafter ends
dormers:
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:

a. Facade: Direction: south

1) Bays: 3

2) Windows: 2

Fenestration: regular

Type: double hung, 6/1

Trim: wood

Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood, wood & glass
 - Trim:** plain
- 4) **Porch(es):** portico

b. Side: Direction: east

- 1) **Bays:** 3
- 2) **Windows:** 3, 1
 - Fenestration:** regular
 - Type:** double hung, fixed, 6/1
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: west

- 1) **Bays:** 3
- 2) **Windows:** 3, 1
 - Fenestration:** regular
 - Type:** double hung, fixed, 6/1
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: north

- 1) **Bays:** 7
- 2) **Windows:** 6
 - Fenestration:** regular
 - Type:** double hung, 6/1
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood, wood & glass
 - Trim:** plain
- 4) **Porch(es):** stoop, hood, shed canopy/hood on knee braces over a poured concrete stoop of 3 risers and a landing

9. INTERIOR:

10. LANDSCAPING: surrounded by shade trees, there are a number of outbuildings and some non-historic dog kennels

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10903.002

1. ADDRESS/LOCATION: Governor Stockley Road

2. FUNCTION(S): historic unidentified agricultural outb current _____

3. YEAR BUILT: 1930 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Bungalow/Craftsman

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. minor changes to door

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Vertical

d. Foundation concrete block: piers

e. Roof
structural system Side Gable
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southeast

1) bays: 3

2) windows: Count: 2; irregular ; other: fixed barn sash

3) door(s): Count: 1; Location: side ; Type: wood
Details: vertical bead board with strap hinges, upper has been replaced with plywood

4) other:

b. Side: direction: southwest

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: wood
Details: vertical board door with side hinges

4) other:

c. Side: direction: northeast

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: wood
Details: vertical board door with side hinges

4) other:

d. Rear: direction: northwest

1) bays:

2) windows:

3) door(s):

4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10903.003

1. ADDRESS/LOCATION: Governor Stockley Road

2. FUNCTION(S): historic stable current _____

3. YEAR BUILT: 1920 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular, one pen

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. minor changes to doors
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Wood Siding Vertical
- d. Foundation
- e. Roof structural system Side Gable coverings Asphalt openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: south
 - 1) bays: 2
 - 2) windows:
 - 3) door(s): Count: 2; Location: other: side by side ; Type: wood
Details: 1 siding door made of vertical bead board on a barn door track, 1 hollow core door
 - 4) other:

- b. **Side: direction:** east
 - 1) **bays:** 1
 - 2) **windows:** Count: 1; regular ; fixed, 6 pane barn sash
 - 3) **door(s):**
 - 4) **other:**

- c. **Side: direction:** west
 - 1) **bays:** 1
 - 2) **windows:** Count: 1; regular ; fixed, 6 pane barn sash
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** north
 - 1) **bays:**
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle ; one pen

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10903.004

1. ADDRESS/LOCATION: Governor Stockley Road

2. FUNCTION(S): **historic** unidentified agricultural outb **current** _____

3. YEAR BUILT: 1920 **CIRCA?:** Y **ARCHITECT/BUILDER:** _____

4. STYLE/FLOOR PLAN: Bungalow/Craftsman, one pen

5. INTEGRITY: **original site** **moved**
if moved, from where **original location's CRS #** **year**

list major alterations and additions with years (if known) **year**
a. none apparent
b.

6. CURRENT CONDITION: **excellent** **good** **fair** **poor**

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Vertical

d. Foundation

e. Roof
structural system Other: clipped gable
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: west
1) bays: 3
2) windows: Count: 2; regular ; other: screened openings
3) door(s): Count: 1; Location: center ; Type: wood
Details: vertical bead board with side hinges
4) other:

b. Side: direction: north

1) bays: 1

2) windows: Count: 1; regular ; other: screened opening, 1

3) door(s):

4) other:

c. Side: direction: south

1) bays:

2) windows:

3) door(s):

4) other:

d. Rear: direction: west

1) bays:

2) windows:

3) door(s):

4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle ; one pen

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10903.005

1. ADDRESS/LOCATION: Governor Stockley Road

2. FUNCTION(S): historic unidentified agricultural outb current _____

3. YEAR BUILT: 1950 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. plexiglass over window openings
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame, concrete block

b. Number of stories 1

c. Wall coverings Wood Siding Vertical

d. Foundation concrete block

e. Roof structural system Side Gable
coverings Other: corrugated galvanized steel
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: south
1) bays: 4
2) windows: Count: 4; regular ; other: square openings covered with plexiglass
3) door(s):
4) other:

- b. **Side: direction:** west
 - 1) **bays:** 3
 - 2) **windows:** Count: 2; regular ; other: square openings covered by plexiglass
 - 3) **door(s):** Count: 1; Location: center ; Type: wood
Details: vertical board door with side hinges
 - 4) **other:**

- c. **Side: direction:** east
 - 1) **bays:** 3
 - 2) **windows:** Count: 2; regular ; other: square openings covered by plexiglass
 - 3) **door(s):** Count: 1; Location: center ; Type: wood
Details: vertical board door with side hinges
 - 4) **other:**

- d. **Rear: direction:** north
 - 1) **bays:** 4
 - 2) **windows:** Count: 4; regular ; other: square openings covered with plexiglass
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10903.006

1. ADDRESS/LOCATION: Governor Stockley Road

2. FUNCTION(S): **historic** unidentified agricultural outb **current** _____

3. YEAR BUILT: 1930 **CIRCA?:** Y **ARCHITECT/BUILDER:** _____

4. STYLE/FLOOR PLAN: Bungalow/Craftsman

5. INTEGRITY: **original site** **moved**
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. none apparent

b.

6. CURRENT CONDITION: **excellent** **good** **fair** **poor**

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Vertical

d. Foundation stone, concrete block

e. Roof
structural system Side Gable
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southwest

1) bays: 3

2) windows: Count: 2; regular ; other: square openings

3) door(s): Count: 1; Location: center ; Type: wood
Details: vertical board door with side hinges

4) other:

- b. **Side: direction:** northwest
 - 1) **bays:** 1
 - 2) **windows:** Count: 1; other: square opening
 - 3) **door(s):**
 - 4) **other:**

- c. **Side: direction:** southeast
 - 1) **bays:** 1
 - 2) **windows:** Count: 1; regular ; other: square opening
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** northeast
 - 1) **bays:**
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10903.007

1. ADDRESS/LOCATION: Governor Stockley Road

2. FUNCTION(S): historic tractor shed current _____

3. YEAR BUILT: 1950 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular, one pen

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Other: corrugated galvanized steel

d. Foundation

e. Roof
structural system Gable Front
coverings Other: galvanized steel decking
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: west
1) bays:
2) windows:
3) door(s): Count: 1
Details: open garage doorway (no door), occupies southern half of west gable end
4) other:

- b. Side: direction: south
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: north
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: east
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle ; one pen

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10903

1. ADDRESS/LOCATION: Governor Stockley Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10903

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10919
SPO Map 14-15-09
Hundred Dagsboro
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 21367 Almshouse Road
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#: Form:	List property types:
X	CRS 2 Main Building Form
X	CRS 3 Secondary Building Form
	CRS 4 Archaeological Site Form
	CRS 5 Structure (Building-Like) Form
	CRS 6 Structure (Land Feature) Form
	CRS 7 Object Form
	CRS 8 Landscape Elements Form
X	CRS 9 Map Form N/A
	CRS 14 Potential District Form

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2006

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10919.001

1. ADDRESS/LOCATION: 21367 Almshouse Road
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1900 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Colonial Revival, side hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. siding and windows changed

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: L-Plan Stories: 2
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Side Gable
materials: Wood
cornice: boxed
dormers: no dormers (attic windows at side)
chimney: location(s): exterior, gable, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: south
- 1) Bays: 3
- 2) Windows: 2, 3
Fenestration: regular
Type: double hung, 1/1
Trim: aluminum
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:**
 - Type:** wood
 - Trim:** plain
- 4) **Porch(es):** stoop, hood

b. Side: Direction: east

- 1) **Bays:** 3
- 2) **Windows:** 2, 2, 1
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** stoop, prefab concrete steps

c. Side: Direction: west

- 1) **Bays:** 3
- 2) **Windows:** 3, 3, 2
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: north

- 1) **Bays:**
- 2) **Windows:**
 - Fenestration:**
 - Type:**
 - Trim:**
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. **INTERIOR:**

10. **LANDSCAPING:** set in a stand of second growth trees

11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10919.002

1. ADDRESS/LOCATION: 21367 Almshouse Road

2. FUNCTION(S): historic shed current _____

3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____
a. _____
b. _____

6. CURRENT CONDITION: excellent _____ good X fair _____ poor _____

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Metal
- d. Foundation other: none
- e. Roof structural system Gable Front
coverings Other: metal
openings _____

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: south
 - 1) bays: 1
 - 2) windows: _____
 - 3) door(s): Count: 1; Location: center ; Type: other
Details: screen door (bottom half), 1 light (broken)
 - 4) other: _____

- b. Side: direction: east
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: west
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: north
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10919

1. ADDRESS/LOCATION: 21367 Almshouse Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10919

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10940
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: County Seat Homes
2. ADDRESS/LOCATION: Dupont Highway Route 113
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10940


office

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10940.001

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1920 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, foursquare
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. siding, windows, non-functioning shutters, and deck at entry are all from ca. 1980-2005

b.

6. CURRENT CONDITION: excellent good X fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block: rock faced
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Other: clipped gable
materials: Asphalt
cornice: boxed
dormers:
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 2
- 2) Windows: 2, 1
Fenestration: regular
Type: double hung, fixed, 6/6
Trim: vinyl
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

b. Side: Direction: south

- 1) **Bays: 3**
- 2) **Windows: 3**
 - Fenestration:** irregular
 - Type:** double hung, 6/6
 - Trim:** vinyl
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s): 1**
 - Location:** side
 - Type:** metal
 - Trim:** plain
- 4) **Porch(es):**other, deck and ramp ca. 1995

c. Side: Direction: north

- 1) **Bays: 3**
- 2) **Windows: 3**
 - Fenestration:** regular
 - Type:** double hung, 6/6
 - Trim:** vinyl
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: east


- 1) **Bays: 2**
- 2) **Windows: 1, 1**
 - Fenestration:** regular
 - Type:** double hung, 6/6
 - Trim:** vinyl
 - Shutters:** vinyl,non-functional
- 3) **Door(s): 1**
 - Location:** side
 - Type:** metal
 - Trim:** plain
- 4) **Porch(es):**hood, hood is small shed-roofed canopy at door, door is accessed by 3 poured concrete steps with concrete block beneath at sides

9. INTERIOR:

10. LANDSCAPING: busy highway location, near other houses and construction/vehicle sales yards, small lawn surrounds house

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-10940

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10952
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 24112 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2006

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10952


insurance records indicate house was built in 1966

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10952.001

1. ADDRESS/LOCATION: 24112 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good X fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Side Gable
materials: Asphalt
cornice:
dormers:
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 5
- 2) Windows: 4
Fenestration: irregular
Type: double hung, casement, 1/1
Trim: aluminum
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood
 - Trim:** plain
- 4) **Porch(es):** inset

b. Side: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:** 2
- 2) **Windows:** 1
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:** (vinyl, non-functional)
- 3) **Door(s):** 1
 - Location:** corner
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** inset, entry


d. Rear: Direction: west

- 1) **Bays:** 6
- 2) **Windows:** 6
 - Fenestration:** irregular
 - Type:** double hung, hopper, 1/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Rt. 113, mature oak trees across front lawn, fallow fields to south

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10952.002

1. ADDRESS/LOCATION: 24112 Dupont Highway

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. replacement garage doors

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Aluminum Siding

d. Foundation concrete block

e. Roof structural system Gable Front
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: east

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: other
Details: aluminum garage door

4) other:

- b. Side: direction: north
 - 1) bays: 2
 - 2) windows:
 - 3) door(s): Count: 2; Location: other: irregular ; Type: metal
 - 4) other:

- c. Side: direction: south
 - 1) bays: 2
 - 2) windows: ; irregular ; hopper
 - 3) door(s):
 - 4) other:

- d. Rear: direction: west
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10952

1. ADDRESS/LOCATION: 24112 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH




4. SITE PLAN:

CRS # S-10952

INDICATE NORTH ON PLAN



USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10953
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

- HISTORIC NAME/FUNCTION: dwelling
- ADDRESS/LOCATION: 24546 Dupont Highway
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-10953

nice and intact ca. 1960 ranch, down to color scheme

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- 1830-1880- Industrialization and Early Urbanization
- 1880-1940- Urbanization and Early Suburbanization
- X 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10953.001

1. ADDRESS/LOCATION: 24546 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch, other: irregular
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. newer building behind

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): wood-frame, brick
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Side Gable, Hipped
materials: Asphalt
cornice: boxed
dormers:
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 5
- 2) Windows: 4
Fenestration: regular
Type: casement, 2/2 (horizontal panes)
Trim: wood
Shutters: wood,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood
 - Trim:** plain
- 4) **Porch(es):** stoop

b. Side: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 2/2 (horizontal)
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: north

- 1) **Bays:** 1
- 2) **Windows:** 1
 - Fenestration:** regular
 - Type:** casement
 - Trim:** wood
 - Shutters:** other: metal awning
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: west


- 1) **Bays:** 6
- 2) **Windows:** 4
 - Fenestration:** irregular
 - Type:** double hung, casement, 1 double hung, 2/2 (horizontal)
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):** 2
 - Location:** corner
 - Type:** wood
 - Trim:** plain
- 4) **Porch(es):** other, screened-in small 'Florida room' and 1 small shed-roofed porch over wood door with 1 turned wood post

9. INTERIOR:

10. **LANDSCAPING:** set in grove of second growth trees, 2 non-historic outbuildings in rear

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10953

1. ADDRESS/LOCATION: 24546 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH




4. SITE PLAN:

CRS # S-10953

INDICATE NORTH ON PLAN



USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10954
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 24568 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10954.001

1. ADDRESS/LOCATION: 24568 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch, other: irregular
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: T-Plan Stories: 1
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding, Stone Veneer
- e. Roof: shape: Complex Gable
 materials: Asphalt
 cornice: boxed
 dormers:
 chimney: location(s): other: exterior/rear wall, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 6
- 2) Windows: 4
 Fenestration: irregular
 Type: double hung, 1/1
 Trim: aluminum
 Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** side
 - Type:** wood
 - Trim:** plain
- 4) **Porch(es):** porte-cochere, inset

b. Side: Direction: north

- 1) **Bays:**
- 2) **Windows:** 1
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:** 3
- 2) **Windows:** 3
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: east


- 1) **Bays:** 6
- 2) **Windows:** 5
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood
 - Trim:** plain
- 4) **Porch(es):** other, wood deck ca. 1995

9. INTERIOR:

10. LANDSCAPING: set in a grove of tall second growth trees

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**


CRS # S-10954

1. ADDRESS/LOCATION: 24568 Dupont Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10954

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10955
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: Educational Facility
2. ADDRESS/LOCATION: 24584 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: education
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10955.001

1. ADDRESS/LOCATION: 24584 Dupont Highway
2. FUNCTION(S): historic current education
3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch, other: irregular
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: L-Plan Stories: 1
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding, Brick Veneer
- e. Roof: shape: Complex Gable
 materials: Asphalt
 cornice: boxed
 dormers:
 chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
 1) Bays: 5
 2) Windows: 4
 Fenestration: irregular
 Type: double hung, 1/1
 Trim: aluminum
 Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** inset

b. Side: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 4
 - Fenestration:** irregular
 - Type:** double hung, 2/2 (horizontal panes)
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** side
 - Type:** metal
 - Trim:** plain
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: west

- 1) **Bays:** 9
- 2) **Windows:** 8
 - Fenestration:** irregular
 - Type:** double hung, fixed, 2/2 (horizontal panes)
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** side
 - Type:** metal
 - Trim:**
- 4) **Porch(es):** other, wood deck ca. 1990

9. INTERIOR:

10. LANDSCAPING: set in a grove of tall second growth trees

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10955.002

1. ADDRESS/LOCATION: 24584 Dupont Highway

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Ranch

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____

a. _____

b. _____

6. CURRENT CONDITION: excellent _____ good X fair _____ poor _____

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories 1

c. Wall coverings Brick Veneer

d. Foundation concrete block

e. Roof
structural system Side Gable
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: east

1) bays:

2) windows:

3) door(s): Count: 2; Location: other: most of façade ; Type: wood
Details: replacement garage doors

4) other:

- b. **Side: direction:** south
 - 1) **bays:** 2
 - 2) **windows:** Count: 1; regular ; double hung, 8/8
 - 3) **door(s):** Count: 1; Location: side ; Type: metal
Details: flush
 - 4) **other:**

- c. **Side: direction:** north
 - 1) **bays:**
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** west
 - 1) **bays:**
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10955

1. ADDRESS/LOCATION: 24584 Dupont Highway


2. NOT FOR PUBLICATION reason: _____


3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10956
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 24602 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10956.001

1. ADDRESS/LOCATION: 24602 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch, other: irregular
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
 Additions:
- b. Structural system (if known): wood-frame, brick
- c. Foundation: materials: brick
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Other: random clinker bricks
- e. Roof: shape: Side Gable
 materials: Asphalt
 cornice: boxed
 dormers:
 chimney: location(s): other: center/rear, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 7
- 2) Windows: 5
 Fenestration: regular
 Type: double hung, 6/6, 8/8, 6/9
 Trim: wood
 Shutters: wood,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
Location: center
Type: wood
Trim: plain
- 4) **Porch(es):** inset

b. Side: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 1
Fenestration: irregular
Type: double hung, 8/8
Trim: wood
Shutters: (wood,non-functional)
- 3) **Door(s):** 1
Location:
Type: wood & glass
Trim:
- 4) **Porch(es):**porte-cochere, carport under continuation of roof of house, on square wood posts

c. Side: Direction: south

- 1) **Bays:** 2
- 2) **Windows:** 2
Fenestration: regular
Type: double hung, 6/6
Trim: wood
Shutters: (wood,non-functional)
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**

d. Rear: Direction: west


- 1) **Bays:** 8
- 2) **Windows:** 6
Fenestration: irregular
Type: double hung, 6/6, 8/8
Trim: wood
Shutters: vinyl,non-functional
- 3) **Door(s):** 1
Location: center
Type: wood
Trim: plain
- 4) **Porch(es):**other, brick deck extending into backyard, surrounded by planting beds, steps and brick retaining walls

9. INTERIOR:

- 10. **LANDSCAPING:** set in a grove of tall second growth trees, non-historic side gable garage and a wood shed at rear, backyard has a landscape with free-form paths, shrubs, etc.

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-10956


1. ADDRESS/LOCATION: 24602 Dupont Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-10957
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

1. HISTORIC NAME/FUNCTION: Commercial Building
2. ADDRESS/LOCATION: 26072 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: commerce/trade commercial
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:


Organization: John Milner Associates Inc. Date: 10/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|--|
| <ul style="list-style-type: none"> Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing X Retailing/Wholesaling Finance Professional Services | <ul style="list-style-type: none"> Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-10957.001

1. ADDRESS/LOCATION: 26072 Dupont Highway
2. FUNCTION(S): historic commercial current commerce/trade
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. siding and entrance shelters are the main changes, roof may have been rebuilt at rear to include a rear addition (originally a T-shape floor plan)
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Side Gable
 materials: Asphalt
 cornice:
 dormers:
 chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 4
- 2) Windows: 3
 Fenestration: irregular
 Type: double hung, fixed, 1/1
 Trim: aluminum
 Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** commercial glass
 - Trim:** plain
- 4) **Porch(es):** entry

b. Side: Direction: south

- 1) **Bays:** 1
- 2) **Windows:**
 - Fenestration:**
 - Type:**
 - Trim:**
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** side
 - Type:** commercial glass
 - Trim:** plain
- 4) **Porch(es):** small gabled shelter over door has glass sides in anodized aluminum frame

c. Side: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: west

- 1) **Bays:** 2
- 2) **Windows:** 1
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** side
 - Type:** commercial glass
 - Trim:** plain
- 4) **Porch(es):** entry, gabled roofed glass shelter at door, with an anodized aluminum frame

9. INTERIOR:

10. LANDSCAPING: almost completely surrounded by gravel, has a ca. 1955 house at northwest corner of lot

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-10957.002

1. ADDRESS/LOCATION: 26072 Dupont Highway

2. FUNCTION(S): historic dwelling current _____

3. YEAR BUILT: 1955 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Ranch

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system wood-frame
b. Number of stories 1
c. Wall coverings Aluminum Siding
d. Foundation concrete block
e. Roof structural system Cross Gable
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: east
1) bays: 3
2) windows: Count: 2; irregular ; double hung, 6/6, 1/1
3) door(s): Count: 1; Location: center ; Type: wood & glass
Details: large center pane with border of smaller
4) other:

b. Side: direction: north

1) bays: 2

2) windows: Count: 2; irregular ; double hung, 6/1,1/1

3) door(s):

4) other:

c. Side: direction: south

1) bays: 3

2) windows: Count: 3; double hung, 6/6

3) door(s):

4) other:

d. Rear: direction: west

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: metal

Details: pressed steel with one large light above 2 pressed metal vertical panels

4) other:

9. INTERIOR (if accessible):


a) Floor plan

L-Plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-10957

1. ADDRESS/LOCATION: 26072 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-10957

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9