

DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-10958  
SPO Map 14-15-09  
Hundred Dagsboro  
Quad Harbeson  
Other \_\_\_\_\_

1. HISTORIC NAME/FUNCTION: Commercial Building
2. ADDRESS/LOCATION: 26088 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:      building       structure       site       object   
   landscape       district
5. MAIN FUNCTION OF PROPERTY: commercial building
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 10/2005

**9. OTHER NOTES OR OBSERVATIONS:**

**CRS#** S-10958

this is an industrial building, maybe built for auto repair


**10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):**

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
- 1600-1750- Contact Period (Native American)  
1630-1730- Exploration and Frontier Settlement  
1730-1770- Intensified and Durable Occupation  
1770-1830- Early Industrialization  
1830-1880- Industrialization and Early Urbanization  
1880-1940- Urbanization and Early Suburbanization  
X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

c) Historic period theme(s)

- |  |  |
|--|--|
| <ul style="list-style-type: none"><li>Agriculture</li><li>Forestry</li><li>Trapping/Hunting</li><li>Mining/Quarrying</li><li>Fishing/Oystering</li><li>Manufacturing</li><li>X Retailing/Wholesaling</li><li>Finance</li><li>Professional Services</li></ul> | <ul style="list-style-type: none"><li>Transportation and Communication</li><li>Settlement Patterns and Demographic Changes</li><li>Architecture, Engineering and Decorative Arts</li><li>Government</li><li>Religion</li><li>Education</li><li>Community Organizations</li><li>Occupational Organizations</li><li>Major Families, Individuals and Events</li></ul> |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-10958.001

1. ADDRESS/LOCATION: 26088 Dupont Highway
2. FUNCTION(S): historic commercial current commerce/trade
3. YEAR BUILT: 1955 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Other: utilitarian, one pen
5. INTEGRITY: original site  moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. front (concrete block) vestibule, maybe newer than steel-clad building behind it

b.

6. CURRENT CONDITION: excellent good fair  poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1  
Additions:
- b. Structural system (if known): concrete block, iron/steel
- c. Foundation: materials: concrete block  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): Other: corrugated galvanized steel and concrete block
- e. Roof: shape: Gable Front  
materials: Other: metal  
cornice: boxed  
dormers:  
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 3
- 2) Windows: 2  
Fenestration: regular  
Type: casement, 15 pane steel casements  
Trim: steel  
Shutters:

**Facade (cont'd)**

- 3) **Door(s):** 1  
    **Location:** center  
    **Type:** wood  
    **Trim:** plain
- 4) **Porch(es):** entry

**b. Side: Direction: south**

- 1) **Bays:** 1
- 2) **Windows:**  
    **Fenestration:**  
    **Type:**  
    **Trim:**  
    **Shutters:**
- 3) **Door(s):** 1  
    **Location:** side  
    **Type:** metal  
    **Trim:** plain
- 4) **Porch(es):**

**c. Side: Direction: north**

- 1) **Bays:**
- 2) **Windows:**  
    **Fenestration:**  
    **Type:**  
    **Trim:**  
    **Shutters:**
- 3) **Door(s):**  
    **Location:**  
    **Type:**  
    **Trim:**
- 4) **Porch(es):**


**d. Rear: Direction: west**

- 1) **Bays:** 1
- 2) **Windows:**  
    **Fenestration:**  
    **Type:**  
    **Trim:**  
    **Shutters:**
- 3) **Door(s):** 1  
    **Location:** side  
    **Type:** metal  
    **Trim:**
- 4) **Porch(es):**

**9. INTERIOR:**

**10. LANDSCAPING:** surrounded by lawn and driveway, with a trailer home behind it

**11. OTHER COMMENTS:**



**CULTURAL RESOURCE SURVEY  
MAP FORM**

CRS # S-10958

1. ADDRESS/LOCATION: 26088 Dupont Highway


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


**INDICATE NORTH ON SKETCH**



4. SITE PLAN:


CRS # S-10958

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-10959  
SPO Map 14-15-09  
Hundred Dagsboro  
Quad Harbeson  
Other \_\_\_\_\_

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 26120 Dupont Highway
3. TOWN/NEAREST TOWN: Millsboro vicinity?
4. MAIN TYPE OF RESOURCE:
 

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
- 1600-1750- Contact Period (Native American)  
 1630-1730- Exploration and Frontier Settlement  
 1730-1770- Intensified and Durable Occupation  
 1770-1830- Early Industrialization  
 1830-1880- Industrialization and Early Urbanization  
 1880-1940- Urbanization and Early Suburbanization  
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |                       |   |   |
|-----------------------|---|---|
| Agriculture           |   | Transportation and Communication              |
| Forestry              |   | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      |   | Government                                    |
| Fishing/Oystering     |   | Religion                                      |
| Manufacturing         |   | Education                                     |
| Retailing/Wholesaling |   | Community Organizations                       |
| Finance               |   | Occupational Organizations                    |
| Professional Services |   | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-10959.001

1. ADDRESS/LOCATION: 26120 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch
5. INTEGRITY: original site  moved  
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. windows have been changed ca. 1980

b.

6. CURRENT CONDITION: excellent good fair  poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1  
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block  
 basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): Asbestos
- e. Roof: shape: Side Gable  
 materials: Asphalt  
 cornice: boxed  
 dormers:  
 chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 4
- 2) Windows: 4  
 Fenestration: irregular  
 Type: double hung, other: sliders, double hung sash  
 Trim: wood  
 Shutters:

**Facade (cont'd)**

- 3) **Door(s):**  
  - Location:**
  - Type:**
  - Trim:**
- 4) **Porch(es):**

**b. Side: Direction: south**

- 1) **Bays: 2**
- 2) **Windows: 1**  
  - Fenestration:** irregular
  - Type:** other: vinyl slider
  - Trim:** wood
  - Shutters:**
- 3) **Door(s): 1**  
  - Location:** side
  - Type:** wood
  - Trim:** plain
- 4) **Porch(es):** porte-cochere, corner of house has a screened in porch and carport, extends south, has a concrete slab floor and square wood posts

**c. Side: Direction: north**

- 1) **Bays: 2**
- 2) **Windows: 2**  
  - Fenestration:** regular
  - Type:** other: vinyl sliders
  - Trim:** wood
  - Shutters:**
- 3) **Door(s):**  
  - Location:**
  - Type:**
  - Trim:**
- 4) **Porch(es):**


**d. Rear: Direction: west**

- 1) **Bays: 5**
- 2) **Windows: 4**  
  - Fenestration:** irregular
  - Type:** other: vinyl sliders
  - Trim:** wood
  - Shutters:**
- 3) **Door(s): 1**  
  - Location:** side
  - Type:** wood & glass
  - Trim:** plain
- 4) **Porch(es):** stoop, concrete steps to door, 3 risers and a landing

**9. INTERIOR:**

**10. LANDSCAPING:** set in a grove of tall second growth trees, almost completely shaded by the canopy, mature shrubbery

**11. OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-10959.002

1. ADDRESS/LOCATION: 26120 Dupont Highway

2. FUNCTION(S): historic shed current \_\_\_\_\_

3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: Other: utilitarian shed, one pen

5. INTEGRITY: original site  moved \_\_\_\_\_  
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. shed extension of corrugated steel to the rear

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Asbestos

d. Foundation concrete block

e. Roof structural system Shed  
coverings Other: corrugate metal  
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: east

1) bays: 2

2) windows:

3) door(s): Count: 2; Location: side ; Type: other  
Details: 2 panes with solid aluminum panel below

4) other:

- b. Side: direction: north
  - 1) bays: 1
  - 2) windows: Count: 1; regular ; fixed
  - 3) door(s):
  - 4) other:

- c. Side: direction: south
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- d. Rear: direction: west
  - 1) bays:
  - 2) windows: Count: 1; irregular ; fixed, 6 pane fixed sash
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle ; one pen

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-10959

1. ADDRESS/LOCATION: 26120 Dupont Highway


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-10959

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-11013  
SPO Map 14-15-09  
Hundred Dagsboro  
Quad Harbeson  
Other \_\_\_\_\_

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 246 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:
 

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
- 1600-1750- Contact Period (Native American)  
 1630-1730- Exploration and Frontier Settlement  
 1730-1770- Intensified and Durable Occupation  
 1770-1830- Early Industrialization  
 1830-1880- Industrialization and Early Urbanization  
 1880-1940- Urbanization and Early Suburbanization  
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |                       |   |   |
|-----------------------|---|---|
| Agriculture           |   | Transportation and Communication              |
| Forestry              |   | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      |   | Government                                    |
| Fishing/Oystering     |   | Religion                                      |
| Manufacturing         |   | Education                                     |
| Retailing/Wholesaling |   | Community Organizations                       |
| Finance               |   | Occupational Organizations                    |
| Professional Services |   | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-11013.001

1. ADDRESS/LOCATION: 246 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch, other: irregular
5. INTEGRITY: original site  moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. additions to south arranged in a stepped/telescoping manner. Garage connected to house.

b.

6. CURRENT CONDITION: excellent good  fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1  
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding, Stone Veneer
- e. Roof: shape: Side Gable  
materials: Asphalt  
cornice: boxed  
dormers:  
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 10
- 2) Windows: 7  
Fenestration: irregular  
Type: double hung, 1/1  
Trim: vinyl  
Shutters: vinyl,non-functional

**Facade (cont'd)**

- 3) **Door(s):** 3  
     **Location:** center, side  
     **Type:** metal  
     **Trim:** plain
- 4) **Porch(es):** stoop

**b. Side: Direction: north**

- 1) **Bays:** 2
- 2) **Windows:** 2  
     **Fenestration:** regular  
     **Type:** double hung, 1/1  
     **Trim:** vinyl  
     **Shutters:**
- 3) **Door(s):**  
     **Location:**  
     **Type:**  
     **Trim:**
- 4) **Porch(es):**

**c. Side: Direction: south**

- 1) **Bays:**
- 2) **Windows:** 2  
     **Fenestration:** regular  
     **Type:** other: vinyl sliders  
     **Trim:** vinyl  
     **Shutters:**
- 3) **Door(s):**  
     **Location:**  
     **Type:**  
     **Trim:**
- 4) **Porch(es):**


**d. Rear: Direction: east**

- 1) **Bays:** 6
- 2) **Windows:** 6  
     **Fenestration:** irregular  
     **Type:** 1/1, 4/4  
     **Trim:** vinyl  
     **Shutters:**
- 3) **Door(s):**  
     **Location:**  
     **Type:**  
     **Trim:**
- 4) **Porch(es):**

**9. INTERIOR:**

**10. LANDSCAPING:** set back in a lawn with a variety of plantings, wooded to rear

**11. OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-11013.002

1. ADDRESS/LOCATION: 246 Dupont Highway

2. FUNCTION(S): historic storage shed current \_\_\_\_\_

3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: Other: storage shed, one pen

5. INTEGRITY: original site  moved \_\_\_\_\_  
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. some of the exterior corrugated steel siding replaced in 1980 with till scored plywood

b.

6. CURRENT CONDITION: excellent good fair  poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories

c. Wall coverings Metal

d. Foundation concrete block

e. Roof structural system Gable Front  
coverings Asphalt  
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: west

1) bays:

2) windows:

3) door(s): Count: 1; Location: center ; Type: wood  
Details: 4 panel wood door.

4) other:

- b. Side: direction: north
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: south
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- d. Rear: direction: east
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle ; one pen

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # S-11013

1. ADDRESS/LOCATION: 246 Dupont Highway
2. NOT FOR PUBLICATION  reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11013

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-11014  
SPO Map 14-15-09  
Hundred Dagsboro  
Quad Harbeson  
Other \_\_\_\_\_

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 24629 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:
 

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
- 1600-1750- Contact Period (Native American)  
 1630-1730- Exploration and Frontier Settlement  
 1730-1770- Intensified and Durable Occupation  
 1770-1830- Early Industrialization  
 1830-1880- Industrialization and Early Urbanization  
 1880-1940- Urbanization and Early Suburbanization  
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |                       |   |   |
|-----------------------|---|---|
| Agriculture           |   | Transportation and Communication              |
| Forestry              |   | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      |   | Government                                    |
| Fishing/Oystering     |   | Religion                                      |
| Manufacturing         |   | Education                                     |
| Retailing/Wholesaling |   | Community Organizations                       |
| Finance               |   | Occupational Organizations                    |
| Professional Services |   | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-11014.001

1. ADDRESS/LOCATION: 24629 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1960-1970 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch
5. INTEGRITY: original site  moved  
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent  good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: Stories: 2  
Additions:
- b. Structural system (if known): wood-frame, concrete block
- c. Foundation: materials: concrete block  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): Other: painted concrete
- e. Roof: shape: Side Gable  
materials: Asphalt  
cornice: boxed  
dormers:  
chimney: location(s): exterior, gable; other: rear/northeast corner, brick, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 4
- 2) Windows: 3, 2  
Fenestration: irregular  
Type: double hung, 2/2  
Trim: wood  
Shutters: vinyl, non-functional

**Facade (cont'd)**

- 3) **Door(s):** 1  
     **Location:** center  
     **Type:** wood  
     **Trim:**
- 4) **Porch(es):** inset

**b. Side: Direction: west**

- 1) **Bays:** 3
- 2) **Windows:** 1, 3  
     **Fenestration:** regular  
     **Type:** double hung, 2/2  
     **Trim:** aluminum  
     **Shutters:**
- 3) **Door(s):**  
     **Location:**  
     **Type:**  
     **Trim:**
- 4) **Porch(es):**

**c. Side: Direction: south**

- 1) **Bays:** 1
- 2) **Windows:** 1  
     **Fenestration:** irregular  
     **Type:** double hung, 6/6  
     **Trim:** aluminum  
     **Shutters:**
- 3) **Door(s):**  
     **Location:**  
     **Type:**  
     **Trim:**
- 4) **Porch(es):**


**d. Rear: Direction: east**

- 1) **Bays:** 6
- 2) **Windows:** 3, 2  
     **Fenestration:** irregular  
     **Type:** double hung, 2/2  
     **Trim:** wood  
     **Shutters:**
- 3) **Door(s):** 2  
     **Location:** center, side  
     **Type:** wood, wood & glass, other  
     **Trim:** plain
- 4) **Porch(es):** other, wood deck with railing and square wood balustrade

**9. INTERIOR:**

**10. LANDSCAPING:** set back from road with landscaping, drive, mature trees and shrubs

**11. OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-11014.002

1. ADDRESS/LOCATION: 24629 Dupont Highway

2. FUNCTION(S): historic storage shed current \_\_\_\_\_

3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: Other: lawn shed, one pen

5. INTEGRITY: original site  moved \_\_\_\_\_  
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good  fair \_\_\_\_\_ poor \_\_\_\_\_

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Other: horizontal corrugated galvanized steel
- d. Foundation concrete block
- e. Roof structural system Gable Front  
coverings Other: metal  
openings \_\_\_\_\_

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: west
  - 1) bays: \_\_\_\_\_
  - 2) windows: \_\_\_\_\_
  - 3) door(s): Count: 1; Location: center ; Type: wood  
Details: vertical till scored plywood with 3 side hinges.
  - 4) other: \_\_\_\_\_

- b. Side: direction: north
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: south
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- d. Rear: direction: west
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle ; one pen

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-11014

1. ADDRESS/LOCATION: 24629 Dupont Highway


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11014

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-11015  
SPO Map 14-15-09  
Hundred Dagsboro  
Quad Harbeson  
Other \_\_\_\_\_

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 24619 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:
 

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
- 1600-1750- Contact Period (Native American)  
 1630-1730- Exploration and Frontier Settlement  
 1730-1770- Intensified and Durable Occupation  
 1770-1830- Early Industrialization  
 1830-1880- Industrialization and Early Urbanization  
 X 1880-1940- Urbanization and Early Suburbanization  
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |                       |   |   |
|-----------------------|---|---|
| Agriculture           |   | Transportation and Communication              |
| Forestry              |   | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      |   | Government                                    |
| Fishing/Oystering     |   | Religion                                      |
| Manufacturing         |   | Education                                     |
| Retailing/Wholesaling |   | Community Organizations                       |
| Finance               |   | Occupational Organizations                    |
| Professional Services |   | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-11015.001

1. ADDRESS/LOCATION: 24619 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Colonial Revival, central hall
5. INTEGRITY: original site  moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. windows have been changed after siding was installed, porch columns are recent replacements

b.

6. CURRENT CONDITION: excellent  good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 2  
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Side Gable  
materials: Asphalt  
cornice: boxed  
dormers:  
chimney: location(s): exterior, gable, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 3
- 2) Windows: 2, 3  
Fenestration: regular  
Type: double hung, 8/8, 6/6  
Trim: aluminum  
Shutters: vinyl,non-functional

**Facade (cont'd)**

- 3) **Door(s):** 1  
**Location:** center  
**Type:**  
**Trim:** plain
- 4) **Porch(es):** portico

**b. Side: Direction: south**

- 1) **Bays:** 2
- 2) **Windows:** 1, 2  
**Fenestration:**  
**Type:** 8/8  
**Trim:** aluminum  
**Shutters:** (vinyl,non-functional)
- 3) **Door(s):** 1  
**Location:** side  
**Type:** wood, wood & glass  
**Trim:** plain
- 4) **Porch(es):**entry, shed-roof porch on one aluminum post, connected to pantry addition, concrete floor and steps, aluminum railing

**c. Side: Direction: north**

- 1) **Bays:** 2
- 2) **Windows:** 1, 1  
**Fenestration:** regular  
**Type:** double hung, 8/8, 6/6  
**Trim:** aluminum  
**Shutters:** (vinyl,non-functional)
- 3) **Door(s):** 1  
**Location:** side  
**Type:** wood  
**Trim:** plain
- 4) **Porch(es):**stoop, concrete stoop with 3 risers to a landing with aluminum railing


**d. Rear: Direction: east**

- 1) **Bays:** 3
- 2) **Windows:** 3, 3  
**Fenestration:** regular  
**Type:** double hung, 6/6, 8/8  
**Trim:** aluminum  
**Shutters:**
- 3) **Door(s):**  
**Location:**  
**Type:**  
**Trim:**
- 4) **Porch(es):**

**9. INTERIOR:**

**10. LANDSCAPING:** front lawn has symmetrically placed shade trees, trees to side and rear also, garage to rear

**11. OTHER COMMENTS:**



**CULTURAL RESOURCE SURVEY  
MAP FORM**


CRS # S-11015

1. ADDRESS/LOCATION: 24619 Dupont Highway
2. NOT FOR PUBLICATION  reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


**INDICATE NORTH ON SKETCH**



4. SITE PLAN:


CRS # S-11015

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-11016  
SPO Map 14-15-09  
Hundred Dagsboro  
Quad Harbeson  
Other \_\_\_\_\_

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 24597 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:
 

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

9. OTHER NOTES OR OBSERVATIONS:


CRS# S-11016

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
- 1600-1750- Contact Period (Native American)  
 1630-1730- Exploration and Frontier Settlement  
 1730-1770- Intensified and Durable Occupation  
 1770-1830- Early Industrialization  
 1830-1880- Industrialization and Early Urbanization  
 1880-1940- Urbanization and Early Suburbanization  
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |                       |   |   |
|-----------------------|---|---|
| Agriculture           |   | Transportation and Communication              |
| Forestry              |   | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      |   | Government                                    |
| Fishing/Oystering     |   | Religion                                      |
| Manufacturing         |   | Education                                     |
| Retailing/Wholesaling |   | Community Organizations                       |
| Finance               |   | Occupational Organizations                    |
| Professional Services |   | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-11016.001

1. ADDRESS/LOCATION: 24597 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch, other: irregular
5. INTEGRITY: original site  moved  
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. replacement windows

b.

6. CURRENT CONDITION: excellent good  fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1  
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): Wood Shingle
- e. Roof: shape: Side Gable  
materials: Asphalt  
cornice: boxed  
dormers:  
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 3
- 2) Windows: 2  
Fenestration: regular  
Type: double hung, 1/1  
Trim: aluminum  
Shutters: vinyl,non-functional

**Facade (cont'd)**

- 3) **Door(s):** 1
  - Location:** center
  - Type:** wood, wood & glass
  - Trim:** plain
- 4) **Porch(es):** stoop

**b. Side: Direction: south**

- 1) **Bays:** 6
- 2) **Windows:** 4
  - Fenestration:** regular
  - Type:** double hung, 1/1
  - Trim:** aluminum
  - Shutters:** (vinyl,non-functional)
- 3) **Door(s):** 2
  - Location:** center, side
  - Type:** wood, metal, wood & glass
  - Trim:** plain
- 4) **Porch(es):** stoop, concrete stop with two risers and a landing with no handrail

**c. Side: Direction: north**

- 1) **Bays:** 5
- 2) **Windows:** 5
  - Fenestration:** regular
  - Type:** double hung, 1/1
  - Trim:** aluminum
  - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
  - Location:**
  - Type:**
  - Trim:**
- 4) **Porch(es):**

**d. Rear: Direction: east**


- 1) **Bays:** 2
- 2) **Windows:** 2
  - Fenestration:** regular
  - Type:** awning, 3 pane
  - Trim:** aluminum
  - Shutters:**
- 3) **Door(s):**
  - Location:**
  - Type:**
  - Trim:**
- 4) **Porch(es):**

**9. INTERIOR:**

**10. LANDSCAPING:** set back from road, front lawn and drive, woods to rear

**11. OTHER COMMENTS:**

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-11016

1. ADDRESS/LOCATION: 24597 Dupont Highway


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11016

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-11017  
SPO Map 14-15-09  
Hundred Dagsboro  
Quad Harbeson  
Other \_\_\_\_\_

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 24577 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:
 

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
- 1600-1750- Contact Period (Native American)  
 1630-1730- Exploration and Frontier Settlement  
 1730-1770- Intensified and Durable Occupation  
 1770-1830- Early Industrialization  
 1830-1880- Industrialization and Early Urbanization  
 1880-1940- Urbanization and Early Suburbanization  
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |                       |   |   |
|-----------------------|---|---|
| Agriculture           |   | Transportation and Communication              |
| Forestry              |   | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      |   | Government                                    |
| Fishing/Oystering     |   | Religion                                      |
| Manufacturing         |   | Education                                     |
| Retailing/Wholesaling |   | Community Organizations                       |
| Finance               |   | Occupational Organizations                    |
| Professional Services |   | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-11017.001

1. ADDRESS/LOCATION: 24577 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch, other: irregular
5. INTEGRITY: original site  moved  
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. new siding

b.

6. CURRENT CONDITION: excellent good  fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1  
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block  
 basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Side Gable  
 materials: Asphalt  
 cornice:  
 dormers:  
 chimney: location(s): other: center rear slope of roof at addition, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 4
- 2) Windows: 3  
 Fenestration: irregular  
 Type: double hung, 1/1, 2/2  
 Trim: aluminum  
 Shutters:

**Facade (cont'd)**

- 3) **Door(s):** 1  
  - Location:** center
  - Type:** metal
  - Trim:** plain
- 4) **Porch(es):** stoop

**b. Side: Direction: south**

- 1) **Bays:** 2
- 2) **Windows:**  
  - Fenestration:** regular
  - Type:** double hung, 2/2
  - Trim:** aluminum
  - Shutters:**
- 3) **Door(s):**  
  - Location:**
  - Type:**
  - Trim:**
- 4) **Porch(es):**

**c. Side: Direction: north**

- 1) **Bays:** 2
- 2) **Windows:** 2  
  - Fenestration:** regular
  - Type:** double hung, 1/1
  - Trim:** wood
  - Shutters:**
- 3) **Door(s):**  
  - Location:**
  - Type:**
  - Trim:**
- 4) **Porch(es):**


**d. Rear: Direction: east**

- 1) **Bays:** 4
- 2) **Windows:** 3  
  - Fenestration:** irregular
  - Type:** double hung, 2/2
  - Trim:** aluminum
  - Shutters:**
- 3) **Door(s):** 1  
  - Location:** side
  - Type:** wood
  - Trim:** plain
- 4) **Porch(es):** stoop, wood stoop with 3 risers to landing at door, handrails on each side

**9. INTERIOR:**

**10. LANDSCAPING:** set back form road, open lawn, gravel drive, large shade trees

**11. OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-11017.002

1. ADDRESS/LOCATION: 24577 Dupont Highway

2. FUNCTION(S): historic shed current \_\_\_\_\_

3. YEAR BUILT: 1930 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: Bungalow/Craftsman

5. INTEGRITY: original site \_\_\_\_\_ moved \_\_\_\_\_  
if moved, from where \_\_\_\_\_ original location's CRS # \_\_\_\_\_ year \_\_\_\_\_

list major alterations and additions with years (if known) \_\_\_\_\_ year \_\_\_\_\_  
a. \_\_\_\_\_  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent \_\_\_\_\_ good X fair \_\_\_\_\_ poor \_\_\_\_\_

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Wood Siding Horizontal, Aluminum Siding
- d. Foundation \_\_\_\_\_
- e. Roof structural system Gable Front  
coverings Other: metal  
openings \_\_\_\_\_

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: east
  - 1) bays: \_\_\_\_\_
  - 2) windows: \_\_\_\_\_
  - 3) door(s): Count: 1; Location: center ; Type: wood  
Details: scrap wood door
  - 4) other: \_\_\_\_\_

- b. Side: direction: north
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

- c. Side: direction: south
  - 1) bays: 1
  - 2) windows: Count: 1; irregular ; fixed, plywood covering
  - 3) door(s):
  - 4) other:

- d. Rear: direction: east
  - 1) bays:
  - 2) windows:
  - 3) door(s):
  - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-11017

1. ADDRESS/LOCATION: 24577 Dupont Highway


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11017

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-11018  
SPO Map 14-15-09  
Hundred Dagsboro  
Quad Harbeson  
Other \_\_\_\_\_

- HISTORIC NAME/FUNCTION: dwelling
- ADDRESS/LOCATION: Dupont Highway Route 113
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE: building  structure  site  object   
landscape  district
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

**9. OTHER NOTES OR OBSERVATIONS:**

**CRS#** S-11018

owner claims portion built ca. 1930, exterior forms and materials consistent with post-1970


**10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):**

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
- 1600-1750- Contact Period (Native American)  
1630-1730- Exploration and Frontier Settlement  
1730-1770- Intensified and Durable Occupation  
1770-1830- Early Industrialization  
1830-1880- Industrialization and Early Urbanization  
1880-1940- Urbanization and Early Suburbanization  
X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

c) Historic period theme(s)

- |                       |   |   |
|-----------------------|---|---|
| Agriculture           |   | Transportation and Communication              |
| Forestry              |   | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      |   | Government                                    |
| Fishing/Oystering     |   | Religion                                      |
| Manufacturing         |   | Education                                     |
| Retailing/Wholesaling |   | Community Organizations                       |
| Finance               |   | Occupational Organizations                    |
| Professional Services |   | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-11018.001

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1930,1970 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, Ranch
5. INTEGRITY: original site  moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good  fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1  
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding, Brick Veneer
- e. Roof: shape: Side Gable  
materials: Asphalt  
cornice: boxed  
dormers:  
chimney: location(s): center; other: north bottom of roof slope, brick, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 5
- 2) Windows: 4
- Fenestration: irregular  
Type: double hung, 1/1  
Trim: aluminum, vinyl  
Shutters:

**Facade (cont'd)**

- 3) **Door(s):** 1  
**Location:**  
**Type:**  
**Trim:**
- 4) **Porch(es):** stoop, hood

**b. Side: Direction: north**

- 1) **Bays:** 4
- 2) **Windows:** 4  
**Fenestration:** irregular  
**Type:** double hung, 1/1  
**Trim:** aluminum, vinyl  
**Shutters:**
- 3) **Door(s):**  
**Location:**  
**Type:**  
**Trim:**
- 4) **Porch(es):**

**c. Side: Direction: south**


- 1) **Bays:** 2
- 2) **Windows:** 1  
**Fenestration:** regular  
**Type:** double hung, 1/1  
**Trim:** aluminum, vinyl  
**Shutters:**
- 3) **Door(s):** 1  
**Location:** side  
**Type:** metal  
**Trim:** plain
- 4) **Porch(es):**

**d. Rear: Direction: east**

- 1) **Bays:** 5
- 2) **Windows:** 3  
**Fenestration:** irregular  
**Type:** double hung, 1/1  
**Trim:** aluminum, vinyl  
**Shutters:**
- 3) **Door(s):** 2  
**Location:** center  
**Type:** metal  
**Trim:** plain
- 4) **Porch(es):** stoop, concrete stoop with 3 steps

9. **INTERIOR:**10. **LANDSCAPING:**11. **OTHER COMMENTS:**

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY  
MAP FORM**

CRS # S-11018

1. ADDRESS/LOCATION: Dupont Highway Route 113


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map )

**INDICATE NORTH ON SKETCH**



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-11019  
SPO Map 14-15-09  
Hundred Dagsboro  
Quad Harbeson  
Other \_\_\_\_\_

1. HISTORIC NAME/FUNCTION: Georgetown Speedway
2. ADDRESS/LOCATION: Rt. 113; Seacoast Speedway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:
 

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: grandstands
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
X	CRS 5 Structure (Building-Like) Form	
X	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:

Organization: John Milner Associates Inc. Date: 08/2005; 3/2006

**9. OTHER NOTES OR OBSERVATIONS:**

**CRS# S-11019**


As per property manager: steel grandstands and flag stand built c. 1970; ticket booths moved to site (former toll booths); 3 of the ticket booths are for public, 1 for racers; pit was originally on east side of track. NASCAR sanctioned c. 1970.

**10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):**

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
- 1600-1750- Contact Period (Native American)  
 1630-1730- Exploration and Frontier Settlement  
 1730-1770- Intensified and Durable Occupation  
 1770-1830- Early Industrialization  
 1830-1880- Industrialization and Early Urbanization  
 1880-1940- Urbanization and Early Suburbanization  
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

- c) Historic period theme(s)
- |                       |   |   |
|-----------------------|---|---|
| Agriculture           | X | Transportation and Communication              |
| Forestry              |   | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      |   | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      |   | Government                                    |
| Fishing/Oystering     |   | Religion                                      |
| Manufacturing         |   | Education                                     |
| Retailing/Wholesaling | X | Community Organizations                       |
| Finance               |   | Occupational Organizations                    |
| Professional Services |   | Major Families, Individuals and Events        |



CULTURAL RESOURCE SURVEY  
STRUCTURE (BUILDING-LIKE) FORM

CRS # S-11019.001

1. ADDRESS/LOCATION: Rt. 113 / Seacoast Speedway

2. FUNCTION: bleachers / grandstand IN USE?

3. YEAR BUILT: 1949 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/PLAN: Rectangular shaped, concrete-block grandstand with built-in bathrooms underneath seating area.

5. INTEGRITY: original site  moved   
if moved, from where original location's CRS # year

list major alterations and additions with dates (if known) year  
a. Only two original grandstands remain  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION (describe the structure as completely as possible):

a) Overall shape Rectangular  
height 12 ft.  
length 25 ft.  
width 60 ft.

b) Structural system: Concrete Block

c) Foundation:


d) Exterior covering:

7. DESCRIPTION (cont'd):

CRS # S-11019.001

e) Openings Open seating; bathrooms on north side (built into bottom of seating area.)

f) Other features Two steel bleachers in pit area; four steel bleachers in general grandstand area; these bleachers are not original (1970's)



CULTURAL RESOURCE SURVEY  
STRUCTURE (BUILDING-LIKE) FORM

CRS # S-11019.002

1. ADDRESS/LOCATION: Rt. 113 / Seacoast Speedway

2. FUNCTION: bleachers / grandstand IN USE?

3. YEAR BUILT: 1949 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/PLAN: Rectangular shaped, concrete-block grandstand with built-in bathrooms underneath seating area.

5. INTEGRITY: original site  moved   
if moved, from where original location's CRS # year

list major alterations and additions with dates (if known) year  
a. Only two original grandstands remain  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION (describe the structure as completely as possible):

a) Overall shape Rectangular  
height 12 ft.  
length 25 ft.  
width 60 ft.

b) Structural system: Concrete Block

c) Foundation:


d) Exterior covering:

7. DESCRIPTION (cont'd):

CRS # S-11019.002

e) Openings Open seating; bathrooms on north side (built into bottom of seating area.)

f) Other features Two steel bleachers in pit area; four steel bleachers in general grandstand area; these bleachers are not original (1970's)



CULTURAL RESOURCE SURVEY  
STRUCTURE (LAND FEATURE) FORM

CRS # S-11019.003

1. ADDRESS/LOCATION: Rt. 113 / Seacoast Speedway

2. FUNCTION: Race track

3. YEAR BUILT: 1949 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. INTEGRITY:

list major changes with years (if known)

	<u>year</u>
a. Inner track built	1998
b.	

5. CURRENT CONDITION:      excellent       good       fair       poor


6. DESCRIPTION:

a) Circulation system    Dirt track in oval shape; 1/2 mile lap; pit road on south end of track; two pit locations on south end; berm on south end; retaining wall on north side; oval (outside measurement) 1100' x 580'

b) Spatial subdivisions    Retaining wall; in-field; pit grandstands; drag dtrip; general grandstands; flag tower; concession stand; ticket booths; general public parking area.

c) Retaining wall/lining material(s)    Concrete block

d) Other    Reatining wall along north side of track only; advertisement facing along remaining sides; reflectors (poles with tires) sporadically placed in in-field.



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # S-11019

1. ADDRESS/LOCATION: Rt. 113; Seacoast Speedway
2. NOT FOR PUBLICATION  reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11019

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-11020  
SPO Map 14-15-09  
Hundred Dagsboro  
Quad Harbeson  
Other \_\_\_\_\_

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 24255 Dupont Boulevard
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:
 

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11020


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
- 1600-1750- Contact Period (Native American)  
1630-1730- Exploration and Frontier Settlement  
1730-1770- Intensified and Durable Occupation  
1770-1830- Early Industrialization  
1830-1880- Industrialization and Early Urbanization  
1880-1940- Urbanization and Early Suburbanization  
X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - X Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

c) Historic period theme(s)

- |                       |   |   |
|-----------------------|---|---|
| Agriculture           |   | Transportation and Communication              |
| Forestry              |   | Settlement Patterns and Demographic Changes   |
| Trapping/Hunting      | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying      |   | Government                                    |
| Fishing/Oystering     |   | Religion                                      |
| Manufacturing         |   | Education                                     |
| Retailing/Wholesaling |   | Community Organizations                       |
| Finance               |   | Occupational Organizations                    |
| Professional Services |   | Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-11020.001

1. ADDRESS/LOCATION: 24255 Dupont Boulevard
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch
5. INTEGRITY: original site  moved  
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good  fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories:  
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Side Gable  
materials: Asphalt  
cornice: boxed  
dormers:  
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 5
- 2) Windows: 4  
Fenestration: regular  
Type: double hung, 1/1, 8/8  
Trim: aluminum  
Shutters: vinyl,non-functional

**Facade (cont'd)**

- 3) **Door(s):** 1
  - Location:**
  - Type:** metal
  - Trim:** plain
- 4) **Porch(es):** stoop

**b. Side: Direction: south**

- 1) **Bays:** 2
- 2) **Windows:** 1
  - Fenestration:** regular
  - Type:** double hung, 1/1
  - Trim:** aluminum
  - Shutters:** (vinyl,non-functional)
- 3) **Door(s):** 1
  - Location:** center
  - Type:** metal
  - Trim:** plain
- 4) **Porch(es):**

**c. Side: Direction: north**

- 1) **Bays:**
- 2) **Windows:**
  - Fenestration:** regular
  - Type:** double hung, 1/1
  - Trim:** aluminum
  - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
  - Location:**
  - Type:**
  - Trim:**
- 4) **Porch(es):**

**d. Rear: Direction: east**


- 1) **Bays:** 6
- 2) **Windows:** 5
  - Fenestration:** irregular
  - Type:** double hung, 1/1
  - Trim:** aluminum
  - Shutters:** vinyl,non-functional
- 3) **Door(s):** 1
  - Location:** center
  - Type:** metal
  - Trim:** plain
- 4) **Porch(es):** vestibule (enclosed entrance), screened square enclosure with awning windows, wood stoop with 3 risers to landing

**9. INTERIOR:**

**10. LANDSCAPING:** set in a mown lawn with very few trees or other plantings

**11. OTHER COMMENTS:**

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY  
MAP FORM**

CRS # S-11020

1. ADDRESS/LOCATION: 24255 Dupont Boulevard


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


**INDICATE NORTH ON SKETCH**



4. SITE PLAN:

CRS # S-11020

INDICATE NORTH ON PLAN



USE BLACK INK ONLY