

DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11021
SPO Map 14-15-09
Hundred Dagsboro
Quad Harbeson
Other _____

- HISTORIC NAME/FUNCTION: dwelling
- ADDRESS/LOCATION: Dupont Highway Route 113
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE: building structure site object
landscape district
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Terry Necciai

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11021


could have been built after 1962

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11021.001

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1960-1990 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch, central hall
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year
 a. several small additions to rear, surface materials all date 1980-2000
 b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Side Gable
 materials: Asphalt
 cornice: boxed
 dormers:
 chimney: location(s): center, other: metal flue pipe

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 5
- 2) Windows: 4
 Fenestration: irregular
 Type: double hung, 6/6
 Trim: aluminum
 Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** metal
 - Trim:** plain
- 4) **Porch(es):** stoop

b. Side: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 6/6
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:** 1
- 2) **Windows:** 1
 - Fenestration:** regular
 - Type:** double hung, 6/6
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):** 1
 - Location:**
 - Type:** metal
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: east


- 1) **Bays:**
- 2) **Windows:** 4
 - Fenestration:** irregular
 - Type:** double hung, 6/6, 8/8
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):** 1
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):** other, wood deck surrounding oak tree

9. INTERIOR:

10. **LANDSCAPING:** set in grove of trees with large asphalt area connecting to a commercial property.

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-11021

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11021

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11026
SPO Map 14-15-11
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: vacant/not in use
2. ADDRESS/LOCATION: 20171 Wilson Road
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: vacant/not in use
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|--|
| <ul style="list-style-type: none"> X Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services | <ul style="list-style-type: none"> X Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11026.001

1. ADDRESS/LOCATION: 20171 Wilson Road
2. FUNCTION(S): historic current vacant/not in use
3. YEAR BUILT: 1900 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided with asbestos

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: T-Plan Stories: 2
Additions:
- b. Structural system (if known): concrete block
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Asbestos
- e. Roof: shape: Cross Gable
materials: Asphalt
cornice:
dormers:
chimney: location(s): interior, gable, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: south
- 1) Bays: 2
- 2) Windows: 3, 1
Fenestration: regular
Type: 1/1, 2/2
Trim:
Shutters: wood, functional

Facade (cont'd)

- 3) **Door(s):** 1
Location: center
Type: wood & glass
Trim: plain
- 4) **Porch(es):** entry

b. Side: Direction: east

- 1) **Bays:**
- 2) **Windows:** 1, 4
Fenestration: regular
Type: awning, 1/1
Trim: wood
Shutters:
- 3) **Door(s):** 1
Location: center
Type: wood
Trim: plain
- 4) **Porch(es):** other, single story shed-roof porch enclosure covered in asbestos. double hung 2/2 windows and wood replacement door

c. Side: Direction: west

- 1) **Bays:**
- 2) **Windows:** 0, 4
Fenestration:
Type: double hung, 1/2, 2/2
Trim: wood
Shutters:
- 3) **Door(s):** 1
Location: center
Type: wood & glass
Trim: plain
- 4) **Porch(es):** other, single-story shed-roof porch enclosure covered in asbestos, double hung 2/2 windows, wood and glass door


d. Rear: Direction: north

- 1) **Bays:**
- 2) **Windows:**
Fenestration:
Type:
Trim:
Shutters:
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Wilson Rd., fenced perimeter, dirt track to rear of dwelling, outbuilding to northeast

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11026.002

1. ADDRESS/LOCATION: 20171 Wilson Road

2. FUNCTION(S): historic shed current _____

3. YEAR BUILT: 1920 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____
a. _____
b. _____

6. CURRENT CONDITION: excellent _____ good _____ fair X poor _____

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Wood Siding Horizontal
- d. Foundation other: supported on metal pipes
- e. Roof structural system Gable Front
coverings Asbestos
openings _____

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: south
 - 1) bays: 1
 - 2) windows: _____
 - 3) door(s): Count: 1; Location: center ; Type: wood
 - 4) other: _____

- b. Side: direction: east
 - 1) bays: 1
 - 2) windows: ; regular ; awning
 - 3) door(s):
 - 4) other:

- c. Side: direction: west
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: north
 - 1) bays:
 - 2) windows:
 - 3) door(s):
Details: no access to this side.
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11026.003

1. ADDRESS/LOCATION: 20171 Wilson Road

2. FUNCTION(S): historic equipment shed current _____

3. YEAR BUILT: 1930s CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____

a. _____

b. _____

6. CURRENT CONDITION: excellent _____ good _____ fair **X** _____ poor _____

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Vertical

d. Foundation other: none

e. Roof structural system Shed
coverings Other: metal
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: south

1) bays: 2

2) windows:

3) door(s): Count: 2
Details: open bays

4) other:

- b. Side: direction: east
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: west
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: north
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11026

1. ADDRESS/LOCATION: 20171 Wilson Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11026

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11032
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

- 1. HISTORIC NAME/FUNCTION: dwelling
- 2. ADDRESS/LOCATION: North Bedford Street
- 3. TOWN/NEAREST TOWN: Georgetown vicinity?
- 4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
- 5. MAIN FUNCTION OF PROPERTY: domestic
- 6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 08/2005; 10/2008

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11032


built by the late Howard Clendaniel

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11032.001

1. ADDRESS/LOCATION: North Bedford Street
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1935 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in aluminum

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Gable Front
materials: Composition
cornice: exposed rafter ends
dormers: gabled wall dormers on both sides
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: southwest
- 1) Bays: 3
- 2) Windows: 2, 1
Fenestration: regular
Type: double hung, 4/1
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
Location: center
Type: wood & glass
Trim: sidelights
- 4) **Porch(es):** wrap-around

b. Side: Direction: southeast

- 1) **Bays:** 3
- 2) **Windows:** 3
Fenestration:
Type: double hung, other: bay, 4/1, 3/1
Trim: wood
Shutters:
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):** wrap-around, continued porch from front

c. Side: Direction: northwest

- 1) **Bays:** 3
- 2) **Windows:** 3
Fenestration: regular
Type: double hung, 4/1
Trim: wood
Shutters:
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**


d. Rear: Direction: northeast

- 1) **Bays:** 3
- 2) **Windows:** 2, 1
Fenestration: regular
Type: double hung, 4/1, 2/1
Trim: wood
Shutters:
- 3) **Door(s):** 1
Location: center
Type: other: fiberglass
Trim: plain
- 4) **Porch(es):** other: see porch details, modern wood stoop

9. INTERIOR:

- 10. **LANDSCAPING:** faces N. Bedford, gravel driveway to side of dwelling, agricultural fields to rear of dwelling, tall trees shade one side of property

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11032.002

1. ADDRESS/LOCATION: North Bedford Street

2. FUNCTION(S): historic shed current _____

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Vertical

d. Foundation other: none

e. Roof structural system Gable Front
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southeast

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center
Details: open bay

4) other:

- b. **Side: direction:** southwest
 - 1) **bays:** 1
 - 2) **windows:** Count: 1; regular ; fixed, 2 pane
 - 3) **door(s):**
 - 4) **other:**

- c. **Side: direction:** northeast
 - 1) **bays:** 1
 - 2) **windows:** Count: 1; regular ; fixed, 2 pane
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** northwest
 - 1) **bays:**
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-11032


1. ADDRESS/LOCATION: North Bedford Street
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11044
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 11 Seashore Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 11/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11044.001

1. ADDRESS/LOCATION: 11 Seashore Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, WWII-Era Cottage, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. full width addition across rear, 1-story, shed-roof, hopper windows

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: panel-faced concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Side Gable
materials: Asphalt
cornice:
dormers:
chimney: location(s): exterior, gable, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: northeast
- 1) Bays: 3
- 2) Windows: 2, 1
Fenestration: regular
Type: double hung, 6/6
Trim: wood
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** inset

b. Side: Direction: southeast

- 1) **Bays:** 4
- 2) **Windows:** 3
 - Fenestration:** regular
 - Type:** double hung, 6/1
 - Trim:** wood
 - Shutters:** (vinyl, non-functional)
- 3) **Door(s):** 1
 - Location:** side
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** other: metal awning

c. Side: Direction: northwest

- 1) **Bays:** 3
- 2) **Windows:** 3, 1
 - Fenestration:** regular
 - Type:** double hung, 6/6
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: southwest

- 1) **Bays:**
- 2) **Windows:**
 - Fenestration:**
 - Type:** other: obscured by rear addition
 - Trim:**
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Seashore Hwy., trees across front and rear lawn, driveway to one side of dwelling

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11044.002

1. ADDRESS/LOCATION: 11 Seashore Highway

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. addition attached to northwest side, shed-roof; addition attached to rear, gabled roof

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Aluminum Siding

d. Foundation concrete block

e. Roof structural system Gable Front
coverings Wood
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: northeast

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: other: vinyl garage door

4) other:

- b. **Side: direction:** southeast
 - 1) **bays:**
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

- c. **Side: direction:** northwest
 - 1) **bays:**
 - 2) **windows:** ; other: obscured by addition
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** southwest
 - 1) **bays:**
 - 2) **windows:** ; other: obscured by rear addition
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-11044

1. ADDRESS/LOCATION: 11 Seashore Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH




4. SITE PLAN:

CRS # S-11044

INDICATE NORTH ON PLAN



USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11046
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

- HISTORIC NAME/FUNCTION: Peninsula Financial Group
- ADDRESS/LOCATION: Seashore Highway
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE: building structure site object
landscape district
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11046.001

1. ADDRESS/LOCATION: Seashore Highway
2. FUNCTION(S): historic current commerce/trade
3. YEAR BUILT: 1935 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. resided in vinyl, replacement windows and doors, upper level addition, rear addition 1.5 story with gambrel roof, modern wood staircase on rear facade accessing 2nd level
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Side Gable
materials: Other: metal
cornice: other: enclosed
dormers: two gabled dormers across front
chimney: location(s): exterior, gable, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: northeast
- 1) Bays: 3
- 2) Windows: 2, 1
Fenestration:
Type: double hung, 6/6
Trim: vinyl
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** other: fiberglass
 - Trim:** plain
- 4) **Porch(es):** inset

b. Side: Direction: southeast

- 1) **Bays:** 4
- 2) **Windows:** 4, 2
 - Fenestration:** regular
 - Type:** double hung, 6/6
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: northwest

- 1) **Bays:** 2
- 2) **Windows:** 2, 1
 - Fenestration:** regular
 - Type:** double hung, 6/6
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: southwest


- 1) **Bays:**
- 2) **Windows:**
 - Fenestration:**
 - Type:** other: obscured by large addition
 - Trim:**
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. **LANDSCAPING:** faced Seashore Hwy., tall tree to rear of lot, large parking lot to southeast side of building

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-11046

1. ADDRESS/LOCATION: Seashore Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11047
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 15 Seashore Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11047.001

1. ADDRESS/LOCATION: 15 Seashore Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1945 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: WWII-Era Cottage
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. window replacement

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Asbestos
- e. Roof: shape: Side Gable
 materials: Composition
 cornice:
 dormers:
 chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: north
- 1) Bays: 3
- 2) Windows: 2
 Fenestration: regular
 Type: double hung, other: bay with center fixed bay and flanking 1/1, 1/1
 Trim: aluminum, vinyl
 Shutters: vinyl, non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** side
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** inset

b. Side: Direction: west

- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** wood
 - Shutters:** (vinyl, non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: east

- 1) **Bays:**
- 2) **Windows:**
 - Fenestration:**
 - Type:** other: obscured by tall shrubs
 - Trim:**
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: south


- 1) **Bays:** 4
- 2) **Windows:** 3
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** other: see porch details, modern wood deck

9. INTERIOR:

10. LANDSCAPING: faces Seashore Hwy., shared gravel driveway to one side, shrubs across front and side facades

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**


CRS # S-11047

1. ADDRESS/LOCATION: 15 Seashore Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11047

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11048
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 18 Seashore Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11048.001

1. ADDRESS/LOCATION: 18 Seashore Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1935 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, Vernacular, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Asbestos
- e. Roof: shape: Gable Front
materials: Asphalt
cornice: exposed rafter ends
dormers:
chimney: location(s): other: exterior/side, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: south
- 1) Bays: 3
- 2) Windows: 2, 1
Fenestration: regular
Type: double hung, 1/1
Trim: vinyl
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 Location: center
 Type: other: obscured
 Trim:
- 4) **Porch(es):** full-width

b. Side: Direction: west

- 1) **Bays:** 3
- 2) **Windows:** 3
 Fenestration: regular
 Type: double hung, 1/1
 Trim: vinyl
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

c. Side: Direction: east

- 1) **Bays:** 3
- 2) **Windows:** 3
 Fenestration: regular
 Type: double hung, 1/1
 Trim: vinyl
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

d. Rear: Direction: north


- 1) **Bays:** 4
- 2) **Windows:** 4
 Fenestration: regular
 Type: double hung, other: obscured by extension, 1/1
 Trim: vinyl
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

9. INTERIOR:

- 10. **LANDSCAPING:** faces Seashore Hwy., paved driveway to west side of dwelling, trees and shrubs planted across rear and front lawn

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**


CRS # S-11048

1. ADDRESS/LOCATION: 18 Seashore Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11049
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

- HISTORIC NAME/FUNCTION: dwelling
- ADDRESS/LOCATION: 17 Seashore Highway
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE: building structure site object
landscape district
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11049.001

1. ADDRESS/LOCATION: 17 Seashore Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1945 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: WWII-Era Cottage, central hall
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Asbestos
- e. Roof: shape: Side Gable
 materials: Composition
 cornice:
 dormers:
 chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: north
- 1) Bays: 3
- 2) Windows: 2
 Fenestration: regular
 Type: double hung, 2/2
 Trim: wood
 Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** inset, entry

b. Side: Direction: east

- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 2/2
 - Trim:** wood
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: west

- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 2/2
 - Trim:** wood
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: south


- 1) **Bays:** 4
- 2) **Windows:** 3
 - Fenestration:** regular
 - Type:** double hung, 2/2
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** other: see porch details, concrete steps

9. INTERIOR:

10. **LANDSCAPING:** faces Seashore Hwy., shared gravel driveway to one side, tall trees to rear of property

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**


CRS # S-11049

1. ADDRESS/LOCATION: 17 Seashore Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11049

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11050
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 22 Seashore Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11050

built by Mr. Ed Rust; he also built other houses in the area

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- 1830-1880- Industrialization and Early Urbanization
- X 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11050.001

1. ADDRESS/LOCATION: 22 Seashore Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1932 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, Vernacular, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. resided in aluminum, replacement windows and doors enclosed porch on west end, 1-story hipped-roof extension of west end, 1-room in size, doors on front and back
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Side Gable
materials: Composition
cornice:
dormers:
chimney: location(s): other: rear, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: south
- 1) Bays: 4
- 2) Windows: 3
Fenestration: irregular
Type: double hung, 1/1
Trim: vinyl
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** other: fiberglass
 - Trim:** plain
- 4) **Porch(es):** hood

b. Side: Direction: east

- 1) **Bays:**
- 2) **Windows:** , 1
 - Fenestration:** regular
 - Type:** double hung, other: obscured by enclosed porch, 3/1
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: west

- 1) **Bays:** 1
- 2) **Windows:** 1, 1
 - Fenestration:** regular
 - Type:** double hung, other: obscured by extension, 3/1, 1/1
 - Trim:** wood, vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: north

- 1) **Bays:** 4
- 2) **Windows:** 4
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

- 10. **LANDSCAPING:** faces Seashore Hwy., paved driveway to east side of dwelling, trees and shrubs across rear and front lawn

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11050.002

1. ADDRESS/LOCATION: 22 Seashore Highway

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1932 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site X moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. garage door replacement, one bay covered by wood paneling

b. _____

6. CURRENT CONDITION: excellent good X fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Asbestos

d. Foundation concrete block

e. Roof structural system Gable Front
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: south

1) bays: 3

2) windows:

3) door(s): Count: 3; Location: other: side by side ; Type: other: garage door
Details: 1 door southwest side, 2 doors are side-by-side

4) other:

- b. Side: direction: west
 - 1) bays: 1
 - 2) windows: Count: 1; regular ; double hung, 3/1
 - 3) door(s):
 - 4) other:

- c. Side: direction: east
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: north
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901


CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11050

1. ADDRESS/LOCATION: 22 Seashore Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.
(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11050

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11051
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 24 Seashore Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

9. OTHER NOTES OR OBSERVATIONS:


CRS# S-11051

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11051.001

1. ADDRESS/LOCATION: 24 Seashore Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1935 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. resided in vinyl, replacement windows and doors, porch enclosure across front, shed-roof addition to rear, 1-room in size
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Cross Gable
materials: Asphalt
cornice:
dormers: shed-roof dormer across rear with modern 6/6 windows
chimney: location(s): exterior, gable; other: rear, brick, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: south
- 1) Bays: 3
- 2) Windows: 2
Fenestration: regular
Type: double hung, 6/6
Trim: vinyl
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** other: fiberglass
 - Trim:** plain
- 4) **Porch(es):** inset

b. Side: Direction: east

- 1) **Bays:** 4
- 2) **Windows:** 3, 1
 - Fenestration:** regular
 - Type:** double hung, 6/6
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** side
 - Type:** other: fiberglass
 - Trim:** plain
- 4) **Porch(es):** other: see porch details, brick stoop with aluminum railing

c. Side: Direction: west

- 1) **Bays:** 3
- 2) **Windows:** 3, 1
 - Fenestration:** regular
 - Type:** double hung, 6/6
 - Trim:** vinyl
 - Shutters:** (vinyl, non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: north


- 1) **Bays:** 3
- 2) **Windows:** 3
 - Fenestration:** regular
 - Type:** double hung, other: obscured by addition, 6/6
 - Trim:** vinyl
 - Shutters:** vinyl, non-functional
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Seashore Hwy., paved driveway to east side of dwelling, trees and shrubs across front and rear lawns

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-11051

1. ADDRESS/LOCATION: 24 Seashore Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-11051

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9