

DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11221
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: Nationwide Insurance
2. ADDRESS/LOCATION: West North Street
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: commerce/trade
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:


Organization: John Milner Associates Inc. Date: 09/2006

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11221.001

1. ADDRESS/LOCATION: West North Street
2. FUNCTION(S): historic current commerce/trade
3. YEAR BUILT: 1935 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, Vernacular, side hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. resided in vinyl, replacement doors and windows, modern porch entrance, new roof material, rear 1-story shed-roof addition, 1-room in size, modern vinyl deck attached to rear entrance
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: other: obscured by poured concrete
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Side Gable
materials: Other: metal
cornice: other: enclosed
dormers: gable front dormer on front with pair of fixed 4-pane windows
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: north
- 1) Bays: 2
- 2) Windows: 1
Fenestration: irregular
Type: double hung, 4/4, 6/6
Trim: vinyl
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** corner
 - Type:** commercial glass
 - Trim:** plain
- 4) **Porch(es):** portico

b. Side: Direction: west

- 1) **Bays:** 3
- 2) **Windows:** 3, 1
 - Fenestration:** regular
 - Type:** double hung, 6/6
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: east

- 1) **Bays:** 4
- 2) **Windows:** 4, 1
 - Fenestration:** irregular
 - Type:** double hung, fixed, 6/6, 4 pane
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: south

- 1) **Bays:**
- 2) **Windows:** 1
 - Fenestration:** regular
 - Type:** double hung, other: obscured by rear addition, 6/6
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):** 1
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: east side of Rt. 113, faces roadway, modern apartments further east, mixed commercial and residential area

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11221.002

1. ADDRESS/LOCATION: West North Street

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____

a. resided in vinyl, replacement doors

b. _____

6. CURRENT CONDITION: excellent _____ good X fair _____ poor _____

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Vinyl Siding

d. Foundation concrete block

e. Roof
structural system Gable Front
coverings Other: metal
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: east

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: other: vinyl garage door

4) other:

- b. Side: direction: south
 - 1) bays: 1
 - 2) windows:
 - 3) door(s): Count: 1; Location: side ; Type: other: fiberglass
 - 4) other:

- c. Side: direction: north
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: west
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11221

1. ADDRESS/LOCATION: West North Street


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11221

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11233
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 50 Bramhall Road
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#: Form:	List property types:
X CRS 2 Main Building Form	
X CRS 3 Secondary Building Form	
CRS 4 Archaeological Site Form	
CRS 5 Structure (Building-Like) Form	
CRS 6 Structure (Land Feature) Form	
CRS 7 Object Form	
CRS 8 Landscape Elements Form	
X CRS 9 Map Form	N/A
CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2006

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11233.001

1. ADDRESS/LOCATION: 50 Bramhall Road
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1929 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, Vernacular, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in vinyl

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Gable Front
materials: Asphalt
cornice:
dormers:
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: south
- 1) Bays: 3
- 2) Windows: 2, 1
Fenestration: regular
Type: double hung, 1/1
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** full-width

b. Side: Direction: east

- 1) **Bays:** 3
- 2) **Windows:** 3
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: west

- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: north

- 1) **Bays:**
- 2) **Windows:** 0, 1
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):** other, shed-roof rear porch enclosure covered in vinyl with shed-roof attachment

9. INTERIOR:

- 10. **LANDSCAPING:** faces roadway, gravel driveway circles to rear of house, tall trees to rear of property, out buildings to rear

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11233.002

1. ADDRESS/LOCATION: 50 Bramhall Road

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1929 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. bays obscured by plywood; modern garage door put on one side

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories

c. Wall coverings

d. Foundation rusticated concrete block

e. Roof
structural system Side Gable
coverings Other: metal
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: south

1) bays: 3

2) windows: Count: 1; irregular ; double hung, 2/2

3) door(s): Count: 2; Location: other: irregular ; Type: other: covered by plywood/ metal garage door

4) other:

b. Side: direction: east

1) bays: 2

2) windows: Count: 2; other: covered by plywood

3) door(s):

4) other:

c. Side: direction: west

1) bays: 2

2) windows: Count: 2; other: covered by plywood

3) door(s):

4) other:

d. Rear: direction: north

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: wood, other: sliding door

4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11233

1. ADDRESS/LOCATION: 50 Bramhall Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11233

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11238
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

- HISTORIC NAME/FUNCTION: McCabe's Mechanical
- ADDRESS/LOCATION: 404 Dupont Highway
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
- MAIN FUNCTION OF PROPERTY: commercial building
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 10/2006

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|--|
| <ul style="list-style-type: none"> Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing X Retailing/Wholesaling Finance Professional Services | <ul style="list-style-type: none"> Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11238.001

1. ADDRESS/LOCATION: 404 Dupont Highway
2. FUNCTION(S): historic commercial current commerce/trade, domestic
3. YEAR BUILT: 1950 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN:
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. former bays enclosed with siding, 2-story gabled addition to rear, all windows have been replaced

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 2
 Additions:
- b. Structural system (if known): concrete block
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Brick Veneer
- e. Roof: shape: Gable Front
 materials: Other: metal
 cornice:
 dormers:
 chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 3
- 2) Windows: 2, 2
 Fenestration: irregular
 Type: double hung, fixed, 1/1, single pane
 Trim: vinyl
 Shutters: other: vinyl awnings

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood
 - Trim:** plain
- 4) **Porch(es):** wrap-around

b. Side: Direction: north

- 1) **Bays:** 4
- 2) **Windows:** 1, 4
 - Fenestration:** regular
 - Type:** double hung, fixed, 1/1, single pane
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:** 3
- 2) **Windows:** 0, 3
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):** wrap-around, continuation of wrap around porch from front

d. Rear: Direction: east


- 1) **Bays:**
- 2) **Windows:**
 - Fenestration:**
 - Type:** other: obscured by large 2-sty gabled addition
 - Trim:**
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

- 10. **LANDSCAPING:** faces Rt. 113, paved drive and parking lot to south side of building, modern garage southwest of main building

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S-11238

1. ADDRESS/LOCATION: 404 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11238

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11239
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: Commercial Building
2. ADDRESS/LOCATION: 418 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: commercial strip
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2006

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11239


multiple businesses

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|--|
| <ul style="list-style-type: none"> Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing X Retailing/Wholesaling Finance Professional Services | <ul style="list-style-type: none"> Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11239.001

1. ADDRESS/LOCATION: 418 Dupont Highway
2. FUNCTION(S): historic commercial current commerce/trade
3. YEAR BUILT: 1950 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN:
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. rectangular-shaped addition to rear; 1-sty; northeast corner

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
 Additions:
- b. Structural system (if known): concrete block
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding, Brick Veneer
- e. Roof: shape: Flat
 materials:
 cornice:
 dormers:
 chimney: location(s): other: exterior/side, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 3
- 2) Windows:
 Fenestration:
 Type: fixed
 Trim: aluminum
 Shutters:

Facade (cont'd)

- 3) **Door(s):** 3
 - Location:**
 - Type:** commercial glass
 - Trim:** transom
- 4) **Porch(es):** other: modern awning

b. Side: Direction: north

- 1) **Bays:** 1
- 2) **Windows:** 1
 - Fenestration:** irregular
 - Type:** double hung, 1/1
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:**
- 2) **Windows:**
 - Fenestration:**
 - Type:**
 - Trim:**
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: east


- 1) **Bays:** 4
- 2) **Windows:**
 - Fenestration:**
 - Type:**
 - Trim:**
 - Shutters:**
- 3) **Door(s):** 3
 - Location:** other: irregular
 - Type:** metal
 - Trim:** plain
- 4) **Porch(es):**

9. INTERIOR:

10. **LANDSCAPING:** faces Rt. 113, large paved parking area to south side and east side of building

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S-11239

1. ADDRESS/LOCATION: 418 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11240
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: Rogers Graphics
2. ADDRESS/LOCATION: 508 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: commercial building
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|--|
| <ul style="list-style-type: none"> Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing X Retailing/Wholesaling Finance Professional Services | <ul style="list-style-type: none"> Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11240.001

1. ADDRESS/LOCATION: 508 Dupont Highway
2. FUNCTION(S): historic commercial current commerce/trade
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. sided in stucco, 1-story concrete block addition on south side gabled enclosed entrance of north side

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): concrete block
- c. Foundation: materials: brick
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Stucco
- e. Roof: shape: Other: barrel-shaped
materials: Other: tar paper and asphalt
cornice:
dormers:
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: Direction: west
- 1) Bays: 7
- 2) Windows: 5
- Fenestration: irregular
- Type: double hung, fixed, hopper, 1/1, single pane
- Trim: aluminum, vinyl
- Shutters:

Facade (cont'd)

- 3) **Door(s):** 2
 - Location:** center, side
 - Type:** other: fiberglass
 - Trim:** plain
- 4) **Porch(es):** other: cloth awnings

b. Side: Direction: south

- 1) **Bays:**
- 2) **Windows:**
 - Fenestration:**
 - Type:** other: obscured by addition
 - Trim:**
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: north

- 1) **Bays:** 6
- 2) **Windows:** 4
 - Fenestration:** irregular
 - Type:** fixed, other: glass blocks, multi pane
 - Trim:** aluminum, steel
 - Shutters:**
- 3) **Door(s):** 2
 - Location:** corner
 - Type:** commercial glass, other: garage door, other
 - Trim:** plain
- 4) **Porch(es):** other: cloth and metal, 1 cloth awning, 1 metal awning

d. Rear: Direction: east


- 1) **Bays:** 3
- 2) **Windows:** 3
 - Fenestration:** regular
 - Type:** other: glass block, multi pane
 - Trim:**
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Rt. 113, gravel driveway across front, paved parking lot to north side and rear

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S-11240

1. ADDRESS/LOCATION: 508 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11241
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: American Legion Sussex Post #8
2. ADDRESS/LOCATION: North Bedford Street
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: Kiwanis clubhouse
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | X | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11241.001

1. ADDRESS/LOCATION: North Bedford Street
2. FUNCTION(S): historic institutional current social
3. YEAR BUILT: 1950 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, Other: roadside/log cabin
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. east and north sides re-sided in vertical wood paneling; modern door and windows
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: T-Plan Stories: 1
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Other: log
- e. Roof: shape: Cross Gable
materials: Composition
cornice: exposed rafter ends
dormers:
chimney: location(s): other: rear, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 3
- 2) Windows: 2
Fenestration: regular
Type: double hung, 1/1
Trim: vinyl
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** other: fiberglass
 - Trim:** plain
- 4) **Porch(es):**

b. Side: Direction: north

- 1) **Bays:** 6
- 2) **Windows:** 6
 - Fenestration:** irregular
 - Type:** double hung, casement, 1/1, double pane casement
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: west

- 1) **Bays:** 6
- 2) **Windows:** 5
 - Fenestration:** regular
 - Type:** double hung, casement, 1/1, pane and double pane casement
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** side
 - Type:** other: fiberglass
 - Trim:** plain
- 4) **Porch(es):**

d. Rear: Direction: south


- 1) **Bays:** 3
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** casement, double pane
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** center
 - Type:** other: fiberglass
 - Trim:** plain
- 4) **Porch(es):**

9. INTERIOR:

- 10. **LANDSCAPING:** building faces N. Bedford, wedged between Rt. 113 and N. Bedford, semi-circular driveway to front of building tall trees grow to south side

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-11241

1. ADDRESS/LOCATION: North Bedford Street
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11241

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11242
SPO Map 14-15-11
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 2007 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11242.001

1. ADDRESS/LOCATION: 2007 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1945 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, double pen
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: L-Plan Stories: 1
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Asbestos
- e. Roof: shape: Cross Gable
 materials: Composition
 cornice:
 dormers:
 chimney: location(s): other: interior/side, brick, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 5
- 2) Windows: 3
 Fenestration: regular
 Type: double hung, 6/6
 Trim: wood
 Shutters:

Facade (cont'd)

- 3) **Door(s):** 2
 Location: side
 Type: wood & glass
 Trim: plain
- 4) **Porch(es):**

b. Side: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 2
 Fenestration: regular
 Type: double hung, 6/6
 Trim: wood
 Shutters: (wood,non-functional)
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:** 2
- 2) **Windows:** 2
 Fenestration: regular
 Type: double hung, 6/6, 1/1
 Trim: wood, vinyl
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

d. Rear: Direction: east


- 1) **Bays:** 1
- 2) **Windows:** 1
 Fenestration: irregular
 Type: double hung, 6/6
 Trim: wood
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Rt. 113, driveway on south side of property, modern outbuilding to rear (east side) of property, tall trees of perimeter edges of property

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-11242

1. ADDRESS/LOCATION: 2007 Dupont Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11242

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11243
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

- HISTORIC NAME/FUNCTION: Comcast and Shore Distributers
- ADDRESS/LOCATION: Dupont Highway Route 113
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE: building structure site object
landscape district
- MAIN FUNCTION OF PROPERTY: commercial building
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 10/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|--|
| <ul style="list-style-type: none"> Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing X Retailing/Wholesaling Finance Professional Services | <ul style="list-style-type: none"> Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11243.001

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. FUNCTION(S): historic commercial current commerce/trade
3. YEAR BUILT: 1945 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN:
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. resided in vinyl, modern doors and windows, enclosed glass vestibule entry on south side, 1-story flat-roof
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 2
 Additions:
- b. Structural system (if known): concrete block
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Flat
 materials:
 cornice:
 dormers:
 chimney: location(s): other: interior/side, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 4
- 2) Windows: 4
 Fenestration: regular
 Type: casement, single pane
 Trim: vinyl
 Shutters:

Facade (cont'd)

- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

b. Side: Direction: south

- 1) **Bays: 11**
- 2) **Windows: 3, 1**
 - Fenestration:** regular
 - Type:** casement, fixed, single and multi pane
 - Trim:** steel, vinyl
 - Shutters:**
- 3) **Door(s): 8**
 - Location:** other: side by side
 - Type:** commercial glass, other: aluminum and vinyl garage doors
 - Trim:** plain
- 4) **Porch(es):**

c. Side: Direction: north

- 1) **Bays: 11**
- 2) **Windows: 8, 2**
 - Fenestration:** regular
 - Type:** casement, fixed, single and multi pane
 - Trim:** steel, vinyl
 - Shutters:**
- 3) **Door(s): 3**
 - Location:** side, other: irregular locations
 - Type:** metal, commercial glass, other: garage door, other
 - Trim:** plain
- 4) **Porch(es):** other: metal awnings, metal awning over doors on northeast side of building

d. Rear: Direction: east


- 1) **Bays: 2**
- 2) **Windows:**
 - Fenestration:**
 - Type:**
 - Trim:**
 - Shutters:**
- 3) **Door(s): 2**
 - Location:** center, corner
 - Type:** other: vinyl garage doors
 - Trim:** plain
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Rt. 113, southeast corner of Rt. 113 and Seashore Hwy., parking to south and east sides of building

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-11243

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11243

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11244
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: Dupont Highway Route 113
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11244.001

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1950 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: central hall
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in vinyl, window replacement, 1-story shed roof entry additions, 1 room

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Side Gable
 materials: Composition
 cornice:
 dormers:
 chimney: location(s): exterior, gable, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 5
- 2) Windows: 4
 Fenestration: regular
 Type: double hung, casement, other: bay with fixed door sash and flanking, 2/2, diamond pane
 Trim: wood, vinyl
 Shutters: vinyl, non-functional

Facade (cont'd)

- 3) **Door(s):** 1
Location: center
Type: wood & glass
Trim: plain
- 4) **Porch(es):** other

b. Side: Direction: south

- 1) **Bays:** 4
- 2) **Windows:** 4, 1
Fenestration: regular
Type: double hung, casement, hopper, other: bay w/fixed centered sash & flanking, 2/2, 1/1, single and diamond pane
Trim: wood, vinyl
Shutters: (vinyl,non-functional)
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**

c. Side: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 2, 1
Fenestration: regular
Type: double hung, casement, 1/1, diamond pane
Trim: vinyl
Shutters: (vinyl,non-functional)
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**


d. Rear: Direction: west

- 1) **Bays:** 5
- 2) **Windows:** 4
Fenestration: regular
Type: double hung, casement, other: bay, 1/1, diamond pane
Trim: wood, vinyl
Shutters: vinyl,non-functional
- 3) **Door(s):** 1
Location: corner
Type: wood & glass
Trim: plain
- 4) **Porch(es):**other, concrete steps

9. INTERIOR:

10. LANDSCAPING: faces Rt. 113, paved driveway to north side of dwelling, shrubs planted across front lawn

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11244.002

1. ADDRESS/LOCATION: Dupont Highway Route 113

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1955 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____

a. sided in aluminum, replacement garage door

b. _____

6. CURRENT CONDITION: excellent _____ good X fair _____ poor _____

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Aluminum Siding

d. Foundation concrete block, poured concrete

e. Roof
structural system Gable Front
coverings Composition
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: east

1) bays: 1

2) windows: _____

3) door(s): Count: 1; Location: center ; Type: other: vinyl garage door

4) other: _____

- b. Side: direction: north
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: south
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: west
 - 1) bays:
 - 2) windows: ; other: on access
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11244.003

1. ADDRESS/LOCATION: Dupont Highway Route 113

2. FUNCTION(S): **historic** unknown; possible incinerator **current** _____

3. YEAR BUILT: 1940 **CIRCA?:** Y **ARCHITECT/BUILDER:** _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: **original site** **moved** _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____
a. _____
b. _____

6. CURRENT CONDITION: **excellent** **good** _____ **fair** _____ **poor** _____

7. DESCRIPTION:

a. **Structural system** concrete block

b. **Number of stories** 1

c. **Wall coverings**

d. **Foundation** concrete block

e. **Roof**
structural system Gable Front
coverings Composition
openings

8. DESCRIPTION OF ELEVATIONS:

a. **Facade: direction:** east

1) **bays:** 1

2) **windows:**

3) **door(s):** Count: 1; Location: center ; Type: wood & glass

4) **other:**

- b. Side: direction: north
 - 1) bays: 1
 - 2) windows: Count: 1; regular ; other: sliding
 - 3) door(s):
 - 4) other:

- c. Side: direction: south
 - 1) bays: 1
 - 2) windows: Count: 1; regular ; other: sliding
 - 3) door(s):
 - 4) other:

- d. Rear: direction: west
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11244.004

1. ADDRESS/LOCATION: Dupont Highway Route 113

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good _____ fair _____ poor _____

7. DESCRIPTION:

- a. Structural system concrete block
- b. Number of stories 1
- c. Wall coverings Other: asbestos in gable end
- d. Foundation concrete block, poured concrete
- e. Roof structural system Gable Front
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: east
 - 1) bays: 1
 - 2) windows:
 - 3) door(s): Count: 1; Location: center ; Type: other: vinyl & glass garage door
 - 4) other:

- b. Side: direction: north
 - 1) bays: 1
 - 2) windows: Count: 1; regular ; fixed, 3-pane
 - 3) door(s):
 - 4) other:

- c. Side: direction: south
 - 1) bays: 1
 - 2) windows: Count: 1; regular ; fixed, 3 pane
 - 3) door(s):
 - 4) other:

- d. Rear: direction: west
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-11244

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11244

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11245
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: The Insurance Market
2. ADDRESS/LOCATION: Dupont Highway Route 113
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 10/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11245.001

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. FUNCTION(S): historic current commerce/trade
3. YEAR BUILT: 1930 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Bungalow/Craftsman, Vernacular, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in vinyl, replaced doors and windows

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: brick
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Side Gable
materials: Asphalt
cornice:
dormers:
chimney: location(s): other: rear, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 3
- 2) Windows: 2
Fenestration: regular
Type: double hung, 1/1
Trim: vinyl
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** other: fiberglass
 - Trim:** plain
- 4) **Porch(es):** entry

b. Side: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:** 3
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** vinyl
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):** 1
 - Location:** corner
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):**

d. Rear: Direction: west


- 1) **Bays:** 5
- 2) **Windows:** 5
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Rt. 113, paved parking lot to south side of building, shrubs planted across front

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**


CRS # S-11245

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-11245

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9