

DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11246
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: Best Value Inn
2. ADDRESS/LOCATION: Dupont Highway Route 113
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: commerce/trade, recreation & culture, transportation commercial
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:

Organization: John Milner Associates Inc. Date: 09/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11246


2 story buildings built in ca. 1996

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|--|--|
| <ul style="list-style-type: none"> Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing X Retailing/Wholesaling Finance Professional Services | <ul style="list-style-type: none"> Transportation and Communication Settlement Patterns and Demographic Changes Architecture, Engineering and Decorative Arts Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Events |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11246.001

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. FUNCTION(S): historic commercial current commerce/trade, recreation & culture, transportation
3. YEAR BUILT: 1955 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN:
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

- a. window and door replacement, 1-story 1-room addition on west end; wood-panel siding
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): brick
- c. Foundation: materials:
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings):
- e. Roof: shape: Side Gable
materials: Composition
cornice:
dormers:
chimney: location(s): other: interior/rear, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: north
- 1) Bays: 9
- 2) Windows: 5
Fenestration: regular
Type: double hung, other: sliding, 1/1
Trim: vinyl
Shutters:

Facade (cont'd)

- 3) **Door(s):** 4
Location: other: irregular
Type: commercial glass, other: fiberglass
Trim: plain
- 4) **Porch(es):** inset

b. Side: Direction: east

- 1) **Bays:** 2
- 2) **Windows:** 2
Fenestration: regular
Type: double hung, other: sliding, 1/1
Trim: vinyl
Shutters:
- 3) **Door(s):**
Location:
Type:
Trim:
- 4) **Porch(es):**

c. Side: Direction: west

- 1) **Bays:** 2
- 2) **Windows:**
Fenestration:
Type:
Trim:
Shutters:
- 3) **Door(s):** 2
Location: other: side-by-side
Type: other: fiberglass
Trim: plain
- 4) **Porch(es):**


d. Rear: Direction: south

- 1) **Bays:** 9
- 2) **Windows:** 8
Fenestration: regular
Type: double hung, casement, other: sliding, 1/1, single pane
Trim: steel, vinyl
Shutters:
- 3) **Door(s):** 1
Location: side
Type: commercial glass
Trim: plain
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: historic buildings sit in U-shape facing Rt. 113; modern 2-story, buildings sit to rear of property, huge parking area

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11246.002

1. ADDRESS/LOCATION: Dupont Highway Route 113

2. FUNCTION(S): historic motel current _____

3. YEAR BUILT: 1955 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. window and door replacement; 1-story 1-room addition on west end; wood-panel siding

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system brick

b. Number of stories 1

c. Wall coverings

d. Foundation

e. Roof

structural system Side Gable

coverings Composition

openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: northeast

1) bays: 8

2) windows: Count: 4; regular ; double hung, other: sliding, 1/1

3) door(s): Count: 4; Location: other: side by side ; Type: other: fiberglass

4) other:

b. Side: direction: southeast

1) bays: 2

2) windows: Count: 2; regular ; double hung, other: sliding, 1/1

3) door(s):

4) other:

c. Side: direction: northwest

1) bays: 1

2) windows: Count: 1; regular ; double hung, other: sliding, 1/1

3) door(s):

4) other:

d. Rear: direction: southwest

1) bays: 8

2) windows: Count: 8; regular ; double hung, casement, other: sliding, 1/1, single pane

3) door(s):

4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11246.003

1. ADDRESS/LOCATION: Dupont Highway Route 113

2. FUNCTION(S): historic motel current _____

3. YEAR BUILT: 1955 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. window and door replacement; 1-story 1-room addition on west end; wood-panel siding
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system brick

b. Number of stories 1

c. Wall coverings

d. Foundation

e. Roof
structural system Side Gable
coverings Composition
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: southeast
 - 1) bays: 18
 - 2) windows: Count: 9; regular ; double hung, other: sliding, 1/1
 - 3) door(s): Count: 9; Location: other: irregular ; Type: other: fiberglass
 - 4) other:

b. Side: direction: southwest

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: other: fiberglass

4) other:

c. Side: direction: northeast

1) bays: 2

2) windows: Count: 2; regular ; double hung, other: sliding, 1/1

3) door(s):

4) other:

d. Rear: direction: northwest

1) bays: 16

2) windows: Count: 8; regular ; double hung, casement, other: sliding, 1/1, single pane

3) door(s):

4) other:

9. INTERIOR (if accessible):

a) Floor plan

other: dog-leg

b) Partition/walls


c) Finishes

d) Furnishings/machinery

4. SITE PLAN:


CRS # S-11246

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11247
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 231 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:


Organization: John Milner Associates Inc. Date: 09/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11247.001

1. ADDRESS/LOCATION: 231 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, WWII-Era Cottage, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided in vinyl

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories:
- Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
- basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Side Gable
- materials: Composition
- cornice:
- dormers:
- chimney: location(s): other: rear, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 3
- 2) Windows: 2
- Fenestration: regular
- Type: double hung, 1/1
- Trim: wood
- Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood
 - Trim:** plain
- 4) **Porch(es):**

b. Side: Direction: north

- 1) **Bays:** 3
- 2) **Windows:** 3, 1
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** wood
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:** 3
- 2) **Windows:** 2, 1
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** wood
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):**other: screen porch, 1-story, shed-roof, concrete decking


d. Rear: Direction: west

- 1) **Bays:** 3
- 2) **Windows:** 2, 1
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** vinyl
 - Shutters:** vinyl,non-functional
- 3) **Door(s):** 1
 - Location:** center
 - Type:** other: fiberglass
 - Trim:** plain
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Rt. 113, paved driveway to south side of property which extends to street to west, shrubs and trees grow across front lawn

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11247.002

1. ADDRESS/LOCATION: 231 Dupont Highway

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. replacement windows

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Aluminum Siding

d. Foundation concrete block

e. Roof
structural system Gable Front
coverings Composition
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: south

1) bays: 2

2) windows:

3) door(s): Count: 2; Location: other: side by side ; Type: wood

4) other:

- b. **Side: direction:** east
 - 1) **bays:** 2
 - 2) **windows:** Count: 1; regular ; hopper, 3-sash
 - 3) **door(s):** Count: 1; Location: side ; Type: other: fiberglass
 - 4) **other:**

- c. **Side: direction:** west
 - 1) **bays:** 2
 - 2) **windows:** Count: 1; regular ; hopper, 3-sash
 - 3) **door(s):** Count: 1; Location: corner ; Type: other: fiberglass
 - 4) **other:**

- d. **Rear: direction:** north
 - 1) **bays:**
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-11247

1. ADDRESS/LOCATION: 231 Dupont Highway
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11247

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11248
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

- HISTORIC NAME/FUNCTION: dwelling
- ADDRESS/LOCATION: 225 Dupont Highway
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
- MAIN FUNCTION OF PROPERTY: dwelling
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 10/2006

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11248.001

1. ADDRESS/LOCATION: 225 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1947 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, WWII-Era Cottage, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. gabled entry, breezeway extends from rear attached to gabled 1-car garage, brick chimney of northeast corner, gable porch extends to west
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: T-Plan Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Cross Gable
materials: Composition
cornice:
dormers:
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 3
- 2) Windows: 2, 1
Fenestration: regular
Type: double hung, 1/1
Trim: wood
Shutters: other: aluminum awning

Facade (cont'd)

- 3) **Door(s):** 1
 Location: center
 Type: wood & glass
 Trim: plain
- 4) **Porch(es):** entry

b. Side: Direction: north

- 1) **Bays:** 3
- 2) **Windows:** 3, 1
 Fenestration: regular
 Type: double hung, 1/1
 Trim: wood
 Shutters: other: aluminum awnings
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:** 3
- 2) **Windows:** 3, 1
 Fenestration: regular
 Type: double hung, 1/1
 Trim: wood
 Shutters: other: aluminum awnings
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

d. Rear: Direction: west


- 1) **Bays:**
- 2) **Windows:** 2
 Fenestration: regular
 Type: double hung, 1/1
 Trim: wood, other: obscured by rear extension
 Shutters: other: aluminum awnings
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

9. INTERIOR:

- 10. **LANDSCAPING:** faces Rt. 113, paved driveway to south side, shrubs across front and side facades, fencing surrounds rear lawn

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S-11248

1. ADDRESS/LOCATION: 225 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11248

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11249
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: Dupont Highway Route 113
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 10/2006

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11249.001

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1948 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, WWII-Era Cottage, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

- list major alterations and additions with years (if known) year
- a. gable entry, breezeway extends from rear attached, to gable 1-car garage, with concrete chimney in northeast corner, modern wood deck added to breezeway entry
- b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: T-Plan Stories: 1.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Cross Gable
materials: Composition
cornice:
dormers:
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 3
- 2) Windows: 2, 1
Fenestration: regular
Type: double hung, 1/1
Trim: wood
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** other: fiberglass
 - Trim:** plain
- 4) **Porch(es):** other: metal awning

b. Side: Direction: north

- 1) **Bays:** 3
- 2) **Windows:** 3, 1
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** wood
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:** 4
- 2) **Windows:** 4, 1
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** wood
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: west


- 1) **Bays:**
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** wood, other: obscured by rear extension
 - Shutters:** vinyl,non-functional
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

- 10. **LANDSCAPING:** faces Rt. 113, paved driveway to south side, tall trees in front and rear lawn, rear lawn surrounded by wood fence

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**


CRS # S-11249

1. ADDRESS/LOCATION: Dupont Highway Route 113
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11249

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-11250

1. HISTORIC NAME/FUNCTION: Short House

2. ADDRESS/LOCATION: Dupont Highway Route 113, west side

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY:

5. SETTING INTEGRITY:


6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Grace Ziesing

Principal Investigator name: Grace Ziesing

Principal Investigator signature: 

Organization: John Milner Associates, Inc. Date: 12/14/2011

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-11250

This property was demolished after it had been recorded, evaluated, and determined eligible for the National Register of Historic Places under Criterion C, as reviewed and concurred upon by the Delaware Department of Transportation (the Department) and DelSHPO. By December 2011 all buildings on the property were gone, as noted during a field review by representatives of JMA, the Department, DelSHPO, FHWA, and Sussex County. The property as currently configured no longer retains the integrity necessary to convey its significance under Criterion C as an example of a Colonial Revival Cape Cod style dwelling. The property is therefore no longer eligible for listing on the National Register. The original evaluation is included in Appendix E in the final report, *Evaluation of National Register Eligibility for Architectural Properties in the Georgetown Study Area, U.S. 113 North/South Study*, prepared for the Department and FHWA by JMA.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):


- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|--|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11250
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: Short House
2. ADDRESS/LOCATION: Dupont Highway Route 113, west side
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Doug McVarish

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 08/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11250

attached garage with enclosed hyphen 6x6 windows; ca.1935-51

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

b) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750- Contact Period (Native American)
- 1630-1730- Exploration and Frontier Settlement
- 1730-1770- Intensified and Durable Occupation
- 1770-1830- Early Industrialization
- 1830-1880- Industrialization and Early Urbanization
- X 1880-1940- Urbanization and Early Suburbanization
- 1940-1960- Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- X Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11250.001

1. ADDRESS/LOCATION: Dupont Highway Route 113, west side
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1935 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Cape Cod, central hall
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. cement-asbestos shingle

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1.5
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Asbestos
- e. Roof: shape: Side Gable
 materials: Asphalt
 cornice: other: boxed
 dormers: rear-shed -2- 6x1
 chimney: location(s): interior, gable, other: stucco

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: southeast
- 1) Bays:
- 2) Windows: 4
 Fenestration: regular
 Type: double hung, 12/12, 6/6
 Trim: wood
 Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 Location: center
 Type: wood
 Trim: other: fanlight
- 4) **Porch(es):**

b. Side: Direction: northwest

- 1) **Bays:** 2
- 2) **Windows:** 3, 2
 Fenestration: irregular
 Type: double hung, 12/12, 6/1, 6/6 casement
 Trim: wood
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**

c. Side: Direction: northeast

- 1) **Bays:**
- 2) **Windows:** 1, 2
 Fenestration: irregular
 Type: double hung, 12/12, 6/1
 Trim:
 Shutters:
- 3) **Door(s):**
 Location:
 Type:
 Trim:
- 4) **Porch(es):**


d. Rear: Direction: southwest

- 1) **Bays:** 3
- 2) **Windows:** 1, 2
 Fenestration: irregular
 Type: double hung, 6/1, 6/6
 Trim: wood
 Shutters:
- 3) **Door(s):** 1
 Location: center
 Type: wood & glass
 Trim: plain
- 4) **Porch(es):** other: enclosed shed, central door 6x1

9. INTERIOR:

10. LANDSCAPING: mature trees and shrubs, semi-circular driveway

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11250.002

1. ADDRESS/LOCATION: Dupont Highway Route 113, west side

2. FUNCTION(S): historic shed current _____

3. YEAR BUILT: 1935 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Wood Siding Horizontal
- d. Foundation
- e. Roof structural system Gable Front
coverings Composition
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: northeast
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- b. Side: direction: northwest
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: southeast
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: southwest
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11250

1. ADDRESS/LOCATION: Dupont Highway Route 113, west side


2. NOT FOR PUBLICATION reason: _____


3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11276
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: agricultural complex
2. ADDRESS/LOCATION: 22010 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic agricultural complex
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Doug McVarish

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:

Organization: John Milner Associates Inc. Date: 09/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11276

market moved in 1962, concrete block building built in 1968, garage built in 1922, greenhouse gone


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
1630-1730- Exploration and Frontier Settlement
1730-1770- Intensified and Durable Occupation
1770-1830- Early Industrialization
1830-1880- Industrialization and Early Urbanization
X 1880-1940- Urbanization and Early Suburbanization
1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|---|-----------------------|---|
| X | Agriculture | Transportation and Communication |
| | Forestry | Settlement Patterns and Demographic Changes |
| | Trapping/Hunting | X Architecture, Engineering and Decorative Arts |
| | Mining/Quarrying | Government |
| | Fishing/Oystering | Religion |
| | Manufacturing | Education |
| | Retailing/Wholesaling | Community Organizations |
| | Finance | Occupational Organizations |
| | Professional Services | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11276.001

1. ADDRESS/LOCATION: 22010 Dupont Highway
2. FUNCTION(S): historic agricultural complex current domestic
3. YEAR BUILT: 1922 CIRCA?: N ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Foursquare, side hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. aluminum siding

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 2.5
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: rusticated concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Hipped
materials: Asphalt
cornice:
dormers: hipped at front and sides
chimney: location(s): other: 2 interior, brick

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays:
- 2) Windows: 1, 4
Fenestration: regular
Type: double hung, 9/1, 1/1
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** side
 - Type:** wood & glass
 - Trim:** sidelights
- 4) **Porch(es):** wrap-around

b. Side: Direction: south

- 1) **Bays:** 2
- 2) **Windows:** 2, 3
 - Fenestration:** irregular
 - Type:** double hung, 9/1
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood
 - Trim:**
- 4) **Porch(es):** wrap-around from front, screened porch, rusticated concrete block and plinths

c. Side: Direction: north

- 1) **Bays:** 2
- 2) **Windows:** 3, 2
 - Fenestration:** regular
 - Type:** double hung, 1/1, 9/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: west

- 1) **Bays:** 3
- 2) **Windows:** 4, 3
 - Fenestration:** irregular
 - Type:** double hung, 9/1
 - Trim:** wood
 - Shutters:**
- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood & glass
 - Trim:**
- 4) **Porch(es):** other: part sliding and enclosed, rusticated concrete block, aluminum siding, 9x1 windows

9. INTERIOR:

10. LANDSCAPING: mature maple in front lawn; gravel driveway to south side of property

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11276.002

1. ADDRESS/LOCATION: 22010 Dupont Highway

2. FUNCTION(S): historic trailer current _____

3. YEAR BUILT: 1950 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____
a. _____
b. _____

6. CURRENT CONDITION: excellent _____ good X fair _____ poor _____

7. DESCRIPTION:

a. Structural system iron/steel

b. Number of stories 1

c. Wall coverings Metal

d. Foundation other

e. Roof
structural system Flat
coverings Other: metal
openings _____

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: north

1) bays: 3

2) windows: Count: 1; irregular ; hopper, double pane

3) door(s): Count: 2; Location: side ; Type: metal
Details: hopper transoms above each door, 1 door west, 1 door east

4) other: _____

- b. Side: direction: east
 - 1) bays: 1
 - 2) windows: ; other: covered by plywood
 - 3) door(s):
 - 4) other:

- c. Side: direction: west
 - 1) bays: 2
 - 2) windows: Count: 2; regular ; hopper, single pane
 - 3) door(s):
 - 4) other:

- d. Rear: direction: south
 - 1) bays: 3
 - 2) windows: Count: 3; irregular ; fixed, hopper
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11276.003

1. ADDRESS/LOCATION: 22010 Dupont Highway

2. FUNCTION(S): historic corncrib current _____

3. YEAR BUILT: 1922 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. deteriorated, portion re-sided in vinyl, vertical board

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Horizontal, Wood Siding Vertical

d. Foundation concrete block

e. Roof
structural system Side Gable
coverings Other: metal
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: north

1) bays: 2

2) windows:

3) door(s): Count: 2; Location: center, side ; Type: wood
Details: vertical board

4) other:

- b. Side: direction: east
 - 1) bays: 1
 - 2) windows:
 - 3) door(s): Count: 1; Location: center ; Type: wood
Details: vertical board
 - 4) other:

- c. Side: direction: west
 - 1) bays: 1
 - 2) windows:
 - 3) door(s): Count: 1; Location: center ; Type: wood
Details: vertical board door
 - 4) other:

- d. Rear: direction: south
 - 1) bays: 1
 - 2) windows:
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11276.004

1. ADDRESS/LOCATION: 22010 Dupont Highway

2. FUNCTION(S): historic shed current _____

3. YEAR BUILT: 1922 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____
a. _____
b. _____

6. CURRENT CONDITION: excellent _____ good _____ fair X poor _____

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Wood Siding Vertical
- d. Foundation concrete block
- e. Roof structural system Gable Front
coverings Asphalt
openings _____

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: south
 - 1) bays: _____
 - 2) windows: _____
 - 3) door(s): Count: 1; Location: center ; Type: wood
Details: vertical board
 - 4) other: _____

- b. Side: direction: west
 - 1) bays: 1
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: north
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: east
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11276.005

1. ADDRESS/LOCATION: 22010 Dupont Highway

2. FUNCTION(S): historic vehicle shed current _____

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Horizontal

d. Foundation other: none

e. Roof
structural system Shed
coverings Other: metal
openings _____

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: south

1) bays: 2

2) windows: _____

3) door(s): _____

4) other: _____

- b. Side: direction: east
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: west
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: north
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11276.006

1. ADDRESS/LOCATION: 22010 Dupont Highway

2. FUNCTION(S): historic produce stand current _____

3. YEAR BUILT: 1945 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____
a. moved from median of highway _____
b. _____

6. CURRENT CONDITION: excellent _____ good _____ fair _____ poor _____

7. DESCRIPTION:

a. Structural system _____

b. Number of stories 1

c. Wall coverings Wood Siding Horizontal

d. Foundation _____

e. Roof structural system Side Gable
coverings Other: metal/corrugated
openings _____

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: west

1) bays: 3

2) windows: _____

3) door(s): _____

4) other: _____

b. Side: direction: south

1) bays: 2

2) windows:

3) door(s):

4) other:

c. Side: direction: north

1) bays: 2

2) windows:

3) door(s):

4) other:

d. Rear: direction: east

1) bays: 12

2) windows: Count: 12; regular ; other: openings, no windows

3) door(s):

4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11276.007

1. ADDRESS/LOCATION: 22010 Dupont Highway

2. FUNCTION(S): historic produce stand current _____

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____

a. moved to west side of Rt. 113 (originally in the middle of Rt. 113), shed roof extension to north, open sides

b. _____

6. CURRENT CONDITION: excellent good _____ fair _____ poor _____

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Wood Siding Vertical

d. Foundation other

e. Roof structural system Side Gable
coverings Other: metal
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: east

1) bays: 2

2) windows:

3) door(s):

4) other:

- b. Side: direction: north
 - 1) bays: 2
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: south
 - 1) bays: 2
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: west
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11276

1. ADDRESS/LOCATION: 22010 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11276

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11279
SPO Map 14-15-11
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 19096 DuPont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#: Form:	List property types:
X CRS 2 Main Building Form	
X CRS 3 Secondary Building Form	
CRS 4 Archaeological Site Form	
CRS 5 Structure (Building-Like) Form	
CRS 6 Structure (Land Feature) Form	
CRS 7 Object Form	
CRS 8 Landscape Elements Form	
X CRS 9 Map Form	N/A
CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11279

Survey notes limited; surveyed from public right-of-way; owner denied access! No photos allowed or taken.


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
1630-1730- Exploration and Frontier Settlement
1730-1770- Intensified and Durable Occupation
1770-1830- Early Industrialization
1830-1880- Industrialization and Early Urbanization
1880-1940- Urbanization and Early Suburbanization
X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11279.001

1. ADDRESS/LOCATION: 19096 DuPont Highway
2. FUNCTION(S): historic current dwelling
3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Ranch
5. INTEGRITY: original site moved
if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided; new windows; enclosed front porch; carport partially enclosed

b.

6. CURRENT CONDITION: excellent good X fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
 Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials:
 basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): vinyl siding
- e. Roof: shape: side gable
 materials: asphalt
 cornice:
 dormers:
 chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 3
- 2) Windows: 3, first storu (obscured by enclosure)
 Fenestration: irregular
 Type: 6/6 double hung
 Trim: vinyl
 Shutters:

Facade (cont'd)

- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

b. Side: Direction: south

- 1) **Bays: 2**
- 2) **Windows: 1, first story**
 - Fenestration:** regular
 - Type:** double hung
 - Trim:**
 - Shutters:**
- 3) **Door(s): 1**
 - Location:** southwest side
 - Type:**
 - Trim:**
- 4) **Porch(es):**carport; partially enclosed

c. Side: Direction: north

- 1) **Bays: 1**
- 2) **Windows: 1, first story**
 - Fenestration:** irregular
 - Type:** 2/2 double hung
 - Trim:**
 - Shutters:**
- 3) **Door(s): 0**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: west

- 1) **Bays:**
- 2) **Windows:**
 - Fenestration:**
 - Type:** (no access)
 - Trim:**
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces 113. setback; gravel drieway ;eads to carport attached ro south end of house; trees to rear of house

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11279.002

1. ADDRESS/LOCATION: 19096 DuPont Highway

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site _____ moved _____
if moved, from where _____ original location's CRS # _____ year _____

list major alterations and additions with years (if known) _____ year _____

a. _____

b. _____

6. CURRENT CONDITION: excellent _____ good X fair _____ poor _____

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings vinyl siding

d. Foundation

e. Roof

structural system gable front

coverings asphalt

openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: east

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: fiberglass garage door

4) other:

b. Side: direction: south

- 1) bays:
- 2) windows:
- 3) door(s):
- 4) other:

c. Side: direction: north

- 1) bays:
- 2) windows:
- 3) door(s):
- 4) other:

d. Rear: direction: west

- 1) bays:
- 2) windows: ; (no access)
- 3) door(s):
- 4) other:

9. INTERIOR (if accessible):


a) Floor plan

rectangle

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11279

1. ADDRESS/LOCATION: 19096 DuPont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11279

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11280
SPO Map 14-15-11
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 20002 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: dwelling
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Sarah Traum

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 08/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11280.001

1. ADDRESS/LOCATION: 20002 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1950-1960 CIRCA?: N ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: WWII-Era Cottage, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: L-Plan Stories: 1
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Aluminum Siding
- e. Roof: shape: Side Gable, Other: gabled rear ell
materials: Asphalt
cornice: boxed
dormers:
chimney: location(s): exterior, gable, other: parged

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: west
- 1) Bays: 4
- 2) Windows: 3
Fenestration: regular
Type: double hung, other: bow window, 1/1
Trim: aluminum
Shutters: vinyl, non-functional

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** side
 - Type:**
 - Trim:**
- 4) **Porch(es):** other: partial-width

b. Side: Direction: north

- 1) **Bays:** 3
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):** 1
 - Location:** center
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** stoop, concrete deck and steps, wrought iron railing

c. Side: Direction: south

- 1) **Bays:** 3
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):** 1
 - Location:** side
 - Type:** other: sliding
 - Trim:** plain
- 4) **Porch(es):** stoop, concrete stoop and steps

d. Rear: Direction: west


- 1) **Bays:** 2
- 2) **Windows:** 1
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** aluminum
 - Shutters:** vinyl,non-functional
- 3) **Door(s):** 1
 - Location:** side
 - Type:** wood & glass
 - Trim:** plain
- 4) **Porch(es):** stoop, concrete deck and steps

9. INTERIOR:

10. LANDSCAPING: on wooded lot, faces east toward Rt. 113, gravel drive north leads to modern 1-car garage northwest and parking area north, fenced backyard with modern shed

11. OTHER COMMENTS:

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11280

1. ADDRESS/LOCATION: 20002 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11280

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11281
SPO Map 14-15-11
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 20060 Dupont Highway
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Sarah Traum

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 08/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 X 1880-1940- Urbanization and Early Suburbanization
 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11281.001

1. ADDRESS/LOCATION: 20060 Dupont Highway
2. FUNCTION(S): historic current domestic
3. YEAR BUILT: 1940 CIRCA?: N ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: Vernacular, central hall
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided, windows replaced

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): wood-frame
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Gable Front
materials: Asphalt
cornice: boxed
dormers:
chimney: location(s): center, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 2
- 2) Windows: 2
Fenestration: regular
Type: double hung, 1/1
Trim: vinyl
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):** entry

b. Side: Direction: north

- 1) **Bays:** 4
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** vinyl
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):** 2
 - Location:** side
 - Type:** metal
 - Trim:** plain
- 4) **Porch(es):**stoop, concrete deck and steps, entry porch from front east elevation

c. Side: Direction: south

- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** double hung, 1/1
 - Trim:** vinyl
 - Shutters:** (vinyl,non-functional)
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**


d. Rear: Direction: west

- 1) **Bays:**
- 2) **Windows:** 1
 - Fenestration:**
 - Type:** other: not accessible, inside fenced backyard
 - Trim:**
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces east to Rt. 113, asphalt and gravel drive at north side leading to parking area and fenced backyard

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11281.002

1. ADDRESS/LOCATION: 20060 Dupont Highway

2. FUNCTION(S): historic garage current _____

3. YEAR BUILT: 1940 CIRCA?: _____ ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: other: garage

5. INTEGRITY: original site moved _____
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. resided, doors replaced
b. _____

6. CURRENT CONDITION: excellent _____ good fair _____ poor _____

7. DESCRIPTION:

- a. Structural system wood-frame
- b. Number of stories 1
- c. Wall coverings Vinyl Siding, Asphalt, Wood Siding Vertical
- d. Foundation concrete block
- e. Roof structural system Gable Front, Other: shed roof wings on north and south elevations
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: east
 - 1) bays: 5
 - 2) windows: Count: 2; irregular ; double hung, 1/1
 - 3) door(s): Count: 3; Location: center, side ; Type: wood, metal, other: metal overhead garage door
 - 4) other:

- b. Side: direction: north
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: south
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: west
 - 1) bays:
 - 2) windows:
 - 3) door(s):
 - 4) other:

9. INTERIOR (if accessible):


a) Floor plan

other: garage

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11281

1. ADDRESS/LOCATION: 20060 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-11281

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11282
SPO Map 14-15-10
Hundred Georgetown
Quad Georgetown
Other _____

- HISTORIC NAME/FUNCTION: Muncie Insurance/Safety Auto Glass
- ADDRESS/LOCATION: 314 Dupont Highway
- TOWN/NEAREST TOWN: Georgetown vicinity?
- MAIN TYPE OF RESOURCE: building structure
landscape district site object
- MAIN FUNCTION OF PROPERTY: commercial building
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 

Organization: John Milner Associates Inc. Date: 09/2006

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11282

building owned by 'Improved Order of Red Men' Nanticoke Tribe 21


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
1630-1730- Exploration and Frontier Settlement
1730-1770- Intensified and Durable Occupation
1770-1830- Early Industrialization
1830-1880- Industrialization and Early Urbanization
1880-1940- Urbanization and Early Suburbanization
X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|--|
| <ul style="list-style-type: none">AgricultureForestryTrapping/HuntingMining/QuarryingFishing/OysteringManufacturingX Retailing/WholesalingFinanceProfessional Services | <ul style="list-style-type: none">Transportation and CommunicationSettlement Patterns and Demographic ChangesArchitecture, Engineering and Decorative ArtsGovernmentReligionEducationCommunity OrganizationsOccupational OrganizationsMajor Families, Individuals and Events |
|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11282.001

1. ADDRESS/LOCATION: 314 Dupont Highway
2. FUNCTION(S): historic commercial current commerce/trade
3. YEAR BUILT: 1960 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN: other: center entrance
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good X fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: rectangle Stories: 1
Additions:
- b. Structural system (if known): concrete block
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Vinyl Siding
- e. Roof: shape: Gable Front
materials: Other: metal
cornice:
dormers:
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: east
- 1) Bays: 3
- 2) Windows: 2
Fenestration: regular
Type: other: commercial corner bays
Trim: wood
Shutters:

Facade (cont'd)

- 3) **Door(s):** 1
 - Location:** center
 - Type:** commercial glass
 - Trim:** plain
- 4) **Porch(es):**

b. Side: Direction: north

- 1) **Bays:** 5
- 2) **Windows:** 2
 - Fenestration:** irregular
 - Type:** double hung, other: sliding, 1/1
 - Trim:** aluminum
 - Shutters:**
- 3) **Door(s):** 3
 - Location:** other: irregular
 - Type:** wood, other: vinyl
 - Trim:** plain
- 4) **Porch(es):**

c. Side: Direction: south

- 1) **Bays:** 5
- 2) **Windows:** 5
 - Fenestration:** regular
 - Type:** double hung, hopper, other: sliding, 1/1, single pane
 - Trim:** aluminum, vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

d. Rear: Direction: west


- 1) **Bays:** 2
- 2) **Windows:** 2
 - Fenestration:** regular
 - Type:** hopper, single pane
 - Trim:** vinyl
 - Shutters:**
- 3) **Door(s):**
 - Location:**
 - Type:**
 - Trim:**
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: faces Rt. 113, U-shaped driveway circles to rear and front, trees line perimeter edges of property

11. OTHER COMMENTS:

USE BLACK INK ONLY



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S-11282

1. ADDRESS/LOCATION: 314 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:

CRS # S-11282

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9