

Progress Report (2023)

Category	Self-Evaluation total	Self-Evaluation Non-Compliant	Prior Progress	Non-Compliant after Prior Progress	Current Year Progress	Non-Compliant Remaining
Bus Patron Pads	1,951	1,407	134	1,273	49	1,224
Curb Barrier	462	459	92	367	29	338
Curb Ramps	5,240	3,482	1,106	2,376	109	2,267
Driveway Crossings	1,645	950	89	861	16	845
Driveway Crossings Along Non-Compliant Sidewalk	2,230	2,228	133	2,095	31	2,064
Vertical Elevation Difference > 1/2 inch	471	471	43	428	8	420
Horizontal Gaps >1/2 inch	202	202	18	184	4	180
Median/Channelized Island	620	324	125	199	16	183
Non-Compliant Sidewalk 20 Feet or Less	533	533	56	477	10	467
On-Street Parking Location	0	0	0	0	0	0
Path/Trail Berm Running Slope	31	30	2	28	1	27
Pedestrian Signal	1,730	706	254	452	30	422
Pinch Points	297	132	25	107	4	103
Railroad Crossing	44	41	0	41	7	34
Sidewalk Passing Areas	56	0	0	0	0	0
Stub Ends	994	508	76	432	19	413
Marked Crosswalk (Count)	1,922	113	21	92	0	92
Missing Sidewalk Links (Miles)	9.80	9.80	2.38	7.41	0.08	7.33
Sidewalk (Miles)	230.61	98.69	8.08	90.62	2.14	88.48