




RAIL CORRIDOR EXISTING CONDITIONS DATA:

Rail Corridor Study Limits: Approx. 1 mile radius from Rehoboth Avenue (SR 1A) on Church Street and Hebron Road
 Total Length: 0.7 miles
 Active: No
 Rail Corridor Condition: abandoned with no rails or ties some agricultural fields and some areas lightly wooded
 Bridges and Other Structures: n/a
 Water Crossings/Culverts: n/a
 Roadway Crossings: 2
 Physical Barriers: n/a
 Average Right-of-Way Width: Approx. 65 feet wide, no existing ROW in some locations
 Rail Corridor Right-of-Way Ownership: unknown ownership
 Rail-with-Trail Potential: n/a



LEGEND:

- RTT/RWT STUDY CORRIDOR ALIGNMENT
- PHOTO LOCATION
- BRIDGE LOCATIONS
- 100 YEAR FLOODPLAIN
- WATER EDGE
- NATIONAL WETLANDS INVENTORY
- STATEWIDE WETLANDS MAPPING PROJECT
- STATE RESOURCE AREAS
- OTHER RTT/RWT STUDY CORRIDORS



for Preliminary Planning
Purposes Only

DELAWARE RTT/RWT FACILITIES MASTER PLAN
 JUNCTION & BREAKWATER TRAIL (SOUTH TERMINUS)
 ENVIRONMENTAL FEATURES
 MARCH 2006

