DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

 CRS #
 N08815

 SPO Map
 08-09-33

 Hundred
 Newcastle

 Quad
 Newark East

 Other
 Parcel 1002800054

1.	HISTORIC NAME/FUNCTION: Dziewit House				
2.	ADDRESS/LOCATION: 445 Christiana Rd, New Castle, Delaware 19720				
3.	TOWN/NEAREST TOWN: Christiana vicinity?				
4.	MAIN TYPE OF RESOURCE:	building landscape		site 🗌	object 🗌
5.	MAIN FUNCTION OF PROPERTY	':			
6.	PROJECT TITLE/ REASON FOR S	SURVEY (if a	pplicable):		
7.	ADDITIONAL FORMS USED:				
	#: Form:		List property types:		
	1 CRS 2 Main Building Form	<u> </u>	Dwelling		
	0 CRS 3 Secondary Building		N/A		
	0 CRS 4 Archaeological Site		N/A		
	0 CRS 5 Structure (Building		N/A		
	0 CRS 6 Structure (Land Fea		N/A		
	0 CRS 7 Object Form	N/A			
	0 CRS 8 Landscape Elemen	N/A			
	1 CRS 9 Map Form	N/A			
	0 CRS 14 Potential District Form		N/A		
8.	SURVEYOR INFORMATION:				
	Surveyor name: Patti Kuhr		Sarah Groesbeck		
	Principal Investigator name: Patti Kuhn				
Principal Investigator signature:					
Organization: The Lo		The Louis	Berger Group	Date:	June 2012

9.	OTHER NOTES OR OBSE	ERVATIONS:		CRS#	# N08815	
	A prefabricated shed looproperty.	cated to the southeast	of the dw	velling appears to be a modern add	ition to the	
	evaluation assessment Administration as part of Federal Aid NH-N067(26	is triggered by the fed of the SR 1 Roth Bridg)). Further referenced itectural Evaluation er	leral unde e to Inters information	its National Register eligibility or li rtaking initiated by DelDOT and the state 95, Capacity Improvement Pro on on this property as well as other rchitectural Survey Report, SR 1 W	e Federal Highwa Jject (T200511001 r in the vicinity,	Ŋ
10	STATE LISTOPIC CONT	EVT EDAMEWORK (o	hook all a	nnronriata havası rafar ta stata ma	nagament	
	an(s)):	EXT FRAMEWORK (C	ileck all a	ppropriate boxes; refer to state ma	iagement	
	a) Time period(s)	Pre-Europe Paleo-India Archaic Woodland Woodland	in I	ct		
		1880-1940∀ Urbaniza	ion and F ed and Du lustrializa alization a ation and l	rontier Settlement rable Occupation		
	b) Geographical zone	☑ Uppe☐ Lowe☐ Coast	stal	ula ula/Cypress Swamp Wilmington)		
	c) Historic period them	e(s)				
		Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesalin Finance Professional Service		Transportation and Communication Settlement Patterns and Demograte Architecture, Engineering and December Government Religion Education Community Organizations Occupational Organizations Major Families, Individuals and Ex	phic Changes corative Arts	

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CRS# N08815.001

CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

	To many min	1110								
1.	ADI	DRESS/	LOCATION:	445 Christiana	Rd, New Castle,	Delawar	e 19720			
2.	FUN	NCTION	(S): historic	single-fam	ily dwelling		current	single	-family dw	relling
3.	YEA	R BUIL	T: <u>1955</u> C	SIRCA?: ⊠	ARCHITECT/E	BUILDER	: Unkn	own		
4.	STY	LE OR	FLOOR PLAN:	Minimal	Traditional					
5.	INT	EGRITY	: origin	al site 🛚	moved					
if	move	ed, from	where				othe	r locatio	n's CRS#	year
	/A	,					N/A			N/A
N	/A						N/A			N/A
			ations and add		ars (if known)					<u>year</u>
_			the south eleva	ation						Post1965
b	. N/A	1								N/A
6.	CUR	RRENT	CONDITION:	excellent	☐ good	\boxtimes	fair		poor	
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)									
	a. Overall shape: L-shaped Stories: 1 1/2 Additions: dwelling originally rectangular, w/ one-story ell on S elevation now L-shaped									
	b	Struct	ural system (if	known): ballo	on frame					
	c.	Found basem	_	erials: concre partial 🗌 🗆	te not visible ⊠	no basen	nent 🗌			
	d.	Exterio	or walls (origina	al if visible& a	ny subsequent c	overings): vinyl			
	e.	materi cornic dorme	shape: gable als: asphalt sh e: box rs: N/A ey: location(s)	_						
8.	DES	SCRIPTI	ON OF ELEVA	TIONS:						
	а	n. Fac 1) 2)	ade: Direction Bays Windows fenestration	4 3 on 3 unevenly	spaced bays w/ ohung vinyl sash,	-		ounded	by single v	windows

trim

shutters

N/A

fixed vinyl

Facade (cont'd)

3) Door(s) 1

location E end of elevation

type single-leaf, material not visible

trim N/A

4) Porch(es) poured concrete steps

b. Side: Direction: East

1) Bays not visible

2) Windows 1

fenestration one partially visible window in half story of main block

type not visible

trim N/A shutters N/A

3) Door(s) Not visible location Not visible type Not visible trim Not visible

4) Porch(es) N/A

c. Side: Direction: West

1) Bays 2 (only main block visible, bay on rear addition not visible)

2) Windows 1

fenestration S end of elevation

type double hung vinyle sash

trim N/A shutters N/A Door(s) 1

location N end of elevation

type double-leaf wood with glazed lights

trim N/A

4) Porch(es) wood deck with wood slat balustrade

Not visible

d. Rear: Direction: South

Porch(es)

3)

Not visible 1) **Bays** 2) Windows Not visible fenestration Not visible type Not visible trim Not visible shutters Not visible 3) Not visible Door(s) Not visible location Not visible type trim Not visible

9. INTERIOR: not accessible

4)

- 10. LANDSCAPING: The dwelling is situated on a little more than a half-acre of land and is set back from the road, accessed by an unpaved drive. The property has a number of mature trees along the edges of the lot and lining the drive.
- 11. OTHER COMMENTS: N/A

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY MAP FORM

CRS# N08815


1.	ADDRESS/LOCATION:	445 Christiana Rd, New Castle, Delaware 19720
2.	NOT FOR PUBLICATION	reason:

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN



DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY

CRS # N08815 Date 5/21/2012 Photo Roll # n/a Surveyor S Groesbeck & P Kuhn

Description Façade (north elevation) of main building looking south; Northwest corner of main building looking southeast

Negative location (if other than SHPO)

Attach contact print(s):





doc # 20-06-01-05-12 CRS-13