

DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-08571

1. HISTORIC NAME/FUNCTION: dwelling

2. ADDRESS/LOCATION: Dupont Highway

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: New shutters and vinyl siding

5. SETTING INTEGRITY: newer houses/ buildings to the South

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature: *Grace Ziesing*

Organization: John Milner Associates, Inc Date: 8/1/2008

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-08571

Resurveyed for US113 North/South Study, Delaware Department of Transportation, by John Milner Associates, Inc.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750∇ Contact Period (Native American)
- 1630-1730∇ Exploration and Frontier Settlement
- 1730-1770∇ Intensified and Durable Occupation
- 1770-1830∇ Early Industrialization
- 1830-1880∇ Industrialization and Early Urbanization
- 1880-1940∇ Urbanization and Early Suburbanization
- 1940-1960∇ Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-08571.001

1. ADDRESS/LOCATION: Dupont Highway

2. FUNCTION(S): historic Domestic current Domestic

3. YEAR BUILT: 1930 CIRCA?: ARCHITECT/BUILDER:

4. STYLE OR FLOOR PLAN: Colonial revival

5. INTEGRITY: original site moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. New vinyl siding and shutters, vinyl porch cladding

b. Porch columns replaced

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangle Stories: 2
Additions:

b Structural system (if known): wood-framed

c. Foundation: materials:
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): vinyl siding


e. Roof: shape: side gable
materials: asphalt
cornice: boxed
dormers:
chimney: location(s): 2, ext. gable, brick

8. DESCRIPTION OF ELEVATIONS:

a.	Facade: Direction:	E	
	1) Bays	3	
	2)	Windows	2 (1 st story), 3 (2 nd story)
		fenestration	regular
		type	double-hung, 8/8, original wood
		trim	wood
shutters	vinyl, non-functional		

Facade (cont'd)	
3)	Door(s) 1
	location center
	type wood, 6-panel
	trim sidelights
4)	Porch(es) portico, entry; gabled entry porch with brick stoop/floor, aluminum fluted replacement columns, barrel-vaulted gable
b.	Side: Direction: N
1)	Bays 2
	2)
2)	fenestration regular
	type double hung, 8/8, 1/1 replacement; fixed quarter-rounds in attic
	trim wood
	shutters vinyl, non-functional
3)	Door(s) 0
	location
	type
	trim
4)	Porch(es)
c.	Side: Direction: S
1)	Bays 3
2)	Windows 1 (1 st story), 2 (2 nd and 3 rd stories)
	fenestration regular
	type double hung, 8/1; 2 fixed quarter-rounds in attic
	trim wood
	shutters vinyl, non-functional
3)	Door(s) 2
	location both sides
	type wood and glass, 4-panel with row of 4 top lights
	trim plain
4)	Porch(es) portico; full-width shed-roof porch with original large wooden corner columns, slate floor, brick lower walls, mansard overhang w/ scalloped wood trim on all sides
d.	Rear: Direction: W
1)	Bays 3
2)	Windows 2 (1 st story), 2 (2 nd story)
	fenestration regular
	type double-hung, 8/1
	trim wood
	shutters n/a
3)	Door(s) 1
	location center
	type fiberglass, 6-panel
	trim plain
4)	Porch(es) portico, vestibule; shed-roofed vestibule/ bathroom with concrete stoop and scalloped shed overhang

9.	INTERIOR:
10.	LANDSCAPING: set back from road, large grassy level lawn, a few mature trees near house, paved driveway on N side of lawn leads back to garage
11.	OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-08571.002

1. ADDRESS/LOCATION: Dupont Highway

2. FUNCTION(S): historic garage current garage

3. YEAR BUILT: 1955-1960 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: One pen

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. newer fiberglass bay doors
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:
a. Structural system concrete block
b. Number of stories 1
c. Wall coverings wood siding (horizontal) in gables
d. Foundation concrete block, poured concrete slab
e. Roof
structural system gable front, boxed cornice
coverings asphalt
openings _____

8. DESCRIPTION OF ELEVATIONS:
a. Facade: direction: E
1) bays: 2
2) windows: 0
3) door(s): 2, center, fiberglass rolldown doors
4) other: _____

- b. Side: direction: S
 - 1) bays: 3
 - 2) windows: 3, awning, 3-light, steel trim
 - 3) door(s): 0
 - 4) other:

- c. Side: direction: N
 - 1) bays: 2
 - 2) windows: 2, awning, 3-light, steel
 - 3) door(s): 0
 - 4) other:

- d. Rear: direction: W
 - 1) bays: 2
 - 2) windows: 2, awning, 3-light sash steel
 - 3) door(s): 0
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-08571

1. ADDRESS/LOCATION: Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)


INDICATE NORTH ON SKETCH



4. SITE PLAN:


CRS # S-08571

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-08572

1. HISTORIC NAME/FUNCTION: McLaren House

2. ADDRESS/LOCATION: 10769 DuPont Highway

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY: New siding, windows, doors; large new split-level gable-front 2-story addition on N end, 2 large rear additions

5. SETTING INTEGRITY: modernized trailers and newer houses nearby

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature:

Organization: John Milner Associates, Inc Date: 8/1/2008

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-08572

Resurveyed for US113 North/South Study, Delaware Department of Transportation, by John Milner Associates, Inc.

House was originally a double-pile cottage, as surveyed in 1992. Now modernized with a split-level addition

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):


- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-08572.001

1. ADDRESS/LOCATION: 10769 DuPont Highway

2. FUNCTION(S): historic Dwelling current dwelling

3. YEAR BUILT: 1940-1945 CIRCA?: ARCHITECT/BUILDER:

4. STYLE OR FLOOR PLAN: Ranch

5. INTEGRITY: original site moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year
a. new split-level wing, 2 large rear additions
b. new siding, windows, doors, shutters, entry porch

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

- a. Overall shape: rectangle Stories: 1.5
Additions: new split-level wing; 2 large rear additions
- b. Structural system (if known): wood-framed
- c. Foundation: materials: panel-faced concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): vinyl siding
- e. Roof: shape: side gable
materials: asphalt
cornice: boxed
dormers:
chimney: location(s): int. and ext. gable, concrete block

8. DESCRIPTION OF ELEVATIONS:


a.	Facade: Direction: W
	1) Bays 5 (original section)
	2) Windows 4
	fenestration irregular
	type double-hung, 1/1 modern vinyl sash
	trim vinyl
shutters vinyl, non-functional	

Facade (cont'd)	
3)	Door(s) 1
	location center
	type wood and glass, modern multipanel
	trim plain
4)	Porch(es) entry; flat roofed modern entry porch with plain lumber supports, wood deck with railing
b.	Side: Direction: S
1)	Bays 1
	Windows 2 (1 per story)
2)	fenestration regular
	type double-hung, fixed, 1/1
	trim vinyl
	shutters n/a
3)	Door(s) n/a
	location
	type
	trim
4)	Porch(es)
c.	Side: Direction: N
1)	Bays not visible
2)	Windows completely covered by split-level addition
	fenestration
	type
	trim
	shutters
3)	Door(s)
	location
	type
	trim
4)	Porch(es)
d.	Rear: Direction: E
1)	Bays not visible
2)	Windows completely covered by additions
	fenestration
	type
	trim
	shutters
3)	Door(s)
	location
	type
	trim
4)	Porch(es)

9.	INTERIOR:
-----------	------------------

10.	LANDSCAPING: Dirt semicircular driveway, several large shade trees along front, backyard enclosed with chain link fence. Large backyard with play areas
------------	--

11.	OTHER COMMENTS:
------------	------------------------



CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-08572

1. ADDRESS/LOCATION: 10769 DuPont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





CULTURAL RESOURCE SURVEY
SURVEY UPDATE FORM

CRS # S-08573

1. HISTORIC NAME/FUNCTION: Joseph Fisher House

2. ADDRESS/LOCATION: dirt farm road off Beach Road

3. CURRENT CONDITION: excellent good fair poor demolished

4. INTEGRITY:

5. SETTING INTEGRITY:


6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: _____

Principal Investigator name: Grace Ziesing

Principal Investigator signature: 

Organization: John Milner Associates, Inc. Date: 10/2008

8. OTHER NOTES OR OBSERVATIONS:

CRS# S-08573

Resurveyed for US113 North/South Study, Delaware Department of Transportation, by John Milner Associates, Inc.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II

- 1600-1750 Contact Period (Native American)
- 1630-1730 Exploration and Frontier Settlement
- 1730-1770 Intensified and Durable Occupation
- 1770-1830 Early Industrialization
- 1830-1880 Industrialization and Early Urbanization
- 1880-1940 Urbanization and Early Suburbanization
- 1940-1960 Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|--|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY