

DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11468
SPO Map 12-13-13
Hundred Cedar Creek
Quad Ellendale
Other _____

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 12675 Dupont Highway
3. TOWN/NEAREST TOWN: Ellendale vicinity?
4. MAIN TYPE OF RESOURCE:

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):


7. ADDITIONAL FORMS USED:

#: Form:	List property types:
X CRS 2 Main Building Form	
CRS 3 Secondary Building Form	
CRS 4 Archaeological Site Form	
CRS 5 Structure (Building-Like) Form	
CRS 6 Structure (Land Feature) Form	
CRS 7 Object Form	
CRS 8 Landscape Elements Form	
X CRS 9 Map Form	N/A
CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature: 

Organization: John Milner Associates, Inc Date: 4/4/2008

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11468

Owner next door says this house came from Montgomery Ward ca. 1940. Entire triangle owned by great-grandfather; roadside parcels subdivided for descendants and developed with Montgomery Ward dwellings.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II

 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization


- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY

CRS-1



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11468.001

1. ADDRESS/LOCATION: 12675 Dupont Highway

2. FUNCTION(S): historic dwelling current dwelling

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER:

4. STYLE OR FLOOR PLAN: WWII- Era Cottage

5. INTEGRITY: original site moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

- a. New siding and shutters, new garage door, picture windows replaced
- b. breezeway between house and garage enclosed

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)


- a. Overall shape: rectangle Stories: 1
Additions: breezeway between house and garage enclosed
- b. Structural system (if known): wood-framed
- c. Foundation: materials: brick, concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): vinyl siding
- e. Roof: shape: side gable, center gable
materials: asphalt
cornice: boxed
dormers:
chimney: location(s): 2, center, brick

8. DESCRIPTION OF ELEVATIONS:

a.	Facade: Direction:	W
	1) Bays	5
	2) Windows	2
	fenestration	regular
	type	double hung, 2/2 horizontal division; fixed picture windows
	trim	vinyl over wood
	shutters	vinyl, non-funtional

Facade (cont'd)		
3)	Door(s)	3
	location	center, SW side
	type	wood and glass; fiberglass garage door, vinyl clad front door
	trim	plain, sidelights
4)	Porch(es)	brick stoop with wrought iron balustrade
b.	Side: Direction:	N
1)	Bays	2
	Windows	2
2)	fenestration	regular
	type	double hung, 2/2 horizontal division
	trim	vinyl
	shutters	vinyl, non-functional
3)	Door(s)	n/a
	location	
	type	
	trim	
4)	Porch(es)	n/a
c.	Side: Direction:	S
1)	Bays	4
2)	Windows	3
	fenestration	irregular
	type	double hung, 2/2 horizontal; 1/1 replacement
	trim	vinyl
	shutters	vinyl, non-functional
3)	Door(s)	1
	location	in rear, original extension
	type	wood and glass, half-wheel and 4 panel
	trim	plain
4)	Porch(es)	concrete stoop with wrought iron balustrade
d.	Rear: Direction:	E
1)	Bays	5
2)	Windows	4
	fenestration	regular
	type	double hung, 2/2 horizontal division - original
	trim	vinyl
	shutters	n/a
3)	Door(s)	1
	location	center
	type	wood and glass, jalousie door with jalousie sidelights – breezeway area
	trim	sidelights
4)	Porch(es)	n/a

9.	INTERIOR:
10.	LANDSCAPING: lawn with a few large deciduous trees in front and back. Paved driveway apron and gravel parking area in front of a 1-car garage. Agricultural fields at rear and N sides. A few shrubs in rear
11.	OTHER COMMENTS:



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S-11468

1. ADDRESS/LOCATION: 12675 Dupont Highway


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11469
SPO Map 12-13-11
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 18381 Deer Forest Road
3. TOWN/NEAREST TOWN: between Ellendale and Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Scott M. Pickens

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature: 


Organization: John Milner Associates Inc. Date: 12/2005

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
 1630-1730- Exploration and Frontier Settlement
 1730-1770- Intensified and Durable Occupation
 1770-1830- Early Industrialization
 1830-1880- Industrialization and Early Urbanization
 1880-1940- Urbanization and Early Suburbanization
 X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | | |
|-----------------------|---|---|
| Agriculture | | Transportation and Communication |
| Forestry | | Settlement Patterns and Demographic Changes |
| Trapping/Hunting | X | Architecture, Engineering and Decorative Arts |
| Mining/Quarrying | | Government |
| Fishing/Oystering | | Religion |
| Manufacturing | | Education |
| Retailing/Wholesaling | | Community Organizations |
| Finance | | Occupational Organizations |
| Professional Services | | Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11469.001

1.	ADDRESS/LOCATION:	18381 Deer Forest Road
----	-------------------	------------------------

2.	FUNCTION(S):	historic: domestic	current: domestic
----	--------------	--------------------	-------------------

3.	YEAR BUILT:	1940	CIRCA?:	X	ARCHITECT/BUILDER:	
----	-------------	------	---------	---	--------------------	--

4.	STYLE OR FLOOR PLAN:	Colonial Revival
----	----------------------	------------------

5.	INTEGRITY:	original site	X	moved	
----	------------	---------------	---	-------	--

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. front vestibule added

b.

6.	CURRENT CONDITION:	excellent		good	X	fair		poor	
----	--------------------	-----------	--	------	---	------	--	------	--

7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
----	--

a. Overall shape: square Stories: 1
Additions:

b. Structural system (if known): wood-framed

c. Foundation: materials: panel-faced concrete block
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): vinyl siding

e. Roof: shape: side gable
materials: asphalt shingles
cornice: boxed
dormers:
chimney: brick, center

8.	DESCRIPTION OF ELEVATIONS:
----	----------------------------


a.	Facade: Direction: southeast
1)	Bays: 3
2)	Windows: 4
	Fenestration: regular
	Type: 1/1 double-hung sash
	Trim: wood, aluminum
	Shutters: vinyl, non-functional

	Facade (cont'd)
3)	Door(s): 1 Location: center Type: wood-and-glass (1 large light) Trim:
4)	Porch(es): vestibule at center of façade
b.	Side: Direction: northeast
1)	Bays: 3
2)	Windows: 2 Fenestration: regular Type: 1/1 double-hung sash Trim: wood, aluminum Shutters: vinyl, non-functional; aluminum awnings
3)	Door(s): 1 Location: northeast end Type: wood (4 panels) Trim:
4)	Porch(es): wood deck
c.	Side: Direction: southwest
1)	Bays: 2
2)	Windows: 2 Fenestration: regular Type: double-hung sash Trim: wood, aluminum Shutters: aluminum awnings
3)	Door(s): Location: Type: Trim:
4)	Porch(es):
d.	Rear: Direction: northwest
1)	Bays: 2
2)	Windows: 2 Fenestration: regular Type: 1/1 double-hung sash Trim: wood, aluminum Shutters: aluminum awnings
3)	Door(s): Location: Type: Trim:
4)	Porch(es):

9.	INTERIOR:
----	-----------

10.	LANDSCAPING:
-----	--------------

11.	OTHER COMMENTS:
-----	-----------------



**CULTURAL RESOURCE SURVEY
MAP FORM**

CRS # S-11469

1. ADDRESS/LOCATION: 18381 Deer Forest Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11471
SPO Map 12-13-11
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: Commercial Building
2. ADDRESS/LOCATION: Route 113
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE: building structure site object
 landscape district
5. MAIN FUNCTION OF PROPERTY: commercial
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):
US113 North/South Study Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Scott Pickens

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:

Organization: John Milner Associates Inc. Date: 08/2005

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11471

Redden Furniture; house with concrete block structure added, houses, trailers, and appliances in rear


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
- 1600-1750- Contact Period (Native American)
1630-1730- Exploration and Frontier Settlement
1730-1770- Intensified and Durable Occupation
1770-1830- Early Industrialization
1830-1880- Industrialization and Early Urbanization
1880-1940- Urbanization and Early Suburbanization
X 1940-1960- Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - X Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | | |
|---|--|--|
| X | Agriculture
Forestry
Trapping/Hunting
Mining/Quarrying
Fishing/Oystering
Manufacturing
Retailing/Wholesaling
Finance
Professional Services | Transportation and Communication
Settlement Patterns and Demographic Changes
Architecture, Engineering and Decorative Arts
Government
Religion
Education
Community Organizations
Occupational Organizations
Major Families, Individuals and Events |
|---|--|--|



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11471.001

1. ADDRESS/LOCATION: Route 113
2. FUNCTION(S): historic commercial current commerce/trade
3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER:
4. STYLE OR FLOOR PLAN:
5. INTEGRITY: original site moved
- if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. large concrete building addition to house

b.

6. CURRENT CONDITION: excellent good fair poor
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
- a. Overall shape: L-Plan Stories: 1
Additions:
- b. Structural system (if known): wood-frame, concrete block
- c. Foundation: materials: concrete block
basement: full partial not visible no basement
- d. Exterior walls (original if visible& any subsequent coverings): Other: exposed concrete block
- e. Roof: shape: Hipped
materials: Asphalt
cornice: boxed
dormers:
chimney: location(s): center; other: exterior/northwest side/center of original house, concrete block

8. DESCRIPTION OF ELEVATIONS:
- a. Facade: Direction: southwest
- 1) Bays: 4
- 2) Windows: 3
Fenestration: regular
Type: awning, fixed, 9 light awning
Trim: wood, steel
Shutters: vinyl,non-functional

Facade (cont'd)

- 3) **Door(s):** 1
Location: center
Type: commercial glass
Trim: plain
- 4) **Porch(es):**

b. Side: Direction: southeast

- 1) **Bays:** 4
- 2) **Windows:** 3
Fenestration: regular
Type: fixed
Trim: steel
Shutters:
- 3) **Door(s):** 1
Location:
Type: commercial glass
Trim: plain
- 4) **Porch(es):**

c. Side: Direction: northwest

- 1) **Bays:** 6
- 2) **Windows:** 6
Fenestration: irregular
Type: double hung, awning, fixed, 2/2, 4/1, 6 pane awning
Trim: wood, steel
Shutters:
- 3) **Door(s):**
Location: corner
Type: wood
Trim: plain
- 4) **Porch(es):**


d. Rear: Direction: northeast

- 1) **Bays:** 6
- 2) **Windows:** 3
Fenestration: regular
Type: double hung, 4/1
Trim: wood
Shutters:
- 3) **Door(s):** 4
Location: center, side, corner
Type: wood, wood & glass
Trim: plain, other
- 4) **Porch(es):**

9. INTERIOR:

10. LANDSCAPING: many old appliances in rear

11. OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11471.002

1. ADDRESS/LOCATION: Route 113

2. FUNCTION(S): historic unknown current

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Asphalt, Asbestos

d. Foundation

e. Roof

structural system Shed, Other: jerkinhead

coverings Asphalt

openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: northwest

1) bays: 3

2) windows: Count: 2; irregular ; double hung, 1/1

3) door(s): Count: 1; Location: center ; Type: wood & glass
Details: 2 lights over 4 panels

4) other:

b. **Side: direction:** northwest

1) **bays:** 3

2) **windows:** Count: 3; regular ; double hung, hopper, 1/1

3) **door(s):**

4) **other:**

c. **Side: direction:** southeast

1) **bays:** 2

2) **windows:** Count: 2; irregular ; fixed, other: sliding glass

3) **door(s):**

4) **other:**

d. **Rear: direction:** southwest

1) **bays:** 3

2) **windows:** Count: 3; regular ; double hung, 1/1

3) **door(s):**

4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11471.003

1. ADDRESS/LOCATION: Route 113

2. FUNCTION(S): historic unknown current

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular, one pen

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a.
b.

6. CURRENT CONDITION: excellent good fair poor X

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Asbestos

d. Foundation concrete block

e. Roof
structural system Hipped
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southwest
1) bays: 1
2) windows:
3) door(s): Count: 1; Location: center ; Type: wood
Details: solid 4 panels
4) other:

- b. **Side: direction:** northwest
 - 1) **bays:** 1
 - 2) **windows:** Count: 1; regular ; fixed
 - 3) **door(s):**
 - 4) **other:**

- c. **Side: direction:** southeast
 - 1) **bays:** 1
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** northwest
 - 1) **bays:** 1
 - 2) **windows:**
 - 3) **door(s):**
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

square ; one pen

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11471.004

1. ADDRESS/LOCATION: Route 113

2. FUNCTION(S): historic unknown current

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Asbestos

d. Foundation concrete block

e. Roof
structural system Side Gable
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southeast

1) bays:

2) windows: ; irregular ; double hung, fixed, 1/1, 6 light

3) door(s): Count: 2; Location: corner ; Type: metal, other: missing
Details: metal storm door

4) other:

- b. **Side: direction:** southwest
 - 1) **bays:** 3
 - 2) **windows:** Count: 3; irregular ; double hung, fixed, 2/2,4 light, 1 light
 - 3) **door(s):**
 - 4) **other:**

- c. **Side: direction:** northeast
 - 1) **bays:** 2
 - 2) **windows:** Count: 2; regular ; fixed, 12 light, 6 light
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** northwest
 - 1) **bays:** 4
 - 2) **windows:** Count: 4; regular ; double hung, fixed, 1/1, 6 light
 - 3) **door(s):** Count: 1
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11471.005

1. ADDRESS/LOCATION: Route 113

2. FUNCTION(S): historic unknown current

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular, one pen

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings Asbestos

d. Foundation concrete block

e. Roof
structural system Hipped
coverings Asphalt
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southeast

1) bays: 1

2) windows:

3) door(s): Count: 1; Location: center ; Type: wood
Details: solid 5 panel

4) other:

b. Side: direction: northeast

1) bays: 1

2) windows:

3) door(s):

4) other:

c. Side: direction: southwest

1) bays: 1

2) windows: Count: 1; regular ; fixed

3) door(s):

4) other:

d. Rear: direction: northwest

1) bays: 1

2) windows:

3) door(s):

4) other:

9. INTERIOR (if accessible):


a) Floor plan

square ; one pen

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11471.006

1. ADDRESS/LOCATION: Route 113

2. FUNCTION(S): historic unknown current

3. YEAR BUILT: 1940 CIRCA?: Y ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a.

b.

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

a. Structural system wood-frame

b. Number of stories 1

c. Wall coverings

d. Foundation

e. Roof
structural system
coverings
openings

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: southeast

1) bays: 3

2) windows: Count: 3; regular ; double hung, 1/1

3) door(s): Count: 1; Location: center ; Type: wood & glass
Details: 4 lighth over 4 panel

4) other:

- b. **Side: direction:** northeast
 - 1) **bays:** 4
 - 2) **windows:** Count: 2; irregular ; double hung, 1/1
 - 3) **door(s):** Count: 2; Location: side, corner ; Type: wood, other: missing
Details: solid wood door, missing garage door
 - 4) **other:**

- c. **Side: direction:** southwest
 - 1) **bays:** 4
 - 2) **windows:** Count: 4; irregular ; double hung, 1/1
 - 3) **door(s):**
 - 4) **other:**

- d. **Rear: direction:** northwest
 - 1) **bays:** 2
 - 2) **windows:** Count: 1; irregular ; other: missing
 - 3) **door(s):** Count: 1; Location: corner ; Type: wood & glass
Details: 4 lights over 4 panels
 - 4) **other:**

9. **INTERIOR (if accessible):**


a) **Floor plan**

rectangle

b) **Partition/walls**

c) **Finishes**

d) **Furnishings/machinery**



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-11471

1. ADDRESS/LOCATION: Route 113
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN

