

DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-11698  
SPO Map 12-13-13  
Hundred Cedar Creek  
Quad Ellendale  
Other \_\_\_\_\_

1. HISTORIC NAME/FUNCTION: dwelling
2. ADDRESS/LOCATION: 16917 Beach Road
3. TOWN/NEAREST TOWN: Ellendale vicinity?
4. MAIN TYPE OF RESOURCE:
 

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
\_\_\_\_\_


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
x	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature: 

Organization: John Milner Associates, Inc Date: 4/4/2008

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11698

House and garage/barn are part of a large farm but buildings that remain are scattered widely and interspersed with two modern houses and open areas. Same farm as S-08574


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
  - 1600-1750∇ Contact Period (Native American)
  - 1630-1730∇ Exploration and Frontier Settlement
  - 1730-1770∇ Intensified and Durable Occupation
  - 1770-1830∇ Early Industrialization
  - 1830-1880∇ Industrialization and Early Urbanization
  - 1880-1940∇ Urbanization and Early Suburbanization
  - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

c) Historic period theme(s)

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication                         |
| <input type="checkbox"/> Forestry               | <input type="checkbox"/> Settlement Patterns and Demographic Changes              |
| <input type="checkbox"/> Trapping/Hunting       | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying       | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering      | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing          | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling  | <input type="checkbox"/> Community Organizations                                  |
| <input type="checkbox"/> Finance                | <input type="checkbox"/> Occupational Organizations                               |
| <input type="checkbox"/> Professional Services  | <input type="checkbox"/> Major Families, Individuals and Events                   |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-11698.001

1. ADDRESS/LOCATION: 16917 Beach Road

2. FUNCTION(S): historic dwelling current dwelling

3. YEAR BUILT: 1930 CIRCA?:  ARCHITECT/BUILDER:

4. STYLE OR FLOOR PLAN: Bungalow/ Craftsman

5. INTEGRITY: original site  moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

- a. new siding, doors, windows, shutters; windows on N end of house appear to be salvage
- b. large addition on SW corner

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: complex Stories: 1 + Raised Basement  
Additions: large addition on SW corner

b Structural system (if known): wood-framed

c. Foundation: materials: panel-faced concrete block  
basement: full  partial  not visible  no basement

d. Exterior walls (original if visible& any subsequent coverings): vinyl siding


e. Roof: shape: side gable, cross gable  
materials: asphalt  
cornice: boxed  
dormers:  
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:

a.	Facade: Direction: W	
	1)	Bays 3 (includes front addition)
	2)	Windows 2
		fenestration irregular
		type double hung, 8/12 wood replacement, 1/1 new, 8/8 in basement
		trim aluminum, vinyl
shutters n/a		

<b>Facade (cont'd)</b>		
3)	<b>Door(s)</b>	1
	location	center
	type	vinyl clad, 6 panel, new
	trim	plain
4)	<b>Porch(es)</b>	modern wood steps with lattice
<b>b.</b>	<b>Side: Direction:</b>	<b>S</b>
1)	<b>Bays</b>	2
	<b>Windows</b>	2
2)	fenestration	irregular
	type	double hung, 1/1 replacement, vinyl
	trim	aluminum, vinyl
	shutters	n/a
3)	<b>Door(s)</b>	n/a
	location	
	type	
	trim	
4)	<b>Porch(es)</b>	n/a
<b>c.</b>	<b>Side: Direction:</b>	<b>N</b>
1)	<b>Bays</b>	4
2)	<b>Windows</b>	3
	fenestration	regular
	type	(1) casement, 6-light; (1) double hung 8/12 (1) double hung 8/8 wood, salvage
	trim	wood, vinyl
	shutters	n/a
3)	<b>Door(s)</b>	1
	location	left side of rear extension
	type	wood and glass, 4-lights, 2 panels
	trim	plain
4)	<b>Porch(es)</b>	n/a
<b>d.</b>	<b>Rear: Direction:</b>	<b>E</b>
1)	<b>Bays</b>	8
2)	<b>Windows</b>	7 (4 in basement)
	fenestration	irregular
	type	double hung, 1/1 new; 6/6 and 8/8 old
	trim	wood, aluminum and vinyl
	shutters	n/a
3)	<b>Door(s)</b>	1
	location	right side, lower level
	type	wood and glass, 4-lights, 2 panels
	trim	plain
4)	<b>Porch(es)</b>	n/a

<b>9.</b>	<b>INTERIOR:</b>
<b>10.</b>	<b>LANDSCAPING:</b> Open lot with evergreen tree lines on each side and pair of mature deciduous trees flanking front walk; gravel driveway extends from road. House is set far back from road with agricultural fields behind it. Modern chicken house and new dwelling to E/SE, new dwelling to SW, old cottage to W. Old barn and house to NW (previously documented)
<b>11.</b>	<b>OTHER COMMENTS:</b>



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-11698.002

1. ADDRESS/LOCATION: 16917 Beach Road

2. FUNCTION(S): historic Barn/ garage current Vacant/ not in use

3. YEAR BUILT: 1920 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: Bungalow/ Craftsman

5. INTEGRITY: original site  moved   
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year  
a. resided with asbestos then vinyl, windows boarded up  
b. front façade openings blocked, septic pipe in side

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

- a. Structural system wood-framed
- b. Number of stories 1.5
- c. Wall coverings wood siding (horizontal), asbestos, vinyl
- d. Foundation concrete block footers
- e. Roof
  - structural system gable front, exposed rafter ends
  - coverings asphalt
  - openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
  - 1) bays: 1
  - 2) windows: n/a
  - 3) door(s): 1, center, 6 panel new vinyl-clad wood
  - 4) other:

- b. Side: direction: E
  - 1) bays: 2
  - 2) windows: 2, double hung 6/6 wood, 1 boarded up
  - 3) door(s): n/a
  - 4) other:

- c. Side: direction: W
  - 1) bays: 2
  - 2) windows: 2, double hung, 6/6, boarded up
  - 3) door(s): n/a
  - 4) other:

- d. Rear: direction: N
  - 1) bays: 1
  - 2) windows: n/a
  - 3) door(s): 1, center, sliding beadboard batten door - original
  - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-11698

1. ADDRESS/LOCATION: 16917 Beach Road


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-11896  
SPO Map 12-13-13  
Hundred Cedar Creek  
Quad Ellendale  
Other \_\_\_\_\_

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 10749 Dupont Highway
3. TOWN/NEAREST TOWN: Ellendale vicinity?
4. MAIN TYPE OF RESOURCE:
 

building <input checked="" type="checkbox"/>	structure <input type="checkbox"/>	site <input type="checkbox"/>	object <input type="checkbox"/>
landscape <input type="checkbox"/>	district <input type="checkbox"/>		
5. MAIN FUNCTION OF PROPERTY: Domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
\_\_\_\_\_


7. ADDITIONAL FORMS USED:

#: Form:	List property types:
X CRS 2 Main Building Form	
CRS 3 Secondary Building Form	
CRS 4 Archaeological Site Form	
CRS 5 Structure (Building-Like) Form	
CRS 6 Structure (Land Feature) Form	
CRS 7 Object Form	
CRS 8 Landscape Elements Form	
X CRS 9 Map Form	N/A
CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace Ziesing

Principal Investigator signature: 

Organization: John Milner Associates, Inc Date: 8/7/2008

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11896

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):


- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
  - 1600-1750∇ Contact Period (Native American)
  - 1630-1730∇ Exploration and Frontier Settlement
  - 1730-1770∇ Intensified and Durable Occupation
  - 1770-1830∇ Early Industrialization
  - 1830-1880∇ Industrialization and Early Urbanization
  - 1880-1940∇ Urbanization and Early Suburbanization
  - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

c) Historic period theme(s)

- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                         |
| <input type="checkbox"/> Forestry              | <input type="checkbox"/> Settlement Patterns and Demographic Changes              |
| <input type="checkbox"/> Trapping/Hunting      | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                  |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                               |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                   |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-11896.001

1. ADDRESS/LOCATION: 10749 Dupont Highway

2. FUNCTION(S): historic dwelling current dwelling

3. YEAR BUILT: 1960 CIRCA?:  ARCHITECT/BUILDER:

4. STYLE OR FLOOR PLAN: Ranch

5. INTEGRITY: original site  moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

- a. wooden ramp added at front entry
- b.

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)


- a. Overall shape: rectangle Stories: 1  
Additions: ramp at front
- b. Structural system (if known): wood-framed
- c. Foundation: materials: concrete block  
basement: full  partial  not visible  no basement
- d. Exterior walls (original if visible& any subsequent coverings): board and batten, asbestos
- e. Roof: shape: side gable  
materials: composition  
cornice:  
dormers:  
chimney: location(s): center, brick

8. DESCRIPTION OF ELEVATIONS:

a.	Facade: Direction:	W
	1) Bays	4
	2) Windows	2
	fenestration	regular
	type	double hung 2/2; fixed bay with flanking double hung
	trim	wood
	shutters	n/a

<b>Facade (cont'd)</b>		
3)	<b>Door(s)</b>	2
	location	side, garage door
	type	wood, wood and glass
	trim	plain
4)	<b>Porch(es)</b>	partial entry porch
<b>b.</b>	<b>Side: Direction:</b>	<b>N</b>
1)	<b>Bays</b>	2
	<b>Windows</b>	2
2)	fenestration	regular
	type	double hung, 2/2
	trim	wood
	shutters	n/a
3)	<b>Door(s)</b>	n/a
	location	
	type	
	trim	
4)	<b>Porch(es)</b>	n/a
<b>c.</b>	<b>Side: Direction:</b>	<b>S</b>
1)	<b>Bays</b>	2
2)	<b>Windows</b>	2
	fenestration	regular
	type	double hung, 2/2
	trim	wood
	shutters	metal awnings
3)	<b>Door(s)</b>	n/a
	location	
	type	
	trim	
4)	<b>Porch(es)</b>	n/a
<b>d.</b>	<b>Rear: Direction:</b>	<b>E</b>
1)	<b>Bays</b>	4
2)	<b>Windows</b>	3
	fenestration	regular
	type	double hung, 2/2
	trim	wood
	shutters	n/a
3)	<b>Door(s)</b>	1
	location	center
	type	wood and glass
	trim	plain
4)	<b>Porch(es)</b>	shed-roof hood supported by wooden supports, concrete stoop

9.	<b>INTERIOR:</b>
10.	<b>LANDSCAPING:</b> h-shaped gravel driveway to front of house, boxwoods planted across front façade, open front lawn, open rear lawn, tall trees grow vertically across middle of rear lawn
11.	<b>OTHER COMMENTS:</b>



**CULTURAL RESOURCE SURVEY  
MAP FORM**

CRS # S-11896

1. ADDRESS/LOCATION: 10749 Dupont Highway


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map )

**INDICATE NORTH ON SKETCH**



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-11897  
SPO Map 12-13-13  
Hundred Cedar Creek  
Quad Ellendale  
Other \_\_\_\_\_

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: 18078 Beach Highway
3. TOWN/NEAREST TOWN: Ellendale vicinity?
4. MAIN TYPE OF RESOURCE:
 

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
\_\_\_\_\_


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace Ziesing

Principal Investigator signature: 

Organization: John Milner Associates, Inc Date: 8/7/2008

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11897

Dwelling is modern, two outbuildings are historic

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750∇ Contact Period (Native American)
- 1630-1730∇ Exploration and Frontier Settlement
- 1730-1770∇ Intensified and Durable Occupation
- 1770-1830∇ Early Industrialization
- 1830-1880∇ Industrialization and Early Urbanization
- 1880-1940∇ Urbanization and Early Suburbanization
- 1940-1960∇ Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- |   |   |
|---|---|
| <input type="checkbox"/> Agriculture                      | <input type="checkbox"/> Transportation and Communication                         |
| <input type="checkbox"/> Forestry                         | <input type="checkbox"/> Settlement Patterns and Demographic Changes              |
| <input type="checkbox"/> Trapping/Hunting                 | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying                 | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering                | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing                    | <input type="checkbox"/> Education  |
| <input checked="" type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                  |
| <input type="checkbox"/> Finance                          | <input type="checkbox"/> Occupational Organizations                               |
| <input type="checkbox"/> Professional Services            | <input type="checkbox"/> Major Families, Individuals and Events                   |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-11897.001

1. ADDRESS/LOCATION: 18078 Beach Highway

2. FUNCTION(S): historic Roadside stand/ commerce current Vacant/ not in use

3. YEAR BUILT: 1955 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site  moved   
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year  
a. bays are boarded over  
b. \_\_\_\_\_

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

- a. Structural system wood-framed
- b. Number of stories 1
- c. Wall coverings currently covered in painted plywood
- d. Foundation none
- e. Roof  
structural system gable front  
coverings composition  
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: N
  - 1) bays: 2
  - 2) windows: 1, vendor/ open bay
  - 3) door(s): 1, side, screen door, transom trim
  - 4) other:

- b. Side: direction: E
  - 1) bays: boarded over
  - 2) windows:
  - 3) door(s):
  - 4) other:
  
- c. Side: direction: W
  - 1) bays: 2
  - 2) windows: 1, vendor/ open bay
  - 3) door(s): 1, wood
  - 4) other:
  
- d. Rear: direction: S
  - 1) bays: 1
  - 2) windows: n/a
  - 3) door(s): 1, center, wood
  - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-11897.002

1. ADDRESS/LOCATION: 18078 Beach Highway

2. FUNCTION(S): historic Garage/ storage current Apartment house

3. YEAR BUILT: 1955 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site  moved

if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. front, shed-roof enclosure; side lean-to carport

b.

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION:

a. Structural system concrete block

b. Number of stories 1

c. Wall coverings

d. Foundation concrete block

e. Roof  
structural system side gable  
coverings composition  
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: N  
1) bays: 2  
2) windows: 1, double hung, 1/1  
3) door(s): 1, center within enclosure, wood  
4) other:

- b. Side: direction: E
  - 1) bays: 1
  - 2) windows: 1, double hung 1/1, steel trim
  - 3) door(s): n/a
  - 4) other:

- c. Side: direction: W
  - 1) bays: 1
  - 2) windows: 1, double hung, 1/1
  - 3) door(s): n/a
  - 4) other:

- d. Rear: direction: S
  - 1) bays: 2
  - 2) windows: 2, double hung, 1/1
  - 3) door(s): n/a
  - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # S-11897

1. ADDRESS/LOCATION: 18078 Beach Highway
2. NOT FOR PUBLICATION  reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )


INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN

**S-11897**

**Beach Highway**



Not to scale

- Chimney
- Structure
- - - Drive
- Road
- - - Roofline