

DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11905
SPO Map 12-13-13
Hundred Cedar Creek
Quad Ellendale
Other _____

- HISTORIC NAME/FUNCTION: Dwelling
- ADDRESS/LOCATION: north side of Fleatown Road
- TOWN/NEAREST TOWN: Ellendale vicinity?
- MAIN TYPE OF RESOURCE: building structure site object
landscape district
- MAIN FUNCTION OF PROPERTY: domestic
- PROJECT TITLE/ REASON FOR SURVEY (if applicable):

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace Ziesing

Principal Investigator signature:

Organization: John Milner Associates, Inc Date: 10/2/2008

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- Pre-European Contact
- Paleo-Indian
- Archaic
- Woodland I
- Woodland II


- 1600-1750∇ Contact Period (Native American)
- 1630-1730∇ Exploration and Frontier Settlement
- 1730-1770∇ Intensified and Durable Occupation
- 1770-1830∇ Early Industrialization
- 1830-1880∇ Industrialization and Early Urbanization
- 1880-1940∇ Urbanization and Early Suburbanization
- 1940-1960∇ Suburbanization and Early Ex-urbanization

b) Geographical zone

- Piedmont
- Upper Peninsula
- Lower Peninsula/Cypress Swamp
- Coastal
- Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11905.001

1. ADDRESS/LOCATION: North side of Fleatown Road

2. FUNCTION(S): historic domestic current domestic

3. YEAR BUILT: 1920 CIRCA?: ARCHITECT/BUILDER:

4. STYLE OR FLOOR PLAN: Vernacular double-pen

5. INTEGRITY: original site moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. resided, new doors, new windows

b. front and side additions; deck at SE corner

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangle Stories: 1.5
Additions: front and side additions; deck at SE corner

b. Structural system (if known): wood-framed

c. Foundation: materials: poured concrete (which obscures another foundation type)
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): vinyl siding


e. Roof: shape: side gable
materials: composition
cornice: boxed
dormers:
chimney: location(s):

8. DESCRIPTION OF ELEVATIONS:

a.	Facade: Direction:	S	
	1) Bays	3	
	2) Windows	fenestration	regular
		type	double hung, 1/1
		trim	vinyl
		shutters	n/a

Facade (cont'd)		
3)	Door(s)	1
	location	center
	type	fiberglass
	trim	plain
4)	Porch(es)	concrete stoop with iron railing on one side
b.	Side: Direction:	W
1)	Bays	2
	2)	Windows
2)	fenestration	irregular
	type	double hung, 1/1
	trim	vinyl
	shutters	n/a
3)	Door(s)	n/a
	location	
	type	
	trim	
4)	Porch(es)	n/a
c.	Side: Direction:	E
1)	Bays	2
2)	Windows	1
	fenestration	irregular
	type	double hung, 1/1
	trim	vinyl
	shutters	n/a
3)	Door(s)	1
	location	
	type	fiberglass
	trim	plain
4)	Porch(es)	modern wood deck at SE corner
d.	Rear: Direction:	N
1)	Bays	3
2)	Windows	2
	fenestration	irregular
	type	double hung, 1/1
	trim	vinyl
	shutters	n/a
3)	Door(s)	1
	location	side
	type	fiberglass
	trim	plain
4)	Porch(es)	wood step with iron railing to one side

9.	INTERIOR:
10.	LANDSCAPING: dwelling faces Fleatown Road; fronted by a dirt parking area; heavily wooded area to rear and side; open lot to W and across the street
11.	OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM

CRS # S-11905

1. ADDRESS/LOCATION: North side of Fleatown Road


2. NOT FOR PUBLICATION reason: _____

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11906
SPO Map 12-13-13
Hundred Cedar Creek
Quad Ellendale
Other _____

1. HISTORIC NAME/FUNCTION: Dwelling

2. ADDRESS/LOCATION: 18126 Fleatown Road

3. TOWN/NEAREST TOWN: Ellendale vicinity?

4. MAIN TYPE OF RESOURCE: building structure
landscape district site object

5. MAIN FUNCTION OF PROPERTY: domestic

6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Courtney Clark

Principal Investigator name: Grace Ziesing

Principal Investigator signature: 

Organization: John Milner Associates, Inc Date: 10/2/2008

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11906

Dwelling and 2 modern outbuildings

Front addition – large, full-width, hipped-roof

Side addition – long, narrow, side-gabled, on E sidewall

Rear addition – full-width, shed-roof

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization


- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

c) Historic period theme(s)

- | | |
|--|---|
| <input type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY

CRS-1



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11906.001

1.	ADDRESS/LOCATION:	18126 Fleatown Road
----	-------------------	---------------------

2.	FUNCTION(S):	historic	domestic	current	domestic
----	--------------	----------	----------	---------	----------

3.	YEAR BUILT:	1900	CIRCA?:	<input checked="" type="checkbox"/>	ARCHITECT/BUILDER:	
----	-------------	------	---------	-------------------------------------	--------------------	--

4.	STYLE OR FLOOR PLAN:	Vernacular / I-house
----	----------------------	----------------------

5.	INTEGRITY:	original site	<input checked="" type="checkbox"/>	moved	<input type="checkbox"/>
----	------------	---------------	-------------------------------------	-------	--------------------------

if moved, from where

other location's CRS #

year

list major alterations and additions with years (if known)

year

a. resided, new entrances, new windows

b. front, side and rear additions

6.	CURRENT CONDITION:	excellent	<input type="checkbox"/>	good	<input checked="" type="checkbox"/>	fair	<input type="checkbox"/>	poor	<input type="checkbox"/>
----	--------------------	-----------	--------------------------	------	-------------------------------------	------	--------------------------	------	--------------------------

7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
----	--

a. Overall shape: rectangle Stories: 2
Additions: front, side and rear additions, new entrances

b. Structural system (if known): wood-framed

c. Foundation: materials: brick
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings): vinyl siding


e. Roof: shape: side gable
materials: composition
cornice: boxed
dormers:
chimney: location(s):

8.	DESCRIPTION OF ELEVATIONS:
----	----------------------------

a.	Facade: Direction:	N	
	1) Bays	3	
	2) Windows	fenestration	regular
		type	double hung, 1/1
		trim	vinyl
		shutters	vinyl, non-functional

Facade (cont'd)		
3)	Door(s)	1
	location	center
	type	fiberglass
	trim	plain
4)	Porch(es)	n/a
b.	Side: Direction:	W
1)	Bays	4
	2)	Windows
2)	fenestration	
	type	double hung, 1/1
	trim	vinyl
	shutters	vinyl, non-functional
3)	Door(s)	n/a
	location	
	type	
	trim	
4)	Porch(es)	n/a
c.	Side: Direction:	E
1)	Bays	2
2)	Windows	2
	fenestration	
	type	double hung, 1/1
	trim	vinyl
3)	Door(s)	n/a
	location	
	type	
	trim	
4)	Porch(es)	n/a
d.	Rear: Direction:	S
1)	Bays	5
2)	Windows	6 (3 per story)
	fenestration	irregular
	type	double hung, 1/1; fixed; greenhouse box windows
	trim	vinyl
	shutters	vinyl, non-functional
3)	Door(s)	2
	location	
	type	fiberglass
	trim	plain
4)	Porch(es)	n/a

9.	INTERIOR:
10.	LANDSCAPING: dwelling faces roadway; gravel drive to its west side; open front, side and rear lawns with scattered shade trees; arborvitae mark east property line; open/ undeveloped lot to West
11.	OTHER COMMENTS:



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-11906

1. ADDRESS/LOCATION: 18126 Fleetown Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # S-11907
SPO Map 12-13-11
Hundred Georgetown
Quad Georgetown
Other _____

1. HISTORIC NAME/FUNCTION: Dwelling
2. ADDRESS/LOCATION: Shoemaker Lane, North side of Redden Road
3. TOWN/NEAREST TOWN: Georgetown vicinity?
4. MAIN TYPE OF RESOURCE:

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: domestic
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):


7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	
X	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
X	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature: 

Organization: John Milner Associates, Inc Date: 9/4/2008

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-11907

House appears to be an altered bungalow. 2 older outbuildings in overgrown area to NW, 1 shed behind house


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
 - Paleo-Indian
 - Archaic
 - Woodland I
 - Woodland II
 - 1600-1750∇ Contact Period (Native American)
 - 1630-1730∇ Exploration and Frontier Settlement
 - 1730-1770∇ Intensified and Durable Occupation
 - 1770-1830∇ Early Industrialization
 - 1830-1880∇ Industrialization and Early Urbanization
 - 1880-1940∇ Urbanization and Early Suburbanization
 - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
 - Upper Peninsula
 - Lower Peninsula/Cypress Swamp
 - Coastal
 - Urban (City of Wilmington)

- c) Historic period theme(s)
- | | |
|---|---|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication |
| <input type="checkbox"/> Forestry | <input type="checkbox"/> Settlement Patterns and Demographic Changes |
| <input type="checkbox"/> Trapping/Hunting | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying | <input type="checkbox"/> Government |
| <input type="checkbox"/> Fishing/Oystering | <input type="checkbox"/> Religion |
| <input type="checkbox"/> Manufacturing | <input type="checkbox"/> Education |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations |
| <input type="checkbox"/> Finance | <input type="checkbox"/> Occupational Organizations |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events |

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # S-11907.001

1. ADDRESS/LOCATION: Shoemaker Lane, North side of Redden Road

2. FUNCTION(S): historic domestic current domestic

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER:

4. STYLE OR FLOOR PLAN: Bungalow/ craftsman with later addition

5. INTEGRITY: original site moved

if moved, from where other location's CRS # year

list major alterations and additions with years (if known) year

a. new siding, new roofing, windows and chimney

b. front façade obscured by large perpendicular addition

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: complex Stories: 1.5
Additions: large perpendicular addition over front façade

b Structural system (if known): wood-framed

c. Foundation: materials: not visible
basement: full partial not visible no basement

d. Exterior walls (original if visible& any subsequent coverings):


e. Roof: shape: side gable
materials: standing seam metal – modern
cornice: boxed
dormers:
chimney: location(s): ext. gable, concrete block

8. DESCRIPTION OF ELEVATIONS:

a.	Facade: Direction:	E
	1) Bays	6
	2) Windows	5 (1 st story), 1 (upper floor)
	fenestration	irregular
	type	double hung, 1/1, vinyl
	trim	vinyl
	shutters	vinyl, non-functional

Facade (cont'd)		
3)	Door(s)	1
	location	center
	type	wood
	trim	plain
4)	Porch(es)	concrete stoop
b.	Side: Direction:	N
1)	Bays	1
	2)	Windows
	fenestration	regular
	type	double hung, 1/1, vinyl
	trim	vinyl
	shutters	vinyl, non-functional
3)	Door(s)	n/a
	location	
	type	
	trim	
4)	Porch(es)	shed roofed porch obscured by later enclosed porch addition
c.	Side: Direction:	S
1)	Bays	1
2)	Windows	1
	fenestration	irregular
	type	double hung, 1/1, vinyl
	trim	vinyl
	shutters	vinyl, non-functional
3)	Door(s)	n/a
	location	
	type	
	trim	
4)	Porch(es)	same porch as rear
d.	Rear: Direction:	W
1)	Bays	4
2)	Windows	2 (1 st story), 1 (upper floor)
	fenestration	irregular
	type	double hung, 1/1, vinyl
	trim	vinyl
	shutters	vinyl, non-functional
3)	Door(s)	1
	location	right side
	type	modern flush door (wood)
	trim	plain
4)	Porch(es)	shed-roofed modern open porch with plain wood piers, concrete floor

9.	INTERIOR:
10.	LANDSCAPING: long gravel driveway leads to house with open land surrounding it; line of mostly modern outbuildings behind the house W of driveway; agricultural fields to E and NE; overgrown corncrib and chicken house to NW of house – not accessible; several concrete square pads indicating former outbuilding sites; chicken house partially collapsed; many ornamental flowerbed areas
11.	OTHER COMMENTS: original façade faced S; mostly obscured by addition



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11907.002

1. ADDRESS/LOCATION: Shoemaker Lane, North side of Redden Road

2. FUNCTION(S): historic Agricultural shed current unknown

3. YEAR BUILT: 1940 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: Vernacular, one pen

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year
a. _____
b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-framed
- b. Number of stories 1
- c. Wall coverings modern plywood
- d. Foundation concrete block piers
- e. Roof
 - structural system side gable, exposed rafter ends
 - coverings asphalt
 - openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
 - 1) bays: 1
 - 2) windows: n/a
 - 3) door(s): 1, left side, wooden beadboard batten door
 - 4) other:

- b. Side: direction: E
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: W
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: N
 - 1) bays: 0
 - 2) windows:
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
SECONDARY BUILDING FORM

CRS # S-11907.003

1. ADDRESS/LOCATION: Shoemaker Lane, North side of Redden Road

2. FUNCTION(S): historic Chicken house current Vacant/ not in use

3. YEAR BUILT: 1960 CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/FLOOR PLAN: _____

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. overgrown and collapsing

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION:

- a. Structural system wood-framed
- b. Number of stories 1
- c. Wall coverings wood siding (vertical), asbestos

d. Foundation

- e. Roof
 - structural system shed-roof, exposed rafter ends
 - coverings corrugated metal (uncertain)
 - openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: S
 - 1) bays: not visible
 - 2) windows: continuous
 - 3) door(s): several – some missing; wood batten doors at regular intervals
 - 4) other:

- b. Side: direction: E
 - 1) bays: not visible
 - 2) windows:
 - 3) door(s):
 - 4) other:

- c. Side: direction: W
 - 1) bays: not visible
 - 2) windows:
 - 3) door(s):
 - 4) other:

- d. Rear: direction: N
 - 1) bays: not visible
 - 2) windows:
 - 3) door(s):
 - 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
STRUCTURE (BUILDING-LIKE) FORM

CRS # S-11907.004

1. ADDRESS/LOCATION: Shoemaker Lane, North side of Redden Road

2. FUNCTION: corncrib IN USE?

3. YEAR BUILT: _____ CIRCA?: ARCHITECT/BUILDER: _____

4. STYLE/PLAN: Drive-through corncrib with center 1.5 story front gabled main block

5. INTEGRITY: original site moved
if moved, from where original location's CRS # year

list major alterations and additions with dates (if known) year

a. overgrown and inaccessible, none evident

b. _____

6. CURRENT CONDITION: excellent good fair poor

7. DESCRIPTION (describe the structure as completely as possible):

a) Overall shape rectangle
height
length
width

b) Structural system: frame

c) Foundation: inaccessible


d) Exterior covering: wood siding (vertical)

7. DESCRIPTION (cont'd):

CRS # S-11907.004

e) Openings not visible; 1 door on second floor level of center section (full size, wood battens)

f) Other features Drive-through corncrib with center 1.5 story front gabled main block and shed-roof wings on each side



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAP FORM


CRS # S-11907

1. ADDRESS/LOCATION: Shoemaker Lane, North side of Redden Road
2. NOT FOR PUBLICATION reason: _____
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN

