

DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-12178  
SPO Map 12-13-12,  
14-15-12,  
12-13-11  
Hundred Cedar Creek,  
Georgetown,  
Broadkill  
Ellendale,  
Georgetown  
Quad \_\_\_\_\_  
Other \_\_\_\_\_

1. HISTORIC NAME/FUNCTION: Ellendale State Forest
2. ADDRESS/LOCATION: east and west sides, U.S. Route 113, starting approx. 1 mile south of Ellendale crossroad
3. TOWN/NEAREST TOWN: Ellendale vicinity?
4. MAIN TYPE OF RESOURCE: building  structure  site  object   
landscape  district
5. MAIN FUNCTION OF PROPERTY: state forest
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
U.S. Route 113 North/South Study, Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
	CRS 2 Main Building Form	
	CRS 3 Secondary Building Form	
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
1	CRS 8 Landscape Elements Form	
1	CRS 9 Map Form	
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Douglas C. Mcvarish

Principal Investigator name: Grace H. Ziesing

Principal Investigator signature:

Organization: John Milner Associates, Inc. Date: 12/1/2008

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-12178

Established as the Ellendale State Forest in 1931, this tract was merged into the Redden State Forest in 1995 and is now known as the Ellendale Tract. The National-Register listed property S-08151 (Ellendale State Forest Picnic Facility) is located within this tract.

10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
  - 1600-1750∇ Contact Period (Native American)
  - 1630-1730∇ Exploration and Frontier Settlement
  - 1730-1770∇ Intensified and Durable Occupation
  - 1770-1830∇ Early Industrialization
  - 1830-1880∇ Industrialization and Early Urbanization
  - 1880-1940∇ Urbanization and Early Suburbanization
  - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

c) Historic period theme(s)

- |  |  |
|--|--|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication              |
| <input checked="" type="checkbox"/> Forestry   | <input type="checkbox"/> Settlement Patterns and Demographic Changes   |
| <input type="checkbox"/> Trapping/Hunting      | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government                                    |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion                                      |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education                                     |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                       |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                    |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events        |



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
LANDSCAPE ELEMENTS FORM

CRS # S-12178

1. ADDRESS/LOCATION: east and west sides, U.S. Route 113, starting approx. 1 mile south of Ellendale crossroad

2. TYPE/FUNCTION/NAME: Ellendale Tract, Redden State Forest

3. YEAR BUILT: 1915 CIRCA?:

list major alterations and additions with years (if known)

	<u>year</u>
a. establishment of loblolly pine plantation	1988
b. 137-acre tract added	2007

4. DESIGNER: original n/a  
alteration(s) n/a

5. STYLE: n/a

6. CURRENT CONDITION: excellent  good  fair  poor

7. RELATIONSHIP TO OTHER PROPERTIES: located south of the Appenzellar Tract of the Redden State Forest

8. DESCRIPTION:

a) Scenic views/vistas: none discernable

b) Circulation system: unpaved access roads that do not interconnect

c) Spatial subdivisions: the forest is divided into 27 stands based upon tree types and planting dates

d) Paving material(s): none

e) Utilities: none

f) Water elements: tax ditches (installed during the CCC period and in the 1970s)

g) Vegetation: trees in tracts along U.S. Route 113 include loblolly pines, Virginia pines, sweetgum, red and willow oaks, and other mixed hardwoods.

h) Other:

DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-12178

1. ADDRESS/LOCATION: east and west sides, U.S. 113, starting approx. 1 mile south of Ellendale crossroad


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:


Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN





DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
PROPERTY IDENTIFICATION FORM

CRS # S-12179  
SPO Map 12-13-11  
Hundred Georgetown  
Quad Georgetown  
Other \_\_\_\_\_

1. HISTORIC NAME/FUNCTION: ECW Camp S-53 Mess Hall
2. ADDRESS/LOCATION: Southeast corner, intersection of Mccolley's Chapel Road and Redden Road
3. TOWN/NEAREST TOWN: \_\_\_\_\_ vicinity?
4. MAIN TYPE OF RESOURCE:
 

building	<input checked="" type="checkbox"/>	structure	<input type="checkbox"/>	site	<input type="checkbox"/>	object	<input type="checkbox"/>
landscape	<input type="checkbox"/>	district	<input type="checkbox"/>				
5. MAIN FUNCTION OF PROPERTY: fellowship hall for church across street
6. PROJECT TITLE/ REASON FOR SURVEY (if applicable):  
U.S. 113 North/South Study; Delaware Department of Transportation

7. ADDITIONAL FORMS USED:

#:	Form:	List property types:
X	CRS 2 Main Building Form	former barracks
X	CRS 3 Secondary Building Form	shed
	CRS 4 Archaeological Site Form	
	CRS 5 Structure (Building-Like) Form	
	CRS 6 Structure (Land Feature) Form	
	CRS 7 Object Form	
	CRS 8 Landscape Elements Form	
X	CRS 9 Map Form	N/A
	CRS 14 Potential District Form	

8. SURVEYOR INFORMATION:

Surveyor name: Kate Farnham

Principal Investigator name: Grace Ziesing

Principal Investigator signature: 

Organization: John Milner Associates, Inc. Date: 9/5/2008

9. OTHER NOTES OR OBSERVATIONS:

CRS# S-12179

The building is currently used as the fellowship hall for McColley's Chapel, which is across the road, but is not owned by the church. According to a church member, it was moved to its current location ca. 1960 and was originally a CCC building located at the Redden State Forest CCC camp in the Jester Tract, approximately 1.8 miles west on Redden Road.


10. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

- a) Time period(s)
- Pre-European Contact
  - Paleo-Indian
  - Archaic
  - Woodland I
  - Woodland II
  - 1600-1750∇ Contact Period (Native American)
  - 1630-1730∇ Exploration and Frontier Settlement
  - 1730-1770∇ Intensified and Durable Occupation
  - 1770-1830∇ Early Industrialization
  - 1830-1880∇ Industrialization and Early Urbanization
  - 1880-1940∇ Urbanization and Early Suburbanization
  - 1940-1960∇ Suburbanization and Early Ex-urbanization

- b) Geographical zone
- Piedmont
  - Upper Peninsula
  - Lower Peninsula/Cypress Swamp
  - Coastal
  - Urban (City of Wilmington)

c) Historic period theme(s)

- |  |   |
|--|---|
| <input type="checkbox"/> Agriculture           | <input type="checkbox"/> Transportation and Communication                         |
| <input type="checkbox"/> Forestry              | <input type="checkbox"/> Settlement Patterns and Demographic Changes              |
| <input type="checkbox"/> Trapping/Hunting      | <input checked="" type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying      | <input type="checkbox"/> Government   |
| <input type="checkbox"/> Fishing/Oystering     | <input type="checkbox"/> Religion   |
| <input type="checkbox"/> Manufacturing         | <input type="checkbox"/> Education  |
| <input type="checkbox"/> Retailing/Wholesaling | <input type="checkbox"/> Community Organizations                                  |
| <input type="checkbox"/> Finance               | <input type="checkbox"/> Occupational Organizations                               |
| <input type="checkbox"/> Professional Services | <input type="checkbox"/> Major Families, Individuals and Events                   |



CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # S-12179.001

1. ADDRESS/LOCATION: southeast corner, intersection McColley's Chapel Road and Redden Road

2. FUNCTION(S): historic CCC mess hall current fellowship hall

3. YEAR BUILT: 1935 CIRCA?:  ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE OR FLOOR PLAN: vernacular Craftsman

5. INTEGRITY: original site  moved

if moved, from where other location's CRS # year  
CCC camp in Jester Tract of Redden State Forest, approx. 1.8 miles ca.  
west on Redden Road 1960

list major alterations and additions with years (if known) year  
a. handicap ramp added to facade  
b.

6. CURRENT CONDITION: excellent  good  fair  poor

7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)

a. Overall shape: rectangle Stories: 1  
Additions:

b Structural system (if known): wood-framed

c. Foundation: materials: concrete block  
basement: full  partial  not visible  no basement

d. Exterior walls (original if visible& any subsequent coverings): asbestos

e. Roof: shape: side gable  
materials: metal  
cornice:  
dormers:  
chimney: location(s): concrete-block, exterior rear wall

8. DESCRIPTION OF ELEVATIONS:


a. Facade: Direction: North  
1) Bays 5  
2) Windows 4  
fenestration regular  
type 1/1, double-hung  
trim wood  
shutters

**Facade (cont'd)**

- 3) Door(s) 1  
     location center  
     type wood & glass, 6 lights/2 panels; double screen doors  
     trim wood
- 4) Porch(es) gabled entry
- b. Side: Direction: East
- 1) Bays 3
- 2) Windows 2  
     fenestration regular  
     type casement  
     trim wood  
     shutters
- 3) Door(s) 1  
     location center  
     type wood & glass; 6 lights, 2 panels  
     trim wood; screen door
- 4) Porch(es) stoop with concrete steps and aluminum railing to one side
- c. Side: Direction: West
- 1) Bays 3
- 2) Windows 2  
     fenestration regular  
     type 1/1, double-hung  
     trim wood  
     shutters
- 3) Door(s) 1  
     location center  
     type wood & glass; 6 lights, 2 panels  
     trim wood; storm door
- 4) Porch(es) stoop with concrete steps and flanking aluminum hand rails
- d. Rear: Direction: South
- 1) Bays 4
- 2) Windows 4  
     fenestration regular  
     type 1/1, double-hung  
     trim wood  
     shutters
- 3) Door(s) none  
     location  
     type  
     trim
- 4) Porch(es)

**9. INTERIOR:**

10. **LANDSCAPING:** open lot at southeast corner of McColley's Chapel Road and Redden Road; building faces north to Redden Road; heavy, tall trees surround property on south and east
11. **OTHER COMMENTS:**



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # S-12179.002

1. ADDRESS/LOCATION: 18168 McColley's Chapel Road

2. FUNCTION(S): historic Unknown current Storage shed

3. YEAR BUILT: 1920 CIRCA?: Y ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: \_\_\_\_\_

5. INTEGRITY: original site  moved   
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year  
a.  
b.

6. CURRENT CONDITION: excellent  good X fair  poor

7. DESCRIPTION:

- a. Structural system wood-framed
- b. Number of stories 1
- c. Wall coverings wood siding (vertical)
- d. Foundation concrete block piers
- e. Roof gabled front  
structural system  
coverings metal  
openings

8. DESCRIPTION OF ELEVATIONS:

- a. Facade: direction: E
  - 1) bays: 1
  - 2) windows:
  - 3) door(s): 1
  - 4) other:

- b. Side: direction: N
- 1) bays: 0
- 2) windows:
- 3) door(s):
- 4) other:

- c. Side: direction: S
- 1) bays: 0
- 2) windows:
- 3) door(s):
- 4) other:

- d. Rear: direction: W
- 1) bays: 0
- 2) windows:
- 3) door(s):
- 4) other:


9. INTERIOR (if accessible):

a) Floor plan

b) Partition/walls

c) Finishes

d) Furnishings/machinery



CULTURAL RESOURCE SURVEY  
MAP FORM

CRS # S-12179

1. ADDRESS/LOCATION: Redden Road


2. NOT FOR PUBLICATION  reason: \_\_\_\_\_

3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.


(attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN

**S-12179**



Not to scale

- Chimney
- Structure
- - - Drive
- Road
- Roofline